

```
{
  "typeOfReport": {
    "label": "Residential Bungalow ",
    "value": "Residential_Bungalow_"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64d3753487258203eab0187e"
    },
    "type": "CREDITOFFICER",
    "_id": "64d3753487258203eab01880",
    "firstName": "Malge Yogesh",
    "lastName": "Veebhadraswami",
    "mobileNo": "",
    "workMobileNo": "9008175721",
    "email": "yogesh.malge@unionbankofindia.bank"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "4500000",
    "discussWithPerson": "Malge Yogesh",
    "expectedFees": 2250,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64d3753487258203eab0187e",
  "name": "Corporate & SME Powai Branch",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "ubin0556688@unionbankofindia.bank",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Dikshant Bhawan, 1st Floor, Shop No 101, Above Indian Oil Petrol
Pump, Opp IIT Main Gate, Powai, Mumbai - 40076"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "627219d6afd7d55eddedd283",
```

```
"role": "PICKUPPERSON",
"firstName": "Mangesh ",
"email": "mangeshpalande17@gmail.com",
"lastName": "Palande",
"mobileNo": "9833030550",
"shortName": "MP",
"workWithDocumentMaker": "",
"profilePhoto": "users/627219d6afd7d55eddedd283/
profilePhoto_1668055836118_WhatsApp_Image_20221110_at_101725_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63fc575ece84bf289ba9e82d",
"role": "SITEENGINEER",
"firstName": "Deepak ",
"email": "daksh7831@gmail.com",
"lastName": "Jain ",
"mobileNo": "9022815908",
"designation": "",
"shortName": "DJ",
"workWithDocumentMaker": ""
},
"rateVerifier": "",
"maker": "",
"checker": "",
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
}
},

```

```
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.16160328932662",
  "longitude": "72.78345835462096"
},
"geo": {
```

```
"type": "Point",
"coordinates": [
  72.78345835462096,
  19.16160328932662
]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Erangal",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Basement",
```

```
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "20",
  "label": true
},
"buildingName": {
  "status": false,
```

```
"name": "Building Name",
"key": "buildingName",
"value": "",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Madh Marve road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
}
```

```
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
```



```
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
}
```

```
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Malad West",
  "label": false
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
```

```
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentId": [],
"_id": "651fd7e3119cca234ddb8312",
"ownerName": "Sanjay niwaskar",
"ownerPhoneNo": "9820042197",
"appAddress": "plot no 20 survey no 22 bunglow cottage F village erangal madh
Marve Malad w ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Conveyance Deed",
      "value": "60ae1252aa6d152c1801b31f"
    },
    "isHardCopy": false,
    "path": "cases/651fd7e3119cca234ddb8312/
document_1696585466685_TATUS_3.pdf",
    "fileName": "document_1696585466685_TATUS_3.pdf",
    "displayStatus": false,
    "id": "438318",
    "uploadedBy": "627219d6afd7d55eddedd283",
    "createdAt": "Fri Oct 06 2023 15:17:35 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
  },
]
```



```
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1696593268210_Tatus_villa_Agreement_4.pdf",
"path": "cases/651fd7e3119cca234ddb8312/
document_1696593268210_Tatus_villa_Agreement_4.pdf",
"id": "196856",
"uploadedBy": "6006d4ce5080a310ac1fdcf2",
"createdAt": "Fri Oct 06 2023 17:26:37 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae12a0aa6d152c1801b483",
    "label": "site Details"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1696913242898_Mr_sanjay_niwaskar.pdf",
  "path": "cases/651fd7e3119cca234ddb8312/
document_1696913242898_Mr_sanjay_niwaskar.pdf",
  "id": "743485",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Tue Oct 10 2023 10:17:22 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004230",
"createdBy": "627219d6afd7d55eddedd283",
"caseHistory": [
  {
    "id": "884359",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Oct 06 2023 15:18:19 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Sanjay niwaskar",
    "phone": "9820042197",
    "ownershipShare": "",
    "email": "",
    "id": "544831"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
```

```
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6524d709703d7c40db977df7",
    "name": "externalimg_1696913161083_IMG_20231009_165143.jpg",
    "path": "cases/651fd7e3119cca234ddb8312/
externalimg_1696913161083_IMG_20231009_165143.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6524d709703d7c40db977df8",
    "name": "externalimg_1696913161589_IMG_20231009_165205.jpg",
    "path": "cases/651fd7e3119cca234ddb8312/
externalimg_1696913161589_IMG_20231009_165205.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6524d709703d7c40db977df9",
    "name": "externalimg_1696913161602_IMG_20231009_165206.jpg",
    "path": "cases/651fd7e3119cca234ddb8312/
externalimg_1696913161602_IMG_20231009_165206.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6524d709703d7c40db977dfa",
    "name": "externalimg_1696913161613_IMG_20231009_165207.jpg",
    "path": "cases/651fd7e3119cca234ddb8312/
externalimg_1696913161613_IMG_20231009_165207.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6524d709703d7c40db977dfb",
```

```
    "name": "externallmg_1696913161621_IMG_20231009_165226.jpg",
    "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913161621_IMG_20231009_165226.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6524d709703d7c40db977dfc",
    "name": "externallmg_1696913161628_IMG_20231009_224931_Bokeh__01.jpg",
    "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913161628_IMG_20231009_224931_Bokeh__01.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6524d709703d7c40db977dfd",
    "name": "externallmg_1696913161631_IMG_20231009_224942_Bokeh__01.jpg",
    "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913161631_IMG_20231009_224942_Bokeh__01.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6524d709703d7c40db977dfe",
    "name": "externallmg_1696913161633_terrace_1.jpg",
    "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913161633_terrace_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6524d709703d7c40db977dff",
    "name": "externallmg_1696913161642_terrace_2.jpg",
    "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913161642_terrace_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6524d709703d7c40db977e00",
    "name": "externallmg_1696913161648_terrace_3.jpg",
```

```
    "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913161648_terrace_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6524d709703d7c40db977e01",
    "name": "externallmg_1696913161653_terrace_4.jpg",
    "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913161653_terrace_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6524d709703d7c40db977e02",
    "name": "externallmg_1696913161658_1st_floor_1.jpg",
    "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913161658_1st_floor_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6524d709703d7c40db977e03",
    "name": "externallmg_1696913161661_1st_floor_2.jpg",
    "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913161661_1st_floor_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6524d709703d7c40db977e04",
    "name": "externallmg_1696913161664_1st_floor_3.jpg",
    "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913161664_1st_floor_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6524d709703d7c40db977e05",
    "name": "externallmg_1696913161667_1st_floor_4.jpg",
    "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913161667_1st_floor_4.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6524d709703d7c40db977e06",
  "name": "externallmg_1696913161669_1st_floor_5.jpg",
  "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913161669_1st_floor_5.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6524d709703d7c40db977e07",
  "name": "externallmg_1696913161673_agent_number.jpg",
  "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913161673_agent_number.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6524d709703d7c40db977e08",
  "name": "externallmg_1696913161678_compound_1.jpg",
  "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913161678_compound_1.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6524d709703d7c40db977e09",
  "name": "externallmg_1696913161684_compound_3.jpg",
  "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913161684_compound_3.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6524d709703d7c40db977e0a",
  "name": "externallmg_1696913161690_compound_4.jpg",
  "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913161690_compound_4.jpg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6524d724703d7c40db977e88",
  "name": "externallmg_1696913188111_compound_5.jpg",
  "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913188111_compound_5.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6524d724703d7c40db977e89",
  "name": "externallmg_1696913188117_compound_6.jpg",
  "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913188117_compound_6.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6524d724703d7c40db977e8a",
  "name": "externallmg_1696913188122_compound_7.jpg",
  "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913188122_compound_7.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6524d724703d7c40db977e8b",
  "name": "externallmg_1696913188127_compound_8.jpg",
  "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913188127_compound_8.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6524d724703d7c40db977e8c",
  "name": "externallmg_1696913188134_compound_9.jpg",
  "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913188134_compound_9.jpg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6524d724703d7c40db977e8d",
  "name": "externallmg_1696913188139_gate_1.jpg",
  "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913188139_gate_1.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6524d724703d7c40db977e8e",
  "name": "externallmg_1696913188147_gate_2.jpg",
  "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913188147_gate_2.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6524d724703d7c40db977e8f",
  "name": "externallmg_1696913188156_gate_3.jpg",
  "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913188156_gate_3.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6524d724703d7c40db977e90",
  "name": "externallmg_1696913188164_ground_floor_1.jpg",
  "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913188164_ground_floor_1.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6524d724703d7c40db977e91",
  "name": "externallmg_1696913188168_ground_floor_2.jpg",
  "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913188168_ground_floor_2.jpg",
  "orientation": "portrait"
},
{
```

```
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6524d724703d7c40db977e92",
"name": "externallmg_1696913188173_ground_floor_3.jpg",
"path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913188173_ground_floor_3.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6524d724703d7c40db977e93",
"name": "externallmg_1696913188176_ground_floor_4.jpg",
"path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913188176_ground_floor_4.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6524d724703d7c40db977e94",
"name": "externallmg_1696913188179_ground_floor_5.jpg",
"path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913188179_ground_floor_5.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6524d724703d7c40db977e95",
"name": "externallmg_1696913188183_ground_floor_6.jpg",
"path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913188183_ground_floor_6.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6524d724703d7c40db977e96",
"name": "externallmg_1696913188187_ground_floor_7.jpg",
"path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913188187_ground_floor_7.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "6524d724703d7c40db977e97",
  "name": "externallmg_1696913188190_ground_floor_8.jpg",
  "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913188190_ground_floor_8.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6524d724703d7c40db977e98",
  "name": "externallmg_1696913188196_ground_floor_9.jpg",
  "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913188196_ground_floor_9.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6524d724703d7c40db977e99",
  "name": "externallmg_1696913188200_ground_floor_10.jpg",
  "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913188200_ground_floor_10.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6524d724703d7c40db977e9a",
  "name": "externallmg_1696913188206_ground_floor_11.jpg",
  "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913188206_ground_floor_11.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6524d724703d7c40db977e9b",
  "name": "externallmg_1696913188212_ground_floor_12.jpg",
  "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913188212_ground_floor_12.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "6524d743703d7c40db978005",
    "name": "externallmg_1696913219395_IMG_20231009_163310.jpg",
    "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913219395_IMG_20231009_163310.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6524d743703d7c40db978006",
    "name": "externallmg_1696913219401_IMG_20231009_163312.jpg",
    "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913219401_IMG_20231009_163312.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6524d743703d7c40db978007",
    "name": "externallmg_1696913219410_IMG_20231009_163315.jpg",
    "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913219410_IMG_20231009_163315.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6524d743703d7c40db978008",
    "name": "externallmg_1696913219419_IMG_20231009_163420.jpg",
    "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913219419_IMG_20231009_163420.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6524d743703d7c40db978009",
    "name": "externallmg_1696913219533_IMG_20231009_164110.jpg",
    "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913219533_IMG_20231009_164110.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6524d743703d7c40db97800a",
```

```
    "name": "externallmg_1696913219538_IMG_20231009_164118.jpg",
    "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913219538_IMG_20231009_164118.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6524d743703d7c40db97800b",
    "name": "externallmg_1696913219543_IMG_20231009_164136.jpg",
    "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913219543_IMG_20231009_164136.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6524d743703d7c40db97800c",
    "name": "externallmg_1696913219547_IMG_20231009_164159.jpg",
    "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913219547_IMG_20231009_164159.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6524d743703d7c40db97800d",
    "name": "externallmg_1696913219553_IMG_20231009_164228.jpg",
    "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913219553_IMG_20231009_164228.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6524d743703d7c40db97800e",
    "name": "externallmg_1696913219557_IMG_20231009_164248.jpg",
    "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913219557_IMG_20231009_164248.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6524d743703d7c40db97800f",
    "name": "externallmg_1696913219561_IMG_20231009_164250.jpg",
```

```
    "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913219561_IMG_20231009_164250.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6524d743703d7c40db978010",
    "name": "externallmg_1696913219567_IMG_20231009_164302.jpg",
    "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913219567_IMG_20231009_164302.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6524d743703d7c40db978011",
    "name": "externallmg_1696913219573_IMG_20231009_164318.jpg",
    "path": "cases/651fd7e3119cca234ddb8312/
externallmg_1696913219573_IMG_20231009_164318.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-10-06T09:48:19.818Z",
"updatedAt": "2023-10-10T04:47:22.988Z",
"__v": 0,
"invoiceId": "651fd7e4119cca234ddb8318",
"fullAddress": "Residential Residential Bungalow No. Basement Floor, Plot No. 20,
Madh Marve road, Village - Erangal, Malad West, Mumbai, State - Maharashtra, India",
"updatedBy": "6006d4ce5080a310ac1fdfc2",
"addressForMap": "",
"caseReferredBy": "627219d6afd7d55eddedd283",
"contactPersonName": "Sanjay niwaskar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9820042197"
}
```

| <b>Name</b>   | <b>Length</b> | <b>Width</b> | <b>Total</b> |
|---------------|---------------|--------------|--------------|
| <hr/>         |               |              |              |
| Composition : |               |              |              |
| <hr/>         |               |              |              |
| Other         |               |              |              |
| Composition : |               |              |              |
| <hr/>         |               |              |              |