

```
{
  "typeOfReport": {
    "value": "Structural_Report",
    "label": "Structural Report"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64353bf7a99b2228209dbc5f"
    },
    "type": "CREDITOFFICER",
    "_id": "64353bf7a99b2228209dbc61",
    "firstName": "Vaijayanti ",
    "lastName": "Khade",
    "mobileNo": "",
    "workMobileNo": "0000000000",
    "email": "vjbhiw@bankofbaroda.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "6418456a96b58848585f8cb2",
"name": "Thane",
"email": "thane@vastukala.com",
"phone": "1234567890",
"address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
"city": "Thane",
"shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64353bf7a99b2228209dbc5f",
  "name": "old Jakatnaka Branch\t",
  "branchCode": "",
  "mobileNo": "02522252724\t",
  "alternateMobileNo": "",
  "email": "vjbhiw@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Old Jakatnaka Branch , SHop No 1 & 2, Konark Arcade, Near Bhiwandi
Municipal Corporation, Bhiwandi, 4211302"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f90106f3dd69653a590b0b",
  "zoneName": "Mumbai Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "64abdb2806d6ec174986d16b",
"role": "PICKUPPERSON",
"firstName": "Sahadu",
"email": "thoratsahadu8679@gmail.com",
"lastName": "Thorat",
"mobileNo": "9422389642",
"shortName": "ST",
"workWithDocumentMaker": ""
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62ea09ea4e679b264caf07d7",
  "role": "SITEENGINEER",
  "firstName": "Suraj",
  "email": "suraj@vastukala.org",
  "lastName": "Zore",
  "mobileNo": "8652448654",
  "designation": "",
  "shortName": "SZ",
  "workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
  "profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60eebe33f3dd69653a5837ae",
  "role": "MAKER",
  "firstName": "Shamal",
  "email": "shamal@vastukala.org",
  "lastName": "Bodke",
  "mobileNo": "9821740317",
  "designation": "",
```

```
    "shortName": "SB",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "60eeaeddf3dd69653a581316",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Shyam",
    "email": "shyam@vastukala.org",
    "lastName": "Kajvilkar",
    "mobileNo": "9765074720",
    "designation": "",
    "shortName": "SK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "[N]C.C.I.T/I -14/52/2008-09",
          "label": "Wealth Tax"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "6084131a13f01f158c6ea1f3",
      "PANNo": "AEAPC7114Q",
      "role": "VALUER",
      "firstName": "Sharadkumar",
      "fatherName": "Baburao",
      "email": "cmd@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9422171100",
      "designation": "CMD",
      "registrationNo": [
        {
          "title": {
            "value": "Wealth_Tax",
            "label": "Wealth Tax"
          },
          "_id": "6084131a13f01f158c6ea1f4",
          "number": "[N]C.C.I.T/I -14/52/2008-09"
        }
      ]
    }
  ]
}
```

```
    ],
    "shortName": "SBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
  }
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.300939166627867",
  "longitude": "73.05786664160463"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-11",
      "remark": ""
    }
  ]
},
"schedule": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
```

```
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Bhiwandi",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
}
```

```
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Bhiwandi",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "New Chawl",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
```

```
"value": "",
"label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Bazar Peth, M. H. No. 60",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
```



```
"status": true,
"name": "CTS No.",
"key": "CTSNo",
"value": "C.T.S. No. 1839, 1840, 1865 & 1866 & Old House No. 66 & 67",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "103",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
```

```
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "421 302",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
```

```
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
```

```
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
```

```
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentId": [],
"_id": "6523e2ab703d7c40db96d89d",
"ownerName": "Smt. Rohini Prakash Sikchi",
"ownerPhoneNo": "9822533909",
```



```
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9822533909",
"contactPersonName": "Prakash Oil Main Proprietor",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Smt. Rohini Prakash Sikchi",
    "phone": "9822533909",
    "ownershipShare": "",
    "email": "",
    "id": "898728"
  }
],
"caseReferredBy": "64abdb2806d6ec174986d16b",
"relationWithOwner": "NA",
"fullAddress": "Residential Structural Report No. 103, 1st Floor, New Chawl, Bazar Peth, M. H. No. 60, CTS No. C.T.S. No. 1839, 1840, 1865 & 1866 & Old House No. 66 & 67, Village - Bhiwandi, Taluka - Bhiwandi,, District - Thane, 421 302, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1255aa6d152c1801b32b",
      "label": "Valuation Report"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1696850557597_VALAUATION_REPORT_5.pdf",
    "path": "cases/6523e2ab703d7c40db96d89d/document_1696850557597_VALAUATION_REPORT_5.pdf",
    "id": "750203",
    "uploadedBy": "6430f74691d7c62df11f3f15",
    "createdAt": "Mon Oct 09 2023 16:52:42 GMT+0530 (India Standard Time)"
  }
],
"isUrgent": "false",
"isExternal": "false",
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "004300",
"createdBy": "6430f74691d7c62df11f3f15",
"caseHistory": [
  {
    "id": "821750",
    "title": "Create Case",
```

```
    "description": "Create Case",
    "datetime": "Mon Oct 09 2023 16:53:23 GMT+0530 (India Standard Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6526021d703d7c40db9961af",
    "name": "externalimg_r_1696989603912_1696989520892_image_1.jpg",
    "path": "cases/6523e2ab703d7c40db96d89d/
externalimg_r_1696989603912_1696989520892_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6526021d703d7c40db9961b0",
    "name": "externalimg_r_1696989605837_1696989520892_image_2.jpg",
    "path": "cases/6523e2ab703d7c40db96d89d/
externalimg_r_1696989605837_1696989520892_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6526021d703d7c40db9961b1",
    "name": "externalimg_r_1696989601519_1696989520892_image_0.jpg",
    "path": "cases/6523e2ab703d7c40db96d89d/
externalimg_r_1696989601519_1696989520892_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6526021d703d7c40db9961b2",
    "name": "externalimg_r_1696989607577_1696989520892_image_3.jpg",
    "path": "cases/6523e2ab703d7c40db96d89d/
externalimg_r_1696989607577_1696989520892_image_3.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6526021d703d7c40db9961b3",
  "name": "externallmg_r_1696989609900_1696989520892_image_4.jpg",
  "path": "cases/6523e2ab703d7c40db96d89d/
externallmg_r_1696989609900_1696989520892_image_4.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6526021d703d7c40db9961b4",
  "name": "externallmg_r_1696989614036_1696989520892_image_6.jpg",
  "path": "cases/6523e2ab703d7c40db96d89d/
externallmg_r_1696989614036_1696989520892_image_6.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6526021d703d7c40db9961b5",
  "name": "externallmg_r_1696989615852_1696989520892_image_7.jpg",
  "path": "cases/6523e2ab703d7c40db96d89d/
externallmg_r_1696989615852_1696989520892_image_7.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6526021d703d7c40db9961b6",
  "name": "externallmg_r_1696989611662_1696989520892_image_5.jpg",
  "path": "cases/6523e2ab703d7c40db96d89d/
externallmg_r_1696989611662_1696989520892_image_5.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6526021d703d7c40db9961b7",
  "name": "externallmg_r_1696989618160_1696989520892_image_8.jpg",
  "path": "cases/6523e2ab703d7c40db96d89d/
externallmg_r_1696989618160_1696989520892_image_8.jpg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6526021d703d7c40db9961b8",
  "name": "externallmg_r_1696989624283_1696989520892_image_11.jpg",
  "path": "cases/6523e2ab703d7c40db96d89d/
externallmg_r_1696989624283_1696989520892_image_11.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6526021d703d7c40db9961b9",
  "name": "externallmg_r_1696989619761_1696989520892_image_9.jpg",
  "path": "cases/6523e2ab703d7c40db96d89d/
externallmg_r_1696989619761_1696989520892_image_9.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6526021d703d7c40db9961ba",
  "name": "externallmg_r_1696989622182_1696989520892_image_10.jpg",
  "path": "cases/6523e2ab703d7c40db96d89d/
externallmg_r_1696989622182_1696989520892_image_10.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6526021d703d7c40db9961bb",
  "name": "externallmg_r_1696989625811_1696989520892_image_12.jpg",
  "path": "cases/6523e2ab703d7c40db96d89d/
externallmg_r_1696989625811_1696989520892_image_12.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6526021d703d7c40db9961bc",
  "name": "externallmg_r_1696989632677_1696989520892_image_15.jpg",
  "path": "cases/6523e2ab703d7c40db96d89d/
externallmg_r_1696989632677_1696989520892_image_15.jpg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6526021d703d7c40db9961bd",
  "name": "externallmg_r_1696989628092_1696989520892_image_13.jpg",
  "path": "cases/6523e2ab703d7c40db96d89d/
externallmg_r_1696989628092_1696989520892_image_13.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6526021d703d7c40db9961be",
  "name": "externallmg_r_1696989630808_1696989520892_image_14.jpg",
  "path": "cases/6523e2ab703d7c40db96d89d/
externallmg_r_1696989630808_1696989520892_image_14.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6526021d703d7c40db9961bf",
  "name": "externallmg_r_1696989634395_1696989520892_image_16.jpg",
  "path": "cases/6523e2ab703d7c40db96d89d/
externallmg_r_1696989634395_1696989520892_image_16.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6526021d703d7c40db9961c0",
  "name": "externallmg_r_1696989638821_1696989520892_image_18.jpg",
  "path": "cases/6523e2ab703d7c40db96d89d/
externallmg_r_1696989638821_1696989520892_image_18.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6526021d703d7c40db9961c1",
  "name": "externallmg_r_1696989636330_1696989520892_image_17.jpg",
  "path": "cases/6523e2ab703d7c40db96d89d/
externallmg_r_1696989636330_1696989520892_image_17.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6526021d703d7c40db9961c3",
    "name": "externallmg_r_1696989683900_1696989594054_image_4.png",
    "path": "cases/6523e2ab703d7c40db96d89d/
externallmg_r_1696989683900_1696989594054_image_4.png",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6526021d703d7c40db9961c6",
    "name": "externallmg_r_1696989680122_1696989594054_image_2.jpg",
    "path": "cases/6523e2ab703d7c40db96d89d/
externallmg_r_1696989680122_1696989594054_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6526021d703d7c40db9961c7",
    "name": "externallmg_r_1696989684406_1696989594054_image_5.jpg",
    "path": "cases/6523e2ab703d7c40db96d89d/
externallmg_r_1696989684406_1696989594054_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6526021d703d7c40db9961c8",
    "name": "externallmg_r_1696989686219_1696989594054_image_6.jpg",
    "path": "cases/6523e2ab703d7c40db96d89d/
externallmg_r_1696989686219_1696989594054_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6526021d703d7c40db9961c9",
    "name": "externallmg_r_1696989690448_1696989594054_image_8.jpg",
    "path": "cases/6523e2ab703d7c40db96d89d/
externallmg_r_1696989690448_1696989594054_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6526021d703d7c40db9961ca",
  "name": "externalimg_r_1696989688531_1696989594054_image_7.jpg",
  "path": "cases/6523e2ab703d7c40db96d89d/
externalimg_r_1696989688531_1696989594054_image_7.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6526021d703d7c40db9961cb",
  "name": "externalimg_r_1696989691997_1696989594054_image_9.jpg",
  "path": "cases/6523e2ab703d7c40db96d89d/
externalimg_r_1696989691997_1696989594054_image_9.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6526021d703d7c40db9961cc",
  "name": "externalimg_r_1696989693454_1696989594054_image_10.jpg",
  "path": "cases/6523e2ab703d7c40db96d89d/
externalimg_r_1696989693454_1696989594054_image_10.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6526021d703d7c40db9961cd",
  "name": "externalimg_r_1696989696436_1696989594054_image_12.jpg",
  "path": "cases/6523e2ab703d7c40db96d89d/
externalimg_r_1696989696436_1696989594054_image_12.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6526021d703d7c40db9961ce",
  "name": "externalimg_r_1696989694853_1696989594054_image_11.jpg",
  "path": "cases/6523e2ab703d7c40db96d89d/
externalimg_r_1696989694853_1696989594054_image_11.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "6526021d703d7c40db9961cf",
    "name": "externallmg_r_1696989697695_1696989594054_image_13.jpg",
    "path": "cases/6523e2ab703d7c40db96d89d/
externallmg_r_1696989697695_1696989594054_image_13.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6526021d703d7c40db9961d0",
    "name": "externallmg_r_1696989700149_1696989594054_image_14.jpg",
    "path": "cases/6523e2ab703d7c40db96d89d/
externallmg_r_1696989700149_1696989594054_image_14.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6526021d703d7c40db9961d1",
    "name": "externallmg_r_1696989701589_1696989594054_image_15.jpg",
    "path": "cases/6523e2ab703d7c40db96d89d/
externallmg_r_1696989701589_1696989594054_image_15.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6526021d703d7c40db9961d2",
    "name": "externallmg_r_1696989702969_1696989594054_image_16.jpg",
    "path": "cases/6523e2ab703d7c40db96d89d/
externallmg_r_1696989702969_1696989594054_image_16.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6526021d703d7c40db9961d3",
    "name": "externallmg_r_1696989705195_1696989594054_image_17.jpg",
    "path": "cases/6523e2ab703d7c40db96d89d/
externallmg_r_1696989705195_1696989594054_image_17.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6526021d703d7c40db9961d4",
```



```

    "name": "externalImg_r_1696989707283_1696989594054_image_18.jpg",
    "path": "cases/6523e2ab703d7c40db96d89d/
externalImg_r_1696989707283_1696989594054_image_18.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6526021d703d7c40db9961d5",
    "name": "externalImg_r_1696989572670_1696989495403_image_0.png",
    "path": "cases/6523e2ab703d7c40db96d89d/
externalImg_r_1696989572670_1696989495403_image_0.png",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-10-09T11:23:23.770Z",
"updatedAt": "2023-10-11T07:05:23.024Z",
"__v": 0,
"invoiceId": "6523e2ab703d7c40db96d8a0",
"addressForMap": "",
"updatedBy": "60eebe33f3dd69653a5837ae"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			