

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8d5"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f64be948726cc1418f3",
    "email": "kiran@cosmosbank.in",
    "firstName": "Kiran Sir",
    "mobileNo": "9594609519",
    "workMobileNo": "9594609519",
    "lastName": "sir"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "Kiran Sir",
    "expectedFees": 2500,
    "quotedAmount": "4000"
  },
  "organization": {
```

```
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8d5",
  "branchCode": "000007",
  "type": "BRANCH",
  "name": "Mulund (West) Branch",
  "email": "cosmos@mulundwestgmail.com",
  "mobileNo": "022-21640621",
  "alternateMobileNo": "022-21646370",
  "address": "Apurva Co-Op. Housing Society, Govardhan Nagar, L.B.S. Road, Mulund
(West), Mumbai - 400 080, State - Maharashtra, Country - India.\r\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "60b7177d2ffdf65bcd65882a",
"role": "PICKUPPERSON",
"firstName": "Saurabh",
"email": "saurabhvelonde143@gmail.com",
"lastName": "Velonde",
"mobileNo": "8691048846",
"shortName": "SSV",
"workWithDocumentMaker": "",
"profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "60f9343b45132d6a6bdd96e8",
"role": "SITEENGINEER",
"firstName": "Rajesh",
"email": "rajeshb.ghadi@gmail.com",
"lastName": "Ghadi",
"mobileNo": "8652092666",
"designation": "",
"shortName": "RHG",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60f915d3f3dd69653a592199",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": "",
"checker": "",
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
}
]
```

```
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
```

```
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.022108645809023",
  "longitude": "73.08837416626612"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.08837416626612,
    19.022108645809023
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-16",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-16",
      "remark": ""
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
```

```
"status": true,
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Kamothe",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "6",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
```

```
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "21",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sai Blessing CHSL",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "35",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
```

```
"name": "Street 2",
"key": "street2",
"value": "",
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
}
```



```
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "607",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
```

```
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "label": "R. C. C. Slab",
    "value": "rcc_Slab"
  },
  "flooring": {
    "label": "Vitrified Tile Flooring",
    "value": "VerifiedTileFlooring"
  },
  "doors": {
    "label": "Teak Wood Door Frame With Flush Shutters",
    "value": "Teak_Wood_Door_Frame_With_Flush_Shutters"
  },
}
```

```

"windows": {
  "label": "Alluminum sliding windows with tinted glass ",
  "value": "Alluminum_sliding_windows_with_tinted_glass_"
},
"fittings": {
  "label": "Concealed plumbing with C.P. fittings. Casting Capping Electrical wiring",
  "value":
"Concealed_plumbing_with_C.P._fittings._Casting_Capping_Electrical_wiring"
},
"finishing": {
  "label": "Normal",
  "value": "Normal"
}
},
"general": {
  "populationClassList": {
    "label": "Middle Class",
    "value": "MiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Panvel Municipal Corporation",
    "value": "Panvel_Municipal_Corporation"
  },
  "unitBoundaries": {
    "isDisplay": false
  }
},
"outgoingDetail": {
  "areaStatusList": {
    "label": "Middle Class",
    "value": "Middle_Class"
  },
  "propertyTypeOfUseList": {
    "label": "Residential Purpose",
    "value": "Residential_Purpose"
  },
  "propertyOccupiedByList": {
    "label": "Tenant Occupied",
    "value": "Tenant_Occupied"
  },
  "monthlyRent": ""
},

```

```
"siteMeasurement": {
  "partitions": {
    "label": "6\" Thk. Brick Masonery",
    "value": "6\"_Thk._Brick_Masonery"
  },
  "waterTank": {
    "label": "Municipal Water Supply",
    "value": "MuncipalWaterSupply"
  },
  "pavementLaid": {
    "label": "No",
    "value": "No"
  },
  "carParking": {
    "label": "Stilt Parking",
    "value": "Stilt_Parking"
  },
  "constructionWorkStatus": {
    "label": "Completed",
    "value": "Completed"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2012",
    "fullDate": "1/1/2012"
  },
  "propertyTypeList": {
    "value": "Residential",
    "label": "Residential"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "label": "R.C.C. Framed",
    "value": "R.C.C."
  },
  "qualityOfConstruction": {
    "label": "Excellent",
    "value": "Excellent"
  },
  "walls": {
    "label": "Yes",
    "value": "1"
  }
}
```

```
},
"appearanceOfTheBuilding": {
  "label": "Good",
  "value": "Good"
},
"maintenanceOfTheBuilding": {
  "label": "Excellent",
  "value": "Excellent"
},
"visibleDamageInBuilding": {
  "label": "No",
  "value": "0"
},
"groundStilt": {
  "label": "Stilt",
  "value": "stilt"
},
"noOfBasement": "0",
"noOfPodium": "0",
"noOfAmenityFloors": "0",
"flatFloorNo": "",
"noOfLiftsInEachWings": "0",
"totalLifeBuilding": "60",
"ageOfBuilding": "11",
"estimatedAge": "49",
"noOfFloors": "07",
"noOfDwellingUnitsInBuilding": "07",
"noOfLifts": "01"
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
}
```

```
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
```



```
"max": "0.00"
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
```

```
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
```

```
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  }
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": false,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"paymentId": [],
"_id": "6524d675703d7c40db977ae5",
"ownerName": "Aashiq Ali Ayyub Maldar ",
"ownerPhoneNo": "7021484798",
"appAddress": "Flat no. 607, 6th Floor, Plot no. 21, Sector - 35, Sai Blessing CHS,
Kamothe Navi Mumbai ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "path": "cases/6524d675703d7c40db977ae5/
document_1696912907197_Sai_blessings.pdf",
```

```
"fileName": "document_1696912907197_Sai_blessings.pdf",
"displayStatus": false,
"id": "483888",
"uploadedBy": "60b7177d2ffdf65bcd65882a",
"createdAt": "Tue Oct 10 2023 10:12:49 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Building Plan",
    "value": "60ae124eaa6d152c1801b308"
  },
  "isHardCopy": false,
  "path": "cases/6524d675703d7c40db977ae5/
document_1696912965604_52432.pdf",
  "fileName": "document_1696912965604_52432.pdf",
  "displayStatus": false,
  "id": "353988",
  "uploadedBy": "60b7177d2ffdf65bcd65882a",
  "createdAt": "Tue Oct 10 2023 10:12:49 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004311",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "506605",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Oct 10 2023 10:13:33 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Aashiq Ali Ayyub Maldar ",
    "phone": "7021484798",
    "ownershipShare": "",
    "email": "",
    "id": "416636"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
```

```
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652cb103316e1359cebb8910",
    "name": "externallmg_1697427708583_1697427734409_image_0.jpeg",
    "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427708583_1697427734409_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652cb103316e1359cebb8911",
    "name": "externallmg_1697427708718_1697427734409_image_1.jpeg",
    "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427708718_1697427734409_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652cb103316e1359cebb8912",
    "name": "externallmg_1697427709683_1697427734409_image_2.jpeg",
    "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427709683_1697427734409_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652cb103316e1359cebb8913",
    "name": "externallmg_1697427709739_1697427734409_image_3.jpeg",
    "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427709739_1697427734409_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652cb103316e1359cebb8914",
    "name": "externallmg_1697427709793_1697427734409_image_4.jpeg",
    "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427709793_1697427734409_image_4.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652cb103316e1359cebb8915",
  "name": "externallmg_1697427709858_1697427734409_image_5.jpeg",
  "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427709858_1697427734409_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652cb103316e1359cebb8916",
  "name": "externallmg_1697427709913_1697427734409_image_6.jpeg",
  "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427709913_1697427734409_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652cb103316e1359cebb8917",
  "name": "externallmg_1697427709988_1697427734409_image_7.jpeg",
  "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427709988_1697427734409_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652cb103316e1359cebb8918",
  "name": "externallmg_1697427710048_1697427734409_image_8.jpeg",
  "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427710048_1697427734409_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652cb103316e1359cebb8919",
  "name": "externallmg_1697427710108_1697427734409_image_9.jpeg",
  "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427710108_1697427734409_image_9.jpeg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652cb103316e1359cebb891a",
  "name": "externallmg_1697427712493_1697427734409_image_10.jpeg",
  "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427712493_1697427734409_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652cb103316e1359cebb891b",
  "name": "externallmg_1697427712573_1697427734409_image_11.jpeg",
  "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427712573_1697427734409_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652cb103316e1359cebb891c",
  "name": "externallmg_1697427712613_1697427734409_image_12.jpeg",
  "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427712613_1697427734409_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652cb103316e1359cebb891d",
  "name": "externallmg_1697427713393_1697427734409_image_13.jpeg",
  "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427713393_1697427734409_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652cb103316e1359cebb891e",
  "name": "externallmg_1697427713433_1697427734409_image_14.jpeg",
  "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427713433_1697427734409_image_14.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652cb103316e1359cebb891f",
  "name": "externallmg_1697427713439_1697427734409_image_15.jpeg",
  "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427713439_1697427734409_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652cb103316e1359cebb8920",
  "name": "externallmg_1697427713468_1697427734409_image_16.jpeg",
  "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427713468_1697427734409_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652cb103316e1359cebb8921",
  "name": "externallmg_1697427713508_1697427734409_image_17.jpeg",
  "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427713508_1697427734409_image_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652cb103316e1359cebb8922",
  "name": "externallmg_1697427713685_1697427734409_image_18.jpeg",
  "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427713685_1697427734409_image_18.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "652cb103316e1359cebb8923",
  "name": "externallmg_1697427669933_1697427693358_image_0.jpeg",
  "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427669933_1697427693358_image_0.jpeg",
  "orientation": "portrait"
},
{
```



```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "652cb103316e1359cebb8924",
    "name": "externallmg_1697427670098_1697427693358_image_1.jpeg",
    "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427670098_1697427693358_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "652cb103316e1359cebb8925",
    "name": "externallmg_1697427671073_1697427693358_image_2.jpeg",
    "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427671073_1697427693358_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "652cb103316e1359cebb8926",
    "name": "externallmg_1697427671098_1697427693358_image_3.jpeg",
    "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427671098_1697427693358_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "652cb103316e1359cebb8927",
    "name": "externallmg_1697427671148_1697427693358_image_4.jpeg",
    "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427671148_1697427693358_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "652cb103316e1359cebb8928",
    "name": "externallmg_1697427671203_1697427693358_image_5.jpeg",
    "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427671203_1697427693358_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
"status": false,
  "_id": "652cb103316e1359cebb8929",
  "name": "externallmg_1697427671253_1697427693358_image_6.jpeg",
  "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427671253_1697427693358_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "652cb103316e1359cebb892a",
  "name": "externallmg_1697427671309_1697427693358_image_7.jpeg",
  "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427671309_1697427693358_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "652cb103316e1359cebb892b",
  "name": "externallmg_1697427671379_1697427693358_image_8.jpeg",
  "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427671379_1697427693358_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "652cb103316e1359cebb892c",
  "name": "externallmg_1697427671453_1697427693358_image_9.jpeg",
  "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427671453_1697427693358_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "652cb103316e1359cebb892d",
  "name": "externallmg_1697427671494_1697427693358_image_10.jpeg",
  "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427671494_1697427693358_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
```

```
    "_id": "652cb103316e1359cebb892e",
    "name": "externallmg_1697427673723_1697427693358_image_11.jpeg",
    "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427673723_1697427693358_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "652cb103316e1359cebb892f",
    "name": "externallmg_1697427673794_1697427693358_image_12.jpeg",
    "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427673794_1697427693358_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "652cb103316e1359cebb8930",
    "name": "externallmg_1697427673833_1697427693358_image_13.jpeg",
    "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427673833_1697427693358_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "652cb103316e1359cebb8931",
    "name": "externallmg_1697427673888_1697427693358_image_14.jpeg",
    "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427673888_1697427693358_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "652cb103316e1359cebb8932",
    "name": "externallmg_1697427673913_1697427693358_image_15.jpeg",
    "path": "cases/6524d675703d7c40db977ae5/
externallmg_1697427673913_1697427693358_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "652cb103316e1359cebb8933",
```

```
    "name": "externalImg_1697427674389_1697427693358_image_16.jpeg",
    "path": "cases/6524d675703d7c40db977ae5/
externalImg_1697427674389_1697427693358_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "652cb103316e1359cebb8934",
    "name": "externalImg_1697427674390_1697427693358_image_17.jpeg",
    "path": "cases/6524d675703d7c40db977ae5/
externalImg_1697427674390_1697427693358_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "652cb103316e1359cebb8935",
    "name": "externalImg_1697427674391_1697427693358_image_18.jpeg",
    "path": "cases/6524d675703d7c40db977ae5/
externalImg_1697427674391_1697427693358_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "652cb103316e1359cebb8936",
    "name": "externalImg_1697427674798_1697427693358_image_19.jpeg",
    "path": "cases/6524d675703d7c40db977ae5/
externalImg_1697427674798_1697427693358_image_19.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-10-10T04:43:33.417Z",
"updatedAt": "2023-10-16T03:45:07.308Z",
"__v": 0,
"invoiceId": "6524d676703d7c40db977afd",
"updatedBy": "60f9343b45132d6a6bdd96e8",
"fullAddress": " Flat No. 607, 6th Floor, Sai Blessing CHSL, Plot No. 21, Sector 35,
Village - Kamothe, Navi Mumbai",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Aashiq Ali Ayyub Maldar ",
```

"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "7021484798",
"briefDescOfProperty": "",
"carpetTotal": "0",
"finalMeasurementType": "",
"otherCarpetTotal": "0"

}

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			