

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "type": "CREDITOFFICER",
    "_id": "650581d3a8e9b70221e855e5",
    "firstName": "Bhakti",
    "lastName": "Podkar",
    "mobileNo": "",
    "workMobileNo": "8425827511",
    "email": "Bhakti.racpc.sion@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "10000000",
    "discussWithPerson": "Bhakti",
    "expectedFees": 5000,
    "quotedAmount": "2500"
  },
  "organization": {
```

```
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kirol Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9462345132d6a6bddb9d5",
  "role": "SITEENGINEER",
  "firstName": "Dashrath ",
  "email": "dasrat.jaiswar1234@gmail.com",
  "lastName": "Jaiswar",
  "mobileNo": "9987305468",
  "designation": "",
  "shortName": "DFJ",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
  "mobileNo": "9529385821",
```

```
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": "",
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
"number": "AM161706-3"
}
```

```
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.04070956578763",
  "longitude": "72.86893817975968"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.86893817975968,
    19.04070956578763
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-16",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-10-16",

```

```
    "remark": ""
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Salt Pan Division",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "5",
    "label": false
  },
  "buildingNo": {
```

```
"status": true,
"name": "Building No",
"key": "buildingNo",
"value": "M1B of Scheme Code No. 193",
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Sion (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Mumbai",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Pratiksha Nagar Omkar Co-Op. Hsg. Soc. Ltd.",
```

```
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Pratiksha Nagar ",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
```



```
"name": "Old Survey No.",
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "4-5C(Part)",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "504",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
}
```

```
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 022",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
```

```

    "key": "suburb",
    "value": "",
    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {

```

```
"value": "MHADA",
"label": "MHADA"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Building No. M2",
"west": "Pratiksha Nagar Road",
"south": "Internal Road",
"east": "Gulmohar CHSL"
},
"asPerDocumentAgreement": {
"north": "Details not available",
"west": "Details not available",
"south": "Details not available",
"east": "Details not available"
},
"unitBoundaries": {
"asPerActual": {
"north": "Details not available",
"east": "Details not available",
"south": "Details not available",
"west": "Details not available"
},
"asPerDocument": {
"north": "Details not available",
"east": "Details not available",
"south": "Details not available",
"west": "Details not available"
},
"isActive": false,
"title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "As per site inspection, 1BHK flat converted into 2BHK.",
"dateOfIssusApprovePlan": "The Property is constructed by MHADA. MHADA itself is
planning authority.",
"approvePlanVerified": "N.A",
"empanelledOfApprovePlan": "N.A"
},
"compositeRate": {
"remark": "As per site inspection, 1BHK flat converted into 2BHK.",
"depreciationPercentage": "25.5",
"depreciationRatioOfBuilding": "",
"salvageValue": "10",
```

```
"depreciatedCostOfConstruction": "26486",
"depreciatedBuildingRate": "2086"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "103570",
  "landRate": "47210",
  "igrImage": "cases/65291939758ee2361b409c2f/igr_1697529958962_Image.png",
  "squareMeterGuideLineRate": "108749.00",
  "squareFeetGuideLineRate": "10103.00"
},
"igrFinalRate": {
  "rate": "9131.00",
  "squareMeterGuideLineRate": "98287.00",
  "squareFeetGuideLineRate": "9131.00",
  "depreciationPercentage": "83"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Seller_Occupied",
    "label": "Seller Occupied"
  },
  "monthlyRent": "33,500",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "308738760010",
  "meterCardHolderName": "Mr. Narayan Bhagwan Gaikwad ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per MHADA norms",
  "tenantName": "",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  }
},
```

```
"anyFavouringForExtraPotentialValue": "Located in developed area ",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt Car Parking Space",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "fullDate": "1/1/2006",
    "date": "1",
    "month": "1",
    "year": "2006"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "R.C.C._Framed_Structure",
    "label": "R.C.C. Framed Structure"
  },
  "typeOfFoundation": {
    "value": "rcc",
    "label": "R.C.C. Foundation"
  }
}
```

```
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
```

```
"value": "1",
"label": "Yes"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "stilt",
"label": "Stilt"
},
"yearOfConstructionAsPer": {
"value": "As_per_Possession_Letter",
"label": "As per Possession Letter"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "43",
"ageOfBuilding": "17",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "5",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
"areaType": "Built Up",
"area": "524.40",
"measurementType": "Sq. Ft.",
"areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
"routeMapDetail": {
"routeStation": {
"value": "Railway_Station",
"label": "Railway Station"
}
},
"routeMapImg": "cases/65291939758ee2361b409c2f/
routeMap_1697521543250_Image.png",
"routeLat": "19.040854",
"routeLng": "72.868906",
"stationName": "Sion",
"routeDistance": "1.2 Km."
},
}
```



```
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": true,
  "finallatLng": true
},
"locationMapImg": [
  {
    "id": "r3q73l",
    "name": "r3q73l",
    "image": "cases/65291939758ee2361b409c2f/
routeMap_1697521439866_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
```

```
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "11574382.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "11574382.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "4788296.00",
```

```
"selectedBuildUpValue": "524.40",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "652d3da6316e1359cebde4b0",
      "name": "externalimg_1697463706981_1697463660345_image_16.jpeg",
      "path": "cases/65291939758ee2361b409c2f/
externalimg_1697463706981_1697463660345_image_16.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
      "_id": "652d3da6316e1359cebde4a0",
      "name": "Living Room",
      "path": "cases/65291939758ee2361b409c2f/
externalimg_1697463636211_1697463660340_image_0.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "652d3da6316e1359cebde4a2",
      "name": "Living Room",
      "path": "cases/65291939758ee2361b409c2f/
externalimg_1697463641430_1697463660345_image_2.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "652d3da6316e1359cebde4a5",
      "name": "Living Room",
      "path": "cases/65291939758ee2361b409c2f/
externalimg_1697463650393_1697463660345_image_5.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "652d3da6316e1359cebde4a4",
```

```
    "name": "Living Room",
    "path": "cases/65291939758ee2361b409c2f/
externallmg_1697463648377_1697463660345_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "652d3da6316e1359cebde4a7",
    "name": "Living Room",
    "path": "cases/65291939758ee2361b409c2f/
externallmg_1697463655708_1697463660345_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "652d3da6316e1359cebde4ad",
    "name": "Living Room",
    "path": "cases/65291939758ee2361b409c2f/
externallmg_1697463682697_1697463660345_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "652d3da6316e1359cebde4af",
    "name": "Living Room",
    "path": "cases/65291939758ee2361b409c2f/
externallmg_1697463693282_1697463660345_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "652d3da6316e1359cebde4b0",
    "name": "Living Room",
    "path": "cases/65291939758ee2361b409c2f/
externallmg_1697463706981_1697463660345_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "652d3da6316e1359cebde4b2",
    "name": "Living Room",
    "path": "cases/65291939758ee2361b409c2f/
externallmg_1697463713376_1697463660345_image_18.jpeg",
    "orientation": "portrait"
  }
]
```

```
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "21354",
    "max": "27918"
  },
  "builtUpRateRange": {
    "min": "17796",
    "max": "23265"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```



```
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "437.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentId": [],
"_id": "65291939758ee2361b409c2f",
"ownerName": "Mr. Gopal Sadanand Chavan & Mrs. Samidha Gopal Chavan ",
"ownerPhoneNo": "9773418408",
"appAddress": "Flat no. 504, 5th Floor, Building no. M1B, Pratiksha Nagar Omkar
CHS, Pratiksha Nagar, Sion East",
"remark": "",
"documents": [
  {
```

```
"documentType": {
  "value": "60ae1254aa6d152c1801b326",
  "label": "Agreement For Sale"
},
"inputs": {
  "documentDate": "25/09/2023",
  "from": {
    "value": "Vendor",
    "label": "Vendor"
  },
  "Vendor": "Mr. Narayan Bhagwan Gaikwad ",
  "to": {
    "value": "Purchasers",
    "label": "Purchasers"
  },
  "Purchasers": "Mr. Gopal Sadanand Chavan & Mrs. Samidha Gopal Chavan ",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "19736 / 2023"
},
"isHardCopy": false,
"displayStatus": true,
"id": "338145",
"path": "cases/65291939758ee2361b409c2f/
document_1697193095066_Racpc_SionGopal_Chavan.pdf",
"fileName": "document_1697193095066_Racpc_SionGopal_Chavan.pdf"
},
{
  "documentType": {
    "value": "60ae124caa6d152c1801b2ff",
    "label": "Society No Objection Certificate"
  },
  "inputs": {
    "documentDate": "11/09/2023",
    "remark": " in the name of Mr. Gopal Sadanand Chavan & Mrs. Samidha Gopal
Chavan issued by Pratiksha Nagar Omkar Co-Op. Hsg. Soc. Ltd.",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "96 / 2023 - 24"
  },
  "isHardCopy": false,
  "displayStatus": false,
}
```

```
"fileName": "document_1697515743146_542473.pdf",
"path": "cases/65291939758ee2361b409c2f/
document_1697515743146_542473.pdf",
"id": "317707",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Tue Oct 17 2023 09:39:03 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1267aa6d152c1801b37e",
    "label": "MHADA Allotment Letter"
  },
  "inputs": {
    "documentDate": "16/12/2005",
    "remark": " issued by MHADA",
    "to": {
      "value": "Seller",
      "label": "Seller"
    },
    "Seller": "Mr. Narayan Bhagwan Gaikwad ",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "1368"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "703420",
  "path": "cases/65291939758ee2361b409c2f/
document_1697518244261_581978.pdf",
  "fileName": "document_1697518244261_581978.pdf"
},
{
  "documentType": {
    "value": "60ae1255aa6d152c1801b329",
    "label": "Possession Receipt"
  },
  "inputs": {
    "documentDate": "30/03/2006",
    "remark": " issued by MHADA",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "DIR / MKT / 193 / MIB / 504"
  },

```

```
    },
    "isHardCopy": false,
    "displayStatus": false,
    "id": "419780",
    "path": "cases/65291939758ee2361b409c2f/
document_1697518309568_888064.pdf",
    "fileName": "document_1697518309568_888064.pdf"
  },
  {
    "documentType": {
      "value": "60ae1248aa6d152c1801b2ef",
      "label": "Society Share Certificate"
    },
    "inputs": {
      "documentDate": "26/01/2008",
      "remark": " in the name of Mr. Narayan Bhagwan Gaikwad issued by Pratiksha
Nagar Omkar Co-Op. Hsg. Soc. Ltd",
      "to": {
        "value": "Seller",
        "label": "Seller"
      },
      "Seller": "Mr. Narayan Bhagwan Gaikwad ",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "005"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "id": "499041",
    "path": "cases/65291939758ee2361b409c2f/
document_1697518526999_842820.pdf",
    "fileName": "document_1697518526999_842820.pdf"
  },
  {
    "documentType": {
      "value": "60ae1249aa6d152c1801b2f3",
      "label": "Electricity Bill"
    },
    "inputs": {
      "documentDate": "09/08/2023",
      "number": {
        "value": "No",
        "label": "No"
      }
    },
  },
```

```
    "No": "308738760010"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "174079",
  "path": "cases/65291939758ee2361b409c2f/
document_1697518785985_979383.pdf",
  "fileName": "document_1697518785985_979383.pdf"
},
{
  "documentType": {
    "value": "60ae1249aa6d152c1801b2f1",
    "label": "Society Maintenance Bill"
  },
  "inputs": {
    "documentDate": "30/08/2023",
    "remark": " in the name of Mr. Narayan Bhagwan Gaikwad issued by Pratiksha
Nagar Omkar Co-Op. Hsg. Soc. Ltd.",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "708"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "486047",
  "path": "cases/65291939758ee2361b409c2f/
document_1697518862753_785702.pdf",
  "fileName": "document_1697518862753_785702.pdf"
}
],
"caseNumber": "004398",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "557648",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Oct 13 2023 15:47:29 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Gopal Sadanand Chavan & Mrs. Samidha Gopal Chavan ",
    "phone": "9773418408",
```

```
"ownershipShare": "",
"email": "",
"id": "206579"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "308947",
  "name": "Living Room",
  "length": "9.33",
  "length1": "9",
  "length2": "4",
  "width": "18.42",
  "width1": "18",
  "width2": "5",
  "totalArea": "171.89",
  "images": [],
  "extraAreas": [],
  "finalArea": "171.89"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Passage",
  "length": "4.42",
  "length1": "4",
  "length2": "5",
  "width": "2.75",
  "width1": "2",
  "width2": "9",
  "totalArea": "12.15",
  "images": [],
  "extraAreas": [],
  "finalArea": "12.15"
},
{
  "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "5.58",
  "length1": "5",
  "length2": "7",
  "width": "10.92",
  "width1": "10",
  "width2": "11",
  "totalArea": "60.95",
  "images": [],
  "extraAreas": [],
  "finalArea": "60.95"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "8.00",
  "length1": "8",
  "length2": "00",
  "width": "9.00",
  "width1": "9",
  "width2": "00",
  "totalArea": "72.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "72.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "",
  "length1": "3",
  "length2": "0",
  "width": "",
  "width1": "5",
```

```
"width2": "4",
"totalArea": "16.00",
"images": [],
"finalArea": "16.00",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "3.17",
  "length1": "3",
  "length2": "2",
  "width": "7.83",
  "width1": "7",
  "width2": "10",
  "totalArea": "24.81",
  "images": [],
  "extraAreas": [],
  "finalArea": "24.81"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Bedroom",
  "length": "9.67",
  "length1": "9",
  "length2": "8",
  "width": "10.50",
  "width1": "10",
  "width2": "6",
  "totalArea": "101.50",
  "images": [],
  "finalArea": "101.50",
  "extraAreas": []
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
```



```
{
  "typeOfDocument": {
    "value": "60ae1254aa6d152c1801b326",
    "label": "Agreement For Sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "672763",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "437",
  "squareMeterArea": "40.6",
  "docFinalBuiltUp": "524.4",
  "docFinalBuiltUpSquareMeter": "48.72",
  "docBuiltupPercentage": "20",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "652e4089316e1359cebedcdb",
    "property": "Flat",
    "area": "437",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "square_yards",
    "expectedPrice": "12200000",
    "expectedRate": "27917.62",
    "builtUpExpectedRate": "23264.68",
    "image": "cases/65291939758ee2361b409c2f/
indicator_1697529633777_Image.png",
    "squareMeter": "40.60",
    "id": "779339"
  },
  {
    "printlnReport": true,
    "_id": "652e4089316e1359cebedcdc",
    "property": "Flat",
    "area": "437",
```

```
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"source": "square_yards",
"expectedPrice": "11200000",
"expectedRate": "25629.29",
"builtUpExpectedRate": "21357.74",
"image": "cases/65291939758ee2361b409c2f/
indicator_1697529678627_Image.png",
"squareMeter": "40.60",
"id": "139506"
},
{
  "printlnReport": true,
  "_id": "652e4089316e1359cebedcdd",
  "property": "Flat",
  "area": "437",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "square_yards",
  "expectedPrice": "12000000",
  "expectedRate": "27459.95",
  "builtUpExpectedRate": "22883.30",
  "image": "cases/65291939758ee2361b409c2f/
indicator_1697529715399_Image.png",
  "squareMeter": "40.60",
  "id": "171882"
},
{
  "printlnReport": true,
  "_id": "652e4089316e1359cebedcde",
  "property": "Flat",
  "area": "384",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "1",
  "source": "Index_no.2",
  "expectedPrice": "8200000",
  "expectedRate": "21354.17",
  "builtUpExpectedRate": "17795.14",
  "image": "cases/65291939758ee2361b409c2f/
indicator_1697529771586_Image.png",
```

```
    "squareMeter": "35.67",
    "id": "670294"
  }
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652d3da6316e1359cebde4a0",
    "name": "externallmg_1697463636211_1697463660340_image_0.jpeg",
    "path": "cases/65291939758ee2361b409c2f/
externallmg_1697463636211_1697463660340_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652d3da6316e1359cebde4a1",
    "name": "externallmg_1697463639373_1697463660345_image_1.jpeg",
    "path": "cases/65291939758ee2361b409c2f/
externallmg_1697463639373_1697463660345_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652d3da6316e1359cebde4a2",
    "name": "externallmg_1697463641430_1697463660345_image_2.jpeg",
    "path": "cases/65291939758ee2361b409c2f/
externallmg_1697463641430_1697463660345_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652d3da6316e1359cebde4a3",
    "name": "externallmg_1697463645167_1697463660345_image_3.jpeg",
    "path": "cases/65291939758ee2361b409c2f/
externallmg_1697463645167_1697463660345_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652d3da6316e1359cebde4a4",
    "name": "externallmg_1697463648377_1697463660345_image_4.jpeg",
```

```
    "path": "cases/65291939758ee2361b409c2f/
externallmg_1697463648377_1697463660345_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652d3da6316e1359cebde4a5",
    "name": "externallmg_1697463650393_1697463660345_image_5.jpeg",
    "path": "cases/65291939758ee2361b409c2f/
externallmg_1697463650393_1697463660345_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652d3da6316e1359cebde4a6",
    "name": "externallmg_1697463653038_1697463660345_image_6.jpeg",
    "path": "cases/65291939758ee2361b409c2f/
externallmg_1697463653038_1697463660345_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652d3da6316e1359cebde4a7",
    "name": "externallmg_1697463655708_1697463660345_image_7.jpeg",
    "path": "cases/65291939758ee2361b409c2f/
externallmg_1697463655708_1697463660345_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652d3da6316e1359cebde4a8",
    "name": "externallmg_1697463659167_1697463660345_image_8.jpeg",
    "path": "cases/65291939758ee2361b409c2f/
externallmg_1697463659167_1697463660345_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652d3da6316e1359cebde4a9",
    "name": "externallmg_1697463661942_1697463660345_image_9.jpeg",
    "path": "cases/65291939758ee2361b409c2f/
externallmg_1697463661942_1697463660345_image_9.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652d3da6316e1359cebde4aa",
  "name": "externallmg_1697463664487_1697463660345_image_10.jpeg",
  "path": "cases/65291939758ee2361b409c2f/
externallmg_1697463664487_1697463660345_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652d3da6316e1359cebde4ab",
  "name": "externallmg_1697463669717_1697463660345_image_11.jpeg",
  "path": "cases/65291939758ee2361b409c2f/
externallmg_1697463669717_1697463660345_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652d3da6316e1359cebde4ac",
  "name": "externallmg_1697463677447_1697463660345_image_12.jpeg",
  "path": "cases/65291939758ee2361b409c2f/
externallmg_1697463677447_1697463660345_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652d3da6316e1359cebde4ad",
  "name": "externallmg_1697463682697_1697463660345_image_13.jpeg",
  "path": "cases/65291939758ee2361b409c2f/
externallmg_1697463682697_1697463660345_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652d3da6316e1359cebde4ae",
  "name": "externallmg_1697463689412_1697463660345_image_14.jpeg",
  "path": "cases/65291939758ee2361b409c2f/
externallmg_1697463689412_1697463660345_image_14.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "652d3da6316e1359cebde4af",
      "name": "externallmg_1697463693282_1697463660345_image_15.jpeg",
      "path": "cases/65291939758ee2361b409c2f/
externallmg_1697463693282_1697463660345_image_15.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "652d3da6316e1359cebde4b0",
      "name": "externallmg_1697463706981_1697463660345_image_16.jpeg",
      "path": "cases/65291939758ee2361b409c2f/
externallmg_1697463706981_1697463660345_image_16.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "652d3da6316e1359cebde4b1",
      "name": "externallmg_1697463710647_1697463660345_image_17.jpeg",
      "path": "cases/65291939758ee2361b409c2f/
externallmg_1697463710647_1697463660345_image_17.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "652d3da6316e1359cebde4b2",
      "name": "externallmg_1697463713376_1697463660345_image_18.jpeg",
      "path": "cases/65291939758ee2361b409c2f/
externallmg_1697463713376_1697463660345_image_18.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "652d3da6316e1359cebde4b3",
      "name": "externallmg_1697463442965_1697463450104_image_0.jpeg",
      "path": "cases/65291939758ee2361b409c2f/
externallmg_1697463442965_1697463450104_image_0.jpeg",
      "orientation": "portrait"
    },
  ],
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "652d3da6316e1359cebde4b4",
  "name": "externalImg_1697463479364_1697463450109_image_1.jpeg",
  "path": "cases/65291939758ee2361b409c2f/
externalImg_1697463479364_1697463450109_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "652d3da6316e1359cebde4b5",
  "name": "externalImg_1697463541163_1697463450109_image_2.jpeg",
  "path": "cases/65291939758ee2361b409c2f/
externalImg_1697463541163_1697463450109_image_2.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-10-13T10:17:29.152Z",
"updatedAt": "2023-10-17T09:36:06.198Z",
"__v": 0,
"fullAddress": "Residential Flat No. 504, 5th Floor, Building No M1B of Scheme Code
No. 193, Pratiksha Nagar Omkar Co-Op. Hsg. Soc. Ltd., Pratiksha Nagar , Village - Salt
Pan Division, Taluka - Mumbai, District - Mumbai, Sion (East), PIN - 400 022, State -
Maharashtra, Country - India",
"updatedAtBy": "62fe044a48a26047e6552796",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Mr. Narayan Bhagwan Gaikwad ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Seller ",
"siteVisitContactNo": "9819024594",
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Passage + 2 Toilet",
"carpetTotal": "459.3",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "505.23",
```

```

"finalCarpetArea": "459.30",
"finalSalableArea": "555.75",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 437.00",
"siteVisitDate": "2023-10-16",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"buildingServicesRate": "2800",
"flatRate": "27200",
"landOtherRate": "24400"

```

Name	Length	Width	Total
Composition :			
Living Room	9'4"	18'5"	171.89
Passage	4'5"	2'9"	12.15
Kitchen	5'7"	10'11"	60.95
Bedroom	8'00"	9'00"	72.00

Toilet	3'0"	5'4"	16.00
Toilet	3'2"	7'10"	24.81
Bedroom	9'8"	10'6"	101.50
Other Composition :			