

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b80a"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f65be948726cc1419a7",
    "email": "kaushik.datta@sbi.co.in",
    "firstName": "KAUSHUIK",
    "mobileNo": "",
    "workMobileNo": "9757023640",
    "lastName": " DATTA "
  },
  "fees": {
    "type": "fixed"
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
  }
}
```

```
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b80a",
  "branchCode": "000088",
  "type": "BRANCH",
  "name": "RACPC - Chinchpokli ",
  "email": "sbi.17889@sbi.co.in",
  "mobileNo": "022-23707514",
  "alternateMobileNo": "",
  "address": "Retail Assets Centralised Processing Centre, Mumbai South Voltas
House, 'A', 1st Floor, Dr. Ambedkar Road, Chinchpokli (East), Mumbai - 400 033, State
- Maharashtra, Country - India.\r\n",
  "ledgerName": "STATE BANK OF INDIA - CHINCHPOKALI",
  "fax": "022-23707512 / 13",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62727444afd7d55eddee092c",
    "role": "PICKUPPERSON",
    "firstName": "Shantilal",
```

```
"email": "shantilal@vastukala.org",
"lastName": "Patel",
"mobileNo": "9969039853",
"shortName": "SHP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "60f9462345132d6a6bddb9d5",
"role": "SITEENGINEER",
"firstName": "Dashrath ",
"email": "dasrat.jaiswar1234@gmail.com",
"lastName": "Jaiswar",
"mobileNo": "9987305468",
"designation": "",
"shortName": "DFJ",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "627221f4afd7d55eddeddcb4",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Prajakta",
"email": "prajakta@vastukala.org",
"lastName": "Patil",
"mobileNo": "9769797568",
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "627221f4afd7d55eddeddcb4",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Prajakta",
"email": "prajakta@vastukala.org",
"lastName": "Patil",
"mobileNo": "9769797568",
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
```

```
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.04786596428907",
  "longitude": "72.90462977791128"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.90462977791128,
    19.04786596428907
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
```

```
{
  "status": "COMPLETED",
  "dateTime": "2023-10-18",
  "remark": ""
},
{
  "status": "COMPLETED",
  "dateTime": "2023-10-18",
  "remark": ""
}
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Chembur",
    "label": true
  },
}
```

```
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "6",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
```

```
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Hiranandani Tower ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Sion Trombay Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
```



```
"status": true,
"name": "Project Name",
"key": "projectName",
"value": "Maitri Park Co-op. Hsg. Soc. Ltd.",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "1790A",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "601",
```

```
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
```

```

    "name": "Postal Code",
    "key": "postalCode",
    "value": "PIN Code - 400 071",
    "label": false
  },
  "suburb": {
    "status": true,
    "name": "Suburb",
    "key": "suburb",
    "value": "Mumbai",
    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "PowderCoatedAluminiumSliding",
    "label": "Powder Coated Aluminium Sliding"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {

```

```
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "MCGM",
"label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Sion Trombay Road",
"west": "Parking & Bungalows",
"south": "Bungalows",
"east": "Union Park"
},
"asPerDocumentAgreement": {
"north": "Details not available",
"west": "Details not available",
"south": "Details not available",
"east": "Details not available"
},
"unitBoundaries": {
"asPerActual": {
"north": "",
"west": "",
"south": "",
"east": ""
},
"asPerDocument": {
"north": "",
"west": "",
"south": "",
"east": ""
},
"setDisplay": false,
"title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Plan were not provided and not
verified",
```

```
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A."
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "16.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "37005",
  "depreciatedBuildingRate": "2505"
},
"igrRate": {
  "propertyName": "Chembur",
  "rate": "157260",
  "landRate": "69600",
  "igrImage": "cases/652e4f9f31a8c630cfa75ee1/igr_1697698330341_Image.png",
  "squareMeterGuideLineRate": "165123.00",
  "squareFeetGuideLineRate": "15340.00"
},
"igrFinalRate": {
  "depreciationPercentage": "89",
  "rate": "14364.00",
  "squareFeetGuideLineRate": "14364.00",
  "squareMeterGuideLineRate": "154615.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "85,000",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per MCGM norms",
```

```
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developed Area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt car parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2012",
    "fullDate": "1/1/2012"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  }
}
```

```
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenancelssues": {
```

```
"value": "1",
"label": "Yes"
},
"visibleDamageInBuilding": {
"value": "1",
"label": "Yes"
},
"systemOfAirConditioning": {
"value": "1",
"label": "Yes"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "stilt",
"label": "Stilt"
},
"yearOfConstructionAsPer": {
"value": "Approx.",
"label": "Approx."
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "11",
"totalLifeBuilding": "60",
"estimatedAge": "49",
"noOfBasement": "",
"noOfPodium": "1",
"noOfAmenityFloors": "",
"noOfFloors": "20",
"flatFloorNo": "6",
"noOfLifts": "3",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
"areaType": "Built Up",
"area": "1308.00",
"measurementType": "Sq. Ft.",
"areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
"routeMapDetail": {
"routeStation": {
"value": "Monorail",
"label": "Monorail"
}
```



```
    },
    "routeMapImg": "cases/652e4f9f31a8c630cfa75ee1/
routeMap_1697698935405_Image.png",
    "routeLat": "19.048929",
    "routeLng": "19.048929",
    "stationName": "VNP (R.C. Maarg)",
    "routeDistance": "1.7 Km."
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finalLatLng": true
  },
  "locationMapImg": [
    {
      "id": "impap",
      "name": "impap",
      "image": "cases/652e4f9f31a8c630cfa75ee1/
routeMap_1697698837500_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
```

```
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "40335450.00",
"finalValue": "40335450.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "18788112.00",
  "selectedBuildUpValue": "1308.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "652fd10f7e32132d4094d622",
      "name": "externallmg_1697632472618_1697632488398_image_5.jpeg",
      "path": "cases/652e4f9f31a8c630cfa75ee1/externallmg_1697632472618_1697632488398_image_5.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "652fd10f7e32132d4094d623",
      "name": "externallmg_1697632472930_1697632488398_image_6.jpeg",
      "path": "cases/652e4f9f31a8c630cfa75ee1/externallmg_1697632472930_1697632488398_image_6.jpeg",
      "orientation": "portrait"
    }
  ],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
      "_id": "6530e4ab619c14402da52720",
      "name": "Passage",
      "path": "cases/652e4f9f31a8c630cfa75ee1/externallmg_1697703080307_externallmg_1697632472618_1697632488398_image_5.jpeg",
      "orientation": "portrait"
    }
  ],
}
```

```
{
  "status": false,
  "_id": "6530e4ab619c14402da52722",
  "name": "Passage",
  "path": "cases/652e4f9f31a8c630cfa75ee1/externallmg_1697703081186_externallmg_1697632514535_1697632541390_image_0.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "6530e4ab619c14402da52723",
  "name": "Passage",
  "path": "cases/652e4f9f31a8c630cfa75ee1/externallmg_1697703081467_externallmg_1697632516930_1697632541390_image_2.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "6530e4ab619c14402da52724",
  "name": "Passage",
  "path": "cases/652e4f9f31a8c630cfa75ee1/externallmg_1697703081554_externallmg_1697632517071_1697632541390_image_3.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "6530e4ab619c14402da52725",
  "name": "Passage",
  "path": "cases/652e4f9f31a8c630cfa75ee1/externallmg_1697703081660_externallmg_1697632517325_1697632541390_image_4.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "6530e4ab619c14402da52727",
  "name": "Passage",
  "path": "cases/652e4f9f31a8c630cfa75ee1/externallmg_1697703081854_externallmg_1697632519800_1697632541390_image_7.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "6530e4ab619c14402da52728",
  "name": "Passage",
  "path": "cases/652e4f9f31a8c630cfa75ee1/externallmg_1697703081919_externallmg_1697632519963_1697632541390_image_8.jpeg",
  "orientation": "portrait"
}
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6530e4ab619c14402da52729",
    "name": "Passage",
    "path": "cases/652e4f9f31a8c630cfa75ee1/externallmg_1697703082003_externallmg_1697632520544_1697632541390_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6530e4ab619c14402da5272a",
    "name": "Passage",
    "path": "cases/652e4f9f31a8c630cfa75ee1/externallmg_1697703082218_externallmg_1697632521370_1697632541390_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6530e4ab619c14402da5272b",
    "name": "Passage",
    "path": "cases/652e4f9f31a8c630cfa75ee1/externallmg_1697703082343_externallmg_1697632522340_1697632541390_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6530e4ab619c14402da5272c",
    "name": "Passage",
    "path": "cases/652e4f9f31a8c630cfa75ee1/externallmg_1697703082430_externallmg_1697632522444_1697632541390_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6530e4ab619c14402da5272d",
    "name": "Passage",
    "path": "cases/652e4f9f31a8c630cfa75ee1/externallmg_1697703082552_externallmg_1697632523380_1697632541390_image_17.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
```

```
"min": null,
"max": null
},
"builtUpRateRange": {
  "min": null,
  "max": null
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
```

```
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Approximate Rate Lead",
  "value": "APPROXIMATE_LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "1090.00",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentId": [],
"_id": "652e4f9f31a8c630cfa75ee1",
"ownerName": "Dr. Rajesh S. Shinde & Dr. Shital R. Shinde",
"ownerPhoneNo": "0000000000",
"appAddress": "601\nmaitry park co op Housing board\nchembur\nMumbai 400 071",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    }
  },

```

```
"inputs": {
  "documentDate": "23/10/2020",
  "from": {
    "value": "Vendor",
    "label": "Vendor"
  },
  "Vendor": "Mr. Gaurav Agrawal & Ms. Shruti Agarwal",
  "to": {
    "value": "purchaser",
    "label": "purchaser"
  },
  "purchaser": "Dr. Rajesh S. Shinde",
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "8338 / 2020"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1697697261946_RAJESH_SHINDE_SIR_AGREEMENT_23
1012_105832.pdf",
"path": "cases/652e4f9f31a8c630cfa75ee1/document_1697697261946_RAJESH_S
HINDE_SIR_AGREEMENT_231012_105832.pdf",
"id": "467633",
"uploadedBy": "6006d4ce5080a310ac1fdcf2",
"createdAt": "Thu Oct 19 2023 13:49:01 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004450",
"createdBy": "62727444afd7d55eddee092c",
"caseHistory": [
  {
    "id": "309014",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Oct 17 2023 14:40:55 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Dr. Rajesh S. Shinde & Dr. Shital R. Shinde",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "880135"
  }
]
```

```
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "606407",
    "name": "Passage",
    "length": "10.67",
    "length1": "10",
    "length2": "8",
    "width": "4.42",
    "width1": "4",
    "width2": "5",
    "totalArea": "47.11",
    "images": [],
    "extraAreas": [],
    "finalArea": "47.11"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Passage",
    "length": "4.17",
    "length1": "4",
    "length2": "2",
    "width": "1.58",
    "width1": "1",
    "width2": "7",
    "totalArea": "6.60",
    "images": [],
    "extraAreas": [],
    "finalArea": "6.60"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
  },
}
```

```
"id": "3",
"name": "Passage",
"length": "",
"length1": "7",
"length2": "0",
"width": "",
"width1": "4",
"width2": "2",
"totalArea": "29.17",
"images": [],
"finalArea": "29.17",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "13.25",
  "length1": "13",
  "length2": "3",
  "width": "9.67",
  "width1": "9",
  "width2": "8",
  "totalArea": "128.08",
  "images": [],
  "extraAreas": [],
  "finalArea": "128.08"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "WC",
  "length": "7.00",
  "length1": "7",
  "length2": "00",
  "width": "4.25",
  "width1": "4",
  "width2": "3",
  "totalArea": "29.75",
  "images": [],
```

```
"extraAreas": [],
"finalArea": "29.75"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Living Room",
  "length": "11.25",
  "length1": "11",
  "length2": "3",
  "width": "23.00",
  "width1": "23",
  "width2": "00",
  "totalArea": "258.75",
  "images": [],
  "extraAreas": [],
  "finalArea": "258.75"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Dining",
  "length": "8.58",
  "length1": "8",
  "length2": "7",
  "width": "10.75",
  "width1": "10",
  "width2": "9",
  "totalArea": "92.27",
  "images": [],
  "extraAreas": [],
  "finalArea": "92.27"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Bedroom",
```

```
"length": "15.33",
"length1": "15",
"length2": "4",
"width": "10.25",
"width1": "10",
"width2": "3",
"totalArea": "157.17",
"images": [],
"extraAreas": [],
"finalArea": "157.17"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Toilet",
  "length": "5.83",
  "length1": "5",
  "length2": "10",
  "width": "8.33",
  "width1": "8",
  "width2": "4",
  "totalArea": "48.61",
  "images": [],
  "extraAreas": [],
  "finalArea": "48.61"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Passage",
  "length": "4.42",
  "length1": "4",
  "length2": "5",
  "width": "3.92",
  "width1": "3",
  "width2": "11",
  "totalArea": "17.30",
  "images": [],
  "extraAreas": [],
  "finalArea": "17.30"
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "10",
  "name": "Toilet",
  "length": "8.58",
  "length1": "8",
  "length2": "7",
  "width": "4.25",
  "width1": "4",
  "width2": "3",
  "totalArea": "36.48",
  "images": [],
  "extraAreas": [],
  "finalArea": "36.48"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "11",
  "name": "Kitchen",
  "length": "8.42",
  "length1": "8",
  "length2": "5",
  "width": "10.58",
  "width1": "10",
  "width2": "7",
  "totalArea": "89.08",
  "images": [],
  "extraAreas": [],
  "finalArea": "89.08"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "12",
  "name": "Bedroom",
  "length": "10.42",
  "length1": "10",
```



```
"length2": "5",
"width": "14.42",
"width1": "14",
"width2": "5",
"totalArea": "150.17",
"images": [],
"extraAreas": [],
"finalArea": "150.17"
}
],
"otherComposition": [
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Dry Balcony",
    "value": "Dry_Balcony"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length1": "2",
  "length2": "7",
  "length": "2.58",
  "width1": "8",
  "width2": "6",
  "width": "8.50",
  "totalArea": "21.96",
  "percentageBeforeTotal": "21.96",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "21.96"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Dry Balcony Area",
    "value": "Dry_Balcony_Area"
  }
}
```

```
    },
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "length1": "8",
    "length2": "00",
    "length": "8.00",
    "width1": "3",
    "width2": "00",
    "width": "3.00",
    "totalArea": "24.00",
    "percentageBeforeTotal": "24.00",
    "images": [],
    "extraAreas": [],
    "percentage": "100",
    "finalArea": "24"
  }
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "101.26",
    "totalAreaDocument": "1090",
    "docBultupPercentage": "20",
    "docFinalBultUp": "1308.00",
    "docFinalBultUpSquareMeter": "121.52",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "501764"
  }
],
"images": [],
"indicatorArr": [
  {
```

```
"printlnReport": false,
  "_id": "6530d253619c14402da4d1b1",
  "property": "Hiranandani Maitri Park, Chembur, Mumbai",
  "area": "838",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "magic_bricks",
  "expectedPrice": "31900000",
  "expectedRate": "38066.83",
  "builtUpExpectedRate": "31722.35",
  "image": "cases/652e4f9f31a8c630cfa75ee1/indicator_1697697827984_Image.png",
  "squareMeter": "77.85",
  "id": "692399"
},
{
  "printlnReport": false,
  "_id": "6530d253619c14402da4d1b2",
  "property": "Hiranandani Maitri Park, Chembur, Mumbai",
  "area": "740",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "https://www.99acres.com/",
  "expectedPrice": "27500000",
  "expectedRate": "37162.16",
  "builtUpExpectedRate": "30968.47",
  "image": "cases/652e4f9f31a8c630cfa75ee1/indicator_1697697887760_Image.png",
  "squareMeter": "68.75",
  "id": "707767"
},
{
  "printlnReport": false,
  "_id": "6530d253619c14402da4d1b3",
  "property": "Hiranandani Maitri Park, Chembur, Mumbai",
  "area": "720",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "https://www.99acres.com/",
  "expectedPrice": "27000000",
  "expectedRate": "37500.00",
  "builtUpExpectedRate": "31250.00",
```

```
"image": "cases/652e4f9f31a8c630cfa75ee1/indicator_1697698129330_Image.png",
"squareMeter": "66.89",
"id": "921820"
},
{
  "printlnReport": false,
  "_id": "6530d253619c14402da4d1b4",
  "property": "Hiranandani Maitri Park, Chembur, Mumbai",
  "area": "1105",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "https://www.99acres.com/",
  "expectedPrice": "40000000",
  "expectedRate": "36199.10",
  "builtUpExpectedRate": "30165.91",
  "image": "cases/652e4f9f31a8c630cfa75ee1/indicator_1697698190188_Image.png",
  "squareMeter": "102.66",
  "id": "895509"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652fd10f7e32132d4094d61d",
    "name": "externalimg_1697632461640_1697632488396_image_0.jpeg",
    "path": "cases/652e4f9f31a8c630cfa75ee1/
externalimg_1697632461640_1697632488396_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652fd10f7e32132d4094d61e",
    "name": "externalimg_1697632465968_1697632488398_image_1.jpeg",
    "path": "cases/652e4f9f31a8c630cfa75ee1/
externalimg_1697632465968_1697632488398_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652fd10f7e32132d4094d61f",
    "name": "externalimg_1697632466142_1697632488398_image_2.jpeg",
```

```
    "path": "cases/652e4f9f31a8c630cfa75ee1/
externallmg_1697632466142_1697632488398_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652fd10f7e32132d4094d620",
    "name": "externallmg_1697632467966_1697632488398_image_3.jpeg",
    "path": "cases/652e4f9f31a8c630cfa75ee1/
externallmg_1697632467966_1697632488398_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652fd10f7e32132d4094d621",
    "name": "externallmg_1697632469736_1697632488398_image_4.jpeg",
    "path": "cases/652e4f9f31a8c630cfa75ee1/
externallmg_1697632469736_1697632488398_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652fd10f7e32132d4094d622",
    "name": "externallmg_1697632472618_1697632488398_image_5.jpeg",
    "path": "cases/652e4f9f31a8c630cfa75ee1/
externallmg_1697632472618_1697632488398_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652fd10f7e32132d4094d623",
    "name": "externallmg_1697632472930_1697632488398_image_6.jpeg",
    "path": "cases/652e4f9f31a8c630cfa75ee1/
externallmg_1697632472930_1697632488398_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "652fd10f7e32132d4094d624",
    "name": "externallmg_1697632474121_1697632488398_image_7.jpeg",
    "path": "cases/652e4f9f31a8c630cfa75ee1/
externallmg_1697632474121_1697632488398_image_7.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652fd10f7e32132d4094d625",
  "name": "externallmg_1697632474706_1697632488398_image_8.jpeg",
  "path": "cases/652e4f9f31a8c630cfa75ee1/
externallmg_1697632474706_1697632488398_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652fd10f7e32132d4094d626",
  "name": "externallmg_1697632475015_1697632488398_image_9.jpeg",
  "path": "cases/652e4f9f31a8c630cfa75ee1/
externallmg_1697632475015_1697632488398_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652fd10f7e32132d4094d627",
  "name": "externallmg_1697632476505_1697632488398_image_10.jpeg",
  "path": "cases/652e4f9f31a8c630cfa75ee1/
externallmg_1697632476505_1697632488398_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652fd10f7e32132d4094d629",
  "name": "externallmg_1697632515845_1697632541390_image_1.jpeg",
  "path": "cases/652e4f9f31a8c630cfa75ee1/
externallmg_1697632515845_1697632541390_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652fd10f7e32132d4094d62a",
  "name": "externallmg_1697632516930_1697632541390_image_2.jpeg",
  "path": "cases/652e4f9f31a8c630cfa75ee1/
externallmg_1697632516930_1697632541390_image_2.jpeg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652fd10f7e32132d4094d62e",
  "name": "externallmg_1697632518730_1697632541390_image_6.jpeg",
  "path": "cases/652e4f9f31a8c630cfa75ee1/
externallmg_1697632518730_1697632541390_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652fd10f7e32132d4094d631",
  "name": "externallmg_1697632520145_1697632541390_image_9.jpeg",
  "path": "cases/652e4f9f31a8c630cfa75ee1/
externallmg_1697632520145_1697632541390_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652fd10f7e32132d4094d637",
  "name": "externallmg_1697632522635_1697632541390_image_15.jpeg",
  "path": "cases/652e4f9f31a8c630cfa75ee1/
externallmg_1697632522635_1697632541390_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "652fd10f7e32132d4094d638",
  "name": "externallmg_1697632522904_1697632541390_image_16.jpeg",
  "path": "cases/652e4f9f31a8c630cfa75ee1/
externallmg_1697632522904_1697632541390_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "652fd10f7e32132d4094d63a",
  "name": "externallmg_1697632434527_1697632460177_image_0.jpeg",
  "path": "cases/652e4f9f31a8c630cfa75ee1/
externallmg_1697632434527_1697632460177_image_0.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "652fd10f7e32132d4094d63b",
  "name": "externallmg_1697632435247_1697632460205_image_1.jpeg",
  "path": "cases/652e4f9f31a8c630cfa75ee1/
externallmg_1697632435247_1697632460205_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "652fd10f7e32132d4094d63c",
  "name": "externallmg_1697632436765_1697632460205_image_2.jpeg",
  "path": "cases/652e4f9f31a8c630cfa75ee1/
externallmg_1697632436765_1697632460205_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530e4ab619c14402da5271f",
  "name": "externallmg_1697703078581_externallmg_1697632465968_16976324883
98_image_1.jpeg",
  "path": "cases/652e4f9f31a8c630cfa75ee1/externallmg_1697703078581_externallm
g_1697632465968_1697632488398_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530e4ab619c14402da52720",
  "name": "externallmg_1697703080307_externallmg_1697632472618_16976324883
98_image_5.jpeg",
  "path": "cases/652e4f9f31a8c630cfa75ee1/externallmg_1697703080307_externallm
g_1697632472618_1697632488398_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530e4ab619c14402da52721",
  "name": "externallmg_1697703080625_externallmg_1697632472930_16976324883
98_image_6.jpeg",
  "path": "cases/652e4f9f31a8c630cfa75ee1/externallmg_1697703080625_externallm
g_1697632472930_1697632488398_image_6.jpeg",
```



```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530e4ab619c14402da52722",
  "name": "externallmg_1697703081186_externallmg_1697632514535_16976325413
90_image_0.jpeg",
  "path": "cases/652e4f9f31a8c630cfa75ee1/externallmg_1697703081186_externallm
g_1697632514535_1697632541390_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530e4ab619c14402da52723",
  "name": "externallmg_1697703081467_externallmg_1697632516930_16976325413
90_image_2.jpeg",
  "path": "cases/652e4f9f31a8c630cfa75ee1/externallmg_1697703081467_externallm
g_1697632516930_1697632541390_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530e4ab619c14402da52724",
  "name": "externallmg_1697703081554_externallmg_1697632517071_16976325413
90_image_3.jpeg",
  "path": "cases/652e4f9f31a8c630cfa75ee1/externallmg_1697703081554_externallm
g_1697632517071_1697632541390_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530e4ab619c14402da52725",
  "name": "externallmg_1697703081660_externallmg_1697632517325_16976325413
90_image_4.jpeg",
  "path": "cases/652e4f9f31a8c630cfa75ee1/externallmg_1697703081660_externallm
g_1697632517325_1697632541390_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530e4ab619c14402da52726",
```

```
    "name": "externalimg_1697703081757_externalimg_1697632518350_16976325413
90_image_5.jpeg",
    "path": "cases/652e4f9f31a8c630cfa75ee1/externalimg_1697703081757_externalim
g_1697632518350_1697632541390_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6530e4ab619c14402da52727",
    "name": "externalimg_1697703081854_externalimg_1697632519800_16976325413
90_image_7.jpeg",
    "path": "cases/652e4f9f31a8c630cfa75ee1/externalimg_1697703081854_externalim
g_1697632519800_1697632541390_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6530e4ab619c14402da52728",
    "name": "externalimg_1697703081919_externalimg_1697632519963_16976325413
90_image_8.jpeg",
    "path": "cases/652e4f9f31a8c630cfa75ee1/externalimg_1697703081919_externalim
g_1697632519963_1697632541390_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6530e4ab619c14402da52729",
    "name": "externalimg_1697703082003_externalimg_1697632520544_16976325413
90_image_10.jpeg",
    "path": "cases/652e4f9f31a8c630cfa75ee1/externalimg_1697703082003_externalim
g_1697632520544_1697632541390_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6530e4ab619c14402da5272a",
    "name": "externalimg_1697703082218_externalimg_1697632521370_16976325413
90_image_11.jpeg",
    "path": "cases/652e4f9f31a8c630cfa75ee1/externalimg_1697703082218_externalim
g_1697632521370_1697632541390_image_11.jpeg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530e4ab619c14402da5272b",
  "name": "externallmg_1697703082343_externallmg_1697632522340_16976325413
90_image_12.jpeg",
  "path": "cases/652e4f9f31a8c630cfa75ee1/externallmg_1697703082343_externallm
g_1697632522340_1697632541390_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530e4ab619c14402da5272c",
  "name": "externallmg_1697703082430_externallmg_1697632522444_16976325413
90_image_14.jpeg",
  "path": "cases/652e4f9f31a8c630cfa75ee1/externallmg_1697703082430_externallm
g_1697632522444_1697632541390_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6530e4ab619c14402da5272d",
  "name": "externallmg_1697703082552_externallmg_1697632523380_16976325413
90_image_17.jpeg",
  "path": "cases/652e4f9f31a8c630cfa75ee1/externallmg_1697703082552_externallm
g_1697632523380_1697632541390_image_17.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-10-17T09:10:55.694Z",
"updatedAt": "2023-10-19T09:33:49.644Z",
"__v": 0,
"fullAddress": "Residential Flat No. 601, 6th Floor, Wing - B, Hiranandani Tower , Maitri
Park Co-op. Hsg. Soc. Ltd., Sion Trombay Road, Village - Chembur, Mumbai, Taluka -
Kurla, District - Mumbai Suburban, PIN Code - 400 071, State - Maharashtra, India",
"updatedBy": "60092304a16fab0f2af9b0c2",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Rajesh S Shinde ",
"email": "",
"isExternal": "false",
```

```
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "0000000000",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 1090.00",
"flatRate": "37500",
"landOtherRate": "34500",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"finalSaleablePercentage": "0",
"briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + 4 Passage + WC +
Dining + 2 Toilet",
"carpetTotal": "1090.54",
"otherCarpetTotal": "45.96",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "45.96",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "1250.15",
"finalCarpetArea": "1136.50",
"finalSalableArea": "1375.17",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
```

```

"siteMeasurementRemark": "",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"siteVisitDate": "2023-10-18"
}

```

Name	Length	Width	Total
Composition :			
Passage	10'8"	4'5"	47.11
Passage	4'2"	1'7"	6.60
Passage	7'0"	4'2"	29.17
Bedroom	13'3"	9'8"	128.08
WC	7'00"	4'3"	29.75
Living Room	11'3"	23'00"	258.75
Dining	8'7"	10'9"	92.27
Bedroom	15'4"	10'3"	157.17
Toilet	5'10"	8'4"	48.61
Passage	4'5"	3'11"	17.30
Toilet	8'7"	4'3"	36.48
Kitchen	8'5"	10'7"	89.08
Bedroom	10'5"	14'5"	150.17
Other Composition :			
Dry Balcony	2'7"	8'6"	21.96
Dry Balcony Area	8'00"	3'00"	24.00