

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b951"
    },
    "type": "CREDITOFFICER",
    "_id": "635f732fe363ef22db2f1c80",
    "firstName": "Ravindra Sir",
    "lastName": "sir",
    "mobileNo": "",
    "email": "me1@me.com",
    "workMobileNo": "7738642220"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "620000",
    "discussWithPerson": "Ravindra Sir",
    "expectedFees": 310,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b951",
  "branchCode": "000167",
  "type": "BRANCH",
  "name": "RACPC Belapur ",
  "email": "sbi.14677@sbi.co.in",
  "mobileNo": "022-27524090",
  "alternateMobileNo": "",
  "address": "Estate Department Corporate Centre, 4th Floor, CIDCO Tower No. 4,
Railway Station Building, C.B.D. Belapur, Navi Mumbai - 400 614, State - Maharashtra,
Country - India.",
  "ledgerName": "STATE BANK OF INDIA - CBD Estate Department",
  "fax": "022 2757 7002",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7189d2ffdf65bcd65882b",
  "role": "PICKUPPERSON",
  "firstName": "Ravindra",
  "email": "ravindrakasare186@gmail.com",
  "lastName": "Kasare",
  "mobileNo": "9167204055",
  "shortName": "RBK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60b7189d2ffdf65bcd65882b\\
\\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9343b45132d6a6bdd96e8",
  "role": "SITEENGINEER",
  "firstName": "Rajesh",
  "email": "rajeshb.ghadi@gmail.com",
  "lastName": "Ghadi",
  "mobileNo": "8652092666",
  "designation": "",
  "shortName": "RHG",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordinatiion",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
  "mobileNo": "9529385821",
```

```
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordinatiion",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.0375312127046",
  "longitude": "73.06975484112742"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.06975484112742,
    19.0375312127046
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-10-18T03:30:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-10-18T03:30:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
```

```
"value": "Nerul",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "3",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "A-3",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
```

```
"status": true,
"name": "Plot No.",
"key": "plotNo",
"value": "2",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Kendriya Vihar Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "38",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
```



```
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
```

```
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "48",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
}
```

```
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 706",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Sea Woods (West)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
```

```
"label": "Sole Ownership"
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "NMMC",
  "label": "Navi Mumbai Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Road ",
  "west": "Karave Link Road",
  "south": "Building No. A-4",
  "east": "Building No. A-2"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
```

```
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Copy of Occupancy Certificate is received may be
assumed that the construction is as per sanctioned plan",
"approvePlanVerified": "N.A",
"empanelledOfApprovePlan": "N.A"
},
"compositeRate": {
"remark": "The loading between Measured Carpet Area to Built Up Area mentioned
in agreement is 40% for the purpose of valuation we have considering loading factor. ",
"depreciationPercentage": "40.5",
"depreciationRatioOfBuilding": "",
"salvageValue": "10",
"depreciatedCostOfConstruction": "17287.5",
"depreciatedBuildingRate": "1487.5"
},
"igrRate": {
"propertyName": "Residential Flat",
"rate": "118400",
"landRate": "46800",
"igrImage": "cases/652e98ca7e32132d4092fdea/igr_1697865518215_Image.png",
"squareMeterGuideLineRate": "94720.00",
"squareFeetGuideLineRate": "8800.00"
},
"igrFinalRate": {
"rate": "7598.00",
"squareMeterGuideLineRate": "81782.00",
"squareFeetGuideLineRate": "7598.00",
"depreciationPercentage": "73"
},
"outgoingDetail": {
"areaStatusList": {
"value": "Medium",
"label": "Medium"
},
"propertyTypeOfUseList": {
"value": "Residential_Purpose",
"label": "Residential Purpose"
},
"propertyOccupiedByList": {
"value": "Owner_Occupied",
"label": "Owner Occupied"
},
"monthlyRent": "14,000",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
```

```
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per NMMC norms",
"tenantName": "",
"maintenanceOfFlat": "Normal"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed Area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Car Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "1996",
    "fullDate": "1/1/1996"
  }
}
```

```
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
```

```
"value": "Normal",
"label": "Normal"
},
"maintenanceIssues": {
"value": "1",
"label": "Yes"
},
"visibleDamageInBuilding": {
"value": "1",
"label": "Yes"
},
"systemOfAirConditioning": {
"value": "1",
"label": "Yes"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "ground",
"label": "Ground"
},
"yearOfConstructionAsPer": {
"value": "as_per_occupancy_certificate",
"label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "33",
"ageOfBuilding": "27",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "3",
"flatFloorNo": "4",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
"areaType": "Built Up",
"area": "0.00"
},
"routeMap": {
"routeMapDetail": {
"routeStation": {
```



```
    "value": "Railway_Station",
    "label": "Railway Station"
  },
  "routeMapImg": "cases/652e98ca7e32132d4092fdea/
routeMap_1697869705313_Image.png",
  "routeLat": "19.019939",
  "routeLng": "73.013858",
  "stationName": "Seewood ",
  "routeDistance": "1.00 Km"
},
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": true,
  "finallatLng": true
},
"locationMapImg": [
  {
    "id": "awhrec",
    "name": "awhrec",
    "image": "cases/652e98ca7e32132d4092fdea/
routeMap_1697869631385_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
```

```
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "8644000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "8644000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "3799000.00",
  "selectedBuildUpValue": "500.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65334517619c14402da85708",
      "name": "externallmg_r_1697858838481_1697809059420.jpg",
      "path": "cases/652e98ca7e32132d4092fdea/externallmg_r_1697858838481_1697809059420.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
      "_id": "65334517619c14402da85709",
      "name": "Living Room",
      "path": "cases/652e98ca7e32132d4092fdea/externallmg_r_1697858838514_1697809059441.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "65334517619c14402da8570b",
      "name": "Living Room",
      "path": "cases/652e98ca7e32132d4092fdea/externallmg_r_1697858838522_1697809059469.jpg",
      "orientation": "portrait"
    }
  ]
}
```

```
    "status": false,
    "_id": "65334517619c14402da8570c",
    "name": "Living Room",
    "path": "cases/652e98ca7e32132d4092fdea/
externallmg_r_1697858838529_1697809059492.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65334517619c14402da85711",
    "name": "Living Room",
    "path": "cases/652e98ca7e32132d4092fdea/
externallmg_r_1697858838487_1697809059430.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65334517619c14402da85710",
    "name": "Living Room",
    "path": "cases/652e98ca7e32132d4092fdea/
externallmg_r_1697858838541_1697809059532.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65334517619c14402da85708",
    "name": "Living Room",
    "path": "cases/652e98ca7e32132d4092fdea/
externallmg_r_1697858838481_1697809059420.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65334517619c14402da85703",
    "name": "Living Room",
    "path": "cases/652e98ca7e32132d4092fdea/
externallmg_r_1697858838463_1697809059392.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "20896",
    "max": "22222"
  }
},
```

```
"builtUpRateRange": {
  "min": "17413",
  "max": "18519"
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
```



```
    "isEditable": false
  }
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "500.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentId": [],
"_id": "652e98ca7e32132d4092fdea",
"ownerName": "Mr. Vivek Kumar & Mrs. Rashmi Kumari ",
"ownerPhoneNo": "7021244172",
"appAddress": "flat no. 48 3rd floor Bldg no A krndre eya vihar co op hsg soc Ltd plot
no 2 sector no 38 Nerul ",
"remark": "ssl Trushali madam",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "21/12/2022",
      "from": {
        "value": "Vendor",
```

```
    "label": "Vendor"
  },
  "Vendor": "Mr. Vivek Kumar & Mrs. Rashmi Kumari ",
  "to": {
    "value": "Purchaser",
    "label": "Purchaser"
  },
  "Purchaser": "Ms. Manisha Singh ",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "22331 / 2022"
},
"isHardCopy": false,
"displayStatus": true,
"id": "743146",
"path": "cases/652e98ca7e32132d4092fdea/
document_1697552517654_Vivek_kumar__sbi_Racpc_belapur.pdf",
"fileName": "document_1697552517654_Vivek_kumar__sbi_Racpc_belapur.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "20/09/1996",
    "nameOfApprovingAuthority": {
      "value": "Navi_Mumbai_Municipal_Corporation.",
      "label": "Navi Mumbai Municipal Corporation."
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "NMMC / TPO / OC / 95 - 96"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1697866822171_406919.pdf",
"path": "cases/652e98ca7e32132d4092fdea/
document_1697866822171_406919.pdf",
"id": "155174",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Sat Oct 21 2023 11:10:22 GMT+0530 (India Standard Time)"
```

```
}
],
"caseNumber": "004467",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "770653",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Oct 17 2023 19:53:06 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Vivek Kumar & Mrs. Rashmi Kumari ",
    "phone": "7021244172",
    "ownershipShare": "",
    "email": "",
    "id": "305655"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "901237",
    "name": "Living Room",
    "length": "8.00",
    "length1": "8",
    "length2": "00",
    "width": "13.00",
    "width1": "13",
    "width2": "00",
    "totalArea": "104.00",
    "images": [],
    "extraAreas": [],
    "finalArea": "104.00"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  }
]
```

```
},
  "id": "1",
  "name": "WC",
  "length": "2.50",
  "length1": "2",
  "length2": "6",
  "width": "5.67",
  "width1": "5",
  "width2": "8",
  "totalArea": "14.17",
  "images": [],
  "extraAreas": [],
  "finalArea": "14.17"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bathroom",
  "length": "3.50",
  "length1": "3",
  "length2": "6",
  "width": "4.92",
  "width1": "4",
  "width2": "11",
  "totalArea": "17.21",
  "images": [],
  "extraAreas": [],
  "finalArea": "17.21"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Kitchen",
  "length": "9.58",
  "length1": "9",
  "length2": "7",
  "width": "6.08",
  "width1": "6",
  "width2": "1",
  "totalArea": "58.30",
```

```
"images": [],
"extraAreas": [],
"finalArea": "58.30"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Passage",
  "length": "3.33",
  "length1": "3",
  "length2": "4",
  "width": "3.33",
  "width1": "3",
  "width2": "4",
  "totalArea": "11.11",
  "images": [],
  "extraAreas": [],
  "finalArea": "11.11"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Bedroom",
  "length": "11.83",
  "length1": "11",
  "length2": "10",
  "width": "9.92",
  "width1": "9",
  "width2": "11",
  "totalArea": "117.35",
  "images": [],
  "finalArea": "117.35",
  "extraAreas": []
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    }
  }
]
```

```
},
"name": {
  "label": "Cupboard",
  "value": "Cupboard"
},
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
},
"id": "0",
"length1": "4",
"length2": "1",
"length": "4.08",
"width1": "0",
"width2": "11",
"width": "0.92",
"totalArea": "3.74",
"percentageBeforeTotal": "3.74",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "3.74"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Cupboard",
    "value": "Cupboard"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "length1": "4",
  "length2": "6",
  "length": "4.50",
  "width1": "4",
  "width2": "6",
  "width": "4.50",
  "totalArea": "20.25",
  "percentageBeforeTotal": "20.25",
  "images": [],
```

```
"extraAreas": [],
"percentage": "100",
"finalArea": "20.25"
},
],
"externalReport": [],
"documentPerArea": [
{
"typeofDocument": {
"label": "Agreement For Sale",
"value": "60ae1254aa6d152c1801b326"
},
"docMeasurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
},
"selectAreaTypeDocument": "Built_Up",
"squareMeterArea": "46.45",
"totalAreaDocument": "500",
"docBuiltpPercentage": "",
"docFinalBuiltUp": "0.00",
"docFinalBuiltUpSquareMeter": "0.00",
"docSaleablePercentage": "",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00",
"id": "553248"
}
],
"images": [],
"indicatorArr": [
{
"printlnReport": true,
"_id": "65335f8c619c14402da89798",
"property": "Residential Flat",
"area": "678",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"source": "magic_bricks",
"expectedPrice": "15000000",
"expectedRate": "22123.89",
"builtUpExpectedRate": "18436.58",
"image": "cases/652e98ca7e32132d4092fdea/
indicator_1697864661604_Image.png",
"squareMeter": "62.99",
```

```
"id": "957783"
},
{
  "printlnReport": true,
  "_id": "65335f8c619c14402da89799",
  "property": "Residential Flat",
  "area": "720",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "https://www.99acres.com/",
  "expectedPrice": "16000000",
  "expectedRate": "22222.22",
  "builtUpExpectedRate": "18518.52",
  "image": "cases/652e98ca7e32132d4092fdea/
indicator_1697864700805_Image.png",
  "squareMeter": "66.89",
  "id": "112279"
},
{
  "printlnReport": true,
  "_id": "65335f8c619c14402da8979a",
  "property": "Residential Flat",
  "area": "670",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "source": "Index_no.2",
  "expectedPrice": "14000000",
  "expectedRate": "20895.52",
  "builtUpExpectedRate": "17412.94",
  "image": "cases/652e98ca7e32132d4092fdea/
indicator_1697864743701_Image.png",
  "squareMeter": "62.25",
  "id": "393308"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65334517619c14402da85700",
    "name": "externallmg_r_1697858838448_1697809059380.jpg",
    "path": "cases/652e98ca7e32132d4092fdea/
externallmg_r_1697858838448_1697809059380.jpg",
```



```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65334517619c14402da85701",
  "name": "externallmg_r_1697858838425_1697809059373.jpg",
  "path": "cases/652e98ca7e32132d4092fdea/
externallmg_r_1697858838425_1697809059373.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65334517619c14402da85702",
  "name": "externallmg_r_1697858838456_1697809059386.jpg",
  "path": "cases/652e98ca7e32132d4092fdea/
externallmg_r_1697858838456_1697809059386.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65334517619c14402da85703",
  "name": "externallmg_r_1697858838463_1697809059392.jpg",
  "path": "cases/652e98ca7e32132d4092fdea/
externallmg_r_1697858838463_1697809059392.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65334517619c14402da85704",
  "name": "externallmg_r_1697858838469_1697809059398.jpg",
  "path": "cases/652e98ca7e32132d4092fdea/
externallmg_r_1697858838469_1697809059398.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65334517619c14402da85705",
  "name": "externallmg_r_1697858838475_1697809059409.jpg",
  "path": "cases/652e98ca7e32132d4092fdea/
externallmg_r_1697858838475_1697809059409.jpg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65334517619c14402da85706",
  "name": "externallmg_r_1697858838367_1697809059362.jpg",
  "path": "cases/652e98ca7e32132d4092fdea/
externallmg_r_1697858838367_1697809059362.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65334517619c14402da85707",
  "name": "externallmg_r_1697858838398_1697809059368.jpg",
  "path": "cases/652e98ca7e32132d4092fdea/
externallmg_r_1697858838398_1697809059368.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65334517619c14402da85708",
  "name": "externallmg_r_1697858838481_1697809059420.jpg",
  "path": "cases/652e98ca7e32132d4092fdea/
externallmg_r_1697858838481_1697809059420.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65334517619c14402da85709",
  "name": "externallmg_r_1697858838514_1697809059441.jpg",
  "path": "cases/652e98ca7e32132d4092fdea/
externallmg_r_1697858838514_1697809059441.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65334517619c14402da8570a",
  "name": "externallmg_r_1697858838518_1697809059458.jpg",
  "path": "cases/652e98ca7e32132d4092fdea/
externallmg_r_1697858838518_1697809059458.jpg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65334517619c14402da8570b",
  "name": "externallmg_r_1697858838522_1697809059469.jpg",
  "path": "cases/652e98ca7e32132d4092fdea/
externallmg_r_1697858838522_1697809059469.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65334517619c14402da8570c",
  "name": "externallmg_r_1697858838529_1697809059492.jpg",
  "path": "cases/652e98ca7e32132d4092fdea/
externallmg_r_1697858838529_1697809059492.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65334517619c14402da8570d",
  "name": "externallmg_r_1697858838526_1697809059480.jpg",
  "path": "cases/652e98ca7e32132d4092fdea/
externallmg_r_1697858838526_1697809059480.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65334517619c14402da8570e",
  "name": "externallmg_r_1697858838534_1697809059506.jpg",
  "path": "cases/652e98ca7e32132d4092fdea/
externallmg_r_1697858838534_1697809059506.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65334517619c14402da8570f",
  "name": "externallmg_r_1697858838537_1697809059521.jpg",
  "path": "cases/652e98ca7e32132d4092fdea/
externallmg_r_1697858838537_1697809059521.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65334517619c14402da85710",
    "name": "externallmg_r_1697858838541_1697809059532.jpg",
    "path": "cases/652e98ca7e32132d4092fdea/
externallmg_r_1697858838541_1697809059532.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65334517619c14402da85711",
    "name": "externallmg_r_1697858838487_1697809059430.jpg",
    "path": "cases/652e98ca7e32132d4092fdea/
externallmg_r_1697858838487_1697809059430.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation Sheet.xlsx",
    "filename": "1697865547341_Calculation_Sheet.xlsx",
    "path": "cases/652e98ca7e32132d4092fdea/
processingDocuments/1697865547341_Calculation_Sheet.xlsx",
    "size": "16321",
    "createdAt": "Sat Oct 21 2023 10:49:07 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "Summary Sheet.xlsx",
    "filename": "1697865547342_Summary_Sheet.xlsx",
    "path": "cases/652e98ca7e32132d4092fdea/
processingDocuments/1697865547342_Summary_Sheet.xlsx",
    "size": "2843042",
    "createdAt": "Sat Oct 21 2023 10:49:07 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "Vivek kumar - Doc.pdf",
    "filename": "1697865547393_Vivek_kumar__Doc.pdf",
    "path": "cases/652e98ca7e32132d4092fdea/
processingDocuments/1697865547393_Vivek_kumar__Doc.pdf",
    "size": "7193383",
    "createdAt": "Sat Oct 21 2023 10:49:07 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  }
]
```

```
}
],
"remarks": [],
"createdAt": "2023-10-17T14:23:06.229Z",
"updatedAt": "2023-10-21T06:29:45.140Z",
"__v": 0,
"invoiceId": "652e98ca7e32132d4092fdf3",
"fullAddress": "Residential Flat No. 48, 3rd Floor, Building No A-3, Kendriya Vihar Co-
Op. Hsg. Soc. Ltd., Plot No. 2, Sector 38, Village - Nerul, Sea Woods (West), Taluka -
Thane, District - Thane, Navi Mumbai, PIN - 400 706, State - Maharashtra, Country -
India",
"updatedBy": "62fe044a48a26047e6552796",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Mr. Vivek Kumar ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "7021244172",
"buildingServicesRate": "2500",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 500.00",
"flatRate": "18300",
"landOtherRate": "15800",
"builtupPercentage": "10",
"carpetTotal": "322.14",
"extendOfSiteRemark": "",
"finalBuiltupArea": "380.74",
"finalCarpetArea": "346.13",
"finalSalableArea": "418.82",
"otherCarpetTotal": "23.99",
"salablePercentage": "10",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 322.00\nCup Board Area in Sq.
Ft. = 24.00\n\n",
"toBeAdded": "",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + WC + Bathroom +
Passage",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "23.99",
```

```

"otherCompositionSaleableTotal": "0.00",
"finalSaleablePercentage": "",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
}
}
}

```

Name	Length	Width	Total
Composition :			
Living Room	8'00"	13'00"	104.00
WC	2'6"	5'8"	14.17
Bathroom	3'6"	4'11"	17.21
Kitchen	9'7"	6'1"	58.30
Passage	3'4"	3'4"	11.11
Bedroom	11'10"	9'11"	117.35
Other Composition :			
Cupboard	4'1"	0'11"	3.74
Cupboard	4'6"	4'6"	20.25