

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6273b00bafd7d55eddee5f69"
    },
    "type": "CREDITOFFICER",
    "_id": "6363aa704d42487767aeaf99",
    "firstName": "SUNIL BHOSALE",
    "lastName": "BHOSALE",
    "mobileNo": "9004074579",
    "email": "sunil.bhosale@sbi.co.in",
    "workMobileNo": "9004074579"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "00",
    "discussWithPerson": "SUNIL BHOSALE",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6273b00bafd7d55eddee5f69",
  "name": "SPL PBB Fort",
  "branchCode": "4205 ",
  "mobileNo": "02223662641",
  "alternateMobileNo": "",
  "email": "sbi.04205@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Mumbai Main Branch Building, Gate no 1 Horniman Circle Mumbai
samachar marg Fort."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af3d172ffdf65bcd6585cd",
```

```
"role": "PICKUPPERSON",
"firstName": "Sachin",
"email": "sachin.joshi@vastukala.org",
"lastName": "Joshi",
"mobileNo": "9167204063",
"shortName": "SJ",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af3d172ffdf65bcd6585cd\
\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "627362b3afd7d55eddee1ee7",
"role": "SITEENGINEER",
"firstName": "Vicky ",
"email": "vicky@vastukala.org",
"lastName": "Bhor",
"mobileNo": "9004386288",
"designation": "",
"shortName": "VB",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "627221f4afd7d55eddeddcb4",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Prajakta",
"email": "prajakta@vastukala.org",
"lastName": "Patil",
"mobileNo": "9769797568",
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60f91b6f344e052188ffd1fc",
"role": "MAKER",
"firstName": "Jayaraja",
"email": "jayaraja@vastukala.org",
"lastName": "Acharya",
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
```

```
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
  },
  "checker": "",
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "[N]C.C.I.T/I -14/52/2008-09",
          "label": "Wealth Tax"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "6084131a13f01f158c6ea1f3",
      "PANNo": "AEAPC7114Q",
      "role": "VALUER",
      "firstName": "Sharadkumar",
      "fatherName": "Baburao",
      "email": "cmd@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9422171100",
      "designation": "CMD",
      "registrationNo": [
        {
          "title": {
            "value": "Wealth_Tax",
            "label": "Wealth Tax"
          },
          "_id": "6084131a13f01f158c6ea1f4",
          "number": "[N]C.C.I.T/I -14/52/2008-09"
        }
      ],
      "shortName": "SBC",
      "workWithDocumentMaker": "",
      "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
    }
  ],
  "clientType": {
    "label": "BANK",
    "value": "BANK"
  },
  "location": {
    "latitude": "18.974517113562623",
```

```
"longitude": "73.11149041885145"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.11149041885145,
    18.974517113562623
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-10-26T07:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-10-26T07:00:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
```

```
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Karanjade",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "5",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Raigad",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
}
```

```
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Panvel",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "164",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Krishna ",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "4",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
```

```
"value": "",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Sai Vrindavan Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
```



```
"status": false,
"name": "Block No",
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "506",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
```

```
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 410 206",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Navi Mumbai",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "flooring": {
    "value": "Vitrified_tile_flooring",
    "label": "Vitrified tile flooring"
  },
  "doors": {
    "value": "Teak_wood_door_frame_with_flush_shutters",
    "label": "Teak wood door frame with flush shutters"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
}
```

```
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "NMMC",
    "label": "Navi Mumbai Municipal Corporation"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Shree Wing",
    "west": "Residential Building",
    "south": "Railway Track",
    "east": "Radhe Wing"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available",
    "west": "Details not available",
    "south": "Details not available",
    "east": "Details not available"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    }
  },
  "asPerDocument": {
```

```
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received it may be assumed
that the construction is as per Sanctioned Plan.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No"
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Tenant_Occupied",
    "label": "Tenant Occupied"
  },
  "monthlyRent": "10,000",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per CIDCO norms",
  "tenantName": "Mr. Mishra",
  "maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  }
},
```

```
"anyFavouringForExtraPotentialValue": "Located in developed area",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Covered Car Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2019",
    "fullDate": "1/1/2019"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "R.C.C._Framed_Structure",
    "label": "R.C.C. Framed Structure"
  },
  "typeOfFoundation": {
    "value": "rcc",
    "label": "R.C.C. Foundation"
  }
}
```

```
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
```

```
"value": "0",
"label": "No"
},
"provisionOfFirefighting": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"groundStilt": {
"value": "stilt",
"label": "Stilt"
},
"yearOfConstructionAsPer": {
"value": "as_per_occupancy_certificate",
"label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "56",
"ageOfBuilding": "4",
"noOfBasement": "",
"noOfPodium": "1",
"noOfAmenityFloors": "1",
"noOfFloors": "7",
"flatFloorNo": "5",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "6"
},
"finalPlinthArea": {
"areaType": "Built Up",
"area": "223.20",
"measurementType": "Sq. Ft.",
"areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
"routeMapDetail": {
"routeStation": {
"value": "Railway_Station",
"label": "Railway Station"
}
},
"routeMapImg": "cases/653a0c26164a9341fb026275/
routeMap_1699424024052_Image.png",
"routeLat": "18.975917",
"routeLng": "73.101833",
"stationName": "Panvel Junction",
"routeDistance": "4.2 km"
},
}
```

```
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": true,
  "finallatLng": true
},
"locationMapImg": [
  {
    "id": "n58qbf",
    "name": "n58qbf",
    "image": "cases/653a0c26164a9341fb026275/
routeMap_1699423787333_Image.png"
  }
],
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
```



```
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
```

```
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
```

```
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0.00",
  "selectedBuildUpValue": "223.20",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "654b0e1a637db60f88b52111",
      "name": "externalimg_1699417626078_IMG_20231107_8336.jpg",
      "path": "cases/653a0c26164a9341fb026275/
externalimg_1699417626078_IMG_20231107_8336.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "654b0e1a637db60f88b5210c",
      "name": "externalimg_1699417626066_IMG_20231107_1350.jpg",
      "path": "cases/653a0c26164a9341fb026275/
externalimg_1699417626066_IMG_20231107_1350.jpg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "654b0e1a637db60f88b52114",
      "name": "externalimg_1699417626084_IMG_20231107_9305.jpg",
      "path": "cases/653a0c26164a9341fb026275/
externalimg_1699417626084_IMG_20231107_9305.jpg",
      "orientation": "landscape"
    }
  ],
  {
```

```
    "status": false,
    "_id": "654b0e1a637db60f88b52113",
    "name": "externallmg_1699417626082_IMG_20231107_8991.jpg",
    "path": "cases/653a0c26164a9341fb026275/
externallmg_1699417626082_IMG_20231107_8991.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "654b0e29637db60f88b5218c",
    "name": "externallmg_r_1699417641375_IMG20231107171107.jpg",
    "path": "cases/653a0c26164a9341fb026275/
externallmg_r_1699417641375_IMG20231107171107.jpg",
    "orientation": "landscape"
  }
],
"compositionImages": [
  {
    "status": false,
    "_id": "654b0e29637db60f88b5217d",
    "name": "Living Room",
    "path": "cases/653a0c26164a9341fb026275/
externallmg_1699417641359_IMG_20231107_10435.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "654b0e29637db60f88b5217f",
    "name": "Living Room",
    "path": "cases/653a0c26164a9341fb026275/
externallmg_1699417641363_IMG_20231107_11389.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "654b0e29637db60f88b52182",
    "name": "Living Room",
    "path": "cases/653a0c26164a9341fb026275/
externallmg_1699417641368_IMG_20231107_12488.jpg",
    "orientation": "landscape"
  },
  {
    "status": false,
```

```
    "_id": "654b0e29637db60f88b5218a",
    "name": "Living Room",
    "path": "cases/653a0c26164a9341fb026275/
externallmg_1699417641497_IMG_20231107_13399.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
```

```
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "186.00",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"paymentId": [],
"_id": "653a0c26164a9341fb026275",
"ownerName": "Nilima Mahendra Salekar",
"ownerPhoneNo": "9769025655",
```

```
"appAddress": "Flat no 506,5floor,Sai Vrindavan CHS,Plot no 164,Sector 4,Karanjade
Panvel ",
"remark": "9167665465",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "29/06/2017",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Today Homes",
      "to": {
        "value": "Allottee",
        "label": "Allottee"
      },
      "Allottee": "Nilima Mahendra Salekar & Mahendra C. Salekar",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "7259/2017"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1699425914576_Sale_Deed_2017.pdf",
    "path": "cases/653a0c26164a9341fb026275/
document_1699425914576_Sale_Deed_2017.pdf",
    "id": "205391",
    "uploadedBy": "60f91b6f344e052188ffd1fc",
    "createdAt": "Wed Nov 08 2023 12:15:14 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124baa6d152c1801b2fd",
      "label": "Occupancy Certificate"
    },
    "inputs": {
      "documentDate": "15/03/2019",
      "nameOfApprovingAuthority": {
        "value": "City_and_Industrial_Development_Corp_Of_Maharashtra_ltd.",
        "label": "City and Industrial Development Corp Of Maharashtra Ltd."
      }
    }
  }
]
```



```
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "BP-11917/4205"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1699425986107_Occupancy_Certificate.pdf",
  "path": "cases/653a0c26164a9341fb026275/
document_1699425986107_Occupancy_Certificate.pdf",
  "id": "571696",
  "uploadedBy": "60f91b6f344e052188ffd1fc",
  "createdAt": "Wed Nov 08 2023 12:16:26 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae125eaa6d152c1801b353",
    "label": "Maintenance Bill"
  },
  "inputs": {
    "documentDate": "01/09/2023",
    "remark": "issued by Sai Vridavan Co-op. Hsg. Soc. Ltd",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "2301662"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1699426073274_Maintenance_Bill.pdf",
  "path": "cases/653a0c26164a9341fb026275/
document_1699426073274_Maintenance_Bill.pdf",
  "id": "348711",
  "uploadedBy": "60f91b6f344e052188ffd1fc",
  "createdAt": "Wed Nov 08 2023 12:17:53 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "004663",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "461078",
    "title": "Create Lead",
```

```
"description": "Create Lead",
"datetime": "Thu Oct 26 2023 12:20:14 GMT+0530 (India Standard Time)"
}
],
"owners": [
  {
    "name": "Nilima Mahendra Salekar",
    "phone": "9769025655",
    "ownershipShare": "",
    "email": "",
    "id": "686387"
  },
  {
    "name": "Mahendra C. Salekar",
    "phone": "",
    "email": "",
    "ownershipShare": "",
    "id": "706345"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "516877",
    "name": "Living Room",
    "length": "13.83",
    "length1": "13",
    "length2": "10",
    "width": "8.83",
    "width1": "8",
    "width2": "10",
    "totalArea": "122.19",
    "images": [],
    "extraAreas": [],
    "finalArea": "122.19"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  },
]
```

```
"id": "6",
"name": "Bedroom",
"length": "8.67",
"length1": "8",
"length2": "8",
"width": "9.75",
"width1": "9",
"width2": "9",
"totalArea": "84.50",
"images": [],
"finalArea": "93.24",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "5.83",
  "length1": "5",
  "length2": "10",
  "width": "7.67",
  "width1": "7",
  "width2": "8",
  "totalArea": "44.72",
  "images": [],
  "extraAreas": [],
  "finalArea": "44.72"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "4.83",
  "length1": "4",
  "length2": "10",
  "width": "2.83",
  "width1": "2",
  "width2": "10",
  "totalArea": "13.69",
  "images": [],
```

```
"extraAreas": [],
"finalArea": "13.69"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "3.67",
  "length1": "3",
  "length2": "8",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "11.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "11.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "5.75",
  "length1": "5",
  "length2": "9",
  "width": "3.83",
  "width1": "3",
  "width2": "10",
  "totalArea": "22.04",
  "images": [],
  "extraAreas": [],
  "finalArea": "22.04"
}
],
"otherComposition": [
  {
    "toBeAdded": {
      "label": "Carpet",
      "value": "Carpet"
    }
  },

```

```
"name": {
  "label": "Balcony Area",
  "value": "Balcony_Area"
},
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"length1": "8",
"length2": "10",
"length": "8.83",
"width1": "4",
"width2": "9",
"width": "4.75",
"totalArea": "41.96",
"percentageBeforeTotal": "41.96",
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "41.96"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "length1": "8",
  "length2": "2",
  "length": "8.17",
  "width1": "2",
  "width2": "0",
  "width": "2.00",
  "totalArea": "16.33",
  "percentageBeforeTotal": "16.33",
  "images": [],
  "extraAreas": [],
```

```
"percentage": "100",
"finalArea": "16.33"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "length1": "7",
  "length2": "8",
  "length": "7.67",
  "width1": "2",
  "width2": "8",
  "width": "2.67",
  "totalArea": "20.44",
  "percentageBeforeTotal": "20.44",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "20.44"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "501076",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "186",
    "squareMeterArea": "17.28",
```

```
"docFinalBuiltUp": "223.2",
"docFinalBuiltUpSquareMeter": "20.736",
"docBuiltupPercentage": "20",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [],
"externalImages": [
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654b0e1a637db60f88b5210b",
  "name": "externalImg_1699417626063_IMG_20231107_1187.jpg",
  "path": "cases/653a0c26164a9341fb026275/
externalImg_1699417626063_IMG_20231107_1187.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654b0e1a637db60f88b5210c",
  "name": "externalImg_1699417626066_IMG_20231107_1350.jpg",
  "path": "cases/653a0c26164a9341fb026275/
externalImg_1699417626066_IMG_20231107_1350.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654b0e1a637db60f88b5210d",
  "name": "externalImg_1699417626068_IMG_20231107_1434.jpg",
  "path": "cases/653a0c26164a9341fb026275/
externalImg_1699417626068_IMG_20231107_1434.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654b0e1a637db60f88b5210e",
  "name": "externalImg_1699417626071_IMG_20231107_5674.jpg",
  "path": "cases/653a0c26164a9341fb026275/
externalImg_1699417626071_IMG_20231107_5674.jpg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "654b0e1a637db60f88b5210f",
      "name": "externallmg_1699417626072_IMG_20231107_6186.jpg",
      "path": "cases/653a0c26164a9341fb026275/
externallmg_1699417626072_IMG_20231107_6186.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "654b0e1a637db60f88b52110",
      "name": "externallmg_1699417626076_IMG_20231107_7729.jpg",
      "path": "cases/653a0c26164a9341fb026275/
externallmg_1699417626076_IMG_20231107_7729.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "654b0e1a637db60f88b52111",
      "name": "externallmg_1699417626078_IMG_20231107_8336.jpg",
      "path": "cases/653a0c26164a9341fb026275/
externallmg_1699417626078_IMG_20231107_8336.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "654b0e1a637db60f88b52112",
      "name": "externallmg_1699417626080_IMG_20231107_8722.jpg",
      "path": "cases/653a0c26164a9341fb026275/
externallmg_1699417626080_IMG_20231107_8722.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "654b0e1a637db60f88b52113",
      "name": "externallmg_1699417626082_IMG_20231107_8991.jpg",
      "path": "cases/653a0c26164a9341fb026275/
externallmg_1699417626082_IMG_20231107_8991.jpg",
      "orientation": "portrait"
    },
  },
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654b0e1a637db60f88b52114",
  "name": "externallmg_1699417626084_IMG_20231107_9305.jpg",
  "path": "cases/653a0c26164a9341fb026275/
externallmg_1699417626084_IMG_20231107_9305.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654b0e29637db60f88b5217b",
  "name": "externallmg_1699417641354_IMG_20231107_9668.jpg",
  "path": "cases/653a0c26164a9341fb026275/
externallmg_1699417641354_IMG_20231107_9668.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654b0e29637db60f88b5217c",
  "name": "externallmg_1699417641357_IMG_20231107_10163.jpg",
  "path": "cases/653a0c26164a9341fb026275/
externallmg_1699417641357_IMG_20231107_10163.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654b0e29637db60f88b5217d",
  "name": "externallmg_1699417641359_IMG_20231107_10435.jpg",
  "path": "cases/653a0c26164a9341fb026275/
externallmg_1699417641359_IMG_20231107_10435.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654b0e29637db60f88b5217e",
  "name": "externallmg_1699417641362_IMG_20231107_10759.jpg",
  "path": "cases/653a0c26164a9341fb026275/
externallmg_1699417641362_IMG_20231107_10759.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654b0e29637db60f88b5217f",
    "name": "externallmg_1699417641363_IMG_20231107_11389.jpg",
    "path": "cases/653a0c26164a9341fb026275/
externallmg_1699417641363_IMG_20231107_11389.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654b0e29637db60f88b52180",
    "name": "externallmg_1699417641365_IMG_20231107_11626.jpg",
    "path": "cases/653a0c26164a9341fb026275/
externallmg_1699417641365_IMG_20231107_11626.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654b0e29637db60f88b52181",
    "name": "externallmg_1699417641366_IMG_20231107_12223.jpg",
    "path": "cases/653a0c26164a9341fb026275/
externallmg_1699417641366_IMG_20231107_12223.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654b0e29637db60f88b52182",
    "name": "externallmg_1699417641368_IMG_20231107_12488.jpg",
    "path": "cases/653a0c26164a9341fb026275/
externallmg_1699417641368_IMG_20231107_12488.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "654b0e29637db60f88b52183",
    "name": "externallmg_1699417641370_IMG_20231107_13717.jpg",
    "path": "cases/653a0c26164a9341fb026275/
externallmg_1699417641370_IMG_20231107_13717.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "654b0e29637db60f88b52184",
  "name": "externallmg_1699417641373_IMG_20231107_14376.jpg",
  "path": "cases/653a0c26164a9341fb026275/
externallmg_1699417641373_IMG_20231107_14376.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654b0e29637db60f88b52185",
  "name": "externallmg_1699417641468_Screenshot_2023110717272781_3d9111e2
d3171bf4882369f490c087b4.jpg",
  "path": "cases/653a0c26164a9341fb026275/externallmg_1699417641468_Screens
hot_2023110717272781_3d9111e2d3171bf4882369f490c087b4.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654b0e29637db60f88b52186",
  "name": "externallmg_1699417641494_IMG_20231107_839.jpg",
  "path": "cases/653a0c26164a9341fb026275/
externallmg_1699417641494_IMG_20231107_839.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654b0e29637db60f88b52187",
  "name": "externallmg_1699417641495_IMG_20231107_9898.jpg",
  "path": "cases/653a0c26164a9341fb026275/
externallmg_1699417641495_IMG_20231107_9898.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654b0e29637db60f88b52188",
  "name": "externallmg_1699417641496_IMG_20231107_11947.jpg",
  "path": "cases/653a0c26164a9341fb026275/
externallmg_1699417641496_IMG_20231107_11947.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "654b0e29637db60f88b52189",
  "name": "externallmg_1699417641497_IMG_20231107_12717.jpg",
  "path": "cases/653a0c26164a9341fb026275/
externallmg_1699417641497_IMG_20231107_12717.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654b0e29637db60f88b5218a",
  "name": "externallmg_1699417641497_IMG_20231107_13399.jpg",
  "path": "cases/653a0c26164a9341fb026275/
externallmg_1699417641497_IMG_20231107_13399.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654b0e29637db60f88b5218b",
  "name": "externallmg_r_1699417641449_IMG20231108003459.jpg",
  "path": "cases/653a0c26164a9341fb026275/
externallmg_r_1699417641449_IMG20231108003459.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654b0e29637db60f88b5218c",
  "name": "externallmg_r_1699417641375_IMG20231107171107.jpg",
  "path": "cases/653a0c26164a9341fb026275/
externallmg_r_1699417641375_IMG20231107171107.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "654b0e29637db60f88b5218d",
  "name": "externallmg_r_1699417641398_IMG20231107171111.jpg",
  "path": "cases/653a0c26164a9341fb026275/
externallmg_r_1699417641398_IMG20231107171111.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
  "_id": "654b0e29637db60f88b5218e",
  "name": "externalimg_r_1699417641423_IMG20231108003454.jpg",
  "path": "cases/653a0c26164a9341fb026275/
externalimg_r_1699417641423_IMG20231108003454.jpg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-10-26T06:50:14.442Z",
"updatedAt": "2023-11-08T07:15:44.665Z",
"__v": 0,
"invoiceId": "653a0c26164a9341fb0262aa",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 506, 5th Floor, Krishna , Sai Vrindavan Co-op. Hsg.
Soc. Ltd., Plot No. 164, Sector 4, Village - Karanjade, Navi Mumbai, Taluka - Panvel,
District - Raigad, PIN - 410 206, State - Maharashtra, India",
"updatedBy": "60f91b6f344e052188ffd1fc",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Nilima Mahendra Salekar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner",
"siteVisitContactNo": "9769025655",
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + Passage + 2 Toilet",
"carpetTotal": "306.88",
"finalMeasurementType": "Sq. Ft.",
"otherCarpetTotal": "78.73",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "79.96",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "464.21",
"finalCarpetArea": "386.84",
"finalSalableArea": "464.21",
"salablePercentage": "0",
"toBeAdded": "",
"extendOfSiteRemark": "",
```

"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 306.88\nBalcony Area in sq. Ft. = 79.86",
 "finalAreaType": "Carpet Area",
 "finalAsPerArea": "Agreement for sale",
 "finalBuiltUpPercentage": "20",
 "finalCarpetConvertToBuiltUpPer": "20",
 "finalSaleablePercentage": "0",
 "finalValuationAreaString": "Carpet Area in Sq. Ft. = 186.00"

}

Name	Length	Width	Total
Composition :			
Living Room	13'10"	8'10"	122.19
Bedroom	8'8"	9'9"	84.50
Kitchen	5'10"	7'8"	44.72
Passage	4'10"	2'10"	13.69
Toilet	3'8"	3'00"	11.00
Toilet	5'9"	3'10"	22.04
Other Composition :			
Balcony Area	8'10"	4'9"	41.96
Balcony Area	8'2"	2'0"	16.33
Balcony Area	7'8"	2'8"	20.44