

```
{
  "typeOfReport": {
    "label": "Structural Report",
    "value": "Structural_Report"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "label": "Education Loan",
    "value": "Education_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "652e3ee4316e1359cebed68e"
    },
    "type": "CREDITOFFICER",
    "_id": "652e3ee4316e1359cebed690",
    "firstName": "Siddharth",
    "lastName": "Jha",
    "mobileNo": "",
    "workMobileNo": "8657798653",
    "email": "brmgr1756@mahabank.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "9552760",
    "discussWithPerson": "Siddharth",
    "expectedFees": 4776.38,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180e",
  "type": "BANK",
  "name": "Bank Of Maharashtra",
  "displayName": "Bank Of Maharashtra",
  "initial": "BOM",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "652e3ee4316e1359cebed68e",
  "name": "Andheri East Seepz Branch",
  "branchCode": "1756",
  "mobileNo": "0000000000",
  "alternateMobileNo": "",
  "email": "brmgr1756@mahabank.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Shop No 4 & 5, Options PrimoBuilding , Plot no 21, MIDC Andheri East
Mumbai 400093"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "63abe77f4e30460e90087d32",
  "zoneName": "Mumbai City Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af6ae22ffdf65bcd65861d",
```

```
"role": "PICKUPPERSON",
"firstName": "Sunil",
"email": "misalsunil87@gmail.com",
"lastName": "Misal",
"mobileNo": "8422982721",
"shortName": "SM",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af6ae22ffdf65bcd65861d\
\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "648fcad91b499c2d52dc86f3",
"role": "SITEENGINEER",
"firstName": "Barkat",
"email": "barkathodekar68@gmail.com",
"lastName": "Hodekar",
"mobileNo": "8879011615",
"designation": "Site Engg",
"shortName": "Barkat",
"workWithDocumentMaker": "",
"profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shymam_Photo.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60eebe33f3dd69653a5837ae",
"role": "MAKER",
"firstName": "Shamal",
"email": "shamal@vastukala.org",
"lastName": "Bodke",
"mobileNo": "9821740317",
```

```
"designation": "",
"shortName": "SB",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eebe33f3dd69653a5837ae\
\profilePhoto_1626258995038_IMG-20210602-WA0046.jpg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shyma_Photo.jpg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "[N]C.C.I.T/I -14/52/2008-09",
"label": "Wealth Tax"
}
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
{
"title": {
"value": "Wealth_Tax",
"label": "Wealth Tax"
}
},
"_id": "6084131a13f01f158c6ea1f4",
"number": "[N]C.C.I.T/I -14/52/2008-09"
```

```
    }
  ],
  "shortName": "SBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.115061276033412",
  "longitude": "72.8732716850274"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.8732716850274,
    19.115061276033412
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-10-30T12:00:00.000Z",
      "remark": ""
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
```

```
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Kondivita",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
}
```

```
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Akshay Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Kondivita Road, J. B. Nagar",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
```

```
"value": "",
"label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Y. A. C. Nagar",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
```



```
"status": false,
"name": "CTS No.",
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "203",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
```

```
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Andheri (East)",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
```

```
"areaType": "Built Up",
"area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
```

```
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
```

```
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
```

```
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
finalValuationArea": "0",
empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
```



```
"paymentId": [],
"_id": "653f98b0d6fbd83553d6554f",
"ownerName": "Mr. Pravin Kanji Singhal",
"ownerPhoneNo": "8211965006",
"appAddress": "Flat no 203 Second Floor A-wing , Akshay Co-op HSG Soc Ltd Y.A.C
Nagar Kondivita Road J.B Nagar Andheri East 400059",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement (4 pages from the document)",
      "value": "60ae12aaaa6d152c1801b4b4"
    },
    "isHardCopy": false,
    "path": "cases/653f98b0d6fbd83553d6554f/document_1698666553080_Bom.pdf",
    "fileName": "document_1698666553080_Bom.pdf",
    "displayStatus": false,
    "id": "328032",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Mon Oct 30 2023 17:20:20 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "004766",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "212045",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Oct 30 2023 17:21:12 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Pravin Kanji Singhal",
    "phone": "8211965006",
    "ownershipShare": "",
    "email": "",
    "id": "266554"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
```

```
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f9e12eb542d69409891ae",
    "name": "externalImg_1698668050243_externalImg_1698493582001_1698493618822_image_0.jpeg",
    "path": "cases/653f98b0d6fbd83553d6554f/externalImg_1698668050243_externalImg_1698493582001_1698493618822_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f9e12eb542d69409891af",
    "name": "externalImg_1698668050265_externalImg_1698493586657_1698493618822_image_1.jpeg",
    "path": "cases/653f98b0d6fbd83553d6554f/externalImg_1698668050265_externalImg_1698493586657_1698493618822_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f9e12eb542d69409891b0",
    "name": "externalImg_1698668050290_externalImg_1698493611834_1698493648761_image_0.jpeg",
    "path": "cases/653f98b0d6fbd83553d6554f/externalImg_1698668050290_externalImg_1698493611834_1698493648761_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f9e12eb542d69409891b1",
    "name": "externalImg_1698668050330_externalImg_1698493618171_1698493648761_image_1.jpeg",
    "path": "cases/653f98b0d6fbd83553d6554f/externalImg_1698668050330_externalImg_1698493618171_1698493648761_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "653f9e12eb542d69409891b2",
    "name": "externallmg_1698668050353_externallmg_1698493621745_16984936487
61_image_2.jpeg",
    "path": "cases/653f98b0d6fbd83553d6554f/externallmg_1698668050353_externall
mg_1698493621745_1698493648761_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f9e12eb542d69409891b3",
    "name": "externallmg_1698668050372_externallmg_1698493624131_16984936487
61_image_3.jpeg",
    "path": "cases/653f98b0d6fbd83553d6554f/externallmg_1698668050372_externall
mg_1698493624131_1698493648761_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f9e12eb542d69409891b4",
    "name": "externallmg_1698668050401_externallmg_1698493626719_16984936487
61_image_4.jpeg",
    "path": "cases/653f98b0d6fbd83553d6554f/externallmg_1698668050401_externall
mg_1698493626719_1698493648761_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f9e12eb542d69409891b5",
    "name": "externallmg_1698668050424_externallmg_1698493628981_16984936487
61_image_5.jpeg",
    "path": "cases/653f98b0d6fbd83553d6554f/externallmg_1698668050424_externall
mg_1698493628981_1698493648761_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f9e12eb542d69409891b6",
    "name": "externallmg_1698668050450_externallmg_1698493663110_16984937008
76_image_0.jpeg",
    "path": "cases/653f98b0d6fbd83553d6554f/externallmg_1698668050450_externall
mg_1698493663110_1698493700876_image_0.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653f9e12eb542d69409891b7",
  "name": "externallmg_1698668050484_externallmg_1698493668155_1698493700876_image_1.jpeg",
  "path": "cases/653f98b0d6fbd83553d6554f/externallmg_1698668050484_externallmg_1698493668155_1698493700876_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653f9e12eb542d69409891b8",
  "name": "externallmg_1698668050518_externallmg_1698493670778_1698493700876_image_2.jpeg",
  "path": "cases/653f98b0d6fbd83553d6554f/externallmg_1698668050518_externallmg_1698493670778_1698493700876_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653f9e12eb542d69409891b9",
  "name": "externallmg_1698668050544_externallmg_1698493672655_1698493700876_image_3.jpeg",
  "path": "cases/653f98b0d6fbd83553d6554f/externallmg_1698668050544_externallmg_1698493672655_1698493700876_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653f9e12eb542d69409891ba",
  "name": "externallmg_1698668050561_externallmg_1698493673738_1698493700876_image_4.jpeg",
  "path": "cases/653f98b0d6fbd83553d6554f/externallmg_1698668050561_externallmg_1698493673738_1698493700876_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653f9e12eb542d69409891bb",
```

```
    "name": "externalimg_1698668050583_externalimg_1698493675149_1698493700876_image_5.jpeg",
    "path": "cases/653f98b0d6fbd83553d6554f/externalimg_1698668050583_externalimg_1698493675149_1698493700876_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f9e12eb542d69409891bc",
    "name": "externalimg_1698668050605_externalimg_1698493709761_1698493746162_image_0.jpeg",
    "path": "cases/653f98b0d6fbd83553d6554f/externalimg_1698668050605_externalimg_1698493709761_1698493746162_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f9e12eb542d69409891bd",
    "name": "externalimg_1698668050638_externalimg_1698493739797_1698493746162_image_1.jpeg",
    "path": "cases/653f98b0d6fbd83553d6554f/externalimg_1698668050638_externalimg_1698493739797_1698493746162_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f9e12eb542d69409891be",
    "name": "externalimg_1698668050674_externalimg_1698493746243_1698493746162_image_2.jpeg",
    "path": "cases/653f98b0d6fbd83553d6554f/externalimg_1698668050674_externalimg_1698493746243_1698493746162_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "653f9e12eb542d69409891bf",
    "name": "externalimg_1698668050695_externalimg_1698493749528_1698493746162_image_3.jpeg",
    "path": "cases/653f98b0d6fbd83553d6554f/externalimg_1698668050695_externalimg_1698493749528_1698493746162_image_3.jpeg",
    "orientation": "landscape"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653f9e12eb542d69409891c0",
  "name": "externalimg_1698668050723_externalimg_1698493757154_1698493746162_image_4.jpeg",
  "path": "cases/653f98b0d6fbd83553d6554f/externalimg_1698668050723_externalimg_1698493757154_1698493746162_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "653f9e12eb542d69409891c1",
  "name": "externalimg_1698668050768_externalimg_1698493769474_1698493746162_image_5.jpeg",
  "path": "cases/653f98b0d6fbd83553d6554f/externalimg_1698668050768_externalimg_1698493769474_1698493746162_image_5.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [
  {
    "originalname": "Pravin Kanji Singhal.docx",
    "filename": "1698668019611_Pravin_Kanji_Singhal.docx",
    "path": "cases/653f98b0d6fbd83553d6554f/externalDocuments/1698668019611_Pravin_Kanji_Singhal.docx",
    "size": "1064244",
    "documentType": {
      "value": "649998c6cab24d3d1a2cc577",
      "label": "Draft Word Report"
    },
    "createdAt": "Mon Oct 30 2023 17:43:39 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eebe33f3dd69653a5837ae"
  }
],
"processingDocuments": [
  {
    "originalname": "1698648919511_Valuation_Report_Pravin_Kanji_Singhal.pdf",
    "filename": "1698668033888_1698648919511_Valuation_Report_Pravin_Kanji_Singhal.pdf",
    "path": "cases/653f98b0d6fbd83553d6554f/processingDocuments/1698668033888_1698648919511_Valuation_Report_Pravin_Kanji_Singhal.pdf",
    "size": "1072668",
    "createdAt": "Mon Oct 30 2023 17:43:53 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eebe33f3dd69653a5837ae"
  }
]
```

```

    }
  ],
  "remarks": [],
  "createdAt": "2023-10-30T11:51:12.316Z",
  "updatedAt": "2023-10-30T12:14:10.970Z",
  "__v": 0,
  "invoiceId": "653f98b5d6fbd83553d65616",
  "updatedBy": "60eebe33f3dd69653a5837ae",
  "assignmentType": {
    "value": "Retail",
    "label": "Retail"
  },
  "fullAddress": " Structural Report No. 203, 2nd Floor, Wing - A, Akshay Co-op. Hsg. Soc. Ltd., Y. A. C. Nagar, Kondivita Road, J. B. Nagar, Village - Kondivita, Andheri (East)",
  "addressForMap": "",
  "caseReferredBy": "60af6ae22ffdf65bcd65861d",
  "contactPersonName": "Mr. Pravin Kanji Singhal",
  "email": "",
  "isExternal": "false",
  "isUrgent": "false",
  "ownershipShare": "",
  "purchaseValueAsPerDocument": "",
  "relationWithOwner": "self",
  "siteVisitContactNo": "8211965006"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			