

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9ff"
    },
    "type": "CREDITOFFICER",
    "_id": "652695d5703d7c40db9b3b77",
    "firstName": "Vishant ",
    "lastName": "Verma",
    "mobileNo": "",
    "workMobileNo": "9507000088",
    "email": "1cord.21117@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "7769000",
    "discussWithPerson": "Vishant ",
    "expectedFees": 3884.5,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9ff",
  "branchCode": "000220",
  "type": "BRANCH",
  "name": "RASMECCC Panvel",
  "email": "cord.21117@sbi.co.in",
  "mobileNo": "02227572748",
  "alternateMobileNo": "",
  "address": "Shop No 5,Ground Floor,Sharda Terrace, Plot No 65,Sector-11,CBD
Belapur, Navi Mumbai, Taluka & District - Thane, State - Maharashtra, Country - India",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
    "_id": "60b7189d2ffdf65bcd65882b",
    "role": "PICKUPPERSON",
    "firstName": "Ravindra",
    "email": "ravindrakasare186@gmail.com",
    "lastName": "Kasare",
    "mobileNo": "9167204055",
    "shortName": "RBK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60b7189d2ffdf65bcd65882b\\
\\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "627362b3afd7d55eddee1ee7",
    "role": "SITEENGINEER",
    "firstName": "Vicky ",
    "email": "vicky@vastukala.org",
    "lastName": "Bhor",
    "mobileNo": "9004386288",
    "designation": "",
    "shortName": "VB",
    "workWithDocumentMaker": ""
  },
  "rateVerifier": "",
  "maker": "",
  "checker": "",
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ]
    },
    {
      "type": "EMPLOYEE",
      "_id": "5ffe92d27737ca4d986b6453",
      "role": "VALUER",
      "firstName": "Manoj",
      "email": "manoj@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9819597579",
      "designation": "Registered Valuer",
      "registrationNo": [
        {
          "title": {
            "label": "IBBI"
          }
        }
      ]
    }
  ]
}
```

```
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "18.973673389984434",
  "longitude": "73.07798349665052"
},
```

```
"geo": {
  "type": "Point",
  "coordinates": [
    73.07798349665052,
    18.973673389984434
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-11-10T12:00:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Dapoli",
    "label": true
  }
}
```

```
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
```

```
"key": "plotNo",
"value": "20",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Bhagwati Elsiya 2",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "4",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
}
```

```
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
```



```
"value": "102",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
```

```
"status": false,
"name": "Postal Code",
"key": "postalCode",
"value": "",
"label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "areaType": "Built Up",
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
```

```
"rccFootingFoundation": {
  "label": "RCC Footing/Foundation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
```

```
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
"carpetRateRange": {
"min": "0.00",
"max": "0.00"
}
},
```

```
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
```

```
    "isEditable": false
  }
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentId": [],
"_id": "654de56a637db60f88b96bc7",
"ownerName": "Mukul Rawat",
"ownerPhoneNo": "9779586748",
"appAddress": "flat no. 102 1st floor B wing Bldg Bhagwati Eiysial 11 plot no 20
sector no. 4 . pushpak Dapoli pa'vel ",
"remark": "Bankar. vishant sir",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "path": "cases/654de56a637db60f88b96bc7/
document_1699603773121_Mukul_Rawat_SBI_RASMECC_PANVEL_.pdf",
    "fileName":
"document_1699603773121_Mukul_Rawat_SBI_RASMECC_PANVEL_.pdf",
```



```
"displayStatus": false,
"id": "609262",
"uploadedBy": "60b7189d2ffdf65bcd65882b",
"createdAt": "Fri Nov 10 2023 13:40:18 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "005004",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
{
"id": "853640",
"title": "Create Lead",
"description": "Create Lead",
"datetime": "Fri Nov 10 2023 13:40:18 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
"name": "Mukul Rawat",
"phone": "9779586748",
"ownershipShare": "",
"email": "",
"id": "870056"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "65558a6a637db60f88b99d0d",
"name": "externalImg_1700104810156_IMG_20231115_5194.jpg",
"path": "cases/654de56a637db60f88b96bc7/
externalImg_1700104810156_IMG_20231115_5194.jpg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
```

```
    "_id": "65558a6a637db60f88b99d0e",
    "name": "externallmg_1700104810161_IMG_20231115_5272.jpg",
    "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104810161_IMG_20231115_5272.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65558a6a637db60f88b99d0f",
    "name": "externallmg_1700104810165_IMG_20231115_5652.jpg",
    "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104810165_IMG_20231115_5652.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65558a6a637db60f88b99d10",
    "name": "externallmg_1700104810169_IMG_20231115_150447.jpg",
    "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104810169_IMG_20231115_150447.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65558a6a637db60f88b99d11",
    "name": "externallmg_1700104810206_IMG20231115WA0003.jpg",
    "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104810206_IMG20231115WA0003.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65558a6a637db60f88b99d12",
    "name": "externallmg_1700104810245_Screenshot_2023111515083361_3d9111e2
d3171bf4882369f490c087b4.jpg",
    "path": "cases/654de56a637db60f88b96bc7/externallmg_1700104810245_Screens
hot_2023111515083361_3d9111e2d3171bf4882369f490c087b4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "65558a6a637db60f88b99d13",
    "name": "externallmg_1700104810264_IMG_20231115_049.jpg",
    "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104810264_IMG_20231115_049.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65558a6a637db60f88b99d14",
    "name": "externallmg_1700104810267_IMG_20231115_410.jpg",
    "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104810267_IMG_20231115_410.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65558a6a637db60f88b99d15",
    "name": "externallmg_1700104810269_IMG_20231115_0607.jpg",
    "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104810269_IMG_20231115_0607.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65558a6a637db60f88b99d16",
    "name": "externallmg_1700104810271_IMG_20231115_0938.jpg",
    "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104810271_IMG_20231115_0938.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65558a6a637db60f88b99d17",
    "name": "externallmg_1700104810273_IMG_20231115_1402.jpg",
    "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104810273_IMG_20231115_1402.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65558a6a637db60f88b99d18",
```

```
    "name": "externallmg_1700104810275_IMG_20231115_1746.jpg",
    "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104810275_IMG_20231115_1746.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65558a6a637db60f88b99d19",
    "name": "externallmg_1700104810276_IMG_20231115_2160.jpg",
    "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104810276_IMG_20231115_2160.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65558a6a637db60f88b99d1a",
    "name": "externallmg_1700104810278_IMG_20231115_2579.jpg",
    "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104810278_IMG_20231115_2579.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65558a6a637db60f88b99d1b",
    "name": "externallmg_1700104810280_IMG_20231115_2907.jpg",
    "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104810280_IMG_20231115_2907.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65558a6a637db60f88b99d1c",
    "name": "externallmg_1700104810282_IMG_20231115_3226.jpg",
    "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104810282_IMG_20231115_3226.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65558a6a637db60f88b99d1d",
    "name": "externallmg_1700104810283_IMG_20231115_3552.jpg",
```

```
    "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104810283_IMG_20231115_3552.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65558a6a637db60f88b99d1e",
    "name": "externallmg_1700104810284_IMG_20231115_4442.jpg",
    "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104810284_IMG_20231115_4442.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65558a6a637db60f88b99d1f",
    "name": "externallmg_1700104810287_IMG_20231115_4767.jpg",
    "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104810287_IMG_20231115_4767.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65558a6a637db60f88b99d20",
    "name": "externallmg_r_1700104810211_IMG20231115153301.jpg",
    "path": "cases/654de56a637db60f88b96bc7/
externallmg_r_1700104810211_IMG20231115153301.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65558a7c637db60f88b99d64",
    "name": "externallmg_1700104828275_IMG_20231115_4767.jpg",
    "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104828275_IMG_20231115_4767.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65558a7c637db60f88b99d65",
    "name": "externallmg_1700104828276_IMG_20231115_5493.jpg",
    "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104828276_IMG_20231115_5493.jpg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65558a7c637db60f88b99d66",
  "name": "externallmg_1700104828280_IMG_20231115_5746.jpg",
  "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104828280_IMG_20231115_5746.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65558a7c637db60f88b99d67",
  "name": "externallmg_1700104828283_IMG_20231115_5868.jpg",
  "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104828283_IMG_20231115_5868.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65558a7c637db60f88b99d68",
  "name": "externallmg_1700104828286_IMG_20231115_52525.jpg",
  "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104828286_IMG_20231115_52525.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65558a7c637db60f88b99d69",
  "name": "externallmg_1700104828290_IMG_20231115_54476.jpg",
  "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104828290_IMG_20231115_54476.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65558a7c637db60f88b99d6a",
  "name": "externallmg_1700104828293_IMG_20231115_54871.jpg",
  "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104828293_IMG_20231115_54871.jpg",
  "orientation": "portrait"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65558a7c637db60f88b99d6b",
    "name": "externallmg_1700104828295_IMG_20231115_55244.jpg",
    "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104828295_IMG_20231115_55244.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65558a7c637db60f88b99d6c",
    "name": "externallmg_1700104828300_IMG_20231115_55634.jpg",
    "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104828300_IMG_20231115_55634.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65558a7c637db60f88b99d6d",
    "name": "externallmg_1700104828303_IMG_20231115_56570.jpg",
    "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104828303_IMG_20231115_56570.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65558a7c637db60f88b99d6e",
    "name": "externallmg_1700104828305_IMG_20231115_57395.jpg",
    "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104828305_IMG_20231115_57395.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65558a7c637db60f88b99d6f",
    "name": "externallmg_1700104828306_IMG_20231115_57713.jpg",
    "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104828306_IMG_20231115_57713.jpg",
    "orientation": "landscape"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65558a7c637db60f88b99d70",
  "name": "externallmg_1700104828308_IMG_20231115_58515.jpg",
  "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104828308_IMG_20231115_58515.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65558a7c637db60f88b99d71",
  "name": "externallmg_1700104828311_IMG_20231115_58938.jpg",
  "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104828311_IMG_20231115_58938.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65558a7c637db60f88b99d72",
  "name": "externallmg_1700104828312_IMG_20231115_59339.jpg",
  "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104828312_IMG_20231115_59339.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65558a7c637db60f88b99d73",
  "name": "externallmg_1700104828314_IMG_20231115_59698.jpg",
  "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104828314_IMG_20231115_59698.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65558a7c637db60f88b99d74",
  "name": "externallmg_1700104828316_IMG20231115WA0005.jpg",
  "path": "cases/654de56a637db60f88b96bc7/
externallmg_1700104828316_IMG20231115WA0005.jpg",
  "orientation": "landscape"
},
{
```



```

    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65558a7c637db60f88b99d75",
    "name": "externalImg_1700104828317_IMG20231115WA0006.jpg",
    "path": "cases/654de56a637db60f88b96bc7/
externalImg_1700104828317_IMG20231115WA0006.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-11-10T08:10:18.738Z",
"updatedAt": "2023-11-16T03:20:28.413Z",
"__v": 0,
"invoiceId": "654de56a637db60f88b96bd0",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": " Flat No. 102, 1st Floor, Wing - B, Bhagwati Elsiya 2, Plot No. 20,
Sector 4, Village - Dapoli",
"updatedBy": "6006d4ce5080a310ac1fdfc2",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Mukul Rawat",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9779586748"
}

```

| Name                   | Length | Width | Total |
|------------------------|--------|-------|-------|
| Composition :          |        |       |       |
| Other<br>Composition : |        |       |       |