

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6401aa2a0e28255fb44e5222"
    },
    "type": "CREDITOFFICER",
    "_id": "6524deba703d7c40db979df7",
    "firstName": "Minakshi",
    "lastName": "Ajila",
    "mobileNo": "",
    "workMobileNo": "9930375648",
    "email": "1bmmsro0630@centrabank.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "9500000",
    "discussWithPerson": "Minakshi",
    "expectedFees": 4750,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17fa",
  "type": "BANK",
  "name": "Central Bank of India",
  "displayName": "Central Bank of India",
  "initial": "CBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6401aa2a0e28255fb44e5222",
  "name": "Kandivali East Branch",
  "branchCode": "",
  "mobileNo": "02228546591",
  "alternateMobileNo": "",
  "email": "bmmsro0630@centralbank.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Ground Floor, G-Bungalow, Crystal Lane, Thakur Complex, Kandivali
east, Mumbai - 400 101 "
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60f917e0f3dd69653a592221",
  "zoneName": "South Mumbai Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af6ae22ffdf65bcd65861d",
```

```
"role": "PICKUPPERSON",
"firstName": "Sunil",
"email": "misalsunil87@gmail.com",
"lastName": "Misal",
"mobileNo": "8422982721",
"shortName": "SM",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af6ae22ffdf65bcd65861d\
\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63fc575ece84bf289ba9e82d",
"role": "SITEENGINEER",
"firstName": "Deepak ",
"email": "daksh7831@gmail.com",
"lastName": "Jain ",
"mobileNo": "9022815908",
"designation": "",
"shortName": "DJ",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"maker": "",
"checker": "",
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
}
],
```

```
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
```

```
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.21351725612353",
  "longitude": "72.8804772879628"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.8804772879628,
    19.21351725612353
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-11-16T03:30:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
```

```
"status": true,
"name": "Country",
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Poisar",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahsilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahsilNo",
  "value": "",
```

```
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Aangan",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Thakut Village",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
```

```
"name": "Landmark",
"key": "landmark",
"value": "",
"label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
}
```



```
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "103",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
```

```
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Kandivali East",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00",
  "areaType": "Built Up"
},
"routeMap": {
  "finalLatLng": {
```

```
"coordinates": []
},
"locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
```

```
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentId": [],
"audioRemarks": [],
"_id": "6554c175637db60f88b999e5",
"ownerName": "Jigeesha Arun Desai ",
"ownerPhoneNo": "9821430458",
```



```
"appAddress": "Flat E/103, 1st floor Bldg Angan Shri Ganesh Angane HSC Ltd Thakur
Village Kandivali East ",
"remark": "Tommoro visit ",
"documents": [
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    },
    "isHardCopy": false,
    "path": "cases/6554c175637db60f88b999e5/
document_1700053353906_1700053410630_20231115_1832.pdf",
    "fileName": "document_1700053353906_1700053410630_20231115_1832.pdf",
    "displayStatus": false,
    "id": "647506",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Wed Nov 15 2023 18:32:45 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae12a0aa6d152c1801b483",
      "label": "site Details"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1700195601692_Arun_desai.pdf",
    "path": "cases/6554c175637db60f88b999e5/
document_1700195601692_Arun_desai.pdf",
    "id": "113733",
    "uploadedBy": "6006d4ce5080a310ac1fdcf2",
    "createdAt": "Fri Nov 17 2023 10:03:21 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "005011",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "238610",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Nov 15 2023 18:32:45 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Jigeesha Arun Desai ",
```

```
    "phone": "9821430458",
    "ownershipShare": "",
    "email": "",
    "id": "587685"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6556ece95586e0081588bd3f",
    "name": "externalImg_1700195561017_IMG_20231116_172924.jpg",
    "path": "cases/6554c175637db60f88b999e5/
externalImg_1700195561017_IMG_20231116_172924.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6556ece95586e0081588bd40",
    "name": "externalImg_1700195561025_IMG_20231116_172931.jpg",
    "path": "cases/6554c175637db60f88b999e5/
externalImg_1700195561025_IMG_20231116_172931.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6556ece95586e0081588bd41",
    "name": "externalImg_1700195561035_IMG_20231116_172937.jpg",
    "path": "cases/6554c175637db60f88b999e5/
externalImg_1700195561035_IMG_20231116_172937.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6556ece95586e0081588bd42",
```

```
    "name": "externallmg_1700195561044_IMG_20231116_172944.jpg",
    "path": "cases/6554c175637db60f88b999e5/
externallmg_1700195561044_IMG_20231116_172944.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6556ece95586e0081588bd43",
    "name": "externallmg_1700195561049_IMG_20231116_172950.jpg",
    "path": "cases/6554c175637db60f88b999e5/
externallmg_1700195561049_IMG_20231116_172950.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6556ece95586e0081588bd44",
    "name": "externallmg_1700195561054_IMG_20231116_172954.jpg",
    "path": "cases/6554c175637db60f88b999e5/
externallmg_1700195561054_IMG_20231116_172954.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6556ece95586e0081588bd45",
    "name": "externallmg_1700195561060_IMG_20231116_172958.jpg",
    "path": "cases/6554c175637db60f88b999e5/
externallmg_1700195561060_IMG_20231116_172958.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6556ece95586e0081588bd46",
    "name": "externallmg_1700195561065_IMG_20231116_174318.jpg",
    "path": "cases/6554c175637db60f88b999e5/
externallmg_1700195561065_IMG_20231116_174318.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6556ece95586e0081588bd47",
    "name": "externallmg_1700195561068_IMG_20231116_174324.jpg",
```

```
    "path": "cases/6554c175637db60f88b999e5/
externallmg_1700195561068_IMG_20231116_174324.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6556ecfb5586e0081588bd9d",
    "name": "externallmg_1700195579338_IMG_20231116_174351.jpg",
    "path": "cases/6554c175637db60f88b999e5/
externallmg_1700195579338_IMG_20231116_174351.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6556ecfb5586e0081588bd9e",
    "name": "externallmg_1700195579346_IMG_20231116_174356.jpg",
    "path": "cases/6554c175637db60f88b999e5/
externallmg_1700195579346_IMG_20231116_174356.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6556ecfb5586e0081588bd9f",
    "name": "externallmg_1700195579351_IMG_20231116_174403.jpg",
    "path": "cases/6554c175637db60f88b999e5/
externallmg_1700195579351_IMG_20231116_174403.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6556ecfb5586e0081588bda0",
    "name": "externallmg_1700195579356_IMG_20231116_174407.jpg",
    "path": "cases/6554c175637db60f88b999e5/
externallmg_1700195579356_IMG_20231116_174407.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6556ecfb5586e0081588bda1",
    "name": "externallmg_1700195579359_IMG_20231116_174435.jpg",
    "path": "cases/6554c175637db60f88b999e5/
externallmg_1700195579359_IMG_20231116_174435.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6556ecfb5586e0081588bda2",
  "name": "externallmg_1700195579371_IMG_20231116_174518.jpg",
  "path": "cases/6554c175637db60f88b999e5/
externallmg_1700195579371_IMG_20231116_174518.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6556ecfb5586e0081588bda3",
  "name": "externallmg_1700195579376_IMG_20231116_174520.jpg",
  "path": "cases/6554c175637db60f88b999e5/
externallmg_1700195579376_IMG_20231116_174520.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6556ecfb5586e0081588bda4",
  "name": "externallmg_1700195579381_IMG_20231116_174544.jpg",
  "path": "cases/6554c175637db60f88b999e5/
externallmg_1700195579381_IMG_20231116_174544.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6556ecfb5586e0081588bda5",
  "name": "externallmg_1700195579386_IMG_20231116_174546.jpg",
  "path": "cases/6554c175637db60f88b999e5/
externallmg_1700195579386_IMG_20231116_174546.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6556ecfb5586e0081588bda6",
  "name": "externallmg_1700195579391_IMG_20231116_174614.jpg",
  "path": "cases/6554c175637db60f88b999e5/
externallmg_1700195579391_IMG_20231116_174614.jpg",
  "orientation": "portrait"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6556ecfb5586e0081588bda7",
    "name": "externallmg_1700195579449_IMG_20231116_172832.jpg",
    "path": "cases/6554c175637db60f88b999e5/
externallmg_1700195579449_IMG_20231116_172832.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6556ecfb5586e0081588bda8",
    "name": "externallmg_1700195579452_IMG_20231116_172836.jpg",
    "path": "cases/6554c175637db60f88b999e5/
externallmg_1700195579452_IMG_20231116_172836.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6556ecfb5586e0081588bda9",
    "name": "externallmg_1700195579455_IMG_20231116_172840.jpg",
    "path": "cases/6554c175637db60f88b999e5/
externallmg_1700195579455_IMG_20231116_172840.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6556ecfb5586e0081588bdaa",
    "name": "externallmg_1700195579459_IMG_20231116_172857.jpg",
    "path": "cases/6554c175637db60f88b999e5/
externallmg_1700195579459_IMG_20231116_172857.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6556ecfb5586e0081588bdab",
    "name": "externallmg_1700195579470_IMG_20231116_172902.jpg",
    "path": "cases/6554c175637db60f88b999e5/
externallmg_1700195579470_IMG_20231116_172902.jpg",
    "orientation": "portrait"
  },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6556ecfb5586e0081588bdac",
  "name": "externallmg_1700195579482_IMG_20231116_172903.jpg",
  "path": "cases/6554c175637db60f88b999e5/
externallmg_1700195579482_IMG_20231116_172903.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6556ecfb5586e0081588bdad",
  "name": "externallmg_r_1700195579368_IMG_20231116_174459.jpg",
  "path": "cases/6554c175637db60f88b999e5/
externallmg_r_1700195579368_IMG_20231116_174459.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6556ecfb5586e0081588bdae",
  "name": "externallmg_r_1700195579363_IMG_20231116_174452.jpg",
  "path": "cases/6554c175637db60f88b999e5/
externallmg_r_1700195579363_IMG_20231116_174452.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6556ecfb5586e0081588bdaf",
  "name": "externallmg_r_1700195579396_20231117_094415.jpg",
  "path": "cases/6554c175637db60f88b999e5/
externallmg_r_1700195579396_20231117_094415.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6556ecfb5586e0081588bdb0",
  "name": "externallmg_r_1700195579414_20231117_094430.jpg",
  "path": "cases/6554c175637db60f88b999e5/
externallmg_r_1700195579414_20231117_094430.jpg",
  "orientation": "portrait"
},
{
```

```

    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6556ed045586e0081588bddb",
    "name": "externalImg_1700195588514_IMG_20231116_172913.jpg",
    "path": "cases/6554c175637db60f88b999e5/
externalImg_1700195588514_IMG_20231116_172913.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"remarks": [],
"createdAt": "2023-11-15T13:02:45.965Z",
"updatedAt": "2023-11-17T04:33:21.791Z",
"__v": 0,
"invoiceId": "6554c176637db60f88b999ee",
"updatedBy": "6006d4ce5080a310ac1fd2",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": " Flat No. 103, 1st Floor, Wing - A, Aangan, Thakut Village, Village -
Poisar, Kandivali East, Mumbai",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Jigeesha Arun Desai ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9821430458",
"leadRemarks": []
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			