

```
{
  "typeOfReport": {
    "value": "Amalgamated_Flats",
    "label": "Amalgamated Flats"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Education Loan",
    "value": "Education_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6273b00bafd7d55eddee5f69"
    },
    "type": "CREDITOFFICER",
    "_id": "6555ca2e5586e00815878c20",
    "firstName": "Shankar",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "7709890573",
    "email": "1sbi.04205@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "00",
    "discussWithPerson": "Shankar",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6273b00bafd7d55eddee5f69",
  "name": "SPL PBB Fort",
  "branchCode": "4205 ",
  "mobileNo": "02223662641",
  "alternateMobileNo": "",
  "email": "sbi.04205@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Mumbai Main Branch Building, Gate no 1 Horniman Circle Mumbai
samachar marg Fort."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af3d172ffdf65bcd6585cd",
```

```
"role": "PICKUPPERSON",
"firstName": "Sachin",
"email": "sachin.joshi@vastukala.org",
"lastName": "Joshi",
"mobileNo": "9167204063",
"shortName": "SJ",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af3d172ffdf65bcd6585cd\
\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63fc4680ce84bf289ba9c7fc",
"role": "SITEENGINEER",
"firstName": "Nikhil ",
"email": "valtechnical2022@gmail.com",
"lastName": "Sonawane",
"mobileNo": "9819470709",
"designation": "",
"shortName": "NS",
"workWithDocumentMaker": "6006d4ce5080a310ac1fdfc2",
"profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1681380664371_WhatsApp_Image_20230413_at_33801_PM.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60f915d3f3dd69653a592199",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "62fe044a48a26047e6552796",
"role": "MAKER",
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
```

```
    "designation": "",
    "shortName": "PR",
    "workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
    "profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
  },
  "checker": "",
  "valuers": []
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.25777108110683",
  "longitude": "73.13441244983608"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.13441244983608,
    19.25777108110683
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "2023-11-16T08:00:00.000Z",
      "remark": ""
    },
    {
      "dateTime": "2023-11-16T08:00:00.000Z",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
```

```
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Gandhare ",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "5",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Thane",
    "label": true
  },
  "city": {
    "status": true,
    "name": "City",
```

```
"key": "city",
"value": "Kalyan (West)",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Mrug "D" Wing Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Wayale Nagar ",
  "label": false
},
}
```

```
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "D",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Tarangan ",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "5, Hissa No. 1",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
```

```
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "503",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
```



```
"status": false,
"name": "SRO",
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 421 301",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
}
```

```
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Stilt Car Parking Space",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2011",
    "fullDate": "1/1/2011"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "R.C.C._Framed_Structure",
    "label": "R.C.C. Framed Structure"
  },
  "typeOfFoundation": {
    "value": "rcc",
    "label": "R.C.C. Foundation"
  },
  "qualityOfConstruction": {
    "value": "Good",
```

```
"label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
}
```

```
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "48",
"ageOfBuilding": "12",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "5",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "3"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,

```

```
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
```

```
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
```

```
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentId": [],
"audioRemarks": [],
"_id": "6555c9af5586e00815878b21",
"ownerName": "Ravindra Bhaurao Walhe",
"ownerPhoneNo": "8452014797",
"appAddress": "Flat no 503.5floor,D-Wing,Mrug CHS,Tarangan, wayale Nagar,Kalyan
West",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement",
      "value": "60ae126eaa6d152c1801b39f"
    }
  },
  "isHardCopy": false,
  "path": "cases/6555c9af5586e00815878b21/document_1700120996232_17001210
53917_Ravindra_Bhaurao_Walhe_SBI_PBB_Fort.pdf",
  "fileName": "document_1700120996232_1700121053917_Ravindra_Bhaurao_Walh
e_SBI_PBB_Fort.pdf",
  "displayStatus": false,
  "id": "889708",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
```

```
    "createdAt": "Thu Nov 16 2023 13:20:07 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "005032",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "305356",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Nov 16 2023 13:20:07 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Ravindra Bhaurao Walhe",
    "phone": "8452014797",
    "ownershipShare": "",
    "email": "",
    "id": "627091"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "994656",
    "name": "Living Room",
    "length": "23.00",
    "length1": "23",
    "length2": "00",
    "width": "12.42",
    "width1": "12",
    "width2": "5",
    "totalArea": "285.58",
    "images": [],
    "extraAreas": [],
    "finalArea": "285.58"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "8.00",
  "length1": "8",
  "length2": "00",
  "width": "9.17",
  "width1": "9",
  "width2": "2",
  "totalArea": "73.33",
  "images": [],
  "extraAreas": [],
  "finalArea": "73.33"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "12.00",
  "length1": "12",
  "length2": "00",
  "width": "8.00",
  "width1": "8",
  "width2": "00",
  "totalArea": "96.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "96.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "13.00",
  "length1": "13",
  "length2": "00",
  "width": "12.00",
  "width1": "12",
  "width2": "00",
```



```
"id": "6",
"name": "Passage",
"length": "8.42",
"length1": "8",
"length2": "5",
"width": "3.25",
"width1": "3",
"width2": "3",
"totalArea": "27.35",
"images": [],
"extraAreas": [],
"finalArea": "27.35"
}
],
"otherComposition": [
{
  "name": {
    "label": "Cupboard",
    "value": "Cupboard"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length1": "6",
  "length2": "7",
  "length": "6.58",
  "width1": "2",
  "width2": "00",
  "width": "2.00",
  "totalArea": "13.17",
  "percentageBeforeTotal": "13.17",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "13.17"
},
{
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  }
}
```

```
    },
    "id": "1",
    "length1": "3",
    "length2": "00",
    "length": "3.00",
    "width1": "13",
    "width2": "00",
    "width": "13.00",
    "totalArea": "39.00",
    "percentageBeforeTotal": "39.00",
    "images": [],
    "extraAreas": [],
    "percentage": "100",
    "finalArea": "39"
  }
],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655747975586e0081589f937",
    "name":
"externallmg_1700218775912_WhatsApp_Image_20231117_at_42304_PM_1.jpeg",
    "path": "cases/6555c9af5586e00815878b21/
externallmg_1700218775912_WhatsApp_Image_20231117_at_42304_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655747975586e0081589f938",
    "name":
"externallmg_1700218775916_WhatsApp_Image_20231117_at_42304_PM_2.jpeg",
    "path": "cases/6555c9af5586e00815878b21/
externallmg_1700218775916_WhatsApp_Image_20231117_at_42304_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655747975586e0081589f939",
    "name":
"externallmg_1700218775920_WhatsApp_Image_20231117_at_42304_PM_3.jpeg",
```

```
    "path": "cases/6555c9af5586e00815878b21/
externallmg_1700218775920_WhatsApp_Image_20231117_at_42304_PM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655747975586e0081589f93a",
    "name":
"externallmg_1700218775923_WhatsApp_Image_20231117_at_42304_PM_4.jpeg",
    "path": "cases/6555c9af5586e00815878b21/
externallmg_1700218775923_WhatsApp_Image_20231117_at_42304_PM_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655747975586e0081589f93b",
    "name":
"externallmg_1700218775926_WhatsApp_Image_20231117_at_42304_PM_5.jpeg",
    "path": "cases/6555c9af5586e00815878b21/
externallmg_1700218775926_WhatsApp_Image_20231117_at_42304_PM_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655747a75586e0081589f985",
    "name":
"externallmg_1700218791017_WhatsApp_Image_20231117_at_42304_PM_6.jpeg",
    "path": "cases/6555c9af5586e00815878b21/
externallmg_1700218791017_WhatsApp_Image_20231117_at_42304_PM_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "655747a75586e0081589f986",
    "name":
"externallmg_1700218791020_WhatsApp_Image_20231117_at_42304_PM_7.jpeg",
    "path": "cases/6555c9af5586e00815878b21/
externallmg_1700218791020_WhatsApp_Image_20231117_at_42304_PM_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "655747a75586e0081589f987",
  "name":
"externallmg_1700218791023_WhatsApp_Image_20231117_at_42304_PM_8.jpeg",
  "path": "cases/6555c9af5586e00815878b21/
externallmg_1700218791023_WhatsApp_Image_20231117_at_42304_PM_8.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655747a75586e0081589f988",
  "name":
"externallmg_1700218791026_WhatsApp_Image_20231117_at_42304_PM_9.jpeg",
  "path": "cases/6555c9af5586e00815878b21/
externallmg_1700218791026_WhatsApp_Image_20231117_at_42304_PM_9.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655747a75586e0081589f989",
  "name":
"externallmg_1700218791029_WhatsApp_Image_20231117_at_42304_PM_10.jpeg",
  "path": "cases/6555c9af5586e00815878b21/
externallmg_1700218791029_WhatsApp_Image_20231117_at_42304_PM_10.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655747a75586e0081589f98a",
  "name":
"externallmg_1700218791031_WhatsApp_Image_20231117_at_42304_PM_11.jpeg",
  "path": "cases/6555c9af5586e00815878b21/
externallmg_1700218791031_WhatsApp_Image_20231117_at_42304_PM_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655747a75586e0081589f98b",
  "name":
"externallmg_1700218791034_WhatsApp_Image_20231117_at_42304_PM_12.jpeg",
  "path": "cases/6555c9af5586e00815878b21/
externallmg_1700218791034_WhatsApp_Image_20231117_at_42304_PM_12.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655747a75586e0081589f98c",
  "name":
"externallmg_1700218791036_WhatsApp_Image_20231117_at_42304_PM_13.jpeg",
  "path": "cases/6555c9af5586e00815878b21/
externallmg_1700218791036_WhatsApp_Image_20231117_at_42304_PM_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655747a75586e0081589f98d",
  "name":
"externallmg_1700218791040_WhatsApp_Image_20231117_at_42304_PM_14.jpeg",
  "path": "cases/6555c9af5586e00815878b21/
externallmg_1700218791040_WhatsApp_Image_20231117_at_42304_PM_14.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655747a75586e0081589f98e",
  "name":
"externallmg_1700218791042_WhatsApp_Image_20231117_at_42304_PM_15.jpeg",
  "path": "cases/6555c9af5586e00815878b21/
externallmg_1700218791042_WhatsApp_Image_20231117_at_42304_PM_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655747a75586e0081589f98f",
  "name":
"externallmg_1700218791044_WhatsApp_Image_20231117_at_42304_PM_16.jpeg",
  "path": "cases/6555c9af5586e00815878b21/
externallmg_1700218791044_WhatsApp_Image_20231117_at_42304_PM_16.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655747a75586e0081589f990",
```

```
    "name":
"externallmg_1700218791047_WhatsApp_Image_20231117_at_42304_PM_17.jpeg",
  "path": "cases/6555c9af5586e00815878b21/
externallmg_1700218791047_WhatsApp_Image_20231117_at_42304_PM_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655747a75586e0081589f991",
  "name":
"externallmg_1700218791049_WhatsApp_Image_20231117_at_42304_PM_18.jpeg",
  "path": "cases/6555c9af5586e00815878b21/
externallmg_1700218791049_WhatsApp_Image_20231117_at_42304_PM_18.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655747a75586e0081589f992",
  "name":
"externallmg_1700218791050_WhatsApp_Image_20231117_at_42304_PM.jpeg",
  "path": "cases/6555c9af5586e00815878b21/
externallmg_1700218791050_WhatsApp_Image_20231117_at_42304_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "655747a75586e0081589f993",
  "name":
"externallmg_1700218791053_WhatsApp_Image_20231117_at_42305_PM.jpeg",
  "path": "cases/6555c9af5586e00815878b21/
externallmg_1700218791053_WhatsApp_Image_20231117_at_42305_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "1700114326532_1699252194037_Calculation (1).xlsx",
    "filename":
"1700223281130_1700114326532_1699252194037_Calculation_1.xlsx",
    "path": "cases/6555c9af5586e00815878b21/processingDocuments/1700223281130
_1700114326532_1699252194037_Calculation_1.xlsx",
    "size": "1336876",
```

```
"createdAt": "Fri Nov 17 2023 17:44:41 GMT+0530 (India Standard Time)",
"uploadedBy": "60f915d3f3dd69653a592199"
},
{
  "originalname": "indicator_1700222384317_Image.png",
  "filename": "1700223281152_indicator_1700222384317_Image.png",
  "path": "cases/6555c9af5586e00815878b21/
processingDocuments/1700223281152_indicator_1700222384317_Image.png",
  "size": "436001",
  "createdAt": "Fri Nov 17 2023 17:44:41 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f915d3f3dd69653a592199"
},
{
  "originalname": "indicator_1700222463378_Image.png",
  "filename": "1700223281161_indicator_1700222463378_Image.png",
  "path": "cases/6555c9af5586e00815878b21/
processingDocuments/1700223281161_indicator_1700222463378_Image.png",
  "size": "519205",
  "createdAt": "Fri Nov 17 2023 17:44:41 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f915d3f3dd69653a592199"
},
{
  "originalname": "indicator_1700222786359_Image.png",
  "filename": "1700223281169_indicator_1700222786359_Image.png",
  "path": "cases/6555c9af5586e00815878b21/
processingDocuments/1700223281169_indicator_1700222786359_Image.png",
  "size": "169753",
  "createdAt": "Fri Nov 17 2023 17:44:41 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f915d3f3dd69653a592199"
}
],
"leadRemarks": [],
"remarks": [],
"createdAt": "2023-11-16T07:50:07.840Z",
"updatedAt": "2023-11-17T12:20:42.779Z",
"__v": 0,
"invoiceId": "6555c9af5586e00815878b27",
"updatedBy": "62fe044a48a26047e6552796",
"fullAddress": "Residential Flat No. 503, 5th Floor, Wing - D, Mrug "D" Wing Co-Op.
Hsg. Soc. Ltd., Tarangan , Wayale Nagar , Village - Gandhare , Taluka - Kalyan, District
- Thane, Kalyan (West), PIN - 421 301, State - Maharashtra, Country - India",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Ravindra Bhaurao Walhe",
"email": "",
"isExternal": "false",
```

"isUrgent": "false",
 "ownershipShare": "",
 "purchaseValueAsPerDocument": "",
 "relationWithOwner": "self",
 "siteVisitContactNo": "8452014797",
 "briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + 2 Toilet + Passage",
 "carpetTotal": "704.34",
 "finalMeasurementType": "Sq. Ft.",
 "otherCarpetTotal": "52.17"

}

Name	Length	Width	Total
Composition :			
Living Room	23'00"	12'5"	285.58
Kitchen	8'00"	9'2"	73.33
Bedroom	12'00"	8'00"	96.00
Bedroom	13'00"	12'00"	156.00
Toilet	5'00"	7'5"	37.08
Toilet	7'3"	4'00"	29.00
Passage	8'5"	3'3"	27.35
Other Composition :			
Cupboard	6'7"	2'00"	13.17
Balcony Area	3'00"	13'00"	39.00