

Structural Stability Report

Structural Observation Report of Residential Flat No. 705, 7th Floor, Building No. 2, Wing - B, "Harshgiri Co-op. Hsg. Soc. Ltd.", Shiv Vallabh Cross Road, Rawalpada, Village - Dahisar, Taluka - Borivali, District - Mumbai, Dahisar (East), PIN - 400 068, State - Maharashtra, India.

Name of Owner: **Smt. Shradha Sharad Jadhav & Shri. Sharad Dattaram Jadhav.**

This is to certify that on visual inspection, it appears that the structure of the Building No. 2, Wing - B at "Harshgiri Co-op. Hsg. Soc. Ltd.", is in normal condition and the future life can be reasonably taken under good condition and with proper periodic repairs & maintenance is about 40 years.

General Information:

A.	Introduction	
1	Name of Building	"Harshgiri Co-op. Hsg. Soc. Ltd."
2	Property Address	Residential Flat No. 705, 7 th Floor, Building No. 2, Wing - B, "Harshgiri Co-op. Hsg. Soc. Ltd.", Shiv Vallabh Cross Road, Rawalpada, Village - Dahisar, Taluka - Borivali, District - Mumbai, Dahisar (East), PIN - 400 068, State - Maharashtra, India.
3	Type of Building	Residential used
4	No. of Floors	(Part) Ground + (Part) Stilt + 8 th Upper Floors
5	Whether stilt / podium / open parking provided	Stilt + Open Car Parking
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	2003 (As per occupancy certificate)
11	Present age of building	20 years
12	Residual age of the building	40 years Subject to proper, preventive periodic maintenance & structural repairs.
13	No. of flats (Per Floor)	6 Flats on 7 th Floor
14	Methodology adopted	As per visual site inspection



Our Pan India Presence at :

- Mumbai Aurangabad Pune Rajkot
Thane Nanded Indore Raipur
Delhi NCR Nashik Ahmedabad Jaipur



Regd. Office : B1-001, U/B Floor, Boomerang,
Chandivali Farm Road, Andheri (East),
Mumbai - 400 072, (M.S.), INDIA
TeleFax : +91 22 28371325/24
mumbai@vastukala.org

B.	External Observation of the Building	
1	Plaster	Normal Condition
2	Chajjas	Normal Condition
3	Plumbing	Normal Condition
4	Cracks on the external walls	Not found
5	Filling cracks on the external walls	Not found
6	Cracks on columns & beams	Not found
7	Vegetation	Not found
8	Leakages of water in the drainage pipes, or water pipes	Not found
9	Dampness external in the wall due to leakages	Not found
10	Any other observation about the condition of external side of the building	The external condition of the building is in normal condition

C	Internal Observation of the common areas of the building and captioned premises	
1	Beams (Cracks & Leakages)	Good Condition
2	Columns (Cracks & Leakages)	Good Condition
3	Ceiling (Cracks & Leakages)	Good Condition
4	Leakages inside the property	Not found
5	Painting inside the property	Good
6	Maintenance of staircase & cracks	Good

D	Common Observation	
1	Structural Audit of the Building Under Bye – Laws No. 77 of the Model Bye Laws (Co-Operative Societies Act / Rules)	As per bye Laws No. 77 of Co-Op. Societies bye Laws under the Act the society shall conduct a Structural Audit of the building of the society as follows
2	Remark	No Structural Audit Report is furnished for the perusal.

E	Conclusion
	<p>The captioned building is having (Part) Ground + (Part) Stilt + 8th Upper Floors which are constructed in year 2003 as per occupancy certificate. Estimated future life under present circumstances is about 40 years subject to proper, preventive periodic maintenance & structural repairs.</p> <p>The inspection dated 13.10.2023 reveals minor structural damage or deterioration to the building. The building is well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & Good structural repairs.</p> <p>Our Observations about the structure are given above.</p> <p>The above assessment is based on visual inspection only. Separate structural audit from licensed structural engineers is advised to assess exact balance life of structure.</p>

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Sharadkumar
B. Chalikwar

Digitally signed by Sharadkumar B. Chalikwar
DN: cn=Sharadkumar B. Chalikwar, o=Vastukala Consultants (I) Pvt. Ltd., ou=CMD, email=cmd@vastukala.org, c=IN
Date: 2023.11.21 13:05:15 +05'30'

Director

Auth. Sign.

Sharadkumar B. Chalikwar

Govt. Reg. Valuer

Chartered Engineer (India)

Reg. No. (N) CCIT/1-14/52/2008-09

SBI Empanelment No.: SME/TCC/2021-22/85/13



Vastukala Consultants (I) Pvt. Ltd.
An ISO 9001:2015 Certified Company
www.vastukala.org



