CIN: U74120MH2010PTC207869 MSME Reg. No.: UDYAM-MH-18-0083617 An ISO 9001:2015 Certified Company





Structural Stability Report Prepared For: SBI / Churchgate (Mumbai) Branch / Mr. Dinesh Lakhan Sharma (5306/2303719) Page 1 of 3

Vastu/Mumbai/11/2023/5306/2303719 29/05-415-JASH Date: 29.11.2023

Structural Stability Report

Structural Observation Report of Residential Flat No. 101, 1st Floor, "Shri Ram Apartment", "Jai Shree Ram Coop. Hsg. Soc. Ltd.", Plot No. 34 & 35, Narayan Nagar Road, Village - Titwala, Titwala (East), Taluka - Kalyan, District - Thane, PIN - 421 605, State - Maharashtra, Country - India.

Name of Owner: Mr. Dinesh Lakhan Sharma & Mrs. Murti Dinesh Sharma

This is to certify that on visual inspection, it appears that the structure of the at "Jai Shree Ram Co-op. Hsg. Soc. Ltd.", is in normal condition and the future life can be reasonably taken under good condition and with proper periodic repairs & maintenance is about 44 years.

General Information:

1 Name of Building "Shri Ram Apartment" 2 Property Address Residential Flat No. 101, 1st Apartment", "Jai Shree Ram Co-op. No. 34 & 35, Narayan Nagar Roa Titwala (East), Taluka - Kalyan, Distr	·
Apartment", "Jai Shree Ram Co-op. No. 34 & 35, Narayan Nagar Roa	·
No. 34 & 35, Narayan Nagar Roa	. Hsg. Soc. Ltd.", Plot
1.31	
Titwala (East), Taluka - Kalyan, Distr	ad, Village - Titwala,
i i i i i i i i i i i i i i i i i i i	rict - Thane, PIN - 421
605, State – Maharashtra, Country –	India.
3 Type of Building Residential	
4 No. of Floors Ground + 3 Upper Floors	
5 Whether stilt / podium / open parking Open Car Parking Space	
provided	
6 Type of Construction R.C.C. Framed Structure	
7 Type of Foundation R.C.C. Footing	
8 Thickness of the External Walls 9" thick brick walls both sides plastered	ed
9 Type of Compound Brick Masonry Walls	
10 Year of Construction 2007 (As per Building Completion Ce	ertificate)
11 Present age of building 16 Years 16 Years	
12 Residual age of the building 44 Years Subject to proper,	preventive periodic
maintenance & structural repairs.	
13 No. of flats (Per Floor) 1st Floor is having 5 Flats	
14 Methodology adopted As per visual site inspection	

B.	External Observation of the Building		
1	Plaster	Normal Condition	S-CONSULTAD:
2	Chajjas	Normal Condition	Acceptance of the Control of the Con
3	Plumbing	Normal Condition	
4	Cracks on the external walls	Found	FO MIN 2818 PICEOU
5	Filling cracks on the external walls	Not found	



Regd. Office: B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Andheri (East), Mumbai - 400 072, (M.S.), INDIA

TeleFax: +91 22 28371325/24 mumbai@vastukala.org

6	Cracks on columns & beams	Not found	
7	Vegetation	Found	
8	Leakages of water in the drainage pipes or water pipes	Not found	
9	Dampness external in the wall due to leakages	Found	
10	Any other observation about the condition of external side of the building	 At the time of site inspection, external condition of the building is normal. Structural Stability Report from licensed structural engineers not provided for our verification. 	
С	Internal Observation of the common areas of the building and captioned premises		
1	Beams (Cracks & Leakages)	Not found	
2	Columns (Cracks & Leakages)	Not found	
3	Ceiling (Cracks & Leakages)	Not found	
4	Leakages inside the property	Not found	
5	Painting inside the property	Normal	
6	Maintenance of staircase & cracks	Normal	

D	Common Observation		
1	Structural Audit of the Building Under Bye	As per bye Laws No. 77 of Co-Op. Societies bye Laws	
	- Laws No. 77 of the Model Bye Laws	under the Act the society shall conduct a Structural Audit	
	(Co-Operative Societies Act / Rules)	of the building of the society as follows	
2	Remark	No Structural Audit Report is furnished for the perusal.	

E Conclusion

The captioned building is having Ground + 3 upper floors which are constructed in year 2007 (as per Building Completion Certificate). Estimated future life under present circumstances is about 44 years subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 17.11.2023 reveals no structural damage or deterioration to the building. The building is well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & Good structural repairs.

Our Observations about the structure are given above.

The above assessment is based on visual inspection only. Separate structural audit from licensed structural engineers is advised to assess exact balance life of structure.

For VASTUKALA CONSULTANTS (I) PVT. LTD

Sharadkumar Chalikwar Digitally signed by Sharadkumar Chalilwar DN: cn=Sharadkumar Chalikwar, q=Vastukala Consultants (I) Pvt. Ltd. qu=Mumbar, email=cmd@vastukala.org, c=IN

Date: 2023.11.29 13:08:54 +05'30'

Director

Auth, Sign.

Sharadkumar B. Chalikwar

Govt. Reg. Valuer Chartered Engineer (India)

Reg. No. (N) CCIT/1-14/52/2008-09

SBI Empanelment No.: SME/TCC/2021-22/85/13





Actual Site Photographs





















