CIN: U74120MH2010PTC207869 MSME Reg. No.: UDYAM-MH-18-0083617 An ISO 9001:2015 Certified Company





Structural Stability Report Prepared For: SBI / RACPC Sion / Mrs. Vijaya Rajesh Golla (5339/2303903)

Page 1 of 3

Vastu/Mumbai/12/2023/5539/2303903 11/07-132-PA Date: 11.12.2023

Structural Stability Report

Structural Observation Report of Residential Flat No. 403, 4th Floor, Building No L - 6, Wing - B, "Pratiksha Nagar Sindhudurg Co-op. Hsg. Soc. Ltd.", New MHADA Colony, Pratiksha Nagar, Village - Salt pan Division, Municipality Ward No. F/ North Ward, Sion (East), District - Mumbai District, Mumbai, PIN Code - 400 022, State - Maharashtra, India.

Name of Owner: Mrs. Vijaya Rajesh Golla & Mr. Pranay Rajesh Golla.

This is to certify that on visual inspection, it appears that the structure of the at "Pratiksha Nagar Sindhudurg Co-op. Hsg. Soc. Ltd." is in normal condition and the future life can be reasonably taken under good condition and with proper periodic repairs & maintenance is about 42 years.

General Information:

| Α. | | Introduction |
|----|---------------------------------------|--|
| 1 | Name of Building | Pratiksha Nagar Sindhudurg Co-op. Hsg. Soc. Ltd. |
| 2 | Property Address | Residential Flat No. 403, 4th Floor, Building No L - 6, Wing |
| | // | - B, "Pratiksha Nagar Sindhudurg Co-op. Hsg. Soc. |
| | 1001 | Ltd.", New MHADA Colony, Pratiksha Nagar, Village - |
| | | Salt pan Division, Municipality Ward No. F/ North Ward, |
| | (8) | Sion (East), District - Mumbai District, Mumbai, PIN Code - |
| | 7) | 400 022, State - Maharashtra, India. |
| 3 | Type of Building | Residential used |
| 4 | No. of Floors | Ground + 7 Upper Floors |
| 5 | Whether stilt / podium / open parking | Open Car Parking |
| | provided | |
| 6 | Type of Construction | R.C.C. Framed Structure |
| 7 | Type of Foundation | R.C.C. Footing |
| 8 | Thickness of the External Walls | 9" thick brick walls both sides plastered |
| 9 | Type of Compound | Brick Masonry Walls |
| 10 | Year of Construction | 2005 (As per agreement) |
| 11 | Present age of building | 18 years |
| 12 | Residual age of the building | 42 years Subject to proper, preventive periodic |
| | | maintenance & structural repairs |
| 13 | No. of flats (Per Floor) | 4th Floor is having 4 Flats |
| 14 | Methodology adopted | As per visual site inspection |



Regd. Office: B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Andheri (East), Mumbai - 400 072, (M.S.), INDIA

TeleFax : +91 22 28371325/24 mumbai@vastukala.org

| B. | External O | bservation of the Building |
|----|---|---|
| 1 | Plaster | Normal Condition |
| 2 | Chajjas | Normal Condition |
| 3 | Plumbing | Normal Condition |
| 4 | Cracks on the external walls | Not Found |
| 5 | Filling cracks on the external walls | Not Found |
| 6 | Cracks on columns & beams | Not Found |
| 7 | Vegetation | Not Found |
| 8 | Leakages of water in the drainage pipes. | Not Found . |
| | or water pipes | |
| 9 | Dampness external in the wall due to | Not Found |
| | leakages | |
| 10 | Any other observation about the | The external condition of the building is in normal condition |
| | condition of external side of the building | (B) |
| С | Internal Observation of the common areas of the building and captioned premises | |
| 1 | Beams (Cracks & Leakages) | Normal Condition |
| 2 | Columns (Cracks & Leakages) | Normal Condition |
| 3 | Ceiling (Cracks & Leakages) | Normal Condition |
| 4 | Leakages inside the property | Not Found |
| 5 | Painting inside the property | Normal |
| 6 | Maintenance of staircase & cracks | Normal |

| D | Common Observation | |
|---|--|--|
| 1 | Structural Audit of the Building Under Bye | As per bye Laws No. 77 of Co-Op. Societies bye Laws |
| | - Laws No. 77 of the Model Bye Laws | under the Act the society shall conduct a Structural Audit |
| | (Co-Operative Societies Act / Rules) | of the building of the society as follows |
| 2 | Remark | No Structural Audit Report is furnished for the perusal |

E Conclusion

The captioned building is having Ground + 7 Upper Floors which are constructed in year 2005 (As per agreement). Estimated future life under present circumstances is about 42 years' subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 22.11.2023 reveals no structural damage or deterioration to the building. The building is well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & Good structural repairs.

Our Observations about the structure are given above.

The above assessment is based on visual inspection only.

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Sharadkumar B. Chalikwar

Digitally signed by Sharadkumar B. Chalikwar DN: cn=Sharadkumar B. Chalikwar,

DN: cn=Sharadkumar B. Chalikwar, o=Vastukala Consultants (I) Pvt. Ltd., ou=CMD, email=cmd@vastukala.org, c=IN Date: 2023.12.11 17:46:41 +05'30'

Director

Auth. Sign

Sharadkumar B. Chalikwar

Govt. Reg. Valuer Chartered Engineer (India)

Reg. No. (N) CCIT/1-14/52/2008-09

BOB Empanelment No.: ZO:MZ:ADV:46:941





Actual Site Photographs

















