

Structural Stability Report

Structural Observation Report of Commercial Unit No. 206, 2nd Floor, "Sterling Chambers", Sterling Centre Premises Co-op. Society Ltd., Old Nagardas Road, Mograpada, Andheri (East), Mumbai – 400 069, State – Maharashtra, Country – India.

Name of Owner: **Mr. Sitesh Bipin Shah & Mr. Bipin Chimanlal Shah**

This is to certify that on visual inspection, it appears that the structure of the "Sterling Chambers", Sterling Centre Premises Co-op. Society Ltd., is in normal condition and the future life can be reasonably taken under good condition and with proper periodic repairs & maintenance is about 26 years.

General Information:

A.	Introduction	
1	Name of Building	"Sterling Centre Premises Co-op. Society Ltd."
2	Property Address	Commercial Unit No. 206, 2 nd Floor, "Sterling Chambers", Sterling Centre Premises Co-op. Society Ltd., Old Nagardas Road, Mograpada, Andheri (East), Mumbai – 400 069, State – Maharashtra, Country – India.
3	Type of Building	Commercial used
4	No. of Floors	Ground + 3rd Upper Floors
5	Whether stilt / podium / open parking provided	Open Car Parking
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	1989 (As per documents)
11	Present age of building	34 years
12	Residual age of the building	26 years Subject to proper, preventive periodic maintenance & structural repairs.
13	No. of flats (Per Floor)	14 Units on 2 nd Floor
14	Methodology adopted	As per visual site inspection

B.	External Observation of the Building	
1	Plaster	Normal Condition
2	Chajjas	Normal Condition
3	Plumbing	Normal Condition
4	Cracks on the external walls	Not found
5	Filling cracks on the external walls	Not found



6	Cracks on columns & beams	Not found
7	Vegetation	Not found
8	Leakages of water in the drainage pipes or water pipes	Not found
9	Dampness external in the wall due to leakages	Not found
10	Any other observation about the condition of external side of the building	The external condition of the building is in normal condition
C	Internal Observation of the common areas of the building and captioned premises	
1	Beams (Cracks & Leakages)	Normal Condition
2	Columns (Cracks & Leakages)	Normal Condition
3	Ceiling (Cracks & Leakages)	Normal Condition
4	Leakages inside the property	Not found
5	Painting inside the property	Normal
6	Maintenance of staircase & cracks	Normal

D	Common Observation	
1	Structural Audit of the Building Under Bye – Laws No. 77 of the Model Bye Laws (Co-Operative Societies Act / Rules)	As per bye Laws No. 77 of Co-Op. Societies bye Laws under the Act the society shall conduct a Structural Audit of the building of the society as follows
2	Remark	No Structural Audit Report is furnished for the perusal.

E	Conclusion
<p>The captioned building is having Ground + 3rd Upper Floors which are constructed in year 1989 as per documents. Estimated future life under present circumstances is about 26 years subject to proper, preventive periodic maintenance & structural repairs.</p> <p>The inspection dated 20.12.2023 the building is well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & Good structural repairs.</p> <p>Our Observations about the structure are given above.</p> <p>The above assessment is based on visual inspection only. Separate structural audit from licensed structural engineers is advised to assess exact balance life of structure.</p>	

For VASTUKALA CONSULTANTS (I) PVT. LTD.

**Sharadkumar
B. Chalikwar**
Director

Digitally signed by Sharadkumar B. Chalikwar
DN: cn=Sharadkumar B. Chalikwar,
o=Vastukala Consultants (I) Pvt. Ltd.,
ou=CMD, email=cmd@vastukala.org, c=IN
Date: 2023.12.21 10:51:33 +05'30'

Auth. Sign.

Sharadkumar B. Chalikwar

Govt. Reg. Valuer
Chartered Engineer (India)
Reg. No. (N) CCIT/1-14/52/2008-09
BOB Empanelment No.: ZO:MZ:ADV:46:941



Vastukala Consultants (I) Pvt. Ltd.
An ISO 9001:2015 Certified Company
www.vastukala.org



Actual Site Photographs

