CIN: U74120MH2010PTC207869 MSME Reg. No.: UDYAM-MH-18-0083617 An ISO 9001:2015 Certified Company





Structural Stability Report Prepared For: SBI / Racpc Borivali West Shimpoli Road/ Geeta Ram Ashish Yadav (5956/2304314)

Page 1 of 3

Vastu/Mumbai/01/2024/5956/2304314 03/1-16-PASH Date: 03.01.2024

Structural Stability Report

Structural Observation Report of Residential Flat No. 001, Ground Floor, Building No 12, Wing - B, "Vaastu Sankalp Co-op. Hsg. Soc. Ltd.", Plot No. 12, Sankalp Sahanivas, NNP Colony, Film City Road, Dindoshi, Village - Malad, Goregaon (East), Taluka - Borivali, District - Mumbai Suburban District, Mumbai, PIN Code - 400 097, State - Maharashtra, India.

Name of Owner: Geeta Ram Ashish Yadav

This is to certify that on visual inspection, it appears that the structure of the at "Vaastu Sankalp Co-op. Hsg. Soc. Ltd." is in normal condition and the future life can be reasonably taken under good condition and with proper periodic repairs & maintenance is about 44 years.

General Information:

A.		Introduction
1	Name of Building	Vaastu Sankalp Co-op. Hsg. Soc. Ltd.
2	Property Address	Residential Flat No. 001, Ground Floor, Building No 12, Wing - B, "Vaastu Sankalp Co-op. Hsg.Soc. Ltd.", Plot No. 12, Sankalp Sahanivas, NNP Colony, Film City Road, Dindoshi, Village - Malad, Goregaon (East), Taluka -
	D	Borivali, District - Mumbai Suburban District, Mumbai, PIN Code - 400 097, State - Maharashtra, India
3	Type of Building	Residential used
4	No. of Floors	Ground + 7 Upper Floors
5	Whether stilt / podium / open parking	Open Car Parking
	provided	
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	2007 (As per occupancy certificate)
11	Present age of building	16 years
12	Residual age of the building	44 years Subject to proper, preventive periodic maintenance & structural repairs
13	No. of flats (Per Floor)	Ground Floor is having 4 Flats
14	Methodology adopted	As per visual site inspection



Regd. Office: B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Andheri (East), Mumbai - 400 072, (M.S.), INDIA

TeleFax: +91 22 28371325/24
mumbai@vastukala.org

B.	External O	bservation of the Building
1	Plaster	Normal Condition
2	Chajjas	Normal Condition
3	Plumbing	Normal Condition
4	Cracks on the external walls	Not Found
5	Filling cracks on the external walls	Not Found
6	Cracks on columns & beams	Not Found
7	Vegetation	Not Found
8	Leakages of water in the drainage pipes	Not Found
	or water pipes	
9	Dampness external in the wall due to	Not Found
	leakages	
10	Any other observation about the condition	The external condition of the building is in normal condition
	of external side of the building	
С	Internal Observation of the comm	on areas of the building and captioned premises
1	Beams (Cracks & Leakages)	Normal Condition
2	Columns (Cracks & Leakages)	Normal Condition
3	Ceiling (Cracks & Leakages)	Normal Condition
4	Leakages inside the property	Not Found
5	Painting inside the property	Normal
6	Maintenance of staircase & cracks	Normal

D	Common Observation	
1	Structural Audit of the Building Under Bye	As per bye Laws No. 77 of Co-Op. Societies bye Laws
	- Laws No. 77 of the Model Bye Laws (Co-	under the Act the society shall conduct a Structural Audit of
	Operative Societies Act / Rules)	the building of the society as follows
2	Remark	No Structural Audit Report is furnished for the perusal

Conclusion

The captioned building is having Ground + 7 Upper Floors which are constructed in year 2007 (As per occupancy certificate). Estimated future life under present circumstances is about 44 years' subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 28.12.2023 reveals no structural damage or deterioration to the building. The building is well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & Good structural repairs.

Our Observations about the structure are given above.

The above assessment is based on visual inspection only.

For VASTUKALA CONSULTANTS (I) PVT. LTD

Sharadkumar Digitally signed by Sharadkumar B B. Chalikwar

DN: cn=Sharadkumar B. Chalikwar, o=Vastukala Consultants (I) Pvt. Ltd., ou=CMD, email=cmd@vastukala.org, Date: 2024.01.03 10:57:16 +05'30'

Auth Sign.

Director

Sharadkumar B. Chalikwar

Registered Valuer

Chartered Engineer (India)

Reg. No. CAT-I-F-1763

Cosmos Emp. No. H.O./Credit/67/2019-20





Actual Site Photographs















