

```
{
  "typeOfReport": {
    "value": "Land_and_Building",
    "label": "Land and Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64130b50e6a52007fbaa7d90"
    },
    "type": "CREDITOFFICER",
    "_id": "64130b50e6a52007fbaa7d92",
    "firstName": "testgangapur",
    "lastName": "testgangapur",
    "mobileNo": "",
    "workMobileNo": "0000000000",
    "email": ""
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "3540"
  },
  "organization": {
```

```
"_id": "643a5bee108b68389ed736e5",
"name": "Nashik Branch",
"shortName": "NSK",
"email": "nashik@vastukala.org",
"address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
"city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64130b50e6a52007fbaa7d90",
  "name": "Gangapur Branch\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "GangapurBranch@me.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "SHree Ganesh Avanie, Gangapur road, Nashik 422013, State
Maharashtra"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "63fda9ecce84bf289baadd43",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "63f9ed37ce84bf289ba991ac",
    "role": "FRONTDESK",
```

```
"firstName": "Rushikesh",
"email": "rushipingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63f9f4adce84bf289ba9956e",
"role": "FRONTDESK + ENGINEER",
"firstName": "Swapnnil",
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"designation": "",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1688707461551_image.jpeg"
},
"rateVerifier": null,
"maker": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"designation": "",
"shortName": "Chintamani",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "64dc7184ccaf1e7b7f637f47",
"role": "FRONTDESK",
"firstName": "Binumon",
"email": "binu@vastukala.org",
"lastName": "Moozhickal",
"mobileNo": "9930252906",
```

```
    "designation": "Back Office Team Leader",
    "shortName": "BS",
    "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "valuers": [],
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.95549911330059",
  "longitude": "73.76724901293692"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
```

```
"name": "Country",
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Nashik",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
}
```

```
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "14",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
```

```
    "key": "landmark",
    "value": "Opposite Sai Coaching Classes, Mauli Nagari, Dnyaneshwar Nagar, Vidya
Nagar, ",
    "label": false
  },
  "wing": {
    "status": false,
    "name": "Wing",
    "key": "wing",
    "value": "",
    "label": true
  },
  "projectName": {
    "status": false,
    "name": "Project Name",
    "key": "projectName",
    "value": "",
    "label": false
  },
  "oldSurveyNumber": {
    "status": false,
    "name": "Old Survey No.",
    "key": "oldSurveyNumber",
    "value": "",
    "label": true
  },
  "newSurveyNumber": {
    "status": true,
    "name": "New/Current Survey No.",
    "key": "newSurveyNumber",
    "value": ".908/3/14, ",
    "label": true
  },
  "hissaNo": {
    "status": false,
    "name": "Hissa No.",
    "key": "hissaNo",
    "value": "",
    "label": true
  },
  "CTSNo": {
    "status": false,
    "name": "CTS No.",
    "key": "CTSNo",
    "value": "",
    "label": true
  }
}
```

```
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
```



```
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422010",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  }
}
```

```
    },
    "locationMapImg": [],
  },
  "outward": {
    "status": false,
    "remark": "SYSTEM_GENERATED"
  },
  "rateVerify": {
    "status": false
  },
  "underConstruction": {
    "rccFootingFoundation": {
      "label": "RCC Footing/Foundation",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": true
    },
    "rccPlinth": {
      "label": "RCC Plinth",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    },
    "fullBuildingRcc": {
      "label": "Full Building Rcc",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    },
    "internalBrickWork": {
      "label": "Internal Brick Work",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    },
    "externalBrickWork": {
      "label": "External Brick Work",
      "floorsCompleted": "",
      "percentage": "0.00",
      "isHideFloor": false,
      "status": false
    }
  },
}
```

```
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
```

```
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentId": [],
"_id": "658fc2cb545844510d0be460",
"ownerName": "Vasant Palve",
"ownerPhoneNo": "9637099351",
"fullAddress": " Land and Building No. Ground Floor, Opposite Sai Coaching Classes,
Maui Nagari, Dnyaneshwar Nagar, Vidya Nagar, , Plot No. 14, New/Current Survey
```

No. .908/3/14, , Village - Nashik, Taluka - Nashik, District - Nashik, Nashik, 422010",

"remark": "",

"documents": [

{  
 "documentType": {  
 "value": "60ae1247aa6d152c1801b2e8",  
 "label": "Layout Plan"

},

"isHardCopy": false,

"displayStatus": false,

"fileName": "document\_1703920285006\_Pritam\_Plawe\_Layout.pdf",

"path": "cases/658fc2cb545844510d0be460/

document\_1703920285006\_Pritam\_Plawe\_Layout.pdf",

"id": "391913",

"uploadedBy": "63f9ed37ce84bf289ba991ac",

"createdAt": "Sat Dec 30 2023 12:42:11 GMT+0530 (India Standard Time)"

},

{  
 "documentType": {  
 "value": "60ae124aaa6d152c1801b2f7",  
 "label": "Any Other Document"

},

"isHardCopy": false,

"displayStatus": false,

"fileName": "document\_1703920297432\_Pritam\_Plawe\_Plan\_Cc.pdf",

"path": "cases/658fc2cb545844510d0be460/

document\_1703920297432\_Pritam\_Plawe\_Plan\_Cc.pdf",

"id": "585944",

"uploadedBy": "63f9ed37ce84bf289ba991ac",

"createdAt": "Sat Dec 30 2023 12:42:11 GMT+0530 (India Standard Time)"

},

{  
 "documentType": {  
 "value": "60ae124aaa6d152c1801b2f7",  
 "label": "Any Other Document"

},

"isHardCopy": false,

"displayStatus": false,

"fileName": "document\_1703920312746\_Pritam\_Plawe\_Sale\_Deed.pdf",

"path": "cases/658fc2cb545844510d0be460/

document\_1703920312746\_Pritam\_Plawe\_Sale\_Deed.pdf",

"id": "719657",

"uploadedBy": "63f9ed37ce84bf289ba991ac",

"createdAt": "Sat Dec 30 2023 12:42:11 GMT+0530 (India Standard Time)"

},

{



```
"documentType": {
  "value": "60ae124aaa6d152c1801b2f7",
  "label": "Any Other Document"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1703920460152_171530.pdf",
"path": "cases/658fc2cb545844510d0be460/
document_1703920460152_171530.pdf",
"id": "213942",
"uploadedBy": "63f9ed37ce84bf289ba991ac",
"createdAt": "Sat Dec 30 2023 12:44:20 GMT+0530 (India Standard Time)"
},
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "006019",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "469933",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Dec 30 2023 12:42:11 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Vasant Palve",
    "phone": "9637099351",
    "ownershipShare": "",
    "email": "",
    "id": "682196"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658fc340545844510d0be917",
  "name":
"externallmg_1703920443935_WhatsApp_Image_20231220_at_24710_PM.jpeg",
  "path": "cases/658fc2cb545844510d0be460/
externallmg_1703920443935_WhatsApp_Image_20231220_at_24710_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658fc340545844510d0be918",
  "name":
"externallmg_1703920443994_WhatsApp_Image_20231220_at_24717_PM.jpeg",
  "path": "cases/658fc2cb545844510d0be460/
externallmg_1703920443994_WhatsApp_Image_20231220_at_24717_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658fc340545844510d0be919",
  "name":
"externallmg_1703920444061_WhatsApp_Image_20231220_at_24720_PM.jpeg",
  "path": "cases/658fc2cb545844510d0be460/
externallmg_1703920444061_WhatsApp_Image_20231220_at_24720_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658fc340545844510d0be91a",
  "name":
"externallmg_1703920444130_WhatsApp_Image_20231220_at_24727_PM.jpeg",
  "path": "cases/658fc2cb545844510d0be460/
externallmg_1703920444130_WhatsApp_Image_20231220_at_24727_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658fc340545844510d0be91b",
  "name":
"externallmg_1703920444267_WhatsApp_Image_20231220_at_24730_PM.jpeg",
```

```
    "path": "cases/658fc2cb545844510d0be460/
externallmg_1703920444267_WhatsApp_Image_20231220_at_24730_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fc340545844510d0be91c",
    "name":
"externallmg_1703920444348_WhatsApp_Image_20231220_at_24732_PM_1.jpeg",
    "path": "cases/658fc2cb545844510d0be460/
externallmg_1703920444348_WhatsApp_Image_20231220_at_24732_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fc340545844510d0be91d",
    "name":
"externallmg_1703920444430_WhatsApp_Image_20231220_at_24732_PM.jpeg",
    "path": "cases/658fc2cb545844510d0be460/
externallmg_1703920444430_WhatsApp_Image_20231220_at_24732_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fc340545844510d0be91e",
    "name":
"externallmg_1703920444511_WhatsApp_Image_20231220_at_24733_PM.jpeg",
    "path": "cases/658fc2cb545844510d0be460/
externallmg_1703920444511_WhatsApp_Image_20231220_at_24733_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fc340545844510d0be91f",
    "name":
"externallmg_1703920444565_WhatsApp_Image_20231220_at_24734_PM_1.jpeg",
    "path": "cases/658fc2cb545844510d0be460/
externallmg_1703920444565_WhatsApp_Image_20231220_at_24734_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "658fc340545844510d0be920",
  "name":
"externallmg_1703920444593_WhatsApp_Image_20231220_at_24734_PM.jpeg",
  "path": "cases/658fc2cb545844510d0be460/
externallmg_1703920444593_WhatsApp_Image_20231220_at_24734_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658fc340545844510d0be921",
  "name":
"externallmg_1703920444648_WhatsApp_Image_20231220_at_24736_PM.jpeg",
  "path": "cases/658fc2cb545844510d0be460/
externallmg_1703920444648_WhatsApp_Image_20231220_at_24736_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658fc340545844510d0be922",
  "name":
"externallmg_1703920444687_WhatsApp_Image_20231220_at_24739_PM.jpeg",
  "path": "cases/658fc2cb545844510d0be460/
externallmg_1703920444687_WhatsApp_Image_20231220_at_24739_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658fc340545844510d0be923",
  "name":
"externallmg_1703920444739_WhatsApp_Image_20231220_at_24741_PM.jpeg",
  "path": "cases/658fc2cb545844510d0be460/
externallmg_1703920444739_WhatsApp_Image_20231220_at_24741_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "658fc340545844510d0be924",
  "name":
"externallmg_1703920444779_WhatsApp_Image_20231220_at_24744_PM.jpeg",
  "path": "cases/658fc2cb545844510d0be460/
externallmg_1703920444779_WhatsApp_Image_20231220_at_24744_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fc340545844510d0be925",
    "name":
"externallmg_1703920444819_WhatsApp_Image_20231220_at_24746_PM.jpeg",
    "path": "cases/658fc2cb545844510d0be460/
externallmg_1703920444819_WhatsApp_Image_20231220_at_24746_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fc340545844510d0be926",
    "name":
"externallmg_1703920444883_WhatsApp_Image_20231220_at_24750_PM.jpeg",
    "path": "cases/658fc2cb545844510d0be460/
externallmg_1703920444883_WhatsApp_Image_20231220_at_24750_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fc340545844510d0be927",
    "name":
"externallmg_1703920444955_WhatsApp_Image_20231220_at_24756_PM.jpeg",
    "path": "cases/658fc2cb545844510d0be460/
externallmg_1703920444955_WhatsApp_Image_20231220_at_24756_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fc340545844510d0be928",
    "name":
"externallmg_1703920445022_WhatsApp_Image_20231220_at_24801_PM.jpeg",
    "path": "cases/658fc2cb545844510d0be460/
externallmg_1703920445022_WhatsApp_Image_20231220_at_24801_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fc340545844510d0be929",
```

```

    "name":
    "externallmg_1703920445192_WhatsApp_Image_20231220_at_24803_PM.jpeg",
    "path": "cases/658fc2cb545844510d0be460/
externallmg_1703920445192_WhatsApp_Image_20231220_at_24803_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "658fc340545844510d0be92a",
    "name":
    "externallmg_1703920445321_WhatsApp_Image_20231220_at_24804_PM.jpeg",
    "path": "cases/658fc2cb545844510d0be460/
externallmg_1703920445321_WhatsApp_Image_20231220_at_24804_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2023-12-30T07:12:11.835Z",
"updatedAt": "2023-12-30T07:14:20.250Z",
"__v": 0,
"invoiceId": "658fc2cb545844510d0be466",
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "63f9f4adce84bf289ba9956e",
"contactPersonName": "Vasant Palve",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9637099351"
}

```

Name	Length	Width	Total
Composition :			

Other  
Composition :

---