CIN: U74120MH2010PTC207869 MSME Reg. No.: UDYAM-MH-18-0083617 An ISO 9001:2015 Certified Company





Structural Stability Report Prepared For: BOI/ Nashik Main Branch / Shri. Chandrashekhar Mahadu Saundane (006053/2304310) Page 1 of 3

Vastu/Nashik/01/2024/006053/2304310 02/8-12-CCBS Date: 02.01.2024

Structural Stability Report

Residential Flat No.16, Third Floor "Anand Sagar Co.Op.Hsg.Soc.Ltd.Nashik", Survey No.541A-1+541A/4/3, Final Plot No.198, Plot No.3, TP Scheme No.I, Behind Kit Kat Wining Machines, ND Patel Road, Mohan Nagar, Village- Nashik, Taluka & District - Nashik, PIN Code - 422 001, State - Maharashtra, Country - India belongs to Shri.Chandrashekhar Mahadu Saundane & Sau.Surekhabai Chandrashekhar Saundane

This is to certify that on visual inspection, it appears that the structure of " Anand Sagar Co.Op.Hsg.Soc.Ltd.Nashik " is in Average condition and the future life can be reasonably takes under normal condition and with proper periodic repairs & maintenance is about 18 years.

General Information:

A.	1	Introduction
1	Name of Building	" Anand Sagar Co.Op.Hsg.Soc.Ltd.Nashik "
2	Property Address	Residential Flat No.16,Third Floor "Anand Sagar Co.Op.Hsg.Soc.Ltd.Nashik",Survey No.541A- 1+5 41A /4/3, Final Plot No.198, Plot No.3, TP Scheme No.I,Behind Kit Kat Wining Machines,ND Patel Road, Mohan Nagar,Village- Nashik, Taluka & District - Nashik, PIN Code - 422 001, State - Maharashtra, Country - India
3	Type of Building	Residential
4	No. of Floors	Ground + 3 rd Upper Floors
5	Whether stilt / podium / open parking provided	Covered Car Parking
6	Type of Construction Think In	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	6' thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	1981 (As per Occupancy Certificate)
11	Present age of building	42 Years
12	Residual age of the building	18 years Subject to proper, preventive periodic maintenance & structural repairs.
13	No. of Flats	4 Flats on Third Floor
14	Methodology adopted	As per visual site inspection

Nashik: 4, 1st Floor, Madhusha Elite, Vrundavan Nagar, Jatra-Nandur Naka Link Road, Adgaon, Nashik - 422 003, (M.S.) E-mail: nashik@vastukala.org, Tel.: +91 253 4068262 / 9890380564

Our Pan India Presence at :

↑ Thane

P Delhi NCR P Nashik

Aurangabad
Pune Nanded

Rajkot ♀ Raipur Ahmedabad 9 Jaipur

Regd. Office: B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Andheri (East), Mumbai - 400 072, (M.S.), INDIA

B.	External Observation of the Building		
1	Plaster	Average	
2	Chajjas	Average	
3	Plumbing	Average	
4	Cracks on the external walls	Not Found	
5	Filling cracks on the external walls	Not Found	
6	Cracks on columns & beams	Not Found	
7	Vegetation	Not Found	
8	Leakages of water in the drainage pipes or water pipes	Not Found	
9	Dampness external in the wall due to leakages	Not Found	
10	Any other observation about the condition of external side of the building	The external condition of the structure is in Average condition	
C	Internal Observation of the common areas of the building and captioned premises		
1	Beams (Cracks & Leakages)	Not found	
2	Columns (Cracks & Leakages)	Not found	
3	Ceiling (Cracks & Leakages)	Not found	
4	Leakages inside the property	Not Found	
5	Painting inside the property	Average	
6	Maintenance of staircase & cracks	Average	

D	Common Observation		
1	Structural Audit of the Building Under Bye – Laws No. 77 of the Model Bye Laws (Co- Operative Societies Act / Rules)	As per bye Laws No. 77 of Co-Op. Societies bye Laws under the Act the society shall conduct a Structural Audit of the building of the society as follows	
2	Remark	- / · · · / · · · · · · · · · · · · · ·	

Conclusion

The captioned Flat is having Ground floor which are constructed in year 1981 (As per Occupancy Certificate). Estimated future life under present circumstances is about 18 years' subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 22.12.2023 reveals no structural damage or deterioration to the building. The building as well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & Average structural repairs.

Our Observations about the structure are given above.

The above assessment is based on visual inspection only.

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Sharadkumar Digitally signed by Sharadkumar B. Chalikwar DN: cn=Sharadkumar B. Chalikwar, DN: cn=Sharadkumar B. Chalikwar, B. Chalikwar

o=Vastukala Consultants (I) Pvt. Ltd., ou=CMD, email=cmd@vastukala.org

Director

Sharadkumar B. Chalikwar

Govt. Reg. Valuer Chartered Engineer (India)

Reg. No. (N) CCIT/1-14/52/2008-09

Encl: Valuation report...





Actual Site Photographs















