

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8a4"
    },
    "type": "CREDITOFFICER",
    "_id": "64cb46df0faf29427aca399a",
    "firstName": "Rajesh ",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "9975642826",
    "email": "cord2.racpcandheri@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "3000000",
    "discussWithPerson": "Rajesh ",
    "expectedFees": 1500,
    "quotedAmount": ""
  },
  "organization": {
```

```
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8a4",
  "branchCode": "000111",
  "type": "BRANCH",
  "name": "RACPC Andheri (East)",
  "email": "cord2.racpcandheri@sbi.co.in",
  "mobileNo": "02228389765/69",
  "alternateMobileNo": "",
  "address": "1st Floor, UTI Building, Plot No. 12, MIDC, Road No. 9, Behind Tunga
Paradise Hotel, Andheri (East), Mumbai - 400 093, State - Maharashtra, Country -
India.",
  "ledgerName": "STATE BANK OF INDIA - RACPC ANDHERI",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "value": "Residential",
  "label": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60af6ae22ffdf65bcd65861d",
  "role": "PICKUPPERSON",
  "firstName": "Sunil",
  "email": "misalsunil87@gmail.com",
  "lastName": "Misal",
  "mobileNo": "8422982721",
  "shortName": "SM",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "64e5a649daae6a1c98101989",
  "role": "SITEENGINEER",
  "firstName": "Sameer",
  "email": "sameeryp2010@gmail.com",
  "lastName": "Parab",
  "mobileNo": "8291009567",
  "designation": "Site Engineer",
  "shortName": "Sameer",
  "workWithDocumentMaker": "62ea09ea4e679b264caf07d7"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "657157794999312746cdc402",
  "role": "MAKER + RATE VERFIER",
  "firstName": "Komal",
  "email": "pawarkomal580@gmail.com",
  "lastName": "pawar",
  "mobileNo": "7447457799",
```

```
"designation": "Rate Verifier +Maker",
"shortName": "KP",
"workWithDocumentMaker": "60092304a16fab0f2af9b0c2"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Shyma_Photo.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        }
      },
      {
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    }
  }
]
```

```
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.20122819772021",
  "longitude": "73.11151772104452"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.11151772104452,
    19.20122819772021
  ]
},
"siteVisit": {
```

```
"siteVisitStatus": true,
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2024-01-11",
    "remark": ""
  },
  {
    "status": "COMPLETED",
    "dateTime": "2024-01-11",
    "remark": ""
  },
  {
    "status": "COMPLETED",
    "dateTime": "2024-01-11",
    "remark": ""
  }
],
"schedule": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
```

```
"key": "village",
"value": "Davdi",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "1",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "25",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane ",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan ",
  "label": true
},
}
```

```
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Angelica - MHADA",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Kalyan Shill Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
```



```
"value": "",
"label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Regency Anantam Phase 5",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "101/3A, 3B, 3C, 54//1 & 97/1",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
```

```
"status": true,
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "104",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
```

```
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 421203",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Dombivali (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_/_Glass_Door",
    "label": "Teak Wood / Glass Door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
}
},
"general": {
  "ownership": {
```

```
"value": "Sole_Ownership",
"label": "Sole Ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "Kalyan_Dombivali_Municipal_Corporation",
"label": "Kalyan Dombivali Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "Internal Road ",
"west": "Open Plot ",
"south": "Open Plot ",
"east": "Building No. 24"
},
"asPerDocumentAgreement": {
"north": "Details not available ",
"west": "Details not available ",
"south": "Details not available ",
"east": "Details not available "
},
"unitBoundaries": {
"asPerActual": {
"north": "Open to Sky ",
"east": "Flat No. 105",
"south": "Flat No. 101",
"west": "Flat No. 103"
},
"asPerDocument": {
"north": "Details not available ",
"east": "Details not available ",
"south": "Details not available ",
"west": "Details not available "
},
"setDisplay": false,
"title": "Boundaries of The Flat"
```

```
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved plan not provided. ",
"approvePlanVerified": "N.A. ",
"empanelledOfApprovePlan": "N.A."
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "52100",
  "landRate": "4100",
  "igrImage": "cases/659f8fb102c44c777bafefe9/igr_1705034652553_Image.png",
  "squareMeterGuideLineRate": "52100.00",
  "squareFeetGuideLineRate": "4840.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "0",
  "rate": "52100.00",
  "squareMeterGuideLineRate": "52100.00",
  "squareFeetGuideLineRate": "4840.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "monthlyRent": "8000",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available "
```

```
"electricityServiceConnectionNo": "Details not available ",
"meterCardHolderName": "Details not available ",
"undividedAreaOfLandAsPerSaleDeed": "Details not available ",
"floorSpaceIndex": "As per KDMC Norms ",
"tenantName": "",
"maintenanceOfFlat": "Building under construction "
},
"marketability": {
  "marketabilityList": {
    "value": "Average",
    "label": "Average"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developing Area ",
  "negativeFactorsOfAffectMarketValue": "No "
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Covered Parking ",
  "constructionWorkStatus": {
    "value": "InProgress",
    "label": "Under Construction"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "",
    "month": "1",
    "year": "2024",
    "fullDate": "1/1/2024"
```

```
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
```

```
"value": "UnderConstruction",
"label": "Building Under Construction"
},
"maintenanceIssues": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"visibleDamageInBuilding": {
"value": "0",
"label": "No"
},
"systemOfAirConditioning": {
"value": "Information_not_available",
"label": "Information not available"
},
"provisionOfFirefighting": {
"value": "Information_not_available",
"label": "Information not available"
},
"groundStilt": {
"value": "stilt",
"label": "Stilt"
},
"yearOfConstructionAsPer": {
"value": "as_per_site_information",
"label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "30",
"flatFloorNo": "1",
"noOfLifts": "3",
"noOfDwellingUnitsInBuilding": "8"
},
"finalPlinthArea": {
"area": "515.38",
"areaType": "Built Up",
"measurementType": "Sq. Ft.",
"areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
```



```
"routeMapDetail": {
  "routeStation": {
    "value": "Railway_Station",
    "label": "Railway Station"
  },
  "routeMapImg": "cases/659f8fb102c44c777bafefe9/
routeMap_1705056040754_Image.png",
  "routeLat": "19.200703",
  "routeLng": "73.118168",
  "stationName": "Dombivali ",
  "routeDistance": "4.3 Km"
},
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": true,
  "finallatLng": true
},
"locationMapImg": [
  {
    "id": "1faur",
    "name": "1faur",
    "image": "cases/659f8fb102c44c777bafefe9/
routeMap_1705055946097_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
```

```
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "3861000.00",
"finalValue": "3861000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Sat Jan 13 2024 10:30:18 GMT+0530 (India Standard Time)",
  "number": "2304503",
  "dayCount": "3",
  "monthCount": "205",
  "generatedBy": "60eeaeddf3dd69653a581316"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
```

```
"isHideFloor": false,
"status": true
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "32",
  "percentage": "40",
  "isHideFloor": false,
  "status": true
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "32",
  "percentage": "7.00",
  "isHideFloor": false,
  "status": true
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "32",
  "percentage": "7.00",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "32",
  "percentage": "3.50",
  "isHideFloor": false,
  "status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "32",
  "percentage": "3.50",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "32",
  "percentage": "2.50",
  "isHideFloor": false,
  "status": true
},
"window": {
```

```
"label": "Window",
"floorsCompleted": "32",
"percentage": "2.50",
"isHideFloor": false,
"status": true
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "32",
"percentage": "10.00",
"isHideFloor": false,
"status": true
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "32",
"percentage": "1.50",
"isHideFloor": false,
"status": true
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "32",
"percentage": "1.50",
"isHideFloor": false,
"status": true
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "32",
"percentage": "5.00",
"isHideFloor": false,
"status": true
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "2",
"percentage": "1.33",
"isHideFloor": false,
"status": true
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
```

```
"status": true
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "95.33",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "2494439.00",
  "selectedBuildUpValue": "515.38",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "659fdaa602c44c777bb12660",
      "name": "externalimg_1704974836186_1704974945055_image_7.jpeg",
      "path": "cases/659f8fb102c44c777bafefe9/
externalimg_1704974836186_1704974945055_image_7.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "659fdaa602c44c777bb12661",
      "name": "externalimg_1704974836286_1704974945055_image_8.jpeg",
      "path": "cases/659f8fb102c44c777bafefe9/
externalimg_1704974836286_1704974945055_image_8.jpeg",
      "orientation": "landscape"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
```

```
    "_id": "659fdaa602c44c777bb12662",
    "name": "externallmg_1704974836466_1704974945055_image_9.jpeg",
    "path": "cases/659f8fb102c44c777bafefe9/
externallmg_1704974836466_1704974945055_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "659fdaa602c44c777bb12664",
    "name": "externallmg_1704975010249_1704975124598_image_0.jpeg",
    "path": "cases/659f8fb102c44c777bafefe9/
externallmg_1704975010249_1704975124598_image_0.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "659fdaa602c44c777bb12659",
    "name": "Living Room",
    "path": "cases/659f8fb102c44c777bafefe9/
externallmg_1704974834089_1704974945055_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "659fdaa602c44c777bb1265e",
    "name": "Living Room",
    "path": "cases/659f8fb102c44c777bafefe9/
externallmg_1704974835441_1704974945055_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "659fdaa602c44c777bb1265f",
    "name": "Living Room",
    "path": "cases/659f8fb102c44c777bafefe9/
externallmg_1704974835860_1704974945055_image_6.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
```

```
"min": "8539",
"max": "10545"
},
"builtUpRateRange": {
  "min": "7116",
  "max": "8788"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
```



```
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "429.48",
"empanelmentNo": [
  "SME/TCC/2021-22/86/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentId": [],
"_id": "659f8fb102c44c777bafefe9",
"ownerName": "Ashwini Sachin Kuchekar ",
"ownerPhoneNo": "9220846508",
"appAddress": "Flat- 104 1 floor Bldg no 25 Village Davdi Thane ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae126daa6d152c1801b39b",
      "label": "Copy of Offer Letter"
    }
  }
]
```

```
    },
    "inputs": {
      "documentDate": "20/07/2023"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "294104",
    "path": "cases/659f8fb102c44c777bafefe9/
document_1704955670773_1704955781329_Ashwini_Sachin_kuchekar.pdf",
    "fileName":
"document_1704955670773_1704955781329_Ashwini_Sachin_kuchekar.pdf"
  },
  {
    "documentType": {
      "value": "60af71b42ffdf65bcd65862a",
      "label": "Intimation Letter"
    },
    "inputs": {
      "documentDate": "17/05/2023"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1705055090871_document_1704955670773_17049557813
29_Ashwini_Sachin_kuchekar.pdf",
    "path": "cases/659f8fb102c44c777bafefe9/document_1705055090871_document_1
704955670773_1704955781329_Ashwini_Sachin_kuchekar.pdf",
    "id": "162820",
    "uploadedBy": "657157794999312746cdc402",
    "createdAt": "Fri Jan 12 2024 15:54:53 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "006288",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "255770",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Jan 11 2024 12:20:25 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Ashwini Sachin Kuchekar ",
    "phone": "9220846508",
    "ownershipShare": ""
  }
]
```

```
"email": "",
  "id": "495607"
},
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "938984",
    "name": "Living Room",
    "length": "9.25",
    "length1": "9",
    "length2": "3",
    "width": "14.67",
    "width1": "14",
    "width2": "8",
    "totalArea": "135.67",
    "images": [],
    "extraAreas": [],
    "finalArea": "135.67"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Toilet",
    "length": "6.67",
    "length1": "6",
    "length2": "8",
    "width": "4.00",
    "width1": "4",
    "width2": "0",
    "totalArea": "26.67",
    "images": [],
    "extraAreas": [],
    "finalArea": "26.67"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Kitchen",
  "length": "7.75",
  "length1": "7",
  "length2": "9",
  "width": "7.75",
  "width1": "7",
  "width2": "9",
  "totalArea": "60.06",
  "images": [],
  "extraAreas": [],
  "finalArea": "60.06"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "8.67",
  "length1": "8",
  "length2": "8",
  "width": "9.33",
  "width1": "9",
  "width2": "4",
  "totalArea": "80.89",
  "images": [],
  "extraAreas": [],
  "finalArea": "80.89"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Passage",
  "length": "2.08",
  "length1": "2",
  "length2": "1",
  "width": "5.00",
  "width1": "5",
  "width2": "0",
```

```
"totalArea": "10.42",
"images": [],
"extraAreas": [],
"finalArea": "10.42"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "6.67",
  "length1": "6",
  "length2": "8",
  "width": "4.08",
  "width1": "4",
  "width2": "1",
  "totalArea": "27.22",
  "images": [],
  "extraAreas": [],
  "finalArea": "27.22"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Passage",
  "length": "9.33",
  "length1": "9",
  "length2": "4",
  "width": "3.17",
  "width1": "3",
  "width2": "2",
  "totalArea": "29.56",
  "images": [],
  "extraAreas": [],
  "finalArea": "29.56"
}
],
"otherComposition": [
  {
    "name": {
      "label": "Duct",
```

```
    "value": "Duct"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length1": "4",
  "length2": "3",
  "length": "4.25",
  "width1": "5",
  "width2": "9",
  "width": "5.75",
  "totalArea": "24.44",
  "percentageBeforeTotal": "24.44",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "24.44"
},
{
  "name": {
    "label": "Duct",
    "value": "Duct"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "length1": "3",
  "length2": "0",
  "length": "3.00",
  "width1": "4",
  "width2": "5",
  "width": "4.42",
  "totalArea": "13.25",
  "percentageBeforeTotal": "13.25",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "13.25"
},
{
  "toBeAdded": {
    "label": "Carpet",
```

```
    "value": "Carpet"
  },
  "name": {
    "label": "Dry Balcony Area",
    "value": "Dry_Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "length1": "3",
  "length2": "3",
  "length": "3.25",
  "width1": "7",
  "width2": "8",
  "width": "7.67",
  "totalArea": "24.92",
  "percentageBeforeTotal": "24.92",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "24.92"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "length1": "3",
  "length2": "3",
  "length": "3.25",
  "width1": "8",
  "width2": "8",
  "width": "8.67",
  "totalArea": "28.17",
  "percentageBeforeTotal": "28.17",
```

```
"images": [],
"extraAreas": [],
"percentage": "100",
"finalArea": "28.17"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "length1": "3",
  "length2": "9",
  "length": "3.75",
  "width1": "9",
  "width2": "3",
  "width": "9.25",
  "totalArea": "34.69",
  "percentageBeforeTotal": "34.69",
  "images": [],
  "extraAreas": [],
  "percentage": "100",
  "finalArea": "34.69"
}
],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae126daa6d152c1801b39b",
      "label": "Copy of Offer Letter"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "169379",
    "selectAreaTypeDocument": "Carpet",
```



```
"totalAreaDocument": "429.48",
"squareMeterArea": "39.9",
"docFinalBuiltUp": "515.376",
"docFinalBuiltUpSquareMeter": "47.879999999999995",
"docBuiltupPercentage": "20",
"docSaleablePercentage": "10",
"docFinalSaleable": "566.9136",
"docFinalSaleableSquareMeter": "52.667999999999999"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "65a0c3a502c44c777bb195cb",
  "property": "Residential Flat",
  "area": "431",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "square_yards",
  "expectedPrice": "4370000",
  "expectedRate": "10139.21",
  "builtUpExpectedRate": "8449.34",
  "image": "cases/659f8fb102c44c777bafefe9/indicator_1705034547159_Image.png",
  "squareMeter": "40.04",
  "id": "672600"
},
{
  "printlnReport": true,
  "_id": "65a0c3a502c44c777bb195cc",
  "property": "Residential Flat",
  "area": "431",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Housing.Com",
  "expectedPrice": "4545000",
  "expectedRate": "10545.24",
  "builtUpExpectedRate": "8787.70",
  "image": "cases/659f8fb102c44c777bafefe9/indicator_1705034573469_Image.png",
  "squareMeter": "40.04",
  "id": "367039"
},
}
```

```
{
  "printlnReport": true,
  "_id": "65a0c3a502c44c777bb195cd",
  "property": "Residential Flat",
  "area": "527",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "magic_bricks",
  "expectedPrice": "4500000",
  "expectedRate": "8538.90",
  "builtUpExpectedRate": "7115.75",
  "image": "cases/659f8fb102c44c777bafefe9/indicator_1705034598676_Image.png",
  "squareMeter": "48.96",
  "id": "491057"
},
{
  "printlnReport": true,
  "_id": "65a0c3a502c44c777bb195ce",
  "property": "Residential Flat",
  "area": "527",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "magic_bricks",
  "expectedPrice": "4690000",
  "expectedRate": "8899.43",
  "builtUpExpectedRate": "7416.19",
  "image": "cases/659f8fb102c44c777bafefe9/indicator_1705034614602_Image.png",
  "squareMeter": "48.96",
  "id": "949830"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659fdaa602c44c777bb12659",
    "name": "externalImg_1704974834089_1704974945055_image_0.jpeg",
    "path": "cases/659f8fb102c44c777bafefe9/
externalImg_1704974834089_1704974945055_image_0.jpeg",
    "orientation": "portrait"
  },
  {
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659fdaa602c44c777bb1265a",
    "name": "externallmg_1704974834256_1704974945055_image_1.jpeg",
    "path": "cases/659f8fb102c44c777bafefe9/
externallmg_1704974834256_1704974945055_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659fdaa602c44c777bb1265b",
    "name": "externallmg_1704974834554_1704974945055_image_2.jpeg",
    "path": "cases/659f8fb102c44c777bafefe9/
externallmg_1704974834554_1704974945055_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659fdaa602c44c777bb1265c",
    "name": "externallmg_1704974835188_1704974945055_image_3.jpeg",
    "path": "cases/659f8fb102c44c777bafefe9/
externallmg_1704974835188_1704974945055_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659fdaa602c44c777bb1265d",
    "name": "externallmg_1704974835201_1704974945055_image_4.jpeg",
    "path": "cases/659f8fb102c44c777bafefe9/
externallmg_1704974835201_1704974945055_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659fdaa602c44c777bb1265e",
    "name": "externallmg_1704974835441_1704974945055_image_5.jpeg",
    "path": "cases/659f8fb102c44c777bafefe9/
externallmg_1704974835441_1704974945055_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "659fdaa602c44c777bb1265f",
    "name": "externallmg_1704974835860_1704974945055_image_6.jpeg",
    "path": "cases/659f8fb102c44c777bafefe9/
externallmg_1704974835860_1704974945055_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659fdaa602c44c777bb12660",
    "name": "externallmg_1704974836186_1704974945055_image_7.jpeg",
    "path": "cases/659f8fb102c44c777bafefe9/
externallmg_1704974836186_1704974945055_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659fdaa602c44c777bb12661",
    "name": "externallmg_1704974836286_1704974945055_image_8.jpeg",
    "path": "cases/659f8fb102c44c777bafefe9/
externallmg_1704974836286_1704974945055_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659fdaa602c44c777bb12662",
    "name": "externallmg_1704974836466_1704974945055_image_9.jpeg",
    "path": "cases/659f8fb102c44c777bafefe9/
externallmg_1704974836466_1704974945055_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659fdaa602c44c777bb12663",
    "name": "externallmg_1704974836595_1704974945055_image_10.jpeg",
    "path": "cases/659f8fb102c44c777bafefe9/
externallmg_1704974836595_1704974945055_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "659fdaa602c44c777bb12664",
    "name": "externallmg_1704975010249_1704975124598_image_0.jpeg",
    "path": "cases/659f8fb102c44c777bafefe9/
externallmg_1704975010249_1704975124598_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "659fdaa602c44c777bb12665",
    "name": "externallmg_1704975010489_1704975124598_image_1.jpeg",
    "path": "cases/659f8fb102c44c777bafefe9/
externallmg_1704975010489_1704975124598_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "659fdaa602c44c777bb12666",
    "name": "externallmg_1704974796408_1704974910766_image_0.jpeg",
    "path": "cases/659f8fb102c44c777bafefe9/
externallmg_1704974796408_1704974910766_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "659fdaa602c44c777bb12667",
    "name": "externallmg_1704974796621_1704974910766_image_1.jpeg",
    "path": "cases/659f8fb102c44c777bafefe9/
externallmg_1704974796621_1704974910766_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "659fdaa602c44c777bb12668",
    "name": "externallmg_1704974796807_1704974910766_image_2.jpeg",
    "path": "cases/659f8fb102c44c777bafefe9/
externallmg_1704974796807_1704974910766_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "659fdaa602c44c777bb12669",
```

```
    "name": "externallmg_1704974796873_1704974910766_image_3.jpeg",
    "path": "cases/659f8fb102c44c777bafefe9/
externallmg_1704974796873_1704974910766_image_3.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "AGR.pdf",
    "filename": "1705034674095_AGR.pdf",
    "path": "cases/659f8fb102c44c777bafefe9/
processingDocuments/1705034674095_AGR.pdf",
    "size": "3213671",
    "createdAt": "Fri Jan 12 2024 10:14:34 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "externallmg_1704974796408_1704974910766_image_0.jpeg",
    "filename":
"1705034674182_externallmg_1704974796408_1704974910766_image_0.jpeg",
    "path": "cases/659f8fb102c44c777bafefe9/processingDocuments/1705034674182_e
xternallmg_1704974796408_1704974910766_image_0.jpeg",
    "size": "754656",
    "createdAt": "Fri Jan 12 2024 10:14:34 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "externallmg_1704974796621_1704974910766_image_1.jpeg",
    "filename":
"1705034674221_externallmg_1704974796621_1704974910766_image_1.jpeg",
    "path": "cases/659f8fb102c44c777bafefe9/processingDocuments/1705034674221_e
xternallmg_1704974796621_1704974910766_image_1.jpeg",
    "size": "744838",
    "createdAt": "Fri Jan 12 2024 10:14:34 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "externallmg_1704974796807_1704974910766_image_2.jpeg",
    "filename":
"1705034674277_externallmg_1704974796807_1704974910766_image_2.jpeg",
    "path": "cases/659f8fb102c44c777bafefe9/processingDocuments/1705034674277_e
xternallmg_1704974796807_1704974910766_image_2.jpeg",
    "size": "297465",
    "createdAt": "Fri Jan 12 2024 10:14:34 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  }
]
```

```
    },
    {
      "originalName": "Summary New=ASHWINI.xlsx",
      "filename": "1705034674314_Summary_NewASHWINI.xlsx",
      "path": "cases/659f8fb102c44c777bafefe9/
processingDocuments/1705034674314_Summary_NewASHWINI.xlsx",
      "size": "3743687",
      "createdAt": "Fri Jan 12 2024 10:14:34 GMT+0530 (India Standard Time)",
      "uploadedBy": "60eeaeddf3dd69653a581316"
    }
  ],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [],
  "createdAt": "2024-01-11T06:50:25.794Z",
  "updatedAt": "2024-01-13T05:16:36.984Z",
  "__v": 0,
  "invoiceId": "659f8fb102c44c777bafeff2",
  "assignmentType": {
    "value": "Retail",
    "label": "Retail"
  },
},
"fullAddress": "Residential Flat No. 104, 1st Floor, Building No 25, Angelica - MHADA,
Regency Anantam Phase 5, Kalyan Shill Road, Village - Davdi, Dombivali (East),
Taluka - Kalyan , District - Thane , PIN - 421203, State - Maharashtra, India",
"updatedBy": "60eeaeddf3dd69653a581316",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Mr. Sanjeev Verma ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Sales Person",
"siteVisitContactNo": "7977260126",
"buildingServicesRate": "2500",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Copy of Offer Letter",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 429.48",
"flatRate": "9000",
"landOtherRate": "6500",
"shopDetails": {
```

```

"typeOfShops": {
  "label": "Independent Building",
  "value": "Independent_Building"
},
"roadFacing": false,
"mall": false
},
"briefDescOfProperty": "1 Bedroom + Living Room + Kitchen + 2 Toilet + 2 Passage",
"carpetTotal": "370.49",
"otherCarpetTotal": "125.47",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "87.78",
"otherCompositionSaleableTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "504.10",
"finalCarpetArea": "458.27",
"finalSalableArea": "554.51",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "10",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
}
}

```

Name	Length	Width	Total
Composition :			
Living Room	9'3"	14'8"	135.67

Toilet	6'8"	4'0"	26.67
Kitchen	7'9"	7'9"	60.06
Bedroom	8'8"	9'4"	80.89
Passage	2'1"	5'0"	10.42
Toilet	6'8"	4'1"	27.22
Passage	9'4"	3'2"	29.56
Other Composition :			
Duct	4'3"	5'9"	24.44
Duct	3'0"	4'5"	13.25
Dry Balcony Area	3'3"	7'8"	24.92
Balcony Area	3'3"	8'8"	28.17
Balcony Area	3'9"	9'3"	34.69