

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7fb"
    },
    "type": "CREDITOFFICER",
    "_id": "64d1d9dad9f3034f301dcff",
    "firstName": "Prabhat Bhajbai",
    "lastName": "Bhajbai",
    "mobileNo": "",
    "workMobileNo": "9820021086",
    "email": "Prabhat@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "11054367",
    "discussWithPerson": "Prabhat Bhajbai",
    "expectedFees": 5527.1835,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7fb",
  "branchCode": "000068",
  "type": "BRANCH",
  "name": "RBO Sanpada",
  "email": "sme.navimum@sbi.co.in",
  "mobileNo": "022-27759215",
  "alternateMobileNo": "",
  "address": "SMEC VASHI, E/202, 2nd Floor, Sanpada Rly. Station Complex, Navi
Mumbai - 400 705, State - Maharashtra, Country - India.\n\n",
  "ledgerName": "STATE BANK OF INDIA - RBO SANPADA",
  "fax": "022-27752206",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "60b7189d2ffdf65bcd65882b",
  "role": "PICKUPPERSON",
  "firstName": "Ravindra",
  "email": "ravindrakasare186@gmail.com",
  "lastName": "Kasare",
  "mobileNo": "9167204055",
  "shortName": "RBK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60b7189d2ffdf65bcd65882b\\
\\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc575ece84bf289ba9e82d",
  "role": "SITEENGINEER",
  "firstName": "Deepak ",
  "email": "daksh7831@gmail.com",
  "lastName": "Jain ",
  "mobileNo": "9022815908",
  "designation": "",
  "shortName": "DJ",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordinatiion",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
  "mobileNo": "9529385821",
  "designation": ""
```

```
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordinatiion",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
        "value": "FIIV",
```

```
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.178094268697592",
  "longitude": "72.85021710867797"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.85021710867797,
    19.178094268697592
  ]
}
},
```

```
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "24/01/2024 10:50 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-27",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
```

```
"value": "Pagadi Goregaon ",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "19",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban ",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Malad (East)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
```

```
"status": false,
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Tower - 28",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Haji Bapu Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Govind Nagar",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "E",
```



```
"label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Phase - I",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "151, 151 & Hissa No. 1(Part), 5(Part)",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "19, 19/1 to 67, 20 & 20/1 to 121",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
```

```
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "1904",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
}
```

```
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 097",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows_with_M._S._Grills",
    "label": "Powder coated Aluminum sliding windows with M. S. Grills"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering_+_POP_Finish",
    "label": "Cement Plastering + POP Finish"
  }
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
```

```
"label": "Joint Ownership"
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "Slum_Rehabilitation_Authority",
  "label": "Slum Rehabilitation Authority"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Om Heights Building ",
  "west": "Under Construction Building ",
  "south": "Chawl Area ",
  "east": "Haji Bapu Road"
},
"asPerDocumentAgreement": {
  "north": "Details not available ",
  "west": "Details not available ",
  "south": "Details not available ",
  "east": "Details not available "
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Details not available ",
    "east": "Details not available ",
    "south": "Details not available ",
    "west": "Details not available "
  },
  "asPerDocument": {
    "north": "Details not available ",
    "east": "Details not available ",
    "south": "Details not available ",
    "west": "Details not available "
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
```

```
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received may be assumed
that the construction is as per sanctioned plan. \n\n",
"approvePlanVerified": "N.A",
"empanelledOfApprovePlan": "N.A "
},
"compositeRate": {
"remark": "",
"depreciationPercentage": "0",
"depreciationRatioOfBuilding": "",
"salvageValue": "",
"buildingServicesDepreciatedRate": "0",
"depreciatedCostOfConstruction": "27000.00",
"depreciatedBuildingRate": "3000"
},
"igrRate": {
"propertyName": "Residential Flat",
"rate": "122730",
"landRate": "50430",
"igrImage": "cases/65b0978d4817a543416c5d43/igr_1706502858247_Image.png",
"squareMeterGuideLineRate": "135003.00",
"squareFeetGuideLineRate": "12542.00"
},
"igrFinalRate": {
"floorRatePercentage": "10",
"depreciationPercentage": "0",
"rate": "122730.00",
"squareMeterGuideLineRate": "135003.00",
"squareFeetGuideLineRate": "12542.00"
},
"outgoingDetail": {
"areaStatusList": {
"value": "Medium",
"label": "Medium"
},
"propertyTypeOfUseList": {
"value": "Residential_Purpose",
"label": "Residential Purpose"
},
"propertyOccupiedByList": {
"value": "Vacant",
"label": "Vacant"
},
"monthlyRent": "N.A",
"assessmentNo": "Details not available ",
"taxPaidHolderName": "Details not available ",
```

```
"taxAmount": "Details not available ",
"electricityServiceConnectionNo": "Details not available ",
"meterCardHolderName": "Details not available ",
"undividedAreaOfLandAsPerSaleDeed": "Details not available ",
"floorSpaceIndex": "As per SRA norms ",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Along with One Car Parking Space ",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2023",
```

```
"fullDate": "1/1/2023"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
}
```

```
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "1",
"totalLifeBuilding": "60",
"estimatedAge": "59",
"noOfBasement": "1",
"noOfPodium": "2",
"noOfAmenityFloors": "",
"noOfFloors": "21",
"flatFloorNo": "19",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "680.90",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
```



```
"routeMap": {
  "routeMapDetail": {
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    },
    "routeMapImg": "cases/65b0978d4817a543416c5d43/
routeMap_1706510930975_Image.png",
    "routeLat": "19.177722",
    "routeLng": "72.850167",
    "stationName": "Malad ",
    "routeDistance": "1.00 Km. "
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "fzq7r",
      "name": "fzq7r",
      "image": "cases/65b0978d4817a543416c5d43/
routeMap_1706510827814_Image.png"
    }
  ]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
```

```
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "16713000.00",
"finalValue": "16713000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Mon Jan 29 2024 14:24:13 GMT+0530 (India Standard Time)",
  "number": "2304711",
  "dayCount": "8",
  "monthCount": "413",
  "generatedBy": "64cde526dc9f3034f3fefa49"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": ""
  }
}
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "8539848.00",
  "selectedBuildUpValue": "680.90",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65b721c0e1e7bf61f3d0ce34",
      "name": "externallmg_1706500543892_IMG_20240127_121558.jpg",
      "path": "cases/65b0978d4817a543416c5d43/
externallmg_1706500543892_IMG_20240127_121558.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": [
    {
      "status": false,
      "_id": "65b721c0e1e7bf61f3d0ce28",
      "name": "Living Room",
      "path": "cases/65b0978d4817a543416c5d43/
externallmg_1706500543830_IMG_20240127_115734.jpg",
      "orientation": "portrait"
    }
  ]
}
```

```
    },
    {
      "status": false,
      "_id": "65b721b1e1e7bf61f3d0cddc",
      "name": "Living Room",
      "path": "cases/65b0978d4817a543416c5d43/
externallmg_1706500529386_IMG_20240127_115723.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "65b721c0e1e7bf61f3d0ce29",
      "name": "Living Room",
      "path": "cases/65b0978d4817a543416c5d43/
externallmg_1706500543836_IMG_20240127_115740.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "65b721c0e1e7bf61f3d0ce2a",
      "name": "Living Room",
      "path": "cases/65b0978d4817a543416c5d43/
externallmg_1706500543845_IMG_20240127_115744.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "65b721c0e1e7bf61f3d0ce2b",
      "name": "Living Room",
      "path": "cases/65b0978d4817a543416c5d43/
externallmg_1706500543851_IMG_20240127_115751.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "65b721b1e1e7bf61f3d0cdd8",
      "name": "Living Room",
      "path": "cases/65b0978d4817a543416c5d43/
externallmg_1706500529353_IMG_20240127_115616.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "65b721c0e1e7bf61f3d0ce36",
      "name": "Living Room",
      "path": "cases/65b0978d4817a543416c5d43/
externallmg_1706500543902_IMG_20240127_121602.jpg",
```

```
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65b721c0e1e7bf61f3d0ce32",
    "name": "Living Room",
    "path": "cases/65b0978d4817a543416c5d43/
externallmg_1706500543883_IMG_20240127_121421.jpg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "22719",
    "max": "29358"
  },
  "builtUpRateRange": {
    "min": "20655",
    "max": "24465"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
finalValuationArea": "619.00",
empanelmentNo": [
"SME/TCC/2021-22/86/3"
],
isAdvanceInvoice": false,
```

```
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentId": [],
"_id": "65b0978d4817a543416c5d43",
"ownerName": "Mrs. Snehal Shankar Dalvi & Mr. Shankar Jagannath Dalvi ",
"ownerPhoneNo": "9869068900",
"appAddress": "flat no. 1904 . 19 th floor. E wing Tower no. 28 Haji Bapu Road malad
E ",
"remark": "Bankar Alka madam ",
"documents": [
{
  "documentType": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "inputs": {
    "documentDate": "30/01/2020",
    "from": {
      "value": "Promoter",
      "label": "Promoter"
    },
    "Promoter": "M/s. Shiv Shakti Builders & Developers",
    "to": {
      "value": "Purchasers",
      "label": "Purchasers"
    },
    "Purchasers": "Mrs. Snehal Shankar Dalvi & Mr. Shankar Jagannath Dalvi ",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "1234 / 2020"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "511516",
  "path": "cases/65b0978d4817a543416c5d43/
document_1706071922569_1706072040997_Sbi_Rbo_sanpada_.pdf",
  "fileName": "document_1706071922569_1706072040997_Sbi_Rbo_sanpada_.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
}
```

```
"inputs": {
  "documentDate": "18/10/2023",
  "nameOfApprovingAuthority": {
    "value": "Slum_Rehabilitation_Authority_(SRA)",
    "label": "Slum Rehabilitation Authority (SRA)"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "SRA / ENG / 3249 / PN / PL / AP"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1706509378387_document_1706071922569_17060720409
97_Sbi_Rbo_sanpada_.pdf",
"path": "cases/65b0978d4817a543416c5d43/document_1706509378387_document
_1706071922569_1706072040997_Sbi_Rbo_sanpada_.pdf",
"id": "706603",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Mon Jan 29 2024 11:52:58 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "03/09/2019",
    "nameOfApprovingAuthority": {
      "value": "Slum_Rehabilitation_Authority_(SRA)",
      "label": "Slum Rehabilitation Authority (SRA)"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "SRA / ENG / 3249 / PN / PL / AP"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1706509437551_1706502876361_snehal_Dalvi_SBI_sanpa
da_alka_24124_1.pdf",
  "path": "cases/65b0978d4817a543416c5d43/document_1706509437551_17065028
76361_snehal_Dalvi_SBI_sanpada_alka_24124_1.pdf",
  "id": "549491",
```

```
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Mon Jan 29 2024 11:53:58 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "22/08/2017",
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "P51800009511"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1706509482388_1706502876361_snehal_Dalvi_SBI_sanpa
da_alka_24124_1.pdf",
"path": "cases/65b0978d4817a543416c5d43/document_1706509482388_17065028
76361_snehal_Dalvi_SBI_sanpada_alka_24124_1.pdf",
"id": "537769",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Mon Jan 29 2024 11:54:42 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "006527",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "375985",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Jan 24 2024 10:22:29 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Snehal Shankar Dalvi & Mr. Shankar Jagannath Dalvi ",
    "phone": "9869068900",
    "ownershipShare": "",
    "email": "",
    "id": "398909"
  }
],
```

```
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "855672",
    "name": "Living Room",
    "length": "9.83",
    "length1": "9",
    "length2": "10",
    "width": "19.75",
    "width1": "19",
    "width2": "9",
    "totalArea": "194.21",
    "images": [],
    "extraAreas": [],
    "finalArea": "194.21"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "1",
    "name": "Passage",
    "length": "11.08",
    "length1": "11",
    "length2": "1",
    "width": "2.83",
    "width1": "2",
    "width2": "10",
    "totalArea": "31.40",
    "images": [],
    "extraAreas": [
      {
        "measurementType": {
          "value": "Square_Feet",
          "label": "Square Feet"
        },
        "_id": "65b74679e1e7bf61f3d15442",
        "name": "Extra ",
        "extraAreaType": "Add",
        "length": "3.25",
```

```
    "length1": "3",
    "length2": "3",
    "width": "2.92",
    "width1": "2",
    "width2": "11",
    "totalArea": "9.48"
  }
],
"finalArea": "40.879999999999995"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bedroom",
  "length": "10.50",
  "length1": "10",
  "length2": "6",
  "width": "9.17",
  "width1": "9",
  "width2": "2",
  "totalArea": "96.25",
  "images": [],
  "extraAreas": [],
  "finalArea": "96.25"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
  "length": "11.25",
  "length1": "11",
  "length2": "3",
  "width": "9.75",
  "width1": "9",
  "width2": "9",
  "totalArea": "109.69",
  "images": [],
  "extraAreas": [],
  "finalArea": "109.69"
},
}
```

```
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Kitchen",
  "length": "10.42",
  "length1": "10",
  "length2": "5",
  "width": "6.92",
  "width1": "6",
  "width2": "11",
  "totalArea": "72.05",
  "images": [],
  "extraAreas": [],
  "finalArea": "72.05"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Toilet",
  "length": "6.50",
  "length1": "6",
  "length2": "6",
  "width": "4.67",
  "width1": "4",
  "width2": "8",
  "totalArea": "30.33",
  "images": [],
  "extraAreas": [],
  "finalArea": "30.33"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "4.67",
  "length1": "4",
  "length2": "8",
```

```
"width": "6.58",
"width1": "6",
"width2": "7",
"totalArea": "30.72",
"images": [],
"extraAreas": [],
"finalArea": "30.72"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "selectAreaTypeDocument": "Carpet",
  "squareMeterArea": "57.51",
  "totalAreaDocument": "619",
  "docBUILTUPPercentage": "10",
  "docFinalBUILTUP": "680.90",
  "docFinalBUILTUPSquareMeter": "63.26",
  "docSaleablePercentage": "",
  "docFinalSaleable": "0.00",
  "docFinalSaleableSquareMeter": "0.00",
  "id": "807842"
}
],
"images": [],
"indicatorArr": [
{
  "printlnReport": true,
  "_id": "65b72ae0e1e7bf61f3d0de37",
  "property": "Residential Flat",
  "area": "618",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "source": "Commonfloor.com",
  "expectedPrice": "16900000",
}
```



```
    "expectedRate": "27346.28",
    "builtUpExpectedRate": "22788.57",
    "image": "cases/65b0978d4817a543416c5d43/
indicator_1706502579671_Image.png",
    "squareMeter": "57.41",
    "id": "979226"
  },
  {
    "printlnReport": true,
    "_id": "65b72ae0e1e7bf61f3d0de38",
    "property": "Residential Flat",
    "area": "436",
    "builtUpPercentage": "20",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Carpet",
    "source": "magic_bricks",
    "expectedPrice": "12800000",
    "expectedRate": "29357.80",
    "builtUpExpectedRate": "24464.83",
    "image": "cases/65b0978d4817a543416c5d43/
indicator_1706502623744_Image.png",
    "squareMeter": "40.51",
    "id": "451200"
  },
  {
    "printlnReport": true,
    "_id": "65b72ae0e1e7bf61f3d0de39",
    "property": "Residential Flat",
    "area": "681",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "sale_Instance",
    "areaType": "Built_Up",
    "source": "Index_no.2",
    "expectedPrice": "14065400",
    "expectedRate": "20654.04",
    "builtUpExpectedRate": "14065400",
    "image": "cases/65b0978d4817a543416c5d43/
indicator_1706502689531_Image.png",
    "squareMeter": "63.27",
    "id": "822593"
  }
],
"externallImages": [
  {
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b721b1e1e7bf61f3d0cdd8",
    "name": "externallmg_1706500529353_IMG_20240127_115616.jpg",
    "path": "cases/65b0978d4817a543416c5d43/
externallmg_1706500529353_IMG_20240127_115616.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b721b1e1e7bf61f3d0cdd9",
    "name": "externallmg_1706500529360_IMG_20240127_115708.jpg",
    "path": "cases/65b0978d4817a543416c5d43/
externallmg_1706500529360_IMG_20240127_115708.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b721b1e1e7bf61f3d0cdda",
    "name": "externallmg_1706500529368_IMG_20240127_115715.jpg",
    "path": "cases/65b0978d4817a543416c5d43/
externallmg_1706500529368_IMG_20240127_115715.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b721b1e1e7bf61f3d0cddb",
    "name": "externallmg_1706500529379_IMG_20240127_115716.jpg",
    "path": "cases/65b0978d4817a543416c5d43/
externallmg_1706500529379_IMG_20240127_115716.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b721b1e1e7bf61f3d0cddc",
    "name": "externallmg_1706500529386_IMG_20240127_115723.jpg",
    "path": "cases/65b0978d4817a543416c5d43/
externallmg_1706500529386_IMG_20240127_115723.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "65b721c0e1e7bf61f3d0ce28",
  "name": "externallmg_1706500543830_IMG_20240127_115734.jpg",
  "path": "cases/65b0978d4817a543416c5d43/
externallmg_1706500543830_IMG_20240127_115734.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b721c0e1e7bf61f3d0ce29",
  "name": "externallmg_1706500543836_IMG_20240127_115740.jpg",
  "path": "cases/65b0978d4817a543416c5d43/
externallmg_1706500543836_IMG_20240127_115740.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b721c0e1e7bf61f3d0ce2a",
  "name": "externallmg_1706500543845_IMG_20240127_115744.jpg",
  "path": "cases/65b0978d4817a543416c5d43/
externallmg_1706500543845_IMG_20240127_115744.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b721c0e1e7bf61f3d0ce2b",
  "name": "externallmg_1706500543851_IMG_20240127_115751.jpg",
  "path": "cases/65b0978d4817a543416c5d43/
externallmg_1706500543851_IMG_20240127_115751.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b721c0e1e7bf61f3d0ce2c",
  "name": "externallmg_1706500543854_IMG_20240127_115754.jpg",
  "path": "cases/65b0978d4817a543416c5d43/
externallmg_1706500543854_IMG_20240127_115754.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "65b721c0e1e7bf61f3d0ce2d",
    "name": "externalimg_1706500543859_IMG_20240127_115755.jpg",
    "path": "cases/65b0978d4817a543416c5d43/
externalimg_1706500543859_IMG_20240127_115755.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b721c0e1e7bf61f3d0ce2e",
    "name": "externalimg_1706500543864_IMG_20240127_115757.jpg",
    "path": "cases/65b0978d4817a543416c5d43/
externalimg_1706500543864_IMG_20240127_115757.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b721c0e1e7bf61f3d0ce2f",
    "name": "externalimg_1706500543874_IMG_20240127_115759.jpg",
    "path": "cases/65b0978d4817a543416c5d43/
externalimg_1706500543874_IMG_20240127_115759.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b721c0e1e7bf61f3d0ce30",
    "name": "externalimg_1706500543876_IMG_20240127_121119.jpg",
    "path": "cases/65b0978d4817a543416c5d43/
externalimg_1706500543876_IMG_20240127_121119.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b721c0e1e7bf61f3d0ce31",
    "name": "externalimg_1706500543880_IMG_20240127_121125.jpg",
    "path": "cases/65b0978d4817a543416c5d43/
externalimg_1706500543880_IMG_20240127_121125.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b721c0e1e7bf61f3d0ce32",
```

```
    "name": "externallmg_1706500543883_IMG_20240127_121421.jpg",
    "path": "cases/65b0978d4817a543416c5d43/
externallmg_1706500543883_IMG_20240127_121421.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b721c0e1e7bf61f3d0ce33",
    "name": "externallmg_1706500543887_IMG_20240127_121555.jpg",
    "path": "cases/65b0978d4817a543416c5d43/
externallmg_1706500543887_IMG_20240127_121555.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b721c0e1e7bf61f3d0ce34",
    "name": "externallmg_1706500543892_IMG_20240127_121558.jpg",
    "path": "cases/65b0978d4817a543416c5d43/
externallmg_1706500543892_IMG_20240127_121558.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b721c0e1e7bf61f3d0ce35",
    "name": "externallmg_1706500543897_IMG_20240127_121601.jpg",
    "path": "cases/65b0978d4817a543416c5d43/
externallmg_1706500543897_IMG_20240127_121601.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b721c0e1e7bf61f3d0ce36",
    "name": "externallmg_1706500543902_IMG_20240127_121602.jpg",
    "path": "cases/65b0978d4817a543416c5d43/
externallmg_1706500543902_IMG_20240127_121602.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b721c0e1e7bf61f3d0ce37",
    "name": "externallmg_1706500543908_IMG_20240127_121729.jpg",
```

```
    "path": "cases/65b0978d4817a543416c5d43/
externallmg_1706500543908_IMG_20240127_121729.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b721c0e1e7bf61f3d0ce38",
    "name": "externallmg_1706500543913_IMG_20240127_121731.jpg",
    "path": "cases/65b0978d4817a543416c5d43/
externallmg_1706500543913_IMG_20240127_121731.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b721c0e1e7bf61f3d0ce39",
    "name": "externallmg_1706500543917_IMG_20240128_181604__01__01.jpg",
    "path": "cases/65b0978d4817a543416c5d43/
externallmg_1706500543917_IMG_20240128_181604__01__01.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b721c0e1e7bf61f3d0ce3a",
    "name": "externallmg_1706500543920_IMG_20240128_181608__01__01.jpg",
    "path": "cases/65b0978d4817a543416c5d43/
externallmg_1706500543920_IMG_20240128_181608__01__01.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation Sheet NEW.xlsx",
    "filename": "1706502876143_Calculation_Sheet_NEW.xlsx",
    "path": "cases/65b0978d4817a543416c5d43/
processingDocuments/1706502876143_Calculation_Sheet_NEW.xlsx",
    "size": "2940960",
    "createdAt": "Mon Jan 29 2024 10:04:37 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "snehal Dalvi SBI sanpada alka 24.1.24 (1).pdf",
    "filename": "1706502876361_snehal_Dalvi_SBI_sanpada_alka_24124_1.pdf",
```

```
"path": "cases/65b0978d4817a543416c5d43/processingDocuments/170650287636
1_snehal_Dalvi_SBI_sanpada_alka_24124_1.pdf",
"size": "12466985",
"createdAt": "Mon Jan 29 2024 10:04:37 GMT+0530 (India Standard Time)",
"uploadedBy": "64cde526dc9f3034f3fefa49"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-01-24T04:52:29.583Z",
"updatedAt": "2024-01-29T08:59:14.488Z",
"__v": 0,
"invoiceId": "65b0978d4817a543416c5d49",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 1904, 19th Floor, Wing - E, Tower - 28, Phase - I,
Haji Bapu Road, Govind Nagar, Village - Pagadi Goregaon , Taluka - Borivali, District -
Mumbai Suburban , Malad (East), PIN - 400 097, State - Maharashtra, Country - India",
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Mr. Shankar Jagannath Dalvi ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner",
"siteVisitContactNo": "9869068900",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 619.00",
"flatRate": "27000",
"landOtherRate": "24000",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
```

```
    },
    "roadFacing": false,
    "mall": false
  },
  "builtupPercentage": "10",
  "carpetTotal": "574.13",
  "extendOfSiteRemark": "\nAll the above areas are within 7% of the Agreement for Sale Area. The above calculations and detail measurements taken by us prove that the Agreement for Sale are is not exorbitantly inflated. Hence, valuation is based on the Agreement for Sale area",
  "finalBuiltupArea": "631.54",
  "finalCarpetArea": "574.13",
  "finalSalableArea": "694.70",
  "otherCarpetTotal": "0.00",
  "salablePercentage": "10",
  "siteMeasurementRemark": "\n",
  "toBeAdded": "",
  "briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Passage + 2 Toilet",
  "finalSaleablePercentage": "0",
  "landDetails": {
    "holdType": {
      "label": "Free Hold",
      "value": "Free_Hold"
    }
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Mon Jan 29 2024 11:43:22 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-01-27",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"
}
```


Name	Length	Width	Total
Composition :			
Living Room	9'10"	19'9"	194.21
Passage	11'1"	2'10"	31.40
Bedroom	10'6"	9'2"	96.25
Bedroom	11'3"	9'9"	109.69
Kitchen	10'5"	6'11"	72.05
Toilet	6'6"	4'8"	30.33
Toilet	4'8"	6'7"	30.72
Other Composition :			