

Structural Stability Report

Structural Observation Report of Residential Flat No. 1401, 14th Floor, "Kailash Tower Co-op. Hsg. Soc. Ltd.", Shiv – Shrishti Complex, Mulund - Goregaon Link Road, Village - Nahur, Mulund (West), Taluka - Kurla, District - Mumbai Suburban District, Mumbai, PIN Code - 400 080, State - Maharashtra, India.

Name of Owner: **Mr. Prashant Shrikrishna Joshi.**

This is to certify that on visual inspection, it appears that the structure of the at "Kailash Tower Co-op. Hsg. Soc. Ltd." is in normal condition and the future life can be reasonably taken under good condition and with proper periodic repairs & maintenance is about 42 years.

General Information:

A.	Introduction	
1	Name of Building	Kailash Tower Co-op. Hsg. Soc. Ltd.
2	Property Address	Residential Flat No. 1401, 14 th Floor, "Kailash Tower Co-op. Hsg. Soc. Ltd.", Shiv – Shrishti Complex, Mulund - Goregaon Link Road, Village - Nahur, Mulund (West), Taluka - Kurla, District - Mumbai Suburban District, Mumbai, PIN Code - 400 080, State - Maharashtra, India.
3	Type of Building	Residential used
4	No. of Floors	Part Ground + Part Stilt + 19 Upper Floors
5	Whether stilt / podium / open parking provided	Stilt + Open Car Parking
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	2006 (As per occupancy certificate)
11	Present age of building	18 years
12	Residual age of the building	42 years Subject to proper, preventive periodic maintenance & structural repairs
13	No. of flats (Per Floor)	14 th Floor is having 4 Flats
14	Methodology adopted	As per visual site inspection



Our Pan India Presence at :

Mumbai Aurangabad Pune Rajkot
Thane Nanded Indore Raipur
Delhi NCR Nashik Ahmedabad Jaipur

Regd. Office : B1-001, U/B Floor, Boomerang,
Chandivali Farm Road, Andheri (East),
Mumbai - 400 072, (M.S.), INDIA
TeleFax : +91 22 28371325/24
mumbai@vastukala.org

B. External Observation of the Building		
1	Plaster	Normal Condition
2	Chajjas	Normal Condition
3	Plumbing	Normal Condition
4	Cracks on the external walls	Not Found
5	Filling cracks on the external walls	Not Found
6	Cracks on columns & beams	Not Found
7	Vegetation	Not Found
8	Leakages of water in the drainage pipes or water pipes	Not Found
9	Dampness external in the wall due to leakages	Not Found
10	Any other observation about the condition of external side of the building	The external condition of the building is in normal condition.
C Internal Observation of the common areas of the building and captioned premises		
1	Beams (Cracks & Leakages)	Cracks were found
2	Columns (Cracks & Leakages)	Cracks were found
3	Ceiling (Cracks & Leakages)	Cracks were found
4	Leakages inside the property	Not Found
5	Painting inside the property	Normal
6	Maintenance of staircase & cracks	Normal

D Common Observation		
1	Structural Audit of the Building Under Bye – Laws No. 77 of the Model Bye Laws (Co-Operative Societies Act / Rules)	As per bye Laws No. 77 of Co-Op. Societies bye Laws under the Act the society shall conduct a Structural Audit of the building of the society as follows
2	Remark	No Structural Audit Report is furnished for the perusal

E Conclusion		
<p>The captioned building is having Part Ground + Part Stilt + 19 Upper Floors which are constructed in year 2006 (As per occupancy certificate). Estimated future life under present circumstances is about 42 years' subject to proper, preventive periodic maintenance & structural repairs.</p> <p>The inspection dated 23.01.2024 reveals no structural damage or deterioration to the building. The building is well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & Good structural repairs.</p> <p>Our Observations about the structure are given above.</p> <p>The above assessment is based on visual inspection only.</p>		

For VASTUKALA CONSULTANTS (I) PVT. LTD.

**Manoj
Chalikwar**
Director

Digitally signed by Manoj Chalikwar
DN: cn=Manoj Chalikwar, o=Vastukala
Consultants (I) Pvt. Ltd., ou=Mumbai,
email=manoj@vastukala.org, c=IN
Date: 2024.01.24 16:13:17 +05'30'



Auth. Sign.

Manoj Chalikwar

Govt. Reg. Valuer

Chartered Engineer (India)

Reg. No. IBBI/RV/07/2018/10366

State Bank of India Empanelment No.: SME/TCC/2021-22/86/3



Vastukala Consultants (I) Pvt. Ltd.

An ISO 9001:2015 Certified Company

www.vastukala.org



Actual Site Photographs





Think.Innovate.Create

