

```
{
  "typeOfReport": {
    "value": "Land_and_Building",
    "label": "Land and Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63638ca6e363ef22db2fb2c9"
    },
    "type": "CREDITOFFICER",
    "_id": "63d11f65be948726cc1419f5",
    "email": "bhiwandi.navimumbai@bankofindia.co.in",
    "firstName": "Mr. Snehal",
    "mobileNo": "91-7977133309",
    "workMobileNo": "7977133309",
    "lastName": "Snehal"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "6418456a96b58848585f8cb2",
"name": "Thane",
"email": "thane@vastukala.com",
"phone": "1234567890",
"address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
"city": "Thane",
"shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180a",
  "type": "BANK",
  "name": "Bank of India",
  "displayName": "Bank of India",
  "initial": "BOI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63638ca6e363ef22db2fb2c9",
  "name": "Bhiwandi",
  "branchCode": "0075",
  "mobileNo": "2522225009",
  "alternateMobileNo": "",
  "email": "bhiwandi.navimumbai@bankofindia.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "255, Sonar Kasar Ali, Bhiwandi, Maharashtra Mumbai 421302\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Industrial",
  "value": "Industrial"
},
"zone": {
  "_id": "60e2f4b16576061dae469446",
  "zoneName": "Navi Mumbai Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "656aa949cebbe1714411d21b",
```

```
"role": "FRONTDESK",
"firstName": "Priyanka",
"email": "thane@vastukala.org",
"lastName": "Pawar",
"mobileNo": "8928414480",
"shortName": "PCP",
"workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62ea09ea4e679b264caf07d7",
"role": "SITEENGINEER",
"firstName": "Suraj",
"email": "suraj@vastukala.org",
"lastName": "Zore",
"mobileNo": "8652448654",
"designation": "",
"shortName": "SZ",
"workWithDocumentMaker": "60092304a16fab0f2af9b0c2",
"profilePhoto": "users/62ea09ea4e679b264caf07d7/
profilePhoto_1685629394240_image.jpeg"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
},
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
}
}
],
}
```

```
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.275171466861813",
  "longitude": "73.04908363461355"
},
"geo": {
```

```
"type": "Point",
"coordinates": [
  0,
  0
]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Savde",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Basement",
```

```
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Bhiwandi",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": false,
```

```
"name": "Building Name",
"key": "buildingName",
"value": "",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
}
```

```
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "62",
  "label": true
},
"hissaNo": {
  "status": true,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "1 A",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
```



```
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
}
```

```
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  }
},
```

```
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
```

```
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
"carpetRateRange": {
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
"min": "0.00",
"max": "0.00"
}
},
"detailsOfValuation": {
"presentValueOfFlat": {
```

```
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
```

```
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentId": [],
"_id": "65b4aeef9cb492acffa6d81",
"ownerName": "Mr. Habib Mhendi Hasan",
"ownerPhoneNo": "9823072815",
"fullAddress": "Residential Land and Building No. Basement Floor, New/Current
Survey No. 62, Hissa No. 1 A, Village - Savde, Taluka - Bhiwandi, District - Thane",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1706339887410_DocScanner_23Jan2024_151_pm.pdf",
    "path": "cases/65b4aeef9cb492acffa6d81/
document_1706339887410_DocScanner_23Jan2024_151_pm.pdf",
    "id": "648868",
    "uploadedBy": "656aa949cebbe1714411d21b",
    "createdAt": "Sat Jan 27 2024 12:51:18 GMT+0530 (India Standard Time)"
  },
  {
```



```
"documentType": {
  "value": "60ae124eaa6d152c1801b30b",
  "label": "Other"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1706339897883_DocScanner_23Jan2024_154_pm.pdf",
"path": "cases/65b4aeef9cb492acffa6d81/
document_1706339897883_DocScanner_23Jan2024_154_pm.pdf",
"id": "463796",
"uploadedBy": "656aa949cebbe1714411d21b",
"createdAt": "Sat Jan 27 2024 12:51:18 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1706339907706_DocScanner_23Jan2024_153_pm.pdf",
  "path": "cases/65b4aeef9cb492acffa6d81/
document_1706339907706_DocScanner_23Jan2024_153_pm.pdf",
  "id": "330268",
  "uploadedBy": "656aa949cebbe1714411d21b",
  "createdAt": "Sat Jan 27 2024 12:51:18 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1706339920350_DocScanner_23Jan2024_131_pm.pdf",
  "path": "cases/65b4aeef9cb492acffa6d81/
document_1706339920350_DocScanner_23Jan2024_131_pm.pdf",
  "id": "334103",
  "uploadedBy": "656aa949cebbe1714411d21b",
  "createdAt": "Sat Jan 27 2024 12:51:18 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },

```

```
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1706339935951_DocScanner_23Jan2024_127_pm.pdf",
    "path": "cases/65b4aeef9cb492acffa6d81/
document_1706339935951_DocScanner_23Jan2024_127_pm.pdf",
    "id": "584141",
    "uploadedBy": "656aa949cebbe1714411d21b",
    "createdAt": "Sat Jan 27 2024 12:51:18 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1706340073273_Index_II.pdf",
    "path": "cases/65b4aeef9cb492acffa6d81/
document_1706340073273_Index_II.pdf",
    "id": "369016",
    "uploadedBy": "656aa949cebbe1714411d21b",
    "createdAt": "Sat Jan 27 2024 12:51:18 GMT+0530 (India Standard Time)"
  }
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "006597",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "104537",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Jan 27 2024 12:51:18 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Habib Mhendi Hasan",
    "phone": "9823072815",
    "ownershipShare": "",
    "email": "",
    "id": "392385"
  }
]
```

```
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65b4f3b9e1e7bf61f3d07f7a",
    "name": "externalImg_r_1706357689159_1706357819134_image_0.png",
    "path": "cases/65b4aeef9cb492acffa6d81/
externalImg_r_1706357689159_1706357819134_image_0.png",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b4f414e1e7bf61f3d080f0",
    "name": "externalImg_r_1706357747698_1706357868327_image_2.jpg",
    "path": "cases/65b4aeef9cb492acffa6d81/
externalImg_r_1706357747698_1706357868327_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b4f414e1e7bf61f3d080f1",
    "name": "externalImg_r_1706357746532_1706357868327_image_1.jpg",
    "path": "cases/65b4aeef9cb492acffa6d81/
externalImg_r_1706357746532_1706357868327_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b4f414e1e7bf61f3d080f2",
    "name": "externalImg_r_1706357745004_1706357868327_image_0.jpg",
    "path": "cases/65b4aeef9cb492acffa6d81/
externalImg_r_1706357745004_1706357868327_image_0.jpg",
    "orientation": "portrait"
  },
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b4f414e1e7bf61f3d080f3",
  "name": "externallmg_r_1706357748934_1706357868327_image_3.jpg",
  "path": "cases/65b4aeef9cb492acffa6d81/
externallmg_r_1706357748934_1706357868327_image_3.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b4f414e1e7bf61f3d080f4",
  "name": "externallmg_r_1706357751779_1706357868327_image_5.jpg",
  "path": "cases/65b4aeef9cb492acffa6d81/
externallmg_r_1706357751779_1706357868327_image_5.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b4f414e1e7bf61f3d080f5",
  "name": "externallmg_r_1706357750291_1706357868327_image_4.jpg",
  "path": "cases/65b4aeef9cb492acffa6d81/
externallmg_r_1706357750291_1706357868327_image_4.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b4f414e1e7bf61f3d080f6",
  "name": "externallmg_r_1706357754469_1706357868327_image_6.jpg",
  "path": "cases/65b4aeef9cb492acffa6d81/
externallmg_r_1706357754469_1706357868327_image_6.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65b4f414e1e7bf61f3d080f7",
  "name": "externallmg_r_1706357756325_1706357868327_image_7.jpg",
  "path": "cases/65b4aeef9cb492acffa6d81/
externallmg_r_1706357756325_1706357868327_image_7.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b4f414e1e7bf61f3d080f8",
    "name": "externallmg_r_1706357761904_1706357868327_image_10.jpg",
    "path": "cases/65b4aeef9cb492acffa6d81/
externallmg_r_1706357761904_1706357868327_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b4f414e1e7bf61f3d080f9",
    "name": "externallmg_r_1706357760083_1706357868327_image_9.jpg",
    "path": "cases/65b4aeef9cb492acffa6d81/
externallmg_r_1706357760083_1706357868327_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b4f414e1e7bf61f3d080fa",
    "name": "externallmg_r_1706357763895_1706357868327_image_11.jpg",
    "path": "cases/65b4aeef9cb492acffa6d81/
externallmg_r_1706357763895_1706357868327_image_11.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b4f414e1e7bf61f3d080fb",
    "name": "externallmg_r_1706357758584_1706357868327_image_8.jpg",
    "path": "cases/65b4aeef9cb492acffa6d81/
externallmg_r_1706357758584_1706357868327_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b4f414e1e7bf61f3d080fc",
    "name": "externallmg_r_1706357765303_1706357868327_image_12.jpg",
    "path": "cases/65b4aeef9cb492acffa6d81/
externallmg_r_1706357765303_1706357868327_image_12.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "65b4f414e1e7bf61f3d080fd",
    "name": "externalimg_r_1706357767322_1706357868327_image_13.jpg",
    "path": "cases/65b4aeef9cb492acffa6d81/
externalimg_r_1706357767322_1706357868327_image_13.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b4f414e1e7bf61f3d080fe",
    "name": "externalimg_r_1706357771286_1706357868327_image_15.jpg",
    "path": "cases/65b4aeef9cb492acffa6d81/
externalimg_r_1706357771286_1706357868327_image_15.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b4f414e1e7bf61f3d080ff",
    "name": "externalimg_r_1706357769092_1706357868327_image_14.jpg",
    "path": "cases/65b4aeef9cb492acffa6d81/
externalimg_r_1706357769092_1706357868327_image_14.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b4f414e1e7bf61f3d08100",
    "name": "externalimg_r_1706357775195_1706357868327_image_17.jpg",
    "path": "cases/65b4aeef9cb492acffa6d81/
externalimg_r_1706357775195_1706357868327_image_17.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65b4f414e1e7bf61f3d08101",
    "name": "externalimg_r_1706357773001_1706357868327_image_16.jpg",
    "path": "cases/65b4aeef9cb492acffa6d81/
externalimg_r_1706357773001_1706357868327_image_16.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
```

"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-01-27T07:21:18.925Z",
"updatedAt": "2024-01-27T12:16:20.471Z",
"__v": 0,
"invoiceId": "65b4aeef9cb492acffa6d87",
"updatedBy": "62ea09ea4e679b264caf07d7",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Mr. Habib Mhendi Hasan",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9823072815"

}

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			