

## Structural Stability Report

Structural Observation Report of Residential Flat No. 404, 4<sup>th</sup> Floor, Wing - B, "Om Vikas Co-op. Hsg. Soc. Ltd.", Santoshi Mata Road, Village - Chikanghar, Kalyan (West), Taluka - Kalyan, District - Thane, PIN - 421 301, State - Maharashtra, Country - India.

Name of Owner: **Rammohan Prahlad Singh Tomar**

This is to certify that on visual inspection, it appears that the structure of the at "Om Vikas Co-op. Hsg. Soc. Ltd.", is in normal condition and the future life can be reasonably taken under good condition and with proper periodic repairs & maintenance is about 30 years.

### General Information:

A.	Introduction	
1	Name of Building	"Om Vikas Co-op. Hsg. Soc. Ltd."
2	Property Address	Residential Flat No. 404, 4 <sup>th</sup> Floor, Wing - B, "Om Vikas Co-op. Hsg. Soc. Ltd.", Santoshi Mata Road, Village - Chikanghar, Kalyan (West), Taluka - Kalyan, District - Thane, PIN - 421 301, State - Maharashtra, Country - India.
3	Type of Building	Residential
4	No. of Floors	Ground + 6 Upper Floors
5	Whether stilt / podium / open parking provided	Open Car Parking Space
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	1994 (as per Building Completion Certificate)
11	Present age of building	30 Years
12	Residual age of the building	30 Years Subject to proper, preventive periodic maintenance & structural repairs.
13	No. of flats (Per Floor)	4 <sup>th</sup> Floor is having 4 Flats
14	Methodology adopted	As per visual site inspection



### Our Pan India Presence at :

Mumbai Aurangabad Pune Rajkot  
Thane Nanded Indore Roipur  
Delhi NCR Nashik Ahmedabad Jaipur

Regd. Office : B1-001, U/B Floor, Boomerang,  
Chandivali Farm Road, Andheri (East),  
Mumbai - 400 072, (M.S.), INDIA  
TeleFax : +91 22 28371325/24  
mumbai@vastukala.org

<b>B. External Observation of the Building</b>		
1	Plaster	Good Condition
2	Chajjas	Good Condition
3	Plumbing	Good Condition
4	Cracks on the external walls	Not found
5	Filling cracks on the external walls	Found
6	Cracks on columns & beams	Not found
7	Vegetation	Not found
8	Leakages of water in the drainage pipes or water pipes	Not found
9	Dampness external in the wall due to leakages	Not found
10	Any other observation about the condition of external side of the building	<b>1. Structural Stability Report from licensed structural engineers not provided for our verification.</b>
<b>C Internal Observation of the common areas of the building and captioned premises</b>		
1	Beams (Cracks & Leakages)	Not found
2	Columns (Cracks & Leakages)	Not found
3	Ceiling (Cracks & Leakages)	Not found
4	Leakages inside the property	Not found
5	Painting inside the property	Good
6	Maintenance of staircase & cracks	Good

<b>D Common Observation</b>		
1	Structural Audit of the Building Under Bye – Laws No. 77 of the Model Bye Laws (Co-Operative Societies Act / Rules)	As per bye Laws No. 77 of Co-Op. Societies bye Laws under the Act the society shall conduct a Structural Audit of the building of the society as follows
2	Remark	No Structural Audit Report is furnished for the perusal.

<b>E Conclusion</b>	
<p>The captioned building is having Ground + 6 Upper Floors which are constructed in year 1994 (as per Building Completion Certificate). Estimated future life under present circumstances is about 30 years subject to proper, preventive periodic maintenance &amp; structural repairs.</p> <p>The inspection dated 13.01.2024 reveals no structural damage or deterioration to the building. The building is well as the property is maintained in normal condition &amp; will stand future life subject to proper, preventive periodic maintenance &amp; Good structural repairs.</p> <p>Our Observations about the structure are given above.</p> <p>The above assessment is based on visual inspection only. Separate structural audit from licensed structural engineers is advised to assess exact balance life of structure.</p>	

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Sharadkumar B. Chalikwar  
Digitally signed by Sharadkumar B. Chalikwar  
 DN: cn=Sharadkumar B. Chalikwar,  
 o=Vastukala Consultants (I) Pvt. Ltd., ou=CMD,  
 email=cmd@vastukala.org, c=IN  
 Date: 2024.07.01 13:55:49 +05'30'



Director

Auth. Sign.

**Sharadkumar B. Chalikwar**

Govt. Reg. Valuer

Chartered Engineer (India)

Reg. No. (N) CCIT/1-14/52/2008-09

Janaseva Sahakari Bank Empanelment No.: 36/ LOAN H.O./2016-17/232



Vastukala Consultants (I) Pvt. Ltd.

Think Innovate Create

An ISO 9001:2015 Certified Company

www.vastukala.org



## Actual Site Photographs

