

Structural Stability Report

Structural Observation Report of Residential Flat No. A/401, 4th Floor, "**Rajesh Park View Co-op. Hsg. Soc. Ltd.**", Pipeline Road, Off Nehru Road, Vakola, Village - Kolkalyan, Santacruz (East), Taluka - Andheri, District - Mumbai Suburban, Mumbai, PIN - 400 055, State - Maharashtra, Country - India.

Name of Owner: **Mr. DSA Noel Santosh & Mrs. Preethi Tina Dsouza DSA**

This is to certify that on visual inspection, it appears that the structure of the at "**Rajesh Park View Co-op. Hsg. Soc. Ltd.**", is in normal condition and the future life can be reasonably taken under good condition and with proper periodic repairs & maintenance is about 13 years.

General Information:

A.	Introduction	
1	Name of Building	" Rajesh Park View Co-op. Hsg. Soc. Ltd. "
2	Property Address	of Residential Flat No. A/401, 4 th Floor, " Rajesh Park View Co-op. Hsg. Soc. Ltd. ", Pipeline Road, Off Nehru Road, Vakola, Village - Kolkalyan, Santacruz (East), Taluka - Andheri, District - Mumbai Suburban, Mumbai, PIN - 400 055, State - Maharashtra, Country - India.
3	Type of Building	Residential
4	No. of Floors	Ground + 4 Upper Floors
5	Whether stilt / podium / open parking provided	Open Car Parking Space
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	1977 (as per Occupancy Certificate)
11	Present age of building	47 Years
12	Residual age of the building	13 Years Subject to proper, preventive periodic maintenance & structural repairs.
13	No. of flats (Per Floor)	4 th Floor is having 3 Flats
14	Methodology adopted	As per visual site inspection

B.	External Observation of the Building	
1	Plaster	Normal Condition
2	Chajjas	Normal Condition
3	Plumbing	Normal Condition
4	Cracks on the external walls	Minor cracks found



Our Pan India Presence at :

5	Filling cracks on the external walls	Cracks filling found
6	Cracks on columns & beams	Minor cracks found
7	Vegetation	Not found
8	Leakages of water in the drainage pipes or water pipes	Not found
9	Dampness external in the wall due to leakages	Not found
10	Any other observation about the condition of external side of the building	<ol style="list-style-type: none"> 1. At the time of site inspection, external condition of the building is normal, dampness not found on external walls, leakages are not found, Minor cracks are found with filling. 2. Structural Stability Report from licensed structural engineers not provided for our verification.
C	Internal Observation of the common areas of the building and captioned premises	
1	Beams (Cracks & Leakages)	Minor cracks found
2	Columns (Cracks & Leakages)	Minor cracks found
3	Ceiling (Cracks & Leakages)	Minor cracks found
4	Leakages inside the property	Not found
5	Painting inside the property	Normal
6	Maintenance of staircase & cracks	Normal

D	Common Observation	
1	Structural Audit of the Building Under Bye – Laws No. 77 of the Model Bye Laws (Co-Operative Societies Act / Rules)	As per bye Laws No. 77 of Co-Op. Societies bye Laws under the Act the society shall conduct a Structural Audit of the building of the society as follows
2	Remark	No Structural Audit Report is furnished for the perusal.

E	Conclusion
<p>The captioned building is having Ground + 4 Upper Floors which are constructed in year 1977 (as per Occupancy Certificate). Estimated future life under present circumstances is about 13 years subject to proper, preventive periodic maintenance & structural repairs.</p> <p>The inspection dated 16.01.2024 reveals no structural damage or deterioration to the building. The building is well as the property is maintained in good condition & will stand future life subject to proper, preventive periodic maintenance & Good structural repairs.</p> <p>Our Observations about the structure are given above.</p> <p>The above assessment is based on visual inspection only. Separate structural audit from licensed structural engineers is advised to assess exact balance life of structure.</p>	

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Sharadkumar B. Chalikwar
Director

Digitally signed by Sharadkumar B. Chalikwar
DN: cn=Sharadkumar B. Chalikwar, o=Vastukala Consultants (I) Pvt. Ltd., ou=CMD, email=cmd@vastukala.org, c=IN
Date: 2024.02.07 17:53:36 +05'30'

Auth. Sign.

Sharadkumar B. Chalikwar

Govt. Reg. Valuer

Chartered Engineer (India)

Reg. No. (N) CCIT/1-14/52/2008-09

Janaseva Sahakari Bank Empanelment No.: 36/ LOAN H.O./2016-17/232



Vastukala Consultants (I) Pvt. Ltd.

An ISO 9001:2015 Certified Company

www.vastukala.org



Actual Site Photographs



Actual Site Photographs

