

```
{
  "typeOfReport": {
    "value": "Row_House",
    "label": "Row House"
  },
  "reportInformation": {
    "amalgamated": true,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6405bf97dd383b243e8482fe"
    },
    "type": "CREDITOFFICER",
    "_id": "6437a3084f8e91656ccc08b7",
    "firstName": "vinod Dhage",
    "lastName": "Dhage",
    "mobileNo": "",
    "workMobileNo": "9172888264",
    "email": "vinod.dhage@janasevabank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5000000",
    "discussWithPerson": "vinod Dhage",
    "expectedFees": 2500,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1836",
  "type": "BANK",
  "name": "Janaseva Sahakari Bank",
  "displayName": "Janaseva Sahakari Bank",
  "initial": "JSB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6405bf97dd383b243e8482fe",
  "name": "Charkop Branch",
  "branchCode": "",
  "mobileNo": "02228683113",
  "alternateMobileNo": "",
  "email": "charkop@janasevabank.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Charkop Shivneri RDP-4 , Sector 5, Charkop, Kandiwali Westy, Mumbai
40007"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63afe4ff191f7b344b007ea6",
  "zoneName": "Pan India"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "659ccce98f39506e83489828",
"role": "DELIVERYPERSON",
"firstName": "Amit",
"email": "amitsalvi2909@gmail.com",
"lastName": "Salvi",
"mobileNo": "7499830659",
"shortName": "Amit",
"workWithDocumentMaker": ""
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62691c48afd7d55eddecfda3",
"role": "ADMIN",
"firstName": "Bhavika",
"email": "bhavikachavan0102@gmail.com",
"lastName": "chavan",
"mobileNo": "8390804382",
"designation": "Site Engineer",
"shortName": "BH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60092304a16fab0f2af9b0c2",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Nitesh",
"email": "nitesh.khedekar@vastukala.org",
"lastName": "Khedekar",
"mobileNo": "8369040652",
"designation": "",
"shortName": "NK",
"workWithDocumentMaker": "",
"profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "627221f4afd7d55eddeddcb4",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Prajakta",
"email": "prajakta@vastukala.org",
"lastName": "Patil",
"mobileNo": "9769797568",
"designation": "",
```

```
    "shortName": "P",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
  },
  "checker": null,
  "valuers": []
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.211373952722813",
  "longitude": "72.82274910167577"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.82274910167577,
    19.211373952722813
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-14",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-14",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-02-14",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
}
```

```
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Charkop",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
```

```
"value": "Mumbai Suburban District",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "843",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Charkop Sai Sandesh Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "8",
  "label": true
},
"street1": {
```

```
"status": true,
"name": "Street 1",
"key": "street1",
"value": "RSC - 12",
"label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Near Akshara School",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "41 Part",
```

```
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "B - 19",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
```



```
"name": "Mouza",
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 067",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Kandivali (West)\t",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  }
},
```

```
"flooring": {
  "value": "Proposed_Vitrified_tiles_flooring",
  "label": "Proposed Vitrified tiles flooring"
},
"doors": {
  "value": "Proposed_Powder_Coated_Aluminum_Sliding_Windows",
  "label": "Proposed Powder Coated Aluminum Sliding Windows"
},
"windows": {
  "value": "Proposed_Powder_coated_aluminium_sliding_windows",
  "label": "Proposed Powder coated aluminium sliding windows"
},
"fittings": {
  "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
  "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
},
"finishing": {
  "value": "Internal_Flat_Renovation_work_was_in_progress",
  "label": "Internal Flat Renovation work was in progress"
}
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MHADA",
    "label": "MHADA"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Road",
```

```

    "west": "Open Plot & Mahakali Temple",
    "south": "Open Plot",
    "east": "Swami Samarth CHSL"
  },
  "asPerDocumentAgreement": {
    "north": "Adj. 9.0 meter wide Road, RSC 12",
    "west": "Adj. Amenity Plot",
    "south": "Adj. Scheme Boundary",
    "east": "Adj. Cluster Plot No. 842"
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "",
      "west": "",
      "south": "",
      "east": ""
    }
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"extraDetailOfProperty": "As per Site Inspection, Core House is of Ground + 1st Floor + Terrace Area. The composition of Core House is:\nGround Floor - Living Room + Kitchen + Toilet + Staircase. \nFirst Floor - 2 Bedrooms + Passage + Staircase. \n & Terrace Floor.\n",
"dateOfIssusApprovePlan": "Copy of Approved Plan were not provided and not verified",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": ""
},
"compositeRate": {
  "remark": "1. As per the agreement provided, the Built up area of the Core House is 269.00 Sq. Ft. but as per site inspection the Carpet area is 735.00 Sq. Ft. comprising of ground floor, extended 1st & Top Terrace area. As there is no documentary evidence for the ownership of this additional area, we are considering area as per agreement only for the purpose of valuation. \n2. At the time of visit, renovation work is in progress.",
  "depreciationPercentage": "28.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "15430.5",

```

```
"depreciatedBuildingRate": "1930.5"
},
"igrRate": {
  "propertyName": "Residential ",
  "rate": "138620",
  "landRate": "59310",
  "igrImage": "cases/65cb4951d93fe4510d4e078e/igr_1707982434955_Image.png",
  "squareMeterGuideLineRate": "145551.00",
  "squareFeetGuideLineRate": "13522.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "81",
  "rate": "11478.00",
  "squareMeterGuideLineRate": "123551.00",
  "squareFeetGuideLineRate": "11478.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "10,000/- Expected rental income per month",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per MHADA / MCGM norms",
  "tenantName": "",
  "maintenanceOfFlat": "At the time of visit, renovation work is in progress."
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  }
},
```

```
"anyFavouringForExtraPotentialValue": "Located in Developed Area",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Car Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
    "month": "1",
    "year": "2005",
    "fullDate": "1/1/2005"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "R.C.C.",
    "label": "R.C.C. Framed"
  },
  "typeOfFoundation": {
    "value": "rcc",
    "label": "R.C.C. Foundation"
  }
}
```

```
},
"qualityOfConstruction": {
  "value": "External_building_renovation_work_is_in_progress",
  "label": "External building renovation work is in progress"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "External_building_renovation_work_is_in_progress",
  "label": "External building renovation work is in progress"
},
"maintenanceOfTheBuilding": {
  "value": "External_building_renovation_work_is_in_progress",
  "label": "External building renovation work is in progress"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
```

```
"value": "1",
"label": "Yes"
},
"provisionOfFirefighting": {
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "ground",
"label": "Ground"
},
"yearOfConstructionAsPer": {
"value": "Approx.",
"label": "Approx."
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "41",
"ageOfBuilding": "19",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "1",
"flatFloorNo": "8",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "22"
},
"finalPlinthArea": {
"area": "0.00"
},
"routeMap": {
"routeMapDetail": {
"routeStation": {
"value": "Metro_Station",
"label": "Metro Station"
}
},
"routeMapImg": "cases/65cb4951d93fe4510d4e078e/
routeMap_1707985297142_Image.png",
"routeLat": "19.217988",
"routeLng": "72.817529",
"stationName": "Kandivali (West)",
"routeDistance": "2.7 Km."
},
"finalLatLng": {
"coordinates": [
null,
```

```
    null
  ],
  "type": "Point"
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "eh70bl",
    "name": "eh70bl",
    "image": "cases/65cb4951d93fe4510d4e078e/
routeMap_1707985220501_Image.png"
  }
]
},
"valuation": {
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "4150939.00",
```



```
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "4150939.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "3087582.00",
  "selectedBuildUpValue": "269.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
```

```
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "65cca04ed93fe4510d4fb93e",
      "name": "externallmg_1707908956790_1707909081312_image_4.jpeg",
      "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707908956790_1707909081312_image_4.jpeg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "65cca04ed93fe4510d4fb93b",
      "name": "externallmg_1707908952347_1707909081312_image_1.jpeg",
      "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707908952347_1707909081312_image_1.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "65cca04ed93fe4510d4fb947",
      "name": "externallmg_1707909016615_1707909081313_image_13.jpeg",
      "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707909016615_1707909081313_image_13.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "65cca04ed93fe4510d4fb942",
      "name": "externallmg_1707908985261_1707909081312_image_8.jpeg",
      "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707908985261_1707909081312_image_8.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "65cca04ed93fe4510d4fb93d",
      "name": "externallmg_1707908953391_1707909081312_image_3.jpeg",
      "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707908953391_1707909081312_image_3.jpeg",
      "orientation": "portrait"
    }
  ],
}
```

```
{
  "status": false,
  "_id": "65cca04ed93fe4510d4fb940",
  "name": "externallmg_1707908965875_1707909081312_image_6.jpeg",
  "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707908965875_1707909081312_image_6.jpeg",
  "orientation": "portrait"
}
],
"parkingImages": [
  {
    "status": false,
    "_id": "65cca04ed93fe4510d4fb931",
    "name": "externallmg_1707908965292_1707909108317_image_0.jpeg",
    "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707908965292_1707909108317_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65cca04ed93fe4510d4fb932",
    "name": "externallmg_1707908986471_1707909108317_image_1.jpeg",
    "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707908986471_1707909108317_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65cca04ed93fe4510d4fb933",
    "name": "externallmg_1707908998440_1707909108317_image_2.jpeg",
    "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707908998440_1707909108317_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65cca04ed93fe4510d4fb935",
    "name": "externallmg_1707909056314_1707909108317_image_4.jpeg",
    "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707909056314_1707909108317_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65cca04ed93fe4510d4fb936",
    "name": "externallmg_1707909058983_1707909108317_image_5.jpeg",
```

```
    "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707909058983_1707909108317_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65cca04ed93fe4510d4fb938",
    "name": "externallmg_1707909074313_1707909108317_image_7.jpeg",
    "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707909074313_1707909108317_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65cca04ed93fe4510d4fb945",
    "name": "externallmg_1707909000397_1707909081312_image_11.jpeg",
    "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707909000397_1707909081312_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65cca04ed93fe4510d4fb946",
    "name": "externallmg_1707909002915_1707909081312_image_12.jpeg",
    "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707909002915_1707909081312_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65cca04ed93fe4510d4fb949",
    "name": "externallmg_1707909025544_1707909081313_image_15.jpeg",
    "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707909025544_1707909081313_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "65cca04ed93fe4510d4fb94b",
    "name": "externallmg_1707909046393_1707909081313_image_17.jpeg",
    "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707909046393_1707909081313_image_17.jpeg",
    "orientation": "portrait"
  }
],
"societyNameBoardImage": [
```

```
{
  "status": false,
  "_id": "65cca04ed93fe4510d4fb939",
  "name": "externallmg_1707909084064_1707909108317_image_8.jpeg",
  "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707909084064_1707909108317_image_8.jpeg",
  "orientation": "portrait"
}
],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "14300",
    "max": "18051"
  },
  "builtUpRateRange": {
    "min": "13000",
    "max": "16411"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```



```
"isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isSiteMeasurementAllowed": false,
"finalValuationArea": "269.00",
"empanelmentNo": [
  "36/ LOAN H.O./2016-17/232"
],
"isAdvanceInvoice": false,
"status": true,
```

```
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"invoices": [],
"paymentId": [],
"_id": "65cb4951d93fe4510d4e078e",
"ownerName": "Shri. Chandrakant Daulat Ambadaskar",
"ownerPhoneNo": "9220313515",
"appAddress": "B/19/843 CHARKOP SAI SANDESH CHS LTD SECTOR 8 NEAR
AKSHARA SCHOOL CHARKOP KANIVALI WEST MUMBAI 400067",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "MHADA Allotment Letter",
      "value": "60ae1267aa6d152c1801b37e"
    },
    "inputs": {
      "documentDate": "20/01/1997",
      "nameOfApprovingAuthority": {
        "value": "Maharashtra_Housing_And_Area_Development_Authority",
        "label": "Maharashtra Housing And Area Development Authority"
      },
      "to": {
        "value": "Allottee",
        "label": "Allottee"
      },
      "Allottee": "Shri. Chandrakant Daulat Ambadaskar",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "1941"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "789750",
    "path": "cases/65cb4951d93fe4510d4e078e/
document_1707820766916_1707820910823_Mhada_allotment_letter.pdf",
    "fileName":
"document_1707820766916_1707820910823_Mhada_allotment_letter.pdf"
  },
  {
    "documentType": {
      "label": "Lease Agreement",
      "value": "60ae1297aa6d152c1801b459"
    },
    "inputs": {
```

```
"documentDate": "03/02/2005",
"from": {
  "value": "Administrator",
  "label": "Administrator"
},
"Administrator": "Maharashtra Housing & Development Authority",
"to": {
  "value": "Lessee",
  "label": "Lessee"
},
"Lessee": "The Charkop Sai Sandesh CHSL"
},
"isHardCopy": false,
"displayStatus": false,
"id": "848059",
"path": "cases/65cb4951d93fe4510d4e078e/
document_1707820871447_1707821016209_Mhada_Lease_agreement.pdf",
"fileName":
"document_1707820871447_1707821016209_Mhada_Lease_agreement.pdf"
},
{
  "documentType": {
    "value": "60ae1273aa6d152c1801b3b7",
    "label": "List of Society Members & Area Certificate"
  },
  "inputs": {
    "documentDate": "04/02/2005"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "664362",
  "path": "cases/65cb4951d93fe4510d4e078e/
document_1707989583858_254940.pdf",
  "fileName": "document_1707989583858_254940.pdf"
},
{
  "documentType": {
    "value": "60ae1248aa6d152c1801b2ef",
    "label": "Society Share Certificate"
  },
  "inputs": {
    "documentDate": "30/09/2004",
    "to": {
      "value": "Allottee",
      "label": "Allottee"
    }
  },
}
```

```
"Allottee": "Chandrakant Daulat Ambadaskar",
"number": {
  "value": "Document_No",
  "label": "Document No"
},
"Document_No": "19"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1707989871901_175771.pdf",
"path": "cases/65cb4951d93fe4510d4e078e/
document_1707989871901_175771.pdf",
"id": "555535",
"uploadedBy": "627221f4afd7d55eddeddcb4",
"createdAt": "Thu Feb 15 2024 15:07:52 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "006946",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
  {
    "id": "174787",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Feb 13 2024 16:19:53 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Shri. Chandrakant Daulat Ambadaskar",
    "phone": "9220313515",
    "ownershipShare": "",
    "email": "",
    "id": "962110"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1273aa6d152c1801b3b7",
      "label": "List of Society Members & Area Certificate"
    }
  }
]
```

```
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "818684",
    "selectAreaTypeDocument": "Built_Up",
    "totalAreaDocument": "269",
    "squareMeterArea": "24.99",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docBuiltupPercentage": "",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "printlnReport": true,
    "_id": "65cdbea1d93fe4510d50d72a",
    "property": "2 BHK Owner Residential House For Sale Charkop, Mumbai",
    "area": "500",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
    "source": "magic_bricks",
    "expectedPrice": "6500000.00",
    "expectedRate": "13000.00",
    "builtUpExpectedRate": "6500000.00",
    "image": "cases/65cb4951d93fe4510d4e078e/indicator_1707981360460_Image.png",
    "squareMeter": "46.45",
    "id": "388257"
  },
  {
    "printlnReport": true,
    "_id": "65cdbea1d93fe4510d50d72b",
    "property": "2 BHK Owner Residential House For Sale Charkop, Mumbai",
    "area": "560.00",
    "builtUpPercentage": "0",
    "saleablePercentage": "0",
    "rateType": "price_Indicator",
    "areaType": "Built_Up",
```

```
"source": "magic_bricks",
"expectedPrice": "8000000",
"expectedRate": "14285.71",
"builtUpExpectedRate": "8000000",
"image": "cases/65cb4951d93fe4510d4e078e/
indicator_1707981391182_Image.png",
"squareMeter": "52.03",
"id": "395468"
},
{
"printlnReport": true,
"_id": "65cdbea1d93fe4510d50d72c",
"property": "1 BHK House for sale in charkop, sector 9, Kandivali West",
"area": "420.00",
"builtUpPercentage": "0",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"source": "Nobroker.com",
"expectedPrice": "6200000.00",
"expectedRate": "14761.90",
"builtUpExpectedRate": "6200000.00",
"image": "cases/65cb4951d93fe4510d4e078e/
indicator_1707982225251_Image.png",
"squareMeter": "39.02",
"id": "153360"
},
{
"printlnReport": true,
"_id": "65cdbea1d93fe4510d50d72d",
"property": "4BHK house in charkop sector 5, kandiwali (west)",
"area": "975",
"builtUpPercentage": "0",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"source": "Nobroker.com",
"expectedPrice": "16000000.00",
"expectedRate": "16410.26",
"builtUpExpectedRate": "16000000.00",
"image": "cases/65cb4951d93fe4510d4e078e/
indicator_1707982318939_Image.png",
"squareMeter": "90.58",
"id": "984181"
}
],
```

```
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cca04ed93fe4510d4fb931",
    "name": "externalimg_1707908965292_1707909108317_image_0.jpeg",
    "path": "cases/65cb4951d93fe4510d4e078e/
externalimg_1707908965292_1707909108317_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cca04ed93fe4510d4fb932",
    "name": "externalimg_1707908986471_1707909108317_image_1.jpeg",
    "path": "cases/65cb4951d93fe4510d4e078e/
externalimg_1707908986471_1707909108317_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cca04ed93fe4510d4fb933",
    "name": "externalimg_1707908998440_1707909108317_image_2.jpeg",
    "path": "cases/65cb4951d93fe4510d4e078e/
externalimg_1707908998440_1707909108317_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cca04ed93fe4510d4fb934",
    "name": "externalimg_1707909044419_1707909108317_image_3.jpeg",
    "path": "cases/65cb4951d93fe4510d4e078e/
externalimg_1707909044419_1707909108317_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65cca04ed93fe4510d4fb935",
    "name": "externalimg_1707909056314_1707909108317_image_4.jpeg",
    "path": "cases/65cb4951d93fe4510d4e078e/
externalimg_1707909056314_1707909108317_image_4.jpeg",
    "orientation": "portrait"
  },
  },
]
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cca04ed93fe4510d4fb936",
  "name": "externallmg_1707909058983_1707909108317_image_5.jpeg",
  "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707909058983_1707909108317_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cca04ed93fe4510d4fb937",
  "name": "externallmg_1707909068683_1707909108317_image_6.jpeg",
  "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707909068683_1707909108317_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cca04ed93fe4510d4fb938",
  "name": "externallmg_1707909074313_1707909108317_image_7.jpeg",
  "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707909074313_1707909108317_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65cca04ed93fe4510d4fb939",
  "name": "externallmg_1707909084064_1707909108317_image_8.jpeg",
  "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707909084064_1707909108317_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65cca04ed93fe4510d4fb93a",
  "name": "externallmg_1707908950726_1707909081311_image_0.jpeg",
  "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707908950726_1707909081311_image_0.jpeg",
  "orientation": "landscape"
},
{
```



```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65cca04ed93fe4510d4fb93b",
    "name": "externallmg_1707908952347_1707909081312_image_1.jpeg",
    "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707908952347_1707909081312_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65cca04ed93fe4510d4fb93c",
    "name": "externallmg_1707908952520_1707909081312_image_2.jpeg",
    "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707908952520_1707909081312_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65cca04ed93fe4510d4fb93d",
    "name": "externallmg_1707908953391_1707909081312_image_3.jpeg",
    "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707908953391_1707909081312_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65cca04ed93fe4510d4fb93e",
    "name": "externallmg_1707908956790_1707909081312_image_4.jpeg",
    "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707908956790_1707909081312_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65cca04ed93fe4510d4fb93f",
    "name": "externallmg_1707908960667_1707909081312_image_5.jpeg",
    "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707908960667_1707909081312_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
    "status": false,
    "_id": "65cca04ed93fe4510d4fb940",
    "name": "externallmg_1707908965875_1707909081312_image_6.jpeg",
    "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707908965875_1707909081312_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65cca04ed93fe4510d4fb941",
    "name": "externallmg_1707908972316_1707909081312_image_7.jpeg",
    "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707908972316_1707909081312_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65cca04ed93fe4510d4fb942",
    "name": "externallmg_1707908985261_1707909081312_image_8.jpeg",
    "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707908985261_1707909081312_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65cca04ed93fe4510d4fb943",
    "name": "externallmg_1707908990670_1707909081312_image_9.jpeg",
    "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707908990670_1707909081312_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65cca04ed93fe4510d4fb944",
    "name": "externallmg_1707908994847_1707909081312_image_10.jpeg",
    "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707908994847_1707909081312_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
```

```
    "_id": "65cca04ed93fe4510d4fb945",
    "name": "externallmg_1707909000397_1707909081312_image_11.jpeg",
    "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707909000397_1707909081312_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65cca04ed93fe4510d4fb946",
    "name": "externallmg_1707909002915_1707909081312_image_12.jpeg",
    "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707909002915_1707909081312_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65cca04ed93fe4510d4fb947",
    "name": "externallmg_1707909016615_1707909081313_image_13.jpeg",
    "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707909016615_1707909081313_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65cca04ed93fe4510d4fb948",
    "name": "externallmg_1707909023145_1707909081313_image_14.jpeg",
    "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707909023145_1707909081313_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65cca04ed93fe4510d4fb949",
    "name": "externallmg_1707909025544_1707909081313_image_15.jpeg",
    "path": "cases/65cb4951d93fe4510d4e078e/
externallmg_1707909025544_1707909081313_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65cca04ed93fe4510d4fb94a",
```

```
    "name": "externalImg_1707909036255_1707909081313_image_16.jpeg",
    "path": "cases/65cb4951d93fe4510d4e078e/
externalImg_1707909036255_1707909081313_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65cca04ed93fe4510d4fb94b",
    "name": "externalImg_1707909046393_1707909081313_image_17.jpeg",
    "path": "cases/65cb4951d93fe4510d4e078e/
externalImg_1707909046393_1707909081313_image_17.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-02-13T10:49:53.126Z",
"updatedAt": "2024-02-15T10:01:12.992Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. B - 19, Ground Floor, Charkop Sai Sandesh Co-op.
Hsg. Soc. Ltd., Plot No. 843, Sector 8, RSC - 12, Near Akshara School, Village -
Charkop, Kandivali (West)\t, Taluka - Borivali, District - Mumbai Suburban District,
Mumbai, PIN Code - 400 067, State - Maharashtra, India",
"updatedBy": "627221f4afd7d55eddeddcb4",
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "Shri. Chandrakant Daulat Ambadaskar",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner",
"siteVisitContactNo": "9220313515",
"buildingServicesRate": "2700",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "MHADA Allotment Letter",
```

```
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 269.00",
"flatRate": "16200.00",
"landOtherRate": "13500",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"finalSaleablePercentage": "",
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. as per actual site measurement is
mentioned below:\nGround Floor = 241.00 Sq. Ft. \nFirst Floor =262.00 Sq. Ft.
\nTerrace Floor = 232.00 Sq. Ft. \nTotal Carpet Area = 735.00 Sq. Ft.",
"toBeAdded": "",
"reportGeneratedDate": "Thu Feb 15 2024 13:33:08 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-02-14"
}
```

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			