

## Structural Stability Report

Structural Observation Report of Residential Flat No. AL-5/5/15, 3<sup>rd</sup> Floor, Building No AL-5-5, "Garden View Apartment Owners Association", Plot No. 1, Sector 16, Acharya Vinobha Bhave Road, Village - Chinchavli, Airoli, Gut No. 267 Part & 268 Part, Taluka - Thane, District - Thane, Navi Mumbai, PIN Code - 400 708, State - Maharashtra, India.

Name of Owner: **Mr. Vivek Kumar Singh & Mrs. Priti Kumari**

This is to certify that on visual inspection, it appears that the structure of the at "Garden View Apartment Owners Association", is in good condition and the future life can be reasonably taken under good condition and with proper periodic repairs & maintenance is about 26 years.

### General Information:

A.	Introduction	
1	Name of Building	"Garden View Apartment Owners Association"
2	Property Address	Residential Flat No. AL-5/5/15, 3 <sup>rd</sup> Floor, Building No AL-5-5, "Garden View Apartment Owners Association", Plot No. 1, Sector 16, Acharya Vinobha Bhave Road, Village - Chinchavli, Airoli, Gut No. 267 Part & 268 Part, Taluka - Thane, District - Thane, Navi Mumbai, PIN Code - 400 708, State - Maharashtra, India.
3	Type of Building	Residential used
4	No. of Floors	Ground + 3 Upper Floors
5	Whether stilt / podium / open parking provided	Open Parking
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	1990 (As per site information)
11	Present age of building	34 years
12	Residual age of the building	26 years Subject to proper, preventive periodic maintenance & structural repairs.
13	No. of flats (Per Floor)	4 Flats on 3 <sup>rd</sup> Floor
14	Methodology adopted	As per visual site inspection



Thane : 101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) - 400 601, (M.S.), INDIA  
E-mail : thane@vastukala.org, Tel. : 80978 82976 / 90216 25621

### Our Pan India Presence at :

Mumbai Aurangabad Pune Rojkot  
Thane Nanded Indore Roipur  
Delhi NCR Nashik Ahmedabad Jaipur

Regd. Office : B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Andheri (East), Mumbai - 400 072, (M.S.), INDIA  
TeleFax : +91 22 28371325/24  
mumbai@vastukala.org



<b>B. External Observation of the Building</b>		
1	Plaster	Good Condition
2	Chajjas	Good Condition
3	Plumbing	Good Condition
4	Cracks on the external walls	Not Found
5	Filling cracks on the external walls	Not Found
6	Cracks on columns & beams	Not Found
7	Vegetation	Not Found
8	Leakages of water in the drainage pipes or water pipes	Not Found
9	Dampness external in the wall due to leakages	Not Found
10	Any other observation about the condition of external side of the building	Structural Stability Report from licensed structural engineers not provided for our verification.
<b>C Internal Observation of the common areas of the building and captioned premises</b>		
1	Beams (Cracks & Leakages)	Not Found
2	Columns (Cracks & Leakages)	Not Found
3	Ceiling (Cracks & Leakages)	Not Found
4	Leakages inside the property	Not Found
5	Painting inside the property	Good
6	Maintenance of staircase & cracks	Good

<b>D Common Observation</b>		
1	Structural Audit of the Building Under Bye – Laws No. 77 of the Model Bye Laws (Co-Operative Societies Act / Rules)	As per bye Laws No. 77 of Co-Op. Societies bye Laws under the Act the society shall conduct a Structural Audit of the building of the society as follows
2	Remark	No Structural Audit Report is furnished for the perusal.

<b>E Conclusion</b>	
<p>The captioned building is having Ground + 3 Upper Floors which are constructed in year 1990 as per site information. Estimated future life under present circumstances is about 26 years subject to proper, preventive periodic maintenance &amp; structural repairs.</p> <p>The inspection dated 06.02.2024 reveals minor structural damage or deterioration to the building. The building is well as the property is maintained in good condition &amp; will stand future life subject to proper, preventive periodic maintenance &amp; Good structural repairs.</p> <p>Our Observations about the structure are given above.</p> <p>The above assessment is based on visual inspection only. Separate structural audit from licensed structural engineers is advised to assess exact balance life of structure.</p>	

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Sharadkumar B.  
Chalikwar

Director

Sharadkumar B. Chalikwar

Govt. Reg. Valuer

Chartered Engineer (India)

Reg. No. (N) CCIT/1-14/52/2008-09

SBI Empanelment No.: SME/TCC/2021-22/86/3

Digitally signed by Sharadkumar B. Chalikwar  
DN: cn=Sharadkumar B. Chalikwar,  
o=Vastukala Consultants (I) Pvt. Ltd.,  
ou=CMD, email=cmd@vastukala.org, c=IN  
Date: 2024.02.15 16:56:44 +05'30'

Auth. Sign.



Vastukala Consultants (I) Pvt. Ltd.

An ISO 9001:2015 Certified Company

www.vastukala.org



## Actual Site Photographs

