

Structural Stability Report

Structural Observation Report of Residential Flat No. 10, 2nd Floor, Building No AL / 5 - 21, "**Shiv Vaibhav Apartment Owners Association Limited**", Plot No. 11, Sector 16, CIDCO Colony, Village - Airoli, Navi Mumbai, Taluka - Thane, District - Thane, PIN Code - 400 708, State - Maharashtra, India.

Name of Owner: **Smt. Deepika Deepak Golatkar & Mr. Saurabh Deepak Golatkar.**

This is to certify that on visual inspection, it appears that the structure of the at "**Shiv Vaibhav Apartment Owners Association Limited.**" is in normal condition and the future life can be reasonably taken under normal condition and with proper periodic repairs & maintenance is about 24 years.

General Information:

A.		Introduction
1	Name of Building	Shiv Vaibhav Apartment Owners Association Limited
2	Property Address	Residential Flat No. 10, 2 nd Floor, Building No AL / 5 - 21, " Shiv Vaibhav Apartment Owners Association Limited ", Plot No. 11, Sector 16, CIDCO Colony, Village - Airoli, Navi Mumbai, Taluka - Thane, District - Thane, PIN Code - 400 708, State - Maharashtra, India.
3	Type of Building	Residential used
4	No. of Floors	Ground + 03 Upper Floors
5	Whether still / podium / open parking provided	Open Parking Space
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	1988 (Approx.)
11	Present age of building	36 years
12	Residual age of the building	24 years Subject to proper, preventive periodic maintenance & structural repairs.
13	No. of flats (Per Floor)	2 nd Floor is having 04 Flats
14	Methodology adopted	As per visual site inspection



Our Pan India Presence at :

- Mumbai
- Aurangabad
- Pune
- Rajkot
- Thane
- Nanded
- Indore
- Roipur
- Delhi NCR
- Nashik
- Ahmedabad
- Jaipur

- Regd. Office :** B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Andheri (East), Mumbai - 400 072, (M.S.), INDIA
- TeleFax : +91 22 28371325/24
- mumbai@vastukala.org

B. External Observation of the Building		
1	Plaster	Normal Condition
2	Chajjas	Normal Condition
3	Plumbing	Normal Condition
4	Cracks on the external walls	Not Found
5	Filling cracks on the external walls	Not Found
6	Cracks on columns & beams	Not Found
7	Vegetation	Not Found
8	Leakages of water in the drainage pipes or water pipes	Not Found
9	Dampness external in the wall due to leakages	Not Found
10	Any other observation about the condition of external side of the building	The external condition of the building is in normal condition
C Internal Observation of the common areas of the building and captioned premises		
1	Beams (Cracks & Leakages)	Normal Condition
2	Columns (Cracks & Leakages)	Normal Condition
3	Ceiling (Cracks & Leakages)	Normal Condition
4	Leakages inside the property	Not Found
5	Painting inside the property	Normal
6	Maintenance of staircase & cracks	Normal

D Common Observation		
1	Structural Audit of the Building Under Bye – Laws No. 77 of the Model Bye Laws (Co-Operative Societies Act / Rules)	As per bye Laws No. 77 of Co-Op. Societies bye Laws under the Act the society shall conduct a Structural Audit of the building of the society as follows
2	Remark	No Structural Audit Report is furnished for the perusal

E Conclusion		
<p>The captioned building is having Ground + 03 Upper Floors which are constructed in year 1988 (Approx.). Estimated future life under present circumstances is about 24 Years subject to proper, preventive periodic maintenance & structural repairs.</p> <p>The inspection dated 17.02.2024 reveals no structural damage or deterioration to the building. The building is well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & normal structural repairs.</p> <p>Our Observations about the structure are given above.</p> <p>The above assessment is based on visual inspection only.</p>		

For VASTUKALA CONSULTANTS (I) PVT. LTD.

**Manoj
Chalikwar**
Director

Manoj Chalikwar

Govt. Reg. Valuer

Chartered Engineer (India)

Reg. No. IBBI/RV/07/2018/10366

State Bank of India Empanelment No.: SME/TCC/2021-22/86/3

Digitally signed by Manoj Chalikwar
DN: cn=Manoj Chalikwar, o=Vastukala
Consultants (I) Pvt. Ltd., ou=Mumbai
email=manoj@vastukala.org, c=IN
Date: 2024.02.21 10:48:16 +05'30'

Auth. Sign.



Vastukala Consultants (I) Pvt. Ltd.

An ISO 9001:2015 Certified Company

www.vastukala.org



Actual Site Photographs

