CIN: U74120MH2010PTC207869 MSME Reg. No.: UDYAM-MH-18-0083617 An ISO 9001:2015 Certified Company





Structural Stability Report Prepared for SBI / Jakegram Branch / Mr. Milan Kumar Kushwaha (7244/2305163)

Page 1 of 4

Vastu/Thane/02/2024/7244/2305163 26/15-385-PSVS Date: 26.02.2024

### Structural Stability Report

Structural Observation Report of Residential Flat No. 602, 6th Floor, Building No VI, "Sarvoday Garden", Sarvoday Garden Bldg. No. 3, 4, 5 & 6 Co-Op. Hsg. Soc. Ltd., Near Bhanu - Sagar Theatre, Near Kalyan Railway Station, Off. Valipeer Road, Village - Kalyan, Taluka - Kalyan, District - Thane, Kalyan (West), PIN Code - 421 301, State - Maharashtra, India.

Name of Owner: Mr. Shailesh Suresh Rawool.

Name of Proposed Purchaser: Mr. Milan Kumar Kushwaha & Mrs. Poonam Milan Kushwaha

This is to certify that on visual inspection, it appears that the structure of the at "Sarvoday Garden", is in good condition and the future life can be reasonably taken under good condition and with proper periodic repairs & maintenance is about 43 years.

#### **General Information:**

A.	\ \	Introduction
1	Name of Building	"Sarvoday Garden"
2	Property Address	Residential Flat No. 602, 6th Floor, Building No VI,
		"Sarvoday Garden", Sarvoday Garden Bldg. No. 3, 4, 5 &
		6 Co-Op. Hsg. Soc. Ltd., Near Bhanu - Sagar Theatre,
		Near Kalyan Railway Station, Off. Valipeer Road, Village -
	1/	Kalyan, Taluka - Kalyan, District - Thane, Kalyan (West),
		PIN Code – 421 301, State - Maharashtra, India.
3	Type of Building	Residential used
4	No. of Floors	Stilt + 7 Upper Floors
5	Whether stilt / podium / open parking	Stilt / Covered Parking
	provided	
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	2007 (As Per Part Occupancy Certificate)
11	Present age of building	17 years
12	Residual age of the building	43 years Subject to proper, preventive periodic
		maintenance & structural repairs.
13	No. of flats (Per Floor)	
14	Methodology adopted	As per visual site inspection

www.vastukala.org P Delhi NCR P Nashik

Thane: 101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) - 400 601, (M.S.), INDIA

E-mail: thane@vastukala.org, Tel.: 80978 82976 / 90216 25621


Our Pan India Presence at :

Mumbai Thane

Aurangabad Pune Nanded

Indore Ahmedabad ? Jaipur

Rajkot Raipur



B.	External O	bservation of the Building
1	Plaster	Good Condition
2	Chajjas	Good Condition
3	Plumbing	Good Condition
4	Cracks on the external walls	Not Found
5	Filling cracks on the external walls	Not Found
6	Cracks on columns & beams	Not Found
7	Vegetation	Not Found
8	Leakages of water in the drainage pipes	Not Found
	or water pipes	
9	Dampness external in the wall due to	Not Found
	leakages	
10	Any other observation about the condition	Structural Stability Report from licensed structural
	of external side of the building	engineers not provided for our verification.
С	Internal Observation of the common areas of the building and captioned premises	
1	Beams (Cracks & Leakages)	Not Found
2	Columns (Cracks & Leakages)	Not Found
3	Ceiling (Cracks & Leakages)	Not Found
4	Leakages inside the property	Not Found
5	Painting inside the property	Good Condition
6	Maintenance of staircase & cracks	Good

D	Common Observation	
1	Structural Audit of the Building Under Bye	As per bye Laws No. 77 of Co-Op. Societies bye Laws
	- Laws No. 77 of the Model Bye Laws (Co-	under the Act the society shall conduct a Structural Audit of
	Operative Societies Act / Rules)	the building of the society as follows
2	Remark	No Structural Audit Report is furnished for the perusal.

#### Conclusion

The captioned building is having Stilt + 7 Upper Floor which are constructed in year 2007 As per Part Occupancy Certificate. Estimated future life under present circumstances is about 43 years subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 06.02.2024 of building. The building is well as the property is maintained in good condition & will stand future life subject to proper, preventive periodic maintenance & Good structural repairs.

Our Observations about the structure are given above.

The above assessment is based on visual inspection only. Separate structural audit from licensed structural engineers is advised to assess exact balance life of structure.

## For VASTUKALA CONSULTANTS (I) PVT. LTD.

# Sharadkumar Digitally signed by Sharadkumar B. Chalikwar DN: cn=Sharadkumar B. Chalikwar, B. Chalikwar

o=Vastukala Consultants (I) Pvt Ltd., ou=CMD, email=cmd@vastukala.org, Date: 2024.02.26 17:06:37 +05'30'

Auth. Sign

Sharadkumar B. Chalikwar

Structural Engineer License No.: STATE/R/2022/APL/01785

Govt. Reg. Valuer

Director

Chartered Engineer (India)

Reg. No. (N) CCIT/1-14/52/2008-09

SBI Empanelment No.: SME/TCC/2021-22/85/13





## **Actual site photographs**

















# **Actual site photographs**











Think.Innovate.Create

