CIN: U74120MH2010PTC207869 MSME Reg. No.: UDYAM-MH-18-0083617 An ISO 9001:2015 Certified Company





Structural Stability Report Prepared for SBI / SBI / RACPC Andheri (East)/ Mrs. Sanjana Manish Sawant (7262/2305173)

Page 1 of 3

Vastu/Mumbai/02/2024/7262/2305173 27/04-395-PRSH Date: 27.02.2024

## **Structural Stability Report**

Structural Observation Report of Residential Flat No. A-704, 7th Floor, Wing - A, "Shreeji Paradise Co-Op. Hsg. Soc. Ltd. ", Shreeji Paradise, Jai Bhawani Mata Road, near to Sani Park, off. Ramesh Nagar, Amboli, Village - Ambivali, Andheri (West), Mumbai - 400 058, State - Maharashtra, Country - India.

### Name of Owner: Mrs. Sanjana Manish Sawant

This is to certify that on visual inspection, it appears that the structure of the at " Shreeji Paradise Co-Op. Hsg. Soc. Ltd.", is in good condition and the future life can be reasonably taken under good condition and with proper periodic repairs & maintenance is about 35 years.

#### General Information:

A.	\	Introduction
1	Name of Building	" Shreeji Paradise Co-Op. Hsg. Soc. Ltd."
2	Property Address	Residential Flat No. A-704, 7th Floor, Wing - A, "Shreeji
	X V	Paradise Co-Op. Hsg. Soc. Ltd. ", Shreeji Paradise, Jai
	7.1	Bhawani Mata Road, near to Sani Park, off. Ramesh
	\ <u>\</u>	Nagar, Amboli, Village - Ambivali, Andheri (West), Mumbai
	1	- 400 058, State - Maharashtra, Country - India.
3	Type of Building	Residential used
4	No. of Floors	Stilt + 7 Upper Floors
5	Whether stilt / podium / open parking	Stilt Car Parking Space
	provided	
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	1999 (As per Occupancy Certificate)
11	Present age of building	25 years
12	Residual age of the building	35 years Subject to proper, preventive periodic
		maintenance & structural repairs.
13	No. of flats (Per Floor)	05 Flats on 7th Floor
14	Methodology adopted	As per visual site inspection

B.	External Observation of the Building		
1	Plaster	Good Condition	Stimey & Aplantare Architector
2	Chajjas	Good Condition	Chartest Entract Try Co. Co.
3	Plumbing	Good Condition	Tro Marguo press



Regd. Office: B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Andheri (East), Mumbai - 400 072, (M.S.), INDIA

TeleFax: +91 22 28371325/24 mumbai@vastukala.org

4	Cracks on the external walls	Not Found
5	Filling cracks on the external walls	Not Found
6	Cracks on columns & beams	Not Found
7	Vegetation	Not Found
8	Leakages of water in the drainage pipes	Not Found
	or water pipes	
9	Dampness external in the wall due to	Not Found
	leakages	
10	Any other observation about the	Structural Stability Report from licensed structural
	condition of external side of the building	engineers not provided for our verification.
C	Internal Observation of the common areas of the building and captioned premises	
1	Beams (Cracks & Leakages)	Not Found
2	Columns (Cracks & Leakages)	Not Found
3	Ceiling (Cracks & Leakages)	Not Found
4	Leakages inside the property	Not Found
5	Painting inside the property	Normal Condition
6	Maintenance of staircase & cracks	Good

D	Common Observation	
1	Structural Audit of the Building Under Bye	As per bye Laws No. 77 of Co-Op. Societies bye Laws
	- Laws No. 77 of the Model Bye Laws	under the Act the society shall conduct a Structural Audit
	(Co-Operative Societies Act / Rules)	of the building of the society as follows
2	Remark	i) No Structural Audit Report is furnished for the
	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	perusal.
	7.3	ii) At the time of site visit, flat internal renovation work
		is in progress.

#### Ε Conclusion

The captioned building is having Stilt + 7 Upper Floors which are constructed in year 1999 (As per Occupancy Certificate). Estimated future life under present circumstances is about 35 years subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 09.02.2024 of building. The building is well as the property is maintained in good condition & will stand future life subject to proper, preventive periodic maintenance & Good structural repairs.

Our Observations about the structure are given above.

The above assessment is based on visual inspection only. Separate structural audit from licensed structural engineers is advised to assess exact balance life of structure.

Auth. Sign.

# For VASTUKALA CONSULTANTS (I) PVT. LTD.

# B. Chalikwar

Sharadkumar Digitally signed by Sharadkumar B. Chalikwar DN: cn=Sharadkumar B. Chalikwar, o=Vastukala Consultants (I) Pvt. Ltd., ou=CMD, email=cmd@vastukala.org, c= Date: 2024.02.27 13:06:48 +05'30'

Director

#### Sharadkumar B. Chalikwar

Structural Engineer Licence No. STATE/R/2022/APL/01785 Govt. Reg. Valuer Chartered Engineer (India) Reg No. (N) CCIT/1-14/52/2008-09

SBI Empanelment No.: SME / TCC / 2021 - 22 / 85 / 13





# **Actual site photographs**





















