

Structural Stability Report

Structural Observation Report of Residential Flat No. 42/1666, Ground Floor, Building No 42, "D. N. Nagar Dadabhai Niwas Co-op. Hsg. Soc. Ltd.", D. N. Nagar, Village - Andheri, Municipality Ward No. K/ West Ward, Andheri (West), Taluka - Andheri, District - Mumbai Suburban District, Mumbai, PIN Code - 400 058, State - Maharashtra, India.

Name of Owner: **Mr. Sameer Dashrath Sawant & Mr. Dashrath Vishram Sawant**

This is to certify that on visual inspection, it appears that the structure of the at "D. N. Nagar Dadabhai Niwas Co-op. Hsg. Soc. Ltd." is in normal condition and the future life can be reasonably taken under normal condition and with proper periodic repairs & maintenance is about 5 years.

General Information:

A.		Introduction
1	Name of Building	D. N. Nagar Dadabhai Niwas Co-op. Hsg. Soc. Ltd.
2	Property Address	Residential Flat No. 42/1666, Ground Floor, Building No 42, "D. N. Nagar Dadabhai Niwas Co-op. Hsg. Soc. Ltd.", D. N. Nagar, Village - Andheri, Municipality Ward No. K/ West Ward, Andheri (West), Taluka - Andheri, District - Mumbai Suburban District, Mumbai, PIN Code - 400 058, State - Maharashtra, India.
3	Type of Building	Residential used
4	No. of Floors	Ground + 4 Upper Floors
5	Whether stilt / podium / open parking provided	Open Car Parking
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	1969 (As per agreement)
11	Present age of building	55 years



Our Pan India Presence at :

Mumbai Aurangabad Pune Rajkot
Thane Nanded Indore Raipur
Delhi NCR Nashik Ahmedabad Jaipur

Regd. Office : B1-001, U/B Floor, Boomerang,
Chandivli Farm Road, Andheri (East),
Mumbai - 400 072, (M.S.), INDIA
TeleFax : +91 22 28371325/24
mumbai@vastukala.org

12	Residual age of the building	5 years Subject to proper, preventive periodic maintenance & structural repairs
13	No. of flats (Per Floor)	Ground Floor is having 8 Flats
14	Methodology adopted	As per visual site inspection
B. External Observation of the Building		
1	Plaster	Normal Condition
2	Chajjas	Normal Condition
3	Plumbing	Normal Condition
4	Cracks on the external walls	Found at some place
5	Filling cracks on the external walls	Not Found
6	Cracks on columns & beams	Not Found
7	Vegetation	Not Found
8	Leakages of water in the drainage pipes or water pipes	Not Found
9	Dampness external in the wall due to leakages	Found
10	Any other observation about the condition of external side of the building	The external condition of the building is in normal condition
C Internal Observation of the common areas of the building and captioned premises		
1	Beams (Cracks & Leakages)	Normal Condition
2	Columns (Cracks & Leakages)	Normal Condition
3	Ceiling (Cracks & Leakages)	Normal Condition
4	Leakages inside the property	Not Found
5	Painting inside the property	Normal
6	Maintenance of staircase & cracks	Normal

D Common Observation		
1	Structural Audit of the Building Under Bye – Laws No. 77 of the Model Bye Laws (Co-Operative Societies Act / Rules)	As per bye Laws No. 77 of Co-Op. Societies bye Laws under the Act the society shall conduct a Structural Audit of the building of the society as follows
2	Remark	No Structural Audit Report is furnished for the perusal

E Conclusion
<p>The captioned building is having Ground + 4 Upper Floors which are constructed in year 1969 (As per agreement). Estimated future life under present circumstances is about 5 years' subject to proper, preventive periodic maintenance & structural repairs.</p> <p>The inspection dated 28.02.2024 reveals no structural damage or deterioration to the building. The building is well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & Good structural repairs.</p> <p>Our Observations about the structure are given above.</p> <p>The above assessment is based on visual inspection only.</p>

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Sharadkumar
Chalikwar

Director

Sharadkumar Chalikwar

Govt. Reg. Valuer

Chartered Engineer (India)

Reg. No. [N]C.C.I.T./ - 14/52/2008-09

State Bank of India Empanelment No.: SWE/TCG/2021-22/86/3

Digitally signed by Sharadkumar Chalikwar
DN: cn=Sharadkumar Chalikwar, o=Vastukala
Consultants (I) Pvt. Ltd., ou=Mumbai,
email=cmd@vastukala.org, c=IN
Date: 2024.03.04 13:12:03 +05'30'

Aufh. Sign.

Vastukala Consultants (I) Pvt. Ltd.



Actual Site Photographs



Actual Site Photographs

