

```
{
  "typeOfReport": {
    "value": "Land_and_Building",
    "label": "Land and Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": "",
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
    "city": "Mumbai"
  },
  "client": {
    "_id": "65eabe3ff9222577acc07f2d",
```

```
"type": "PRIVATE_CLIENT",
"name": "M/s. Conco Realty Private Limited",
"displayName": "M/s. Conco Realty Private Limited",
"initial": "M"
},
"branch": "",
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": "",
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "64cde526dc9f3034f3fefa49",
    "role": "FRONTDESK",
    "firstName": "Rashmi",
    "email": "rashmijadhav14feb@gmail.com",
    "lastName": "Jadhav",
    "mobileNo": "7738144625",
    "shortName": "RJ",
    "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
    "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "shortName": "MBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\
\profilePhoto_1622114310919_Manoj C.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60016f965256c07aec8e6dd6",
```

```
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Akhilesh",
"email": "akhilesh.yadav@vastukala.org",
"lastName": "Yadav",
"mobileNo": "9545753921",
"designation": "Processing Officer",
"workWithDocumentMaker": "6009222ca16fab0f2af9b0bf",
"profilePhoto": "users\\60016f965256c07aec8e6dd6\
\profilePhoto_1622371927126_Akhilesh Photo (2).jpg",
"shortName": "AY"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60016f965256c07aec8e6dd6",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Akhilesh",
  "email": "akhilesh.yadav@vastukala.org",
  "lastName": "Yadav",
  "mobileNo": "9545753921",
  "designation": "Processing Officer",
  "workWithDocumentMaker": "6009222ca16fab0f2af9b0bf",
  "profilePhoto": "users\\60016f965256c07aec8e6dd6\
\profilePhoto_1622371927126_Akhilesh Photo (2).jpg",
  "shortName": "AY"
},
"checker": {
  "_id": "60016f965256c07aec8e6dd6",
  "profilePhoto": "users\\60016f965256c07aec8e6dd6\
\profilePhoto_1622371927126_Akhilesh Photo (2).jpg",
  "firstName": "Akhilesh",
  "lastName": "Yadav",
  "shortName": "AY",
  "email": "akhilesh.yadav@vastukala.org",
  "designation": "Processing Officer",
  "mobileNo": "9545753921",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": "6009222ca16fab0f2af9b0bf"
},
"valuers": [],
},
"clientType": {
  "value": "PRIVATE_CLIENT",
  "label": "Private Clients"
},
"location": {
```

```
"latitude": "19.113889",
"longitude": " 72.878131"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
```

```
"status": true,
"name": "Floor No",
"key": "floorNo",
"value": "Basement",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Andheri",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
```

```
"label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
```

```
"name": "Project Name",
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "Land Bearing CTS No. 86, 86/1 to 8 & 88 AND Land Bearing CTS No. 106,
111, 120, 122, 132, 139, 148 and 161 ",
```

```
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
```



```
"name": "Postal Code",
"key": "postalCode",
"value": "400059",
"label": false
},
"suburb": {
"status": false,
"name": "Suburb",
"key": "suburb",
"value": "",
"label": false
}
},
"general": {
"unitBoundaries": {
"isDisplay": false
}
},
"igrFinalRate": {
"floorRatePercentage": "0.00"
},
"outgoingDetail": {
"monthlyRent": ""
},
"siteMeasurement": {
"isSiteVisitAllowed": true
},
"finalPlinthArea": {
"area": "0.00"
},
"routeMap": {
"finalLatLng": {
"coordinates": []
}
},
"locationMapImg": []
},
"outward": {
"status": true,
"remark": "SYSTEMGENERATED",
"date": "Fri Mar 29 2024 11:00:46 GMT+0530 (India Standard Time)",
"number": "2305794",
"dayCount": "4",
"monthCount": "542",
"generatedBy": "60016f965256c07aec8e6dd6"
},
"rateVerify": {
```

```
"status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
```

```
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
"label": "Flooring, Tilling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
```

```
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
```

```
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"invoices": [],
"paymentIds": [],
"_id": "65eabe3ff9222577acc07f35",
"ownerName": "M/s. Conco Realty Private Limited",
"ownerPhoneNo": "8591751697",
"fullAddress": "Residential Amalgamated Flats No. Land Bearing CTS No. 86, 86/1 to
8 & 88 AND Land Bearing CTS No. 106, 111, 120, 122, 132, 139, 148 and 161 ,
Basement Floor, Taluka - Andheri, 400059, State - Maharashtra, India",
"remark": "",
"documents": [],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
}
```

```
"caseNumber": "007558",
"createdBy": "64cde526dc9f3034f3fefa49",
"caseHistory": [
  {
    "id": "968292",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Mar 08 2024 12:59:03 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "M/s. Conco Realty Private Limited",
    "phone": "8591751697",
    "ownershipShare": "",
    "email": "",
    "id": "265566"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6606535a5ca1625e50664f09",
    "name": "externallmg_1711690586018_Dahisar_1.PNG",
    "path": "cases/65eabe3ff9222577acc07f35/externallmg_1711690586018_Dahisar_1.PNG",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6606535a5ca1625e50664f0a",
    "name": "externallmg_1711690586027_Dahisar_2.PNG",
    "path": "cases/65eabe3ff9222577acc07f35/externallmg_1711690586027_Dahisar_2.PNG",
    "orientation": "portrait"
  }
],
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6606535a5ca1625e50664f0b",
  "name": "externallmg_1711690586033_Dahisar_3.PNG",
  "path": "cases/65eabe3ff9222577acc07f35/
externallmg_1711690586033_Dahisar_3.PNG",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6606535a5ca1625e50664f0c",
  "name": "externallmg_r_1711690586015_Dahisar_1.jpg",
  "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690586015_Dahisar_1.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6606535a5ca1625e50664f0d",
  "name": "externallmg_r_1711690586031_Dahisar_3.jpg",
  "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690586031_Dahisar_3.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6606535a5ca1625e50664f0e",
  "name": "externallmg_r_1711690586041_Dahisar_5.jpg",
  "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690586041_Dahisar_5.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6606535a5ca1625e50664f0f",
  "name": "externallmg_r_1711690586042_Dahisar_6.jpg",
  "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690586042_Dahisar_6.jpg",
  "orientation": "landscape"
},
{
```

```
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6606535a5ca1625e50664f10",
"name": "externallmg_r_1711690586044_Dahisar_7.jpg",
"path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690586044_Dahisar_7.jpg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6606535a5ca1625e50664f11",
"name": "externallmg_r_1711690586038_Dahisar_4.jpg",
"path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690586038_Dahisar_4.jpg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6606535a5ca1625e50664f12",
"name": "externallmg_r_1711690586022_Dahisar_2.jpg",
"path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690586022_Dahisar_2.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6606535a5ca1625e50664f13",
"name": "externallmg_r_1711690586048_Dahisar_9.jpg",
"path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690586048_Dahisar_9.jpg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "6606535a5ca1625e50664f14",
"name": "externallmg_r_1711690586045_Dahisar_8.jpg",
"path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690586045_Dahisar_8.jpg",
"orientation": "landscape"
},
{
"type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6606535a5ca1625e50664f15",
  "name": "externalimg_r_1711690586049_Dahisar_10.jpg",
  "path": "cases/65eabe3ff9222577acc07f35/
externalimg_r_1711690586049_Dahisar_10.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6606535a5ca1625e50664f16",
  "name": "externalimg_r_1711690586052_Dahisar_11.jpg",
  "path": "cases/65eabe3ff9222577acc07f35/
externalimg_r_1711690586052_Dahisar_11.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6606536a5ca1625e50664f34",
  "name": "externalimg_r_1711690602554_Dahisar_15.jpg",
  "path": "cases/65eabe3ff9222577acc07f35/
externalimg_r_1711690602554_Dahisar_15.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6606536a5ca1625e50664f35",
  "name": "externalimg_r_1711690602546_Dahisar_13.jpg",
  "path": "cases/65eabe3ff9222577acc07f35/
externalimg_r_1711690602546_Dahisar_13.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6606536a5ca1625e50664f36",
  "name": "externalimg_r_1711690602541_Dahisar_12.jpg",
  "path": "cases/65eabe3ff9222577acc07f35/
externalimg_r_1711690602541_Dahisar_12.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "6606536a5ca1625e50664f37",
    "name": "externallmg_r_1711690602551_Dahisar_14.jpg",
    "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690602551_Dahisar_14.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6606536a5ca1625e50664f38",
    "name": "externallmg_r_1711690602558_Dahisar_16.jpg",
    "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690602558_Dahisar_16.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6606536a5ca1625e50664f39",
    "name": "externallmg_r_1711690602562_Dahisar_17.jpg",
    "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690602562_Dahisar_17.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6606536a5ca1625e50664f3a",
    "name": "externallmg_r_1711690602571_Dahisar_20.jpg",
    "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690602571_Dahisar_20.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6606536a5ca1625e50664f3b",
    "name": "externallmg_r_1711690602575_Dahisar_22.jpg",
    "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690602575_Dahisar_22.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6606536a5ca1625e50664f3c",
```

```
    "name": "externallmg_r_1711690602575_Dahisar_23.jpg",
    "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690602575_Dahisar_23.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6606536a5ca1625e50664f3d",
    "name": "externallmg_r_1711690602563_Dahisar_18.jpg",
    "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690602563_Dahisar_18.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6606536a5ca1625e50664f3e",
    "name": "externallmg_r_1711690602567_Dahisar_19.jpg",
    "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690602567_Dahisar_19.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6606536a5ca1625e50664f3f",
    "name": "externallmg_r_1711690602572_Dahisar_21.jpg",
    "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690602572_Dahisar_21.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6606536a5ca1625e50664f40",
    "name": "externallmg_r_1711690602581_Dahisar_25.jpg",
    "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690602581_Dahisar_25.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6606536a5ca1625e50664f41",
    "name": "externallmg_r_1711690602577_Dahisar_24.jpg",
```

```
    "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690602577_Dahisar_24.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6606537b5ca1625e50664f6d",
    "name": "externallmg_r_1711690618870_Dahisar_29.jpg",
    "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690618870_Dahisar_29.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6606537b5ca1625e50664f6e",
    "name": "externallmg_r_1711690618858_Dahisar_26.jpg",
    "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690618858_Dahisar_26.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6606537b5ca1625e50664f6f",
    "name": "externallmg_r_1711690618874_Dahisar_30.jpg",
    "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690618874_Dahisar_30.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6606537b5ca1625e50664f70",
    "name": "externallmg_r_1711690618876_Dahisar_31.jpg",
    "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690618876_Dahisar_31.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6606537b5ca1625e50664f71",
    "name": "externallmg_r_1711690618879_Dahisar_32.jpg",
    "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690618879_Dahisar_32.jpg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6606537b5ca1625e50664f72",
  "name": "externallmg_r_1711690618883_Dahisar_34.jpg",
  "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690618883_Dahisar_34.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6606537b5ca1625e50664f73",
  "name": "externallmg_r_1711690618862_Dahisar_27.jpg",
  "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690618862_Dahisar_27.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6606537b5ca1625e50664f74",
  "name": "externallmg_r_1711690618866_Dahisar_28.jpg",
  "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690618866_Dahisar_28.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6606537b5ca1625e50664f75",
  "name": "externallmg_r_1711690618888_Dahisar_35.jpg",
  "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690618888_Dahisar_35.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6606537b5ca1625e50664f76",
  "name": "externallmg_r_1711690618889_Dahisar_36.jpg",
  "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690618889_Dahisar_36.jpg",
  "orientation": "landscape"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6606537b5ca1625e50664f77",
  "name": "externallmg_r_1711690618893_Kondivata_1.jpg",
  "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690618893_Kondivata_1.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6606537b5ca1625e50664f78",
  "name": "externallmg_r_1711690618900_Kondivata_3.jpg",
  "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690618900_Kondivata_3.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6606537b5ca1625e50664f79",
  "name": "externallmg_r_1711690618881_Dahisar_33.jpg",
  "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690618881_Dahisar_33.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6606537b5ca1625e50664f7a",
  "name": "externallmg_r_1711690618895_Kondivata_2.jpg",
  "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690618895_Kondivata_2.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "660653c05ca1625e50665027",
  "name": "externallmg_r_1711690688339_Kondivata_5.jpg",
  "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690688339_Kondivata_5.jpg",
  "orientation": "landscape"
},
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "660653c05ca1625e50665028",
  "name": "externallmg_r_1711690688343_Kondivata_6.jpg",
  "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690688343_Kondivata_6.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "660653c05ca1625e50665029",
  "name": "externallmg_r_1711690688344_Kondivata_7.jpg",
  "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690688344_Kondivata_7.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "660653c05ca1625e5066502a",
  "name": "externallmg_r_1711690688336_Kondivata_4.jpg",
  "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690688336_Kondivata_4.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "660653c05ca1625e5066502b",
  "name": "externallmg_r_1711690688357_Kondivata_10.jpg",
  "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690688357_Kondivata_10.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "660653c05ca1625e5066502c",
  "name": "externallmg_r_1711690688364_Kondivata_12.jpg",
  "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690688364_Kondivata_12.jpg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660653c05ca1625e5066502d",
    "name": "externallmg_r_1711690688367_Kondivata_13.jpg",
    "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690688367_Kondivata_13.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660653c05ca1625e5066502e",
    "name": "externallmg_r_1711690688350_Kondivata_8.jpg",
    "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690688350_Kondivata_8.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660653c05ca1625e5066502f",
    "name": "externallmg_r_1711690688354_Kondivata_9.jpg",
    "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690688354_Kondivata_9.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660653c05ca1625e50665030",
    "name": "externallmg_r_1711690688360_Kondivata_11.jpg",
    "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690688360_Kondivata_11.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "660653c05ca1625e50665031",
    "name": "externallmg_r_1711690688370_Kondivata_14.jpg",
    "path": "cases/65eabe3ff9222577acc07f35/
externallmg_r_1711690688370_Kondivata_14.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "660653c05ca1625e50665032",
  "name": "externalImg_r_1711690688372_Kondivata_15.jpg",
  "path": "cases/65eabe3ff9222577acc07f35/
externalImg_r_1711690688372_Kondivata_15.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "660653c05ca1625e50665033",
  "name": "externalImg_r_1711690688375_Kondivata_16.jpg",
  "path": "cases/65eabe3ff9222577acc07f35/
externalImg_r_1711690688375_Kondivata_16.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "660653c05ca1625e50665034",
  "name": "externalImg_r_1711690688377_Kondivata_17.jpg",
  "path": "cases/65eabe3ff9222577acc07f35/
externalImg_r_1711690688377_Kondivata_17.jpg",
  "orientation": "landscape"
}
],
"externalDocuments": [
  {
    "originalname": "Conco Realty Private Limited - Kondivita & Dahisar Present
Government Value.docx",
    "filename": "1709883335786_Conco_Realty_Private_Limited__Kondivita__Dahisar_
Present_Government_Value.docx",
    "path": "cases/65eabe3ff9222577acc07f35/externalDocuments/1709883335786_Co
nco_Realty_Private_Limited__Kondivita__Dahisar_Present_Government_Value.docx",
    "size": "28044179",
    "documentType": {
      "value": "649998c6cab24d3d1a2cc577",
      "label": "Draft Word Report"
    },
    "createdAt": "Fri Mar 08 2024 13:05:36 GMT+0530 (India Standard Time)",
    "uploadedBy": "60016f965256c07aec8e6dd6"
  }
],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
```

```
"remarks": [],
"createdAt": "2024-03-08T07:29:03.616Z",
"updatedAt": "2024-03-29T05:38:08.554Z",
"__v": 0,
"updatedBy": "60016f965256c07aec8e6dd6",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "M/s. Conco Realty Private Limited",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8591751697"
```

}

Name	Length	Width	Total
Composition :			
Other			
Composition :			