CIN: U74120MH2010PTC207869 MSME Reg. No.: UDYAM-MH-18-0083617 An ISO 9001:2015 Certified Company





Structural Stability Report Prepared for SBI / RACPC Ghatkopar (West)/ Shri. Shrikant Nagesh Charjan (007583/2305514)

Page 1 of 3

Vastu/Mumbai/03/2024/007583/2305514 15/02-262-PRNI

Date: 15.03.2024

## **Structural Stability Report**

Structural Observation Report of Residential Flat No. 8, 1st Floor, Wing - E, "Surya Vihar 'D' & 'E' Wing Co-Op. Hsg. Soc. Ltd.", Surya Vihar Complex, Katrap, Village - Kulgaon, Badlapur (East), Taluka – Ambernath, District - Thane, PIN - 421 503, State - Maharashtra, Country – India.

### Name of Owner: Shri. Shrikant Nagesh Charjan

This is to certify that on visual inspection, it appears that the structure of the at "Surya Vihar 'D' & 'E' Wing Co-Op. Hsg. Soc. Ltd.", is in normal condition and the future life can be reasonably taken under good condition and with proper periodic repairs & maintenance is about 34 years.

#### **General Information:**

. Soc. Ltd."
E, <b>"S</b> urya Vihar
<b>"</b> , Surya Vihar
Badlapur (East),
- 421 503, State
)
entive periodic
entive periodic
entive periodic
)

B.	External Observation of the Building		
1	Plaster	Normal Condition	Valuers & Appraisers Architects &
2	Chajjas	Normal Condition	Chartered Engineers (I)  TEV Consultants Leader's Seriences
_3	Plumbing	Normal Condition	FI 20 MH2010 PTC2018



Our Pan India Presence at:

♥ Mumbai
♥ Thane
♥ Nanded
♥ Delhi NCR
♥ Nashik

♥ Ahmedabad
♥ Jaipur

Regd. Office: B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Andheri (East), Mumbai - 400 072, (M.S.), INDIA

4	Cracks on the external walls	Not Found	
5	Filling cracks on the external walls	Not Found	
6	Cracks on columns & beams	Not Found	
7	Vegetation	Not Found	
8	Leakages of water in the drainage pipes or water pipes	Not Found	
9	Dampness external in the wall due to leakages	Found	
10	Any other observation about the	Structural Stability Report from licensed structural	
	condition of external side of the building	engineers not provided for our verification.	
С	Internal Observation of the common areas of the building and captioned premises		
1	Beams (Cracks & Leakages)	Not Found	
2	Columns (Cracks & Leakages)	Not Found	
3	Ceiling (Cracks & Leakages)	Not Found	
4	Leakages inside the property	Not Found	
5	Painting inside the property	Good	
6	Maintenance of staircase & cracks	Normal	

D	Common Observation		
1	Structural Audit of the Building Under Bye	As per bye Laws No. 77 of Co-Op. Societies bye Laws	
	- Laws No. 77 of the Model Bye Laws	under the Act the society shall conduct a Structural Audit	
	(Co-Operative Societies Act / Rules)	of the building of the society as follows	
2	Remark	No Structural Audit Report is furnished for the perusal.	

#### E Conclusion

The captioned building is having Part Ground + Part Stilt + 4 Upper Floors which are constructed in year 1998 (Part Building Completion Certificate). Estimated future life under present circumstances is about 34 years subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 12.03.2024 of building. The building is well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & normal structural repairs.

Our Observations about the structure are given above.

The above assessment is based on visual inspection only. Separate structural audit from licensed structural engineers is advised to assess exact balance life of structure.

# For VASTUKALA CONSULTANTS (I) PVT. LTD.

### **Director**

Auth. Sign.

### Sharadkumar B. Chalikwar

Structural Engineer Licence No. STATE/R/2022/APL/01785 Govt. Reg. Valuer Chartered Engineer (India) Reg No. (N) CCIT/1-14/52/2008-09 SBI Empanelment No.: SME / TCC / 2021 – 22 / 85 / 13





# **Actual site photographs**





















