

```
{
  "typeOfReport": {
    "label": "Row House",
    "value": "Row_House"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "659285df545844510d0e2b12"
    },
    "type": "CREDITOFFICER",
    "_id": "659285df545844510d0e2b14",
    "firstName": "Raghwendra",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "9918146808",
    "email": "raghwendra.kumar@unionbankofindia.bank"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "00",
    "discussWithPerson": "Raghwendra",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "659285df545844510d0e2b12",
  "name": "CAPITAL MARKET Cell M S Marg",
  "branchCode": "",
  "mobileNo": "02222629332",
  "alternateMobileNo": "",
  "email": "kashyapcmcm@unionbankofindia.bank",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Union Bank Of India Building , Ground Floor, 66/80, Mumbai Samachar
Marg, Fort, Mumbai-400023"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "60af3d172ffdf65bcd6585cd",
"role": "PICKUPPERSON",
"firstName": "Sachin",
"email": "sachin.joshi@vastukala.org",
"lastName": "Joshi",
"mobileNo": "9167204063",
"shortName": "SJ",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af3d172ffdf65bcd6585cd\
\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62691c48afd7d55eddecfda3",
"role": "ADMIN",
"firstName": "Bhavika",
"email": "bhavikachavan0102@gmail.com",
"lastName": "chavan",
"mobileNo": "8390804382",
"designation": "Site Engineer",
"shortName": "BH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "627221f4afd7d55eddeddcb4",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Prajakta",
"email": "prajakta@vastukala.org",
"lastName": "Patil",
"mobileNo": "9769797568",
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "627221f4afd7d55eddeddcb4",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Prajakta",
"email": "prajakta@vastukala.org",
"lastName": "Patil",
```

```
"mobileNo": "9769797568",
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "6084131a13f01f158c6ea1f3",
    "PANNo": "AEAPC7114Q",
    "role": "VALUER",
    "firstName": "Sharadkumar",
    "fatherName": "Baburao",
    "email": "cmd@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9422171100",
    "designation": "CMD",
    "registrationNo": [
      {
        "title": {
          "value": "Wealth_Tax",
          "label": "Wealth Tax"
        }
      }
    ],
    "_id": "6084131a13f01f158c6ea1f4",
```

```
        "number": "[N]C.C.I.T/I -14/52/2008-09"
      }
    ],
    "shortName": "SBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.254277",
  "longitude": "72.850227"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.850227,
    19.254277
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },

```

```
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": false,
  "name": "Village",
  "key": "village",
  "value": "",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Basement",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Borivali West",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
```

```
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Evershine Residency CHS,",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Holy Cross Extension Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
```

```
"status": true,
"name": "Landmark",
"key": "landmark",
"value": "I.C.Colony ",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
```



```
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "Row House 2A&2B",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
```

```
"name": "Police Station(P.S)",
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
```

```
"coordinates": []
},
"locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
```

```
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "65f3e674857bdc098aa07fe1",
"ownerName": "Luharuka Tradelink Pvt Ltd ",
"ownerPhoneNo": "0000000000",
```



```
"appAddress": "Row House 2A&2B,Evershine Residency CHS,Holy Cross Extension
Road,I.C.Colony Borivali West ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/65f3e674857bdc098aa07fe1/
document_1710485407572_1710485582093_Evershine_Agreement.pdf",
    "fileName":
"document_1710485407572_1710485582093_Evershine_Agreement.pdf",
    "id": "942946",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Fri Mar 15 2024 12:21:49 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Previous Valuation Report",
      "value": "60ae1248aa6d152c1801b2ee"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/65f3e674857bdc098aa07fe1/
document_1710485488761_1710485664113_Signed_Valuation_report.pdf",
    "fileName":
"document_1710485488761_1710485664113_Signed_Valuation_report.pdf",
    "id": "957371",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Fri Mar 15 2024 12:21:49 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Old Valution Report ",
      "value": "60ae1296aa6d152c1801b455"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/65f3e674857bdc098aa07fe1/document_1710485538998_171048571
5483_Valuation_Report_Luharuka_Tradelink_Pvt_Ltddoc.pdf",
    "fileName": "document_1710485538998_1710485715483_Valuation_Report_Luhar
uka_Tradelink_Pvt_Ltddoc.pdf",
    "id": "786320",
```

```
"uploadedBy": "60af3d172ffdf65bcd6585cd",
"createdAt": "Fri Mar 15 2024 12:22:27 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "007699",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "891895",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Mar 15 2024 11:41:00 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Luharuka Tradelink Pvt Ltd ",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "289304"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f559d6857bdc098aa37455",
    "name": "externalImg_1710578129046_1710578287695_image_0.jpeg",
    "path": "cases/65f3e674857bdc098aa07fe1/externalImg_1710578129046_1710578287695_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f559d6857bdc098aa37456",
    "name": "externalImg_1710578129229_1710578287701_image_1.jpeg",
  }
]
```

```
    "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578129229_1710578287701_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f559d6857bdc098aa37457",
    "name": "externallmg_1710578129372_1710578287701_image_2.jpeg",
    "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578129372_1710578287701_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f559d6857bdc098aa37458",
    "name": "externallmg_1710578129650_1710578287701_image_3.jpeg",
    "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578129650_1710578287701_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f559d6857bdc098aa37459",
    "name": "externallmg_1710578129944_1710578287701_image_4.jpeg",
    "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578129944_1710578287701_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f559d6857bdc098aa3745a",
    "name": "externallmg_1710578129989_1710578287701_image_5.jpeg",
    "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578129989_1710578287701_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "65f559d6857bdc098aa3745b",
    "name": "externallmg_1710578130139_1710578287701_image_6.jpeg",
    "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578130139_1710578287701_image_6.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f559d6857bdc098aa3745c",
  "name": "externallmg_1710578130414_1710578287701_image_7.jpeg",
  "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578130414_1710578287701_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f559d6857bdc098aa3745d",
  "name": "externallmg_1710578130646_1710578287701_image_8.jpeg",
  "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578130646_1710578287701_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f559d6857bdc098aa3745e",
  "name": "externallmg_1710578130944_1710578287701_image_9.jpeg",
  "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578130944_1710578287701_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f559d6857bdc098aa3745f",
  "name": "externallmg_1710578131214_1710578287701_image_10.jpeg",
  "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578131214_1710578287701_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f559d6857bdc098aa37460",
  "name": "externallmg_1710578131502_1710578287701_image_11.jpeg",
  "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578131502_1710578287701_image_11.jpeg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f559d6857bdc098aa37461",
  "name": "externallmg_1710578132019_1710578287701_image_12.jpeg",
  "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578132019_1710578287701_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f559d6857bdc098aa37462",
  "name": "externallmg_1710578132138_1710578287701_image_13.jpeg",
  "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578132138_1710578287701_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f559d6857bdc098aa37463",
  "name": "externallmg_1710578132610_1710578287701_image_14.jpeg",
  "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578132610_1710578287701_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f559d6857bdc098aa37464",
  "name": "externallmg_1710578132691_1710578287701_image_15.jpeg",
  "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578132691_1710578287701_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f559d6857bdc098aa37465",
  "name": "externallmg_1710578133077_1710578287701_image_16.jpeg",
  "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578133077_1710578287701_image_16.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f559d6857bdc098aa37466",
  "name": "externallmg_1710578133242_1710578287701_image_17.jpeg",
  "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578133242_1710578287701_image_17.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "65f559d6857bdc098aa37467",
  "name": "externallmg_1710578133613_1710578287701_image_18.jpeg",
  "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578133613_1710578287701_image_18.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65f559aa857bdc098aa37373",
  "name": "externallmg_1710578085995_1710578240374_image_0.jpeg",
  "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578085995_1710578240374_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65f559aa857bdc098aa37374",
  "name": "externallmg_1710578086006_1710578240375_image_1.jpeg",
  "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578086006_1710578240375_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65f559aa857bdc098aa37375",
  "name": "externallmg_1710578086171_1710578240375_image_2.jpeg",
  "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578086171_1710578240375_image_2.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65f559aa857bdc098aa37376",
    "name": "externallmg_1710578086343_1710578240376_image_3.jpeg",
    "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578086343_1710578240376_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65f559aa857bdc098aa37377",
    "name": "externallmg_1710578086378_1710578240376_image_4.jpeg",
    "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578086378_1710578240376_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65f559aa857bdc098aa37378",
    "name": "externallmg_1710578086580_1710578240376_image_5.jpeg",
    "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578086580_1710578240376_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65f559aa857bdc098aa37379",
    "name": "externallmg_1710578086857_1710578240376_image_6.jpeg",
    "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578086857_1710578240376_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65f559aa857bdc098aa3737a",
    "name": "externallmg_1710578087063_1710578240376_image_7.jpeg",
    "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578087063_1710578240376_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
"status": false,
  "_id": "65f559aa857bdc098aa3737b",
  "name": "externallmg_1710578087479_1710578240376_image_8.jpeg",
  "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578087479_1710578240376_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65f559aa857bdc098aa3737c",
  "name": "externallmg_1710578087659_1710578240376_image_9.jpeg",
  "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578087659_1710578240376_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65f559aa857bdc098aa3737d",
  "name": "externallmg_1710578087754_1710578240376_image_10.jpeg",
  "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578087754_1710578240376_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65f559aa857bdc098aa3737e",
  "name": "externallmg_1710578088230_1710578240376_image_11.jpeg",
  "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578088230_1710578240376_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "65f559aa857bdc098aa3737f",
  "name": "externallmg_1710578088300_1710578240376_image_12.jpeg",
  "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578088300_1710578240376_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
```



```
    "_id": "65f559aa857bdc098aa37380",
    "name": "externallmg_1710578088720_1710578240376_image_13.jpeg",
    "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578088720_1710578240376_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65f559aa857bdc098aa37381",
    "name": "externallmg_1710578089014_1710578240376_image_14.jpeg",
    "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578089014_1710578240376_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65f559aa857bdc098aa37382",
    "name": "externallmg_1710578089120_1710578240376_image_15.jpeg",
    "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578089120_1710578240376_image_15.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65f559aa857bdc098aa37383",
    "name": "externallmg_1710578089320_1710578240376_image_16.jpeg",
    "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578089320_1710578240376_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65f559aa857bdc098aa37384",
    "name": "externallmg_1710578089774_1710578240376_image_17.jpeg",
    "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578089774_1710578240376_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65f559aa857bdc098aa37385",
```

```
    "name": "externallmg_1710578089961_1710578240376_image_18.jpeg",
    "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578089961_1710578240376_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65f559dc857bdc098aa374ab",
    "name": "externallmg_1710578138103_1710578314478_image_0.jpeg",
    "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578138103_1710578314478_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65f559dc857bdc098aa374ac",
    "name": "externallmg_1710578138284_1710578314478_image_1.jpeg",
    "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578138284_1710578314478_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65f559dc857bdc098aa374ad",
    "name": "externallmg_1710578138481_1710578314478_image_2.jpeg",
    "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578138481_1710578314478_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65f559dc857bdc098aa374ae",
    "name": "externallmg_1710578138619_1710578314478_image_3.jpeg",
    "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578138619_1710578314478_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65f559dc857bdc098aa374af",
    "name": "externallmg_1710578138993_1710578314478_image_4.jpeg",
```

```
    "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578138993_1710578314478_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65f559dc857bdc098aa374b0",
    "name": "externallmg_1710578139331_1710578314478_image_5.jpeg",
    "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578139331_1710578314478_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65f559dc857bdc098aa374b1",
    "name": "externallmg_1710578139507_1710578314478_image_6.jpeg",
    "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578139507_1710578314478_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "65f559dc857bdc098aa374b2",
    "name": "externallmg_1710578139642_1710578314478_image_7.jpeg",
    "path": "cases/65f3e674857bdc098aa07fe1/
externallmg_1710578139642_1710578314478_image_7.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-03-15T06:11:00.394Z",
"updatedAt": "2024-03-16T08:35:40.359Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "62691c48afd7d55eddecfda3",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
}
```

"fullAddress": "Residential Row House No. Row House 2A&2B, Basement Floor,  
Evershine Residency CHS,, I.C.Colony , Holy Cross Extension Road, Borivali West,  
State - Maharashtra, India",  
"addressForMap": "",  
"caseReferredBy": "",  
"contactPersonName": "Luharuka Tradelink Pvt Ltd ",  
"email": "",  
"isExternal": "false",  
"isUrgent": "false",  
"ownershipShare": "",  
"proposePurchaserName": "",  
"purchaseValueAsPerDocument": "",  
"relationWithOwner": "self",  
"siteVisitContactNo": "0000000000"

}

| <b>Name</b>   | <b>Length</b> | <b>Width</b> | <b>Total</b> |
|---------------|---------------|--------------|--------------|
| <hr/>         |               |              |              |
| Composition : |               |              |              |
| <hr/>         |               |              |              |
| Other         |               |              |              |
| Composition : |               |              |              |
| <hr/>         |               |              |              |