CIN: U74120MH2010PTC207869 MSME Reg. No.: UDYAM-MH-18-0083617 An ISO 9001:2015 Certified Company





Structural Stability Report / SVC Co-Operative Bank Ltd./ Vakola Branch / Mr. Munnalal Kailashprasad Gupta (007990/2305763)

Page 1 of 3

Vastu/Mumbai/03/2024/007990/2305763 27/14-511-SK Date: 27.03.2024

### **Structural Stability Report**

Structural Observation Report of Residential Room No. 524, Ground Floor, Wing - B, Building No. 7, "Magathane Bharat Darshan Co-Op. Hsg. Soc. Ltd.", Maharashtra Housing Board Colony, Tata Power House, Jay Maharashtra Nagar, Village – Magathane, Borivali (East), Mumbai – 400 066, State - Maharashtra, Country – India.

Name of Owner: Mr. Munnalal Kailashprasad Gupta, Mr. Mukesh Kailashprasad Gupta & Mr. Rakesh Kailashprasad Gupta.

This is to certify that on visual inspection, it appears that the structure of the at **"Magathane Bharat Darshan Co-Op. Hsg. Soc. Ltd."**, is in normal condition and the future life can be reasonably taken under good condition and with proper periodic repairs & maintenance is about 12 years.

#### **General Information:**

| A. |                                       | Introduction  |
|----|---------------------------------------|---|
| 1  | Name of Building                      | "Magathane Bharat Darshan Co-Op. Hsg. Soc. Ltd."      |
| 2  | Property Address                      | Residential Room No. 524, Ground Floor, Wing - B,     |
|    |                                       | Building No. 7, "Magathane Bharat Darshan Co-Op.      |
|    |                                       | Hsg. Soc. Ltd.", Maharashtra Housing Board Colony,    |
|    |                                       | Tata Power House, Jay Maharashtra Nagar, Village –    |
|    |                                       | Magathane, Borivali (East), Mumbai – 400 066, State - |
|    |                                       | Maharashtra, Country – India.                         |
| 3  | Type of Building                      | Residential used                                      |
| 4  | No. of Floors                         | Ground + 4 <sup>th</sup> Upper Floors                 |
| 5  | Whether stilt / podium / open parking | Open Car Parking                                      |
|    | provided                              |   |
| 6  | Type of Construction                  | R.C.C. Framed Structure                               |
| 7  | Type of Foundation                    | R.C.C. Footing . Create                               |
| 8  | Thickness of the External Walls       | 9" thick brick walls both sides plastered             |
| 9  | Type of Compound                      | Brick Masonry Walls                                   |
| 10 | Year of Construction                  | 1976 (As per Agreement for Sale)                      |
| 11 | Present age of building               | 48 years  |
| 12 | Residual age of the building          | 12 years Subject to proper, preventive periodic       |
|    |                                       | maintenance & structural repairs.                     |
| 13 | No. of flats (Per Floor)              | 8 Rooms on Ground Floor                               |
| 14 | Methodology adopted                   | As per visual site inspection                         |





Our Pan India Presence at:

Numbai
Thane
Nanded
Nanded
Nashik
Nashik
Nashik
Nashik
Nashik
Nashik

Regd. Office: B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Andheri (East), Mumbai - 400 072, (M.S.), INDIA

TeleFax: +91 22 28371325/24 mumbai@vastukala.org

| B. | External O   | bservation of the Building   |
|----|--|--|
| 1  | Plaster  | Normal Condition   |
| 2  | Chajjas  | Normal Condition   |
| 3  | Plumbing   | Normal Condition   |
| 4  | Cracks on the external walls   | Not Found  |
| 5  | Filling cracks on the external walls                                       | Not Found  |
| 6  | Cracks on columns & beams  | Not Found  |
| 7  | Vegetation   | Not Found  |
| 8  | Leakages of water in the drainage pipes or water pipes                     | Not Found  |
| 9  | Dampness external in the wall due to leakages                              | Not Found  |
| 10 | Any other observation about the condition of external side of the building | i. Structural Stability Report from licensed structural engineers not provided for our verification. |
| С  | Internal Observation of the comm   | on areas of the building and captioned premises  |
| 1  | Beams (Cracks & Leakages)  | Not Found  |
| 2  | Columns (Cracks & Leakages)  | Not Found  |
| 3  | Ceiling (Cracks & Leakages)  | Not Found  |
| 4  | Leakages inside the property   | Not Found  |
| 5  | Painting inside the property   | Good Condition   |
| 6  | Maintenance of staircase & cracks  | Normal   |

| D | Con   | nmon Observation   |
|---|---|--|
| 1 | Structural Audit of the Building Under Bye            | As per bye Laws No. 77 of Co-Op. Societies bye Laws        |
|   | <ul> <li>Laws No. 77 of the Model Bye Laws</li> </ul> | under the Act the society shall conduct a Structural Audit |
|   | (Co-Operative Societies Act / Rules)                  | of the building of the society as follows                  |
| 2 | Remark  | No Structural Audit Report is furnished for the perusal.   |

#### **E** Conclusion

The captioned building is having Ground + 4<sup>th</sup> Upper Floors which are constructed in year 1976 As per Agreement for Sale. Estimated future life under present circumstances is about 12 years subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 27.03.2024 of building. The building is well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & Good structural repairs.

Our Observations about the structure are given above.

The above assessment is based on visual inspection only. Separate structural audit from licensed structural engineers is advised to assess exact balance life of structure.

## For VASTUKALA CONSULTANTS (I) PVT. LTD.

Director

Auth. Sign.

Sharadkumar B. Chalikwar

Structural Engineer License No.: STATE/R/2022/APL/01785

Govt. Reg. Valuer

Chartered Engineer (India)

Reg. No. (N) CCIT/1-14/52/2008-09





# **Actual site photographs**













