

Vastukala Consultants (I) Pvt. Ltd.

Vastu/Mumbai/04/2024/8071/2305865
02/03-04-JAVS
Date: 02.04.2024

www.vastukala.co.in

Structural Stability Report

Structural Observation Report of Residential Flat No. 301, 3rd Floor, Wing - M, "**Golden Nest-14 Sonam Godavari Co-op. Hsg. Soc. Ltd.**", New Golden Nest Phase - 14, Near Jain Bungalow, Village - Goddev, Bhayandar (East), Taluka - Thane, District - Thane, PIN - 401 105, State - Maharashtra, India.

Name of Owner: **Mr. Surendraprasad Tiwari & Mr. Jagdishprasad Tiwari**

Name of Proposed Purchaser: **Mrs. Smita Sunil Kumar Tiwari**

This is to certify that on visual inspection, it appears that the structure at "**Golden Nest-14 Sonam Godavari Co-op. Hsg. Soc. Ltd.**" is in normal condition and the future life can be reasonably taken under good condition and with proper periodic repairs & maintenance is about 44 years.

General Information:

| A. | Introduction | |
|----|--|---|
| 1 | Name of Building | "Golden Nest-14 Sonam Godavari Co-op. Hsg. Soc. Ltd." |
| 2 | Property Address | Residential Flat No. 301, 3 rd Floor, Wing - M, " Golden Nest-14 Sonam Godavari Co-op. Hsg. Soc. Ltd. ", New Golden Nest Phase - 14, Near Jain Bungalow, Village - Goddev, Bhayandar (East), Taluka - Thane, District - Thane, PIN - 401 105, State - Maharashtra, India. |
| 3 | Type of Building | Residential |
| 4 | No. of Floors | Part Ground + Part Stilt + 7 Upper Floors |
| 5 | Whether stilt / podium / open parking provided | Stilt Car Parking Space |
| 6 | Type of Construction | R.C.C. Framed Structure |
| 7 | Type of Foundation | R.C.C. Footing |
| 8 | Thickness of the External Walls | 9" thick brick walls both sides plastered |
| 9 | Type of Compound | Brick Masonry Walls |
| 10 | Year of Construction | 2008 (As per Occupancy Certificate) |
| 11 | Present age of building | 16 years |
| 12 | Residual age of the building | 44 years Subject to proper, preventive periodic maintenance & structural repairs. |
| 13 | No. of flats (Per Floor) | 4 Flats on 3 rd Floor |
| 14 | Methodology adopted | As per visual site inspection |

| B. | External Observation of the Building | |
|----|--------------------------------------|--|
| 1 | Plaster | External renovation work was in progress |
| 2 | Chajjas | External renovation work was in progress |



Our Pan India Presence at :

- Nanded
- Mumbai
- Aurangabad
- Thane
- Nashik
- Pune
- Ahmedabad
- Rajkot
- Indore
- Delhi NCR
- Raipur
- Jaipur

Regd. Office

BI-001, U/B Floor, BOOMERANG, Chandivali Farm Road, Powai, Andheri East, **Mumbai** :- 400072, (M.S), India

+91 2247495919
mumbai@vastukala.org
www.vastukala.co.in



| | | |
|----------|--|---|
| 3 | Plumbing | External renovation work was in progress |
| 4 | Cracks on the external walls | External renovation work was in progress |
| 5 | Filling cracks on the external walls | External renovation work was in progress |
| 6 | Cracks on columns & beams | External renovation work was in progress |
| 7 | Vegetation | External renovation work was in progress |
| 8 | Leakages of water in the drainage pipes or water pipes | Not found |
| 9 | Dampness external in the wall due to leakages | External renovation work was in progress |
| 10 | Any other observation about the condition of external side of the building | Structural Stability Report from licensed structural engineers not provided for our verification. |
| C | Internal Observation of the common areas of the building and captioned premises | |
| 1 | Beams (Cracks & Leakages) | Not found |
| 2 | Columns (Cracks & Leakages) | Not found |
| 3 | Ceiling (Cracks & Leakages) | Not found |
| 4 | Leakages inside the property | Not found |
| 5 | Painting inside the property | Normal Condition |
| 6 | Maintenance of staircase & cracks | Normal |

| | | |
|----------|---|---|
| D | Common Observation | |
| 1 | Structural Audit of the Building Under Bye – Laws No. 77 of the Model Bye Laws (Co-Operative Societies Act / Rules) | As per bye Laws No. 77 of Co-Op. Societies bye Laws under the Act the society shall conduct a Structural Audit of the building of the society as follows |
| 2 | Remark | i) At the time of site inspection, external renovation work in progress. ii) Structural Stability Report from licensed structural engineers not provided for our verification. |

| | |
|---|-------------------|
| E | Conclusion |
| <p>The captioned building is having Part Ground + Part Stilt + 7 Upper Floors which are constructed in year 2008 (As per Occupancy Certificate). Estimated future life under present circumstances is about 44 years subject to proper, preventive periodic maintenance & structural repairs.</p> <p>The inspection dated 12.03.2024 of building. The building is well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & Good structural repairs.</p> <p>Our Observations about the structure are given above.</p> <p>The above assessment is based on visual inspection only. Separate structural audit from licensed structural engineers is advised to assess exact balance life of structure.</p> | |

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Director

Auth. Sign.

Sharadkumar B. Chalikwar

Structural Engineer Licence No. STATE/R/2022/APL/01785

Govt. Reg. Valuer

Chartered Engineer (India)

Reg No. (N) CCIT/1-14/52/2008-09

SBI Empanelment No.: SME / TCC / 2021 – 22 / 85 / 13






Since 1989

Vastukala Consultants (I) Pvt. Ltd.

An ISO 9001 : 2015 Certified Company



Actual site photographs



Actual site photographs

