



**VASTUKALA**  
Unlocking Excellence

[www.vastukala.co.in](http://www.vastukala.co.in)

MSME Reg No: UDYAM-MH-18-0083617  
An ISO 9001 : 2015 Certified Company  
CIN: U74120MH2010PTC207869

## Vastukala Consultants (I) Pvt. Ltd.

Page 1 of 4

Vastu/Mumbai/04/2024/8092/2305877  
03/05-16-JAVS  
Date: 03.04.2024

### Structural Stability Report

Structural Observation Report of Residential Flat No. B/18, 2<sup>nd</sup> Floor, Wing - B, "I.A. Shelter Co-op. Hsg. Soc. Ltd.", Plot No. 70, 71 & 72, Green Lane, Sher-e-Punjab C.H.S. Ltd., Mahakali Caves Road, Village – Mogra (South Salsette), Andheri (East), Mumbai, Taluka - Andheri, District - Mumbai Suburban, PIN - 400 093, State - Maharashtra, Country - India.

Name of Owner: **Mr. Alkesh Rajnikant Shah & Mrs. Suryaben Rajnikant Shah**

This is to certify that on visual inspection, it appears that the structure at "I.A. Shelter Co-op. Hsg. Soc. Ltd." is in normal condition and the future life can be reasonably taken under good condition and with proper periodic repairs & maintenance is about 21 years.

#### General Information:

A.	Introduction	
1	Name of Building	"I.A. Shelter Co-op. Hsg. Soc. Ltd."
2	Property Address	Residential Flat No. B/18, 2 <sup>nd</sup> Floor, Wing - B, "I.A. Shelter Co-op. Hsg. Soc. Ltd.", Plot No. 70, 71 & 72, Green Lane, Sher-e-Punjab C.H.S. Ltd., Mahakali Caves Road, Village – Mogra (South Salsette), Andheri (East), Mumbai, Taluka - Andheri, District - Mumbai Suburban, PIN - 400 093, State - Maharashtra, Country - India.
3	Type of Building	Residential
4	No. of Floors	Ground + 3 Upper Floors
5	Whether stilt / podium / open parking provided	Open Parking Space
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	1985 (As per Agreement for Sale / Society Letter)
11	Present age of building	39 years
12	Residual age of the building	21 years Subject to proper, preventive periodic maintenance & structural repairs.
13	No. of flats (Per Floor)	2 Flats on 2 <sup>nd</sup> Floor
14	Methodology adopted	As per visual site inspection



#### Our Pan India Presence at :

- Nanded
- Mumbai
- Aurangabad
- Thane
- Nashik
- Pune
- Ahmedabad
- Rajkot
- Indore
- Delhi NCR
- Raipur
- Jaipur



#### Regd. Office

BI-001, U/B Floor, BOOMERANG, Chandivali Farm Road, Powai, Andheri East, Mumbai :-400072, (M.S), India

+91 2247495919

[mumbai@vastukala.org](mailto:mumbai@vastukala.org)

[www.vastukala.co.in](http://www.vastukala.co.in)

<b>B. External Observation of the Building</b>		
1	Plaster	Normal Condition
2	Chajjas	Normal Condition
3	Plumbing	Normal Condition
4	Cracks on the external walls	Not Found
5	Filling cracks on the external walls	Found
6	Cracks on columns & beams	Not Found
7	Vegetation	Not Found
8	Leakages of water in the drainage pipes or water pipes	Not Found
9	Dampness external in the wall due to leakages	Not Found
10	Any other observation about the condition of external side of the building	Structural Stability Report from licensed structural engineers not provided for our verification.
<b>C Internal Observation of the common areas of the building and captioned premises</b>		
1	Beams (Cracks & Leakages)	Not Found
2	Columns (Cracks & Leakages)	Not Found
3	Ceiling (Cracks & Leakages)	Not Found
4	Leakages inside the property	Not Found
5	Painting inside the property	Normal Condition
6	Maintenance of staircase & cracks	Good

<b>D Common Observation</b>		
1	Structural Audit of the Building Under Bye – Laws No. 77 of the Model Bye Laws (Co-Operative Societies Act / Rules)	As per bye Laws No. 77 of Co-Op. Societies bye Laws under the Act the society shall conduct a Structural Audit of the building of the society as follows
2	Remark	<p>i) <b>At the time of site inspection, external condition of the building is normal, dampness not found, leakages are not found &amp; Cracks are not found.</b></p> <p>ii) <b>Structural Stability Report from licensed structural engineers not provided for our verification.</b></p>

<b>E Conclusion</b>	
<p>The captioned building is having Ground + 3 Upper Floors which are constructed in year 1985 (As per Agreement for Sale / Society Letter). Estimated future life under present circumstances is about 21 years subject to proper, preventive periodic maintenance &amp; structural repairs.</p> <p>The inspection dated 28.03.2024 of building. The building is well as the property is maintained in normal condition &amp; will stand future life subject to proper, preventive periodic maintenance &amp; Good structural repairs.</p> <p>Our Observations about the structure are given above.</p> <p>The above assessment is based on visual inspection only. Separate structural audit from licensed structural engineers is advised to assess exact balance life of structure.</p>	

**For VASTUKALA CONSULTANTS (I) PVT. LTD.**

**Director**

**Sharadkumar B. Chalikwar**

Structural Engineer Licence No. STATE/R/2022/APL/01785

Govt. Reg. Valuer

Chartered Engineer (India)

Reg No. (N) CCIT/1-14/52/2008-09

SBI Empanelment No.: SME / TCC / 2021 – 22 / 85 / 13



Since 1989

**Vastukala Consultants (I) Pvt. Ltd.**

An ISO 9001 : 2015 Certified Company



**Auth. Sign.**



## Actual site photographs



## Actual site photographs

