

Vastukala Consultants (I) Pvt. Ltd.

Page 1 of 4

Vastu/Mumbai/05/2024/008966/2306502 28/18-362 -PRBS Date: 28.05.2024

Structural Stability Report

Structural Observation Report of Residential Flat No. 702, 7th Floor, "Cacilda Co - Op. Hsg. Soc. Ltd.", Holy Cross Road, I. C. Colony, Mumbai - 400 103, State - Maharashtra, Country - India.

Name of Owner: Mr. Yogesh Gajanan Ambardekar & Mrs. Amita Yogesh Ambardekar

This is to certify that on visual inspection, it appears that the structure of the at "Cacilda Co - Op. Hsg. Soc. Ltd.", is in normal condition and the future life can be reasonably taken under good condition and with proper periodic repairs & maintenance is about 38 years.

General Information:

A.		Introduction	
1	Name of Building	" Cacilda Co - Op. Hsg. Soc. Ltd."	
2	Property Address	Residential Flat No. 702, 7th Floor, "Cacilda Co - Op. Hsg.	
		Soc. Ltd", Holy Cross Road, I. C. Colony, Mumbai - 400	
		103, State - Maharashtra, Country – India.	
3	Type of Building	Residential used	
4	No. of Floors	Ground + 7 th Upper Floors	
5	Whether stilt / podium / open parking	Open Car Parking Space	
	provided		
6	Type of Construction	R.C.C. Framed Structure	
7	Type of Foundation	R.C.C. Footing	
8	Thickness of the External Walls	9" thick brick walls both sides plastered	
9	Type of Compound	Brick Masonry Walls	
10	Year of Construction	2002 (As per Occupancy Certificate)	
11	Present age of building	22 years	
12	Residual age of the building	38 years Subject to proper, preventive periodic	
		maintenance & structural repairs.	
13	No. of flats (Per Floor)	03 Flats on 7 th Floor	
14	Methodology adopted	As per visual site inspection	

B.	External Observation of the Building		
1	Plaster	Normal Condition	
2	Chajjas	Normal Condition	CONSULTANZO
3	Plumbing	Normal Condition	Valuers & Appraisers
4	Cracks on the external walls	Not Found	Northmetis & Interior Designers Chartered Engineers (I)
	•		Lender's Engineer



Our Pan India Presence at:

♀ Aurangabad
♀ Pune

Nanded Mumbai

Thane Nashik

Rajkot

Ahmedabad Opelhi NCR 💡 Raipur

Jaipur

Regd. Office

B1-001, U/B Floor, BOOMERANG, Chandivali Farm Road, Powai, Andheri East, Mumbai: 400072, (M.S), India



🔀 mumbai@vastukala.co.in www.vastukala.co.in

5	Filling cracks on the external walls	Not Found
6	Cracks on columns & beams	Not Found
7	Vegetation	Not Found
8	Leakages of water in the drainage pipes or water pipes	Not Found
9	Dampness external in the wall due to leakages	Not Found
10	Any other observation about the condition	Structural Stability Report from licensed structural
	of external side of the building	engineers not provided for our verification.
С	Internal Observation of the common areas of the building and captioned premises	
1	Beams (Cracks & Leakages)	Not Found
2	Columns (Cracks & Leakages)	Not Found
3	Ceiling (Cracks & Leakages)	Not Found
4	Leakages inside the property	Not Found
5	Painting inside the property	Normal Condition
6	Maintenance of staircase & cracks	Good

D	Common Observation	
1	Structural Audit of the Building Under Bye	As per bye Laws No. 77 of Co-Op. Societies bye Laws
	- Laws No. 77 of the Model Bye Laws (Co-	under the Act the society shall conduct a Structural Audit of
	Operative Societies Act / Rules)	the building of the society as follows
2	Remark	No Structural Audit Report is furnished for the perusal.

E Conclusion

The captioned building is having Ground + 7th Upper Floors which are constructed in year 2002 (As per Occupancy Certificate). Estimated future life under present circumstances is about 38 years subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 02.05.2024 of building. The building is well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & Good structural repairs.

Our Observations about the structure are given above.

The above assessment is based on visual inspection only. Separate structural audit from licensed structural engineers is advised to assess exact balance life of structure.

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Director

Auth. Sign.

Sharadkumar B. Chalikwar

Structural Engineer Licence No. STATE/R/2022/APL/01785 Govt. Reg. Valuer Chartered Engineer (India) Reg No. (N) CCIT/1-14/52/2008-09

SBI Empanelment No.: SME / TCC / 2021 – 22 / 85 / 13




Valuers & Appraisers
Architects &
Interest Designers
Lender's Engineer

MH2010 97150

An ISO 9001: 2015 Certified Company


Actual site photographs





















Actual site photographs







