

MSME Reg No: UDYAM-MH-18-0083617 An ISO 9001: 2015 Certified Company CIN: U74120MH2010PTC207869

Vastukala Consultants (I) Pvt. Ltd.

Structural Stability Report Prepared for SBI / RACPC Andheri (East)/ Mrs. Trupti Sandeep Asolkar (009603/2306971) Page 1 of 3

Vastu/Mumbai/06/2024/009603/2306971 28/22-415-PRRJ Date: 28.06.2024

Structural Stability Report

Structural Observation Report of Residential Flat No. 503, 5th Floor, Wing - B, "Prasham Co-Op. Hsg. Soc. Ltd. ", Plot No. 276-A of TPS III, Kastur Park, Shimpoli, Village - Eksar, Borivali (West), Mumbai - 400 092, State -Maharashtra, Country - India.

Name of Owner: Mrs. Trupti Sandeep Asolkar & Mr. Sandeep Dattatray Asolkar

This is to certify that on visual inspection, it appears that the structure of the at " Prasham Co-Op. Hsg. Soc. Ltd.", is in normal condition and the future life can be reasonably taken under good condition and with proper periodic repairs & maintenance is about 42 years,

General Information:

A.		Introduction	
1	Name of Building	" Prasham Co-Op. Hsg. Soc. Ltd."	
2	Property Address	Residential Flat No. 503, 5th Floor, Wing - B, "Prasham Co-	
	and the second	Op. Hsg. Soc. Ltd. ", Plot No. 276-A of TPS III, Kastur	
		Park, Shimpoli, Village - Eksar, Borivali (West), Mumbai -	
		400 092, State - Maharashtra, Country - India.	
3	Type of Building	Residential used	
4	No. of Floors	Ground + 7th Upper Floors	
5	Whether stilt / podium / open parking	Open Car Parking Space	
	provided		
6	Type of Construction	R.C.C. Framed Structure	
7	Type of Foundation	R.C.C. Footing	
8	Thickness of the External Walls	9" thick brick walls both sides plastered	
9	Type of Compound	Brick Masonry Walls	
10	Year of Construction	2006 (As per occupancy certificate)	
11	Present age of building	18 years	
12	Residual age of the building	42 years Subject to proper, preventive periodic	
		maintenance & structural repairs.	
13	No. of flats (Per Floor)	04 Flats on 5 th Floor	
14	Methodology adopted	As per visual site inspection	

B.	External Observation of the Building		
1	Plaster	Normal Condition	
2	Chajjas	Normal Condition	and Line
3	Plumbing	Normal Condition	mary heuriters
4	Cracks on the external walls	Not Found	terior Designer
5	Filling cracks on the external walls	Not Found	Chainner S
6	Cracks on columns & beams	Not Found	MH2819 PTC



Nanded

Pune

🥯 Rajkot

Ahmedabad O Delhi NCR Raipur

Powai, Andheri East, Mumbai: 400072, (M.S.), India **2 +91 2247495919**

Regd. Office

🜌 mumbai@vastukala.co.in www.vastukala.co.in

BI-001, U/B Floor, BOOMERANG, Chandivali Farm Road,



Nashik

Jaipur

Mumbai Aurangabad



	Pag	е	2	of	(
--	-----	---	---	----	---

7	Vegetation	Not Found
8	Leakages of water in the drainage pipes or water pipes	Not Found
9	Dampness external in the wall due to leakages	Not Found
10	Any other observation about the condition	Structural Stability Report from licensed structural
	of external side of the building	engineers not provided for our verification.
С	Internal Observation of the common areas of the building and captioned premises	
1	Beams (Cracks & Leakages)	Not Found
2	Columns (Cracks & Leakages)	Not Found
3	Ceiling (Cracks & Leakages)	Not Found
4	Leakages inside the property	Not Found
5	Painting inside the property	Normal Condition
6	Maintenance of staircase & cracks	Good

D	Common Observation	
1	Structural Audit of the Building Under Bye	As per bye Laws No. 77 of Co-Op. Societies bye Laws
	- Laws No. 77 of the Model Bye Laws (Co-	under the Act the society shall conduct a Structural Audit of
	Operative Societies Act / Rules)	the building of the society as follows
2	Remark	No Structural Audit Report is furnished for the perusal.

E Conclusion

The captioned building is having Ground + 7th Upper Floors which are constructed in year 2006 (As per occupancy certificate). Estimated future life under present circumstances is about 42 years subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 27.06.2024 of building. The building is well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & Good structural repairs.

Our Observations about the structure are given above.

The above assessment is based on visual inspection only. Separate structural audit from licensed structural engineers is advised to assess exact balance life of structure.

For VASTUKALA CONSULTANTS (I) PVT. LTD

Sharadkumar Chalikwar Digitally signed by Sharadkumar Chalikwar
DN: cn=Sharadkumar Chalikwar,
o=Vastukala Consultants (I) Pvt. Ltd.,
au=Mumbal, email=cmd@vastukala.osg,

Oate: 2024.06.28 18:15:57 +05'30'

Director

Auth. Sign

Sharadkumar B. Chalikwar

Structural Engineer Licence No. STATE/R/2022/APL/01785 Govt. Reg. Valuer Chartered Engineer (India)

Reg No. (N) CCIT/1-14/52/2008-09

SBI Empanelment No.: SME / TCC / 2021 – 22 / 85 / 13





Actual site photographs























Since 1989

