

```
{
  "typeOfReport": {
    "value": "Land_and_Building",
    "label": "Land and Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8dc"
    },
    "firstName": "Reshma",
    "type": "CREDITOFFICER",
    "_id": "66488ee66f40574290c1d472",
    "lastName": "Kulkarni",
    "mobileNo": "",
    "workMobileNo": "8591096604",
    "email": "1thane@cosmosbank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8dc",
  "branchCode": "000005",
  "type": "BRANCH",
  "name": "Naupada",
  "email": "thane@cosmosbank.in",
  "mobileNo": "022-25345923",
  "alternateMobileNo": "",
  "address": "Kusumanjali, Opp. Devdhar Hospital, Naupada, Thane (West) - 400 602,
State - Maharashtra, Country - India.\r\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Industrial",
  "value": "Industrial"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc4680ce84bf289ba9c7fc",
  "role": "SITEENGINEER",
  "firstName": "Nikhil ",
  "email": "valtechnical2022@gmail.com",
  "lastName": "Sonawane",
  "mobileNo": "9819470709",
  "designation": "",
  "shortName": "NS",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fdfc2",
  "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1720806809901_image.jpg"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "registrationNo": [
    {
```

```
"title": {
  "label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.148718315137167",
```

```
"longitude": "73.24629749757551"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kharvai",
    "label": true
  },
  "floorNo": {
    "status": true,
```

```
"name": "Floor No",
"key": "floorNo",
"value": "Ground",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Ambernath",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Ambernath",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "F - 1/12",
  "label": true
}
```

```
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
```

```
"key": "projectName",
"value": "Badlapur Industrial Area of MIDC",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
}
```



```
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
```

```
"value": "",
"label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
}
```

```
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  }
}
```

```
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
```



```
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66a0d90073ce9d724ff9caf1",
"ownerName": "M/s. Tolani Pipes Private Ltd.",
"ownerPhoneNo": "9890369272",
"fullAddress": "Residential Land and Building No. Ground Floor, Badlapur Industrial
Area of MIDC, Plot No. F - 1/12, Village - Kharvai, Taluka - Ambernath, District -
Ambernath",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1247aa6d152c1801b2e9",
      "label": "Deed Of Assignment"
    },
    "inputs": {
      "from": {
        "value": "The_Assignor",
        "label": "The Assignor"
      },
      "The_Assignor": "M/s. Aaditya Flameproof Private Ltd.",
      "to": {
        "value": "The_Assignee",
        "label": "The Assignee"
      },
      "The_Assignee": "M/s. Tolani Pipes Private Ltd."
    }
  }
],
"isHardCopy": false,
```

```
    "displayStatus": false,
    "fileName":
"document_1721817323911_Cosmos_Naupada_Tolani_pipes_p_Ltd.pdf",
    "path": "cases/66a0d90073ce9d724ff9caf1/
document_1721817323911_Cosmos_Naupada_Tolani_pipes_p_Ltd.pdf",
    "id": "560742",
    "uploadedBy": "656aa949cebbe1714411d21b",
    "createdAt": "Wed Jul 24 2024 16:05:44 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1721817336659_Cosmos_NaupadaTolani_pipes_p_Ltd.pdf",
    "path": "cases/66a0d90073ce9d724ff9caf1/
document_1721817336659_Cosmos_NaupadaTolani_pipes_p_Ltd.pdf",
    "id": "493286",
    "uploadedBy": "656aa949cebbe1714411d21b",
    "createdAt": "Wed Jul 24 2024 16:05:44 GMT+0530 (India Standard Time)"
  }
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "010137",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "704851",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Jul 24 2024 16:05:44 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "M/s. Tolani Pipes Private Ltd.",
    "phone": "9890369272",
    "ownershipShare": "",
    "email": "",
    "id": "703301"
  }
]
```

```
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66a7530f6ade5c6fb59aa4c5",
    "name": "externalImg_r_1722241806124_1722241707398_image_0.jpg",
    "path": "cases/66a0d90073ce9d724ff9caf1/
externalImg_r_1722241806124_1722241707398_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a7534924c0566f8614b426",
    "name": "externalImg_1722241845887_1722241742417_image_1.png",
    "path": "cases/66a0d90073ce9d724ff9caf1/
externalImg_1722241845887_1722241742417_image_1.png",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a7534924c0566f8614b427",
    "name": "externalImg_r_1722241848758_1722241742417_image_4.jpg",
    "path": "cases/66a0d90073ce9d724ff9caf1/
externalImg_r_1722241848758_1722241742417_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a7534924c0566f8614b428",
    "name": "externalImg_r_1722241848049_1722241742417_image_3.jpg",
    "path": "cases/66a0d90073ce9d724ff9caf1/
externalImg_r_1722241848049_1722241742417_image_3.jpg",
    "orientation": "portrait"
  },
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a7534924c0566f8614b429",
  "name": "externallmg_r_1722241843632_1722241742417_image_0.jpg",
  "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241843632_1722241742417_image_0.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a7534924c0566f8614b42a",
  "name": "externallmg_r_1722241847142_1722241742417_image_2.jpg",
  "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241847142_1722241742417_image_2.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a7534924c0566f8614b42b",
  "name": "externallmg_r_1722241849285_1722241742417_image_5.jpg",
  "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241849285_1722241742417_image_5.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a7534924c0566f8614b42c",
  "name": "externallmg_r_1722241851546_1722241742417_image_7.jpg",
  "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241851546_1722241742417_image_7.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a7534924c0566f8614b42d",
  "name": "externallmg_r_1722241852550_1722241742417_image_8.jpg",
  "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241852550_1722241742417_image_8.jpg",
  "orientation": "portrait"
},
{
```

```
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "66a7534924c0566f8614b42e",
"name": "externallmg_r_1722241850496_1722241742417_image_6.jpg",
"path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241850496_1722241742417_image_6.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "66a7534924c0566f8614b42f",
"name": "externallmg_r_1722241853565_1722241742417_image_9.jpg",
"path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241853565_1722241742417_image_9.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "66a7534924c0566f8614b430",
"name": "externallmg_r_1722241855536_1722241742417_image_11.jpg",
"path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241855536_1722241742417_image_11.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "66a7534924c0566f8614b431",
"name": "externallmg_r_1722241856102_1722241742417_image_12.jpg",
"path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241856102_1722241742417_image_12.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "66a7534924c0566f8614b432",
"name": "externallmg_r_1722241854580_1722241742417_image_10.jpg",
"path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241854580_1722241742417_image_10.jpg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66a7534924c0566f8614b433",
  "name": "externalimg_r_1722241857069_1722241742417_image_13.jpg",
  "path": "cases/66a0d90073ce9d724ff9caf1/
externalimg_r_1722241857069_1722241742417_image_13.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a7534924c0566f8614b434",
  "name": "externalimg_r_1722241859850_1722241742417_image_16.jpg",
  "path": "cases/66a0d90073ce9d724ff9caf1/
externalimg_r_1722241859850_1722241742417_image_16.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a7534924c0566f8614b435",
  "name": "externalimg_r_1722241857929_1722241742417_image_14.jpg",
  "path": "cases/66a0d90073ce9d724ff9caf1/
externalimg_r_1722241857929_1722241742417_image_14.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a7534924c0566f8614b436",
  "name": "externalimg_r_1722241858855_1722241742417_image_15.jpg",
  "path": "cases/66a0d90073ce9d724ff9caf1/
externalimg_r_1722241858855_1722241742417_image_15.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a7534924c0566f8614b437",
  "name": "externalimg_r_1722241860355_1722241742417_image_17.jpg",
  "path": "cases/66a0d90073ce9d724ff9caf1/
externalimg_r_1722241860355_1722241742417_image_17.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "66a7534924c0566f8614b438",
    "name": "externallmg_r_1722241861009_1722241742417_image_18.jpg",
    "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241861009_1722241742417_image_18.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a7534924c0566f8614b439",
    "name": "externallmg_r_1722241861936_1722241742417_image_19.jpg",
    "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241861936_1722241742417_image_19.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a753792282636f80b26387",
    "name": "externallmg_r_1722241895606_1722241794421_image_1.jpg",
    "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241895606_1722241794421_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a753792282636f80b26388",
    "name": "externallmg_r_1722241894549_1722241794421_image_0.jpg",
    "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241894549_1722241794421_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a753792282636f80b26389",
    "name": "externallmg_r_1722241896336_1722241794421_image_2.jpg",
    "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241896336_1722241794421_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a753792282636f80b2638a",
```

```
    "name": "externallmg_r_1722241897207_1722241794421_image_3.jpg",
    "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241897207_1722241794421_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a753792282636f80b2638b",
    "name": "externallmg_r_1722241898108_1722241794421_image_4.jpg",
    "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241898108_1722241794421_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a753792282636f80b2638c",
    "name": "externallmg_r_1722241898990_1722241794421_image_5.jpg",
    "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241898990_1722241794421_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a753792282636f80b2638d",
    "name": "externallmg_r_1722241899853_1722241794421_image_6.jpg",
    "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241899853_1722241794421_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a753792282636f80b2638e",
    "name": "externallmg_r_1722241900562_1722241794421_image_7.jpg",
    "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241900562_1722241794421_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a753792282636f80b2638f",
    "name": "externallmg_r_1722241902874_1722241794421_image_10.jpg",
```



```
    "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241902874_1722241794421_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a753792282636f80b26390",
    "name": "externallmg_r_1722241901544_1722241794421_image_8.jpg",
    "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241901544_1722241794421_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a753792282636f80b26391",
    "name": "externallmg_r_1722241902189_1722241794421_image_9.jpg",
    "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241902189_1722241794421_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a753792282636f80b26392",
    "name": "externallmg_r_1722241903278_1722241794421_image_11.jpg",
    "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241903278_1722241794421_image_11.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a753792282636f80b26393",
    "name": "externallmg_r_1722241904727_1722241794421_image_13.jpg",
    "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241904727_1722241794421_image_13.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a753792282636f80b26394",
    "name": "externallmg_r_1722241903797_1722241794421_image_12.jpg",
    "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241903797_1722241794421_image_12.jpg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a753792282636f80b26395",
    "name": "externallmg_r_1722241905759_1722241794421_image_14.jpg",
    "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241905759_1722241794421_image_14.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a753792282636f80b26396",
    "name": "externallmg_r_1722241906575_1722241794421_image_15.jpg",
    "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241906575_1722241794421_image_15.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a753792282636f80b26397",
    "name": "externallmg_r_1722241909061_1722241794421_image_18.jpg",
    "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241909061_1722241794421_image_18.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a753792282636f80b26398",
    "name": "externallmg_r_1722241908207_1722241794421_image_17.jpg",
    "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241908207_1722241794421_image_17.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a753792282636f80b26399",
    "name": "externallmg_r_1722241909862_1722241794421_image_19.jpg",
    "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241909862_1722241794421_image_19.jpg",
    "orientation": "portrait"
  }
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a753792282636f80b2639a",
  "name": "externallmg_r_1722241907581_1722241794421_image_16.jpg",
  "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241907581_1722241794421_image_16.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a753aa2282636f80b2644a",
  "name": "externallmg_r_1722241947874_1722241846276_image_2.jpg",
  "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241947874_1722241846276_image_2.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a753aa2282636f80b2644b",
  "name": "externallmg_r_1722241945826_1722241846276_image_0.jpg",
  "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241945826_1722241846276_image_0.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a753aa2282636f80b2644c",
  "name": "externallmg_r_1722241948809_1722241846276_image_3.jpg",
  "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241948809_1722241846276_image_3.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a753aa2282636f80b2644d",
  "name": "externallmg_r_1722241946827_1722241846276_image_1.jpg",
  "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241946827_1722241846276_image_1.jpg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a753aa2282636f80b2644e",
  "name": "externallmg_r_1722241955852_1722241846276_image_6.jpg",
  "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241955852_1722241846276_image_6.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a753aa2282636f80b2644f",
  "name": "externallmg_r_1722241949733_1722241846276_image_4.jpg",
  "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241949733_1722241846276_image_4.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a753aa2282636f80b26450",
  "name": "externallmg_r_1722241950852_1722241846276_image_5.jpg",
  "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241950852_1722241846276_image_5.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a753aa2282636f80b26451",
  "name": "externallmg_r_1722241956618_1722241846276_image_7.jpg",
  "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241956618_1722241846276_image_7.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a753aa2282636f80b26452",
  "name": "externallmg_r_1722241957799_1722241846276_image_8.jpg",
  "path": "cases/66a0d90073ce9d724ff9caf1/
externallmg_r_1722241957799_1722241846276_image_8.jpg",
  "orientation": "portrait"
},
{
```

```

    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a753aa2282636f80b26453",
    "name": "externalImg_r_1722241958960_1722241846276_image_9.jpg",
    "path": "cases/66a0d90073ce9d724ff9caf1/
externalImg_r_1722241958960_1722241846276_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a753aa2282636f80b26454",
    "name": "externalImg_r_1722241959781_1722241846276_image_10.jpg",
    "path": "cases/66a0d90073ce9d724ff9caf1/
externalImg_r_1722241959781_1722241846276_image_10.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-07-24T10:35:44.266Z",
"updatedAt": "2024-07-29T08:32:42.871Z",
"__v": 0,
"updatedBy": "63fc4680ce84bf289ba9c7fc",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "M/s. Tolani Pipes Private Ltd.",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9890369272"
}

```

Name	Length	Width	Total
Composition :			

Other  
Composition :

---