

Structural Stability Report

Structural Observation Report of Residential Flat No. 202, 2nd Floor, Wing - M, "**Gokul Heaven (D-M) Co-op. Hsg. Soc. Ltd.**", Thakur Complex, Near Western Express Highway, Village - Poisar, Municipality Ward No. R/S Ward, Kandivali (East), Taluka - Borivali, District - Mumbai Suburban District, Mumbai, PIN Code - 400 101, State - Maharashtra, India.

Name of Owner: **Mrs. Deepta Ashok Sannabhadti & Mr. Ashok Madhav Sannabhadti.**

This is to certify that on visual inspection, it appears that the structure of the at "**Gokul Heaven (D-M) Co-op. Hsg. Soc. Ltd.**" is in normal condition and the future life can be reasonably taken under good condition and with proper periodic repairs & maintenance is about 30 years.

General Information:

A.	Introduction	
1	Name of Building	Gokul Heaven (D-M) Co-op. Hsg. Soc. Ltd.
2	Property Address	Residential Flat No. 202, 2 nd Floor, Wing - M, " Gokul Heaven (D-M) Co-op. Hsg. Soc. Ltd. ", Thakur Complex, Near Western Express Highway, Village - Poisar, Municipality Ward No. R/S Ward, Kandivali (East), Taluka - Borivali, District - Mumbai Suburban District, Mumbai, PIN Code - 400 101, State - Maharashtra, India.
3	Type of Building	Residential used
4	No. of Floors	Stilt + 7 Upper Floors
5	Whether stilt / podium / open parking provided	Stilt + Open Car Parking
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	1994 (As per occupancy certificate)
11	Present age of building	30 years
12	Residual age of the building	30 years Subject to proper, preventive periodic maintenance & structural repairs.
13	No. of flats (Per Floor)	2 nd Floor is having 4 Flats
14	Methodology adopted	As per visual site inspection




Our Pan India Presence at :

-  Nanded
-  Thane
-  Ahmedabad
-  Delhi NCR
-  Mumbai
-  Nashik
-  Rajkot
-  Raipur
-  Aurangabad
-  Pune
-  Indore
-  Jaipur

Regd. Office

BI-001, U/B Floor, BOOMERANG, Chandivali Farm Road, Powai, Andheri East, **Mumbai:** 400072, (M.S.), India

 +91 2247495919

 mumbai@vastukala.co.in

 www.vastukala.co.in



B.	External Observation of the Building	
1	Plaster	Normal Condition
2	Chajjas	Normal Condition
3	Plumbing	Normal Condition
4	Cracks on the external walls	Not Found
5	Filling cracks on the external walls	Not Found
6	Cracks on columns & beams	Not Found
7	Vegetation	Not Found
8	Leakages of water in the drainage pipes or water pipes	Not Found
9	Dampness external in the wall due to leakages	Found
10	Any other observation about the condition of external side of the building	The external condition of the building is in normal condition
C	Internal Observation of the common areas of the building and captioned premises	
1	Beams (Cracks & Leakages)	Normal Condition
2	Columns (Cracks & Leakages)	Normal Condition
3	Ceiling (Cracks & Leakages)	Normal Condition
4	Leakages inside the property	Not Found
5	Painting inside the property	Normal
6	Maintenance of staircase & cracks	Normal

D	Common Observation	
1	Structural Audit of the Building Under Bye – Laws No. 77 of the Model Bye Laws (Co-Operative Societies Act / Rules)	As per bye Laws No. 77 of Co-Op. Societies bye Laws under the Act the society shall conduct a Structural Audit of the building of the society as follows
2	Remark	No Structural Audit Report is furnished for the perusal

E	Conclusion
	<p>The captioned building is having Stilt + 7 Upper Floors which are constructed in year 1994 (As per occupancy certificate). Estimated future life under present circumstances is about 30 years' subject to proper, preventive periodic maintenance & structural repairs.</p> <p>The inspection dated 20.07.2024 reveals no structural damage or deterioration to the building. The building is well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & Normal structural repairs.</p> <p>Our Observations about the structure are given above.</p> <p>The above assessment is based on visual inspection only.</p>

For **VASTUKALA CONSULTANTS (I) PVT. LTD.**

Director

Auth. Sign.

Manoj Chalikwar

Govt. Reg. Valuer

Chartered Engineer (India)

Reg. No. IBBI/RV/07/2018/10366

SVC CO-OPERATIVE BANK LTD Empanelment No.:



Since 1989

Vastukala Consultants (I) Pvt. Ltd.

An ISO 9001 : 2015 Certified Company



Actual Site Photographs

