

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6405bf97dd383b243e8482fe"
    },
    "firstName": "Nisha",
    "type": "CREDITOFFICER",
    "_id": "661f43907e1d7332c87e10a7",
    "lastName": "Aswekar",
    "mobileNo": "",
    "workMobileNo": "9768319662",
    "email": "charkop@janasevabank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "7500000",
    "discussWithPerson": "Nisha",
    "expectedFees": 3750,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1836",
  "type": "BANK",
  "name": "Janaseva Sahakari Bank",
  "displayName": "Janaseva Sahakari Bank",
  "initial": "JSB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6405bf97dd383b243e8482fe",
  "name": "Charkop Branch",
  "branchCode": "",
  "mobileNo": "02228683113",
  "alternateMobileNo": "",
  "email": "charkop@janasevabank.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Charkop Shivneri RDP-4 , Sector 5, Charkop, Kandiwali Westy, Mumbai
40007"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63afe4ff191f7b344b007ea6",
  "zoneName": "Pan India"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "659ccce98f39506e83489828",
"role": "DELIVERYPERSON",
"firstName": "Amit",
"email": "amitsalvi2909@gmail.com",
"lastName": "Salvi",
"mobileNo": "7499830659",
"shortName": "Amit",
"workWithDocumentMaker": "",
"profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62691c48afd7d55eddecfda3",
"role": "MAKER",
"firstName": "Bhavika",
"email": "bhavikachavan0102@gmail.com",
"lastName": "chavan",
"mobileNo": "8390804382",
"designation": "Site Engineer",
"shortName": "BH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60f915d3f3dd69653a592199",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "627221f4afd7d55eddeddcb4",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Prajakta",
"email": "prajakta@vastukala.org",
"lastName": "Patil",
```

```
"mobileNo": "9769797568",
"designation": "",
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
"title": {
  "value": "FIIV",
  "label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.227963158584096",
  "longitude": "72.82499889507162"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.82499889507162,
    19.227963158584096
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-08-07",
      "remark": ""
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Gorai",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
```

```
"key": "floorNo",
"value": "Ground",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban District",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahsilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahsilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "(2), CD - 216",
  "label": true
},
```

```
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Gorai (2) Shree Bhavani Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "R.S.C. - 32",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
```



```
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "C - 7",
  "label": false
},
"municipalityWardNo": {
```

```
"status": true,
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "R - Ward",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 092",
```

```
"label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Borivali (West)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  },
  "flooring": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  },
  "doors": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  },
  "windows": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  },
  "fittings": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  },
  "finishing": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  }
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
```

```
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
  "value": "MHADA",
  "label": "MHADA"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Abhilasha CHSL",
  "west": "Sai Darpan CHSL",
  "south": "Om Sai CHSL",
  "east": "Road & Omkar CHSL"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  }
},
```

```
"auto": {
  "title": "Auto"
},
"privateCars": {
  "title": "Private Cars"
}
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Plan were not provided and not
verified",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
}
},
"compositeRate": {
  "remark": "At the time of visit, the property was locked hence internal site inspection
and photographs could not be taken. The structure is in dilapidated condition. It
requires immediate structural strengthening and repairs. The details of repairs,
renovation were not provided at the site. We can't consider the value of the said
structure. we can consider lump sum value of Land as per Mhada plot availability of
Surrounding only. Our report is based on external visit & documents provided by bank
only.",
  "depreciationPercentage": "0",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "12000",
  "depreciatedBuildingRate": "2000"
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "141110",
  "landRate": "65140",
  "igrImage": "cases/66b07c454f2f48da09c9be4b/igr_1723030437323_Image.png",
  "squareMeterGuideLineRate": "141110.00",
  "squareFeetGuideLineRate": "13110.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "98",
  "rate": "12968.00",
```

```
"squareFeetGuideLineRate": "12968.00",
"squareMeterGuideLineRate": "139591.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "11,000/- Expected rental income per month ",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per MHADA / MCGM norms",
  "tenantName": "",
  "maintenanceOfFlat": "At the time of visit, building is in dilapidated condition. It
requires immediate structural strengthening and repairs."
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developed Area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "External_site_visit_only",
    "label": "External site visit only"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
```

```
"value": "MunicipalWaterSupply",
"label": "Municipal Water Supply"
},
"pavementLaid": {
"value": "No",
"label": "No"
},
"carParking": "Open Car Parking",
"constructionWorkStatus": {
"value": "Completed",
"label": "Completed"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "1",
"month": "1",
"year": "1992",
"fullDate": "1/1/1992"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "Kuccha_Structure",
"label": "Kuccha Structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "Poor",
"label": "Poor"
},
"materialUsedList": {
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"buildingSpecification": {
"value": "Average",
"label": "Average"
},
}
```

```
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "Existing",
  "label": "Existing"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Poor",
  "label": "Poor"
},
"maintenanceOfTheBuilding": {
  "value": "Poor",
  "label": "Poor"
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "0",
  "label": "No"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "MHADA_Allotment_Letter",
```



```
"label": "MHADA Allotment Letter"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "28",
"ageOfBuilding": "32",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "1",
"flatFloorNo": "Ground",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": ""
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/66b07c454f2f48da09c9be4b/
routeMap_1723031628870_Image.png",
    "routeLat": "19.227922",
    "routeLng": "72.824764",
    "stationName": "Borivali",
    "routeDistance": "3.9 Km.",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
  {
    "id": "tu1sdk",
    "name": "tu1sdk",
    "image": "cases/66b07c454f2f48da09c9be4b/
routeMap_1723031581989_Image.png"
```

```
    }
  ]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "3876000.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "90",
  "bookValue": "0",
  "finalValue": "3876000.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
```

```
"date": "Wed Aug 07 2024 18:17:33 GMT+0530 (India Standard Time)",
"number": "2307598",
"dayCount": "21",
"monthCount": "76",
"generatedBy": "60f915d3f3dd69653a592199"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
```

```
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "4188664.00",
  "selectedBuildUpValue": "323.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
```

```
    "status": false,
    "_id": "66b2fb98c884d11233432461",
    "name": "externallmg_1723005828682_1723005804974_image_3.jpeg",
    "path": "cases/66b07c454f2f48da09c9be4b/
externallmg_1723005828682_1723005804974_image_3.jpeg",
    "orientation": "portrait"
  }
],
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "66b2fb7fda840b1214c274df",
    "name": "externallmg_1723005822322_1723005818762_image_0.jpeg",
    "path": "cases/66b07c454f2f48da09c9be4b/
externallmg_1723005822322_1723005818762_image_0.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "66b2fb98c884d11233432468",
    "name": "externallmg_1723005846251_1723005804975_image_10.jpeg",
    "path": "cases/66b07c454f2f48da09c9be4b/
externallmg_1723005846251_1723005804975_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66b2fb98c884d11233432467",
    "name": "externallmg_1723005843772_1723005804974_image_9.jpeg",
    "path": "cases/66b07c454f2f48da09c9be4b/
externallmg_1723005843772_1723005804974_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66b2fb98c884d11233432463",
    "name": "externallmg_1723005834359_1723005804974_image_5.jpeg",
    "path": "cases/66b07c454f2f48da09c9be4b/
externallmg_1723005834359_1723005804974_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66b2fb98c884d11233432461",
```

```
    "name": "externallmg_1723005828682_1723005804974_image_3.jpeg",
    "path": "cases/66b07c454f2f48da09c9be4b/
externallmg_1723005828682_1723005804974_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66b2fb98c884d11233432460",
    "name": "externallmg_1723005825043_1723005804974_image_2.jpeg",
    "path": "cases/66b07c454f2f48da09c9be4b/
externallmg_1723005825043_1723005804974_image_2.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "14861.00",
    "max": "16719.00"
  },
  "builtUpRateRange": {
    "min": "12384.00",
    "max": "13932.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
```



```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
```

```
"label": "Lead",
"value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": false,
"finalValuationArea": "323.00",
"empanelmentNo": [
  "36/ LOAN H.O./2016-17/232"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66b07c454f2f48da09c9be4b",
"ownerName": "Sharad Kamalakar Chavhan",
"ownerPhoneNo": "8422882614",
"appAddress": "Flat no C7 gorai (2) shree bhavani chs Ltd plot no 216, gorai part 2
borivli west, Mumbai 92",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "MHADA Allotment Letter",
      "value": "60ae1267aa6d152c1801b37e"
    },
    "inputs": {
      "documentDate": "21/05/1992",
      "nameOfApprovingAuthority": {
        "value": "Maharashtra_Housing_And_Area_Development_Authority",
        "label": "Maharashtra Housing And Area Development Authority"
      },
      "to": {
        "value": "Allottee",
        "label": "Allottee"
      },
      "Allottee": "Sharad Kamalakar Chavhan",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "-"
    },
    "isHardCopy": false,
```

```
    "displayStatus": true,
    "id": "624987",
    "path": "cases/66b07c454f2f48da09c9be4b/
document_1722841940336_1722841940041_Shared_kamalakar_Chavan.pdf",
    "fileName":
"document_1722841940336_1722841940041_Shared_kamalakar_Chavan.pdf"
  },
  {
    "documentType": {
      "value": "60ae1248aa6d152c1801b2ef",
      "label": "Society Share Certificate"
    },
    "inputs": {
      "documentDate": "02/08/1993",
      "to": {
        "value": "Allottee",
        "label": "Allottee"
      },
      "Allottee": "Sharad Kamlakar Chavan",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      },
      "Document_No": "7"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1723032383295_149978.pdf",
    "path": "cases/66b07c454f2f48da09c9be4b/
document_1723032383295_149978.pdf",
    "id": "381779",
    "uploadedBy": "627221f4afd7d55eddeddcb4",
    "createdAt": "Wed Aug 07 2024 17:36:23 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae129faa6d152c1801b47e",
      "label": "Society Maintenance Receipt"
    },
    "inputs": {
      "documentDate": "01/02/2023",
      "remark": " in the name of Mr. Sharad Kamlakar Chavan ",
      "number": {
        "value": "Document_No",
        "label": "Document No"
      }
    }
  },
```

```
    "Document_No": "1231"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1723032457424_91586.pdf",
  "path": "cases/66b07c454f2f48da09c9be4b/document_1723032457424_91586.pdf",
  "id": "610167",
  "uploadedBy": "627221f4afd7d55eddeddcb4",
  "createdAt": "Wed Aug 07 2024 17:37:37 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "010366",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
  {
    "id": "555519",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Aug 05 2024 12:46:21 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Sharad Kamalakar Chavhan",
    "phone": "8422882614",
    "ownershipShare": "",
    "email": "",
    "id": "749159"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "MHADA Allotment Letter",
      "value": "60ae1267aa6d152c1801b37e"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    }
  },
  "selectAreaTypeDocument": "Built_Up",

```

```
"squareMeterArea": "30.01",
"totalAreaDocument": "323",
"docBuiltupPercentage": "",
"docFinalBuiltUp": "0.00",
"docFinalBuiltUpSquareMeter": "0.00",
"docSaleablePercentage": "",
"docFinalSaleable": "0.00",
"docFinalSaleableSquareMeter": "0.00",
"id": "228770"
}
],
"images": [],
"indicatorArr": [
{
"carpetArea": {
"area": "269.17",
"squareMeterArea": "25.01",
"expectedRate": "14860.50",
"percentage": ""
},
"builtUpArea": {
"area": "323.00",
"squareMeterArea": "30.01",
"expectedRate": "12383.90",
"percentage": "20"
},
"saleableArea": {
"area": "0.00",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "66b35bae4388d81213f38f1f",
"property": "Gorai 2, Jaideep CHSL, Borivali West",
"area": "323",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Built_Up",
"floor": "Ground",
"source": "Index_no.2",
"expectedPrice": "4000000",
"expectedRate": "14860.50",
"builtUpExpectedRate": "4000000",
"image": "cases/66b07c454f2f48da09c9be4b/
indicator_1723030351503_Image.png",
```

```
"squareMeter": "30.01",
"id": "363196"
},
{
  "carpetArea": {
    "area": "269.17",
    "squareMeterArea": "25.01",
    "expectedRate": "16718.06",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "323.00",
    "squareMeterArea": "30.01",
    "expectedRate": "13931.89",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66b35bae4388d81213f38f20",
  "property": "Shree Bhawani CHSL., Gorai 2",
  "area": "323",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "4500000",
  "expectedRate": "16718.06",
  "builtUpExpectedRate": "4500000",
  "image": "cases/66b07c454f2f48da09c9be4b/
indicator_1723030382851_Image.png",
  "squareMeter": "30.01",
  "id": "631259"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b2fb7fda840b1214c274df",
```

```
    "name": "externallmg_1723005822322_1723005818762_image_0.jpeg",
    "path": "cases/66b07c454f2f48da09c9be4b/
externallmg_1723005822322_1723005818762_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66b2fb98c884d1123343245e",
    "name": "externallmg_1723005820500_1723005804974_image_0.jpeg",
    "path": "cases/66b07c454f2f48da09c9be4b/
externallmg_1723005820500_1723005804974_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66b2fb98c884d1123343245f",
    "name": "externallmg_1723005822229_1723005804974_image_1.jpeg",
    "path": "cases/66b07c454f2f48da09c9be4b/
externallmg_1723005822229_1723005804974_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66b2fb98c884d11233432460",
    "name": "externallmg_1723005825043_1723005804974_image_2.jpeg",
    "path": "cases/66b07c454f2f48da09c9be4b/
externallmg_1723005825043_1723005804974_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66b2fb98c884d11233432461",
    "name": "externallmg_1723005828682_1723005804974_image_3.jpeg",
    "path": "cases/66b07c454f2f48da09c9be4b/
externallmg_1723005828682_1723005804974_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66b2fb98c884d11233432462",
    "name": "externallmg_1723005831091_1723005804974_image_4.jpeg",
```

```
    "path": "cases/66b07c454f2f48da09c9be4b/
externallmg_1723005831091_1723005804974_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66b2fb98c884d11233432463",
    "name": "externallmg_1723005834359_1723005804974_image_5.jpeg",
    "path": "cases/66b07c454f2f48da09c9be4b/
externallmg_1723005834359_1723005804974_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66b2fb98c884d11233432464",
    "name": "externallmg_1723005836431_1723005804974_image_6.jpeg",
    "path": "cases/66b07c454f2f48da09c9be4b/
externallmg_1723005836431_1723005804974_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66b2fb98c884d11233432465",
    "name": "externallmg_1723005838776_1723005804974_image_7.jpeg",
    "path": "cases/66b07c454f2f48da09c9be4b/
externallmg_1723005838776_1723005804974_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66b2fb98c884d11233432466",
    "name": "externallmg_1723005841072_1723005804974_image_8.jpeg",
    "path": "cases/66b07c454f2f48da09c9be4b/
externallmg_1723005841072_1723005804974_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66b2fb98c884d11233432467",
    "name": "externallmg_1723005843772_1723005804974_image_9.jpeg",
    "path": "cases/66b07c454f2f48da09c9be4b/
externallmg_1723005843772_1723005804974_image_9.jpeg",
```



```
"orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66b2fb98c884d11233432468",
  "name": "externalImg_1723005846251_1723005804975_image_10.jpeg",
  "path": "cases/66b07c454f2f48da09c9be4b/
externalImg_1723005846251_1723005804975_image_10.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Same.pdf",
    "filename": "1723030467521_Same.pdf",
    "path": "cases/66b07c454f2f48da09c9be4b/
processingDocuments/1723030467521_Same.pdf",
    "size": "149277",
    "createdAt": "Wed Aug 07 2024 17:04:28 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "12000.pdf",
    "filename": "1723030467539_12000.pdf",
    "path": "cases/66b07c454f2f48da09c9be4b/
processingDocuments/1723030467539_12000.pdf",
    "size": "146629",
    "createdAt": "Wed Aug 07 2024 17:04:28 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  },
  {
    "originalname": "1718776194681_1716026508753_1715323634339_17116066606
30_1700891975573_1695465043548_1694516251783_1694241590859_Calculation_1
_2.xlsx",
    "filename": "1723030467551_1718776194681_1716026508753_1715323634339_1
711606660630_1700891975573_1695465043548_1694516251783_1694241590859_
Calculation_1_2.xlsx",
    "path": "cases/66b07c454f2f48da09c9be4b/processingDocuments/1723030467551_
1718776194681_1716026508753_1715323634339_1711606660630_1700891975573_
1695465043548_1694516251783_1694241590859_Calculation_1_2.xlsx",
    "size": "1738712",
    "createdAt": "Wed Aug 07 2024 17:04:28 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f915d3f3dd69653a592199"
  }
]
```

```
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60f915d3f3dd69653a592199",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Shobha",
      "lastName": "Kuperkar",
      "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "66b33c714388d81213f3577c",
    "note": "Pending for bank confirmation ",
    "taskId": "66b07eefdb97d26120509cd1",
    "createdAt": "2024-08-07T09:20:49.083Z"
  }
],
"createdAt": "2024-08-05T07:16:21.718Z",
"updatedAt": "2024-08-07T12:50:25.463Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. C - 7, Ground Floor, Gorai (2) Shree Bhavani Co-
op. Hsg. Soc. Ltd., Plot No. (2), CD - 216, R.S.C. - 32, Village - Gorai, Municipality Ward
No. R - Ward, Borivali (West), Taluka - Borivali, District - Mumbai Suburban District,
Mumbai, PIN Code - 400 092, State - Maharashtra, India",
"updatedBy": "60f915d3f3dd69653a592199",
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "Sharad Kamalakar Chavhan",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner",
"siteVisitContactNo": "8422882614",
"buildingServicesRate": "2000",
```

```

"finalAreaType": "Built Up Area",
"finalAsPerArea": "MHADA Allotment Letter",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 323.00",
"flatRate": "12000",
"landOtherRate": "10000",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"finalSaleablePercentage": "",
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": ""
}

```

Name	Length	Width	Total
Composition :			

Other
Composition :
