

Vastukala Consultants (I) Pvt. Ltd.

Page 1 of 3

Vastu/Mumbai/08/2024/010555/2307819 23/07-297-PRSK Date: 22.08.2024

Structural Stability Report

Structural Observation Report of Residential Flat No. 12, 2nd Floor, "Vasant Vihar Co-Op. Hsg. Soc. Ltd.", Plot No. 17, New Nagardas Cross Road, Village - Andheri, Andheri (East), Mumbai - 400 069, State - Maharashtra, Country - India.

Name of Owner: Mr. Kamabhai Jivraj Solanki, Mr. Chetan Kamabhai Solanki & Mrs. Kanta Kamabhai Solanki

This is to certify that on visual inspection, it appears that the structure of the at "Vasant Vihar Co-Op. Hsg. Soc. Ltd.", is in normal condition and the future life can be reasonably taken under good condition and with proper periodic repairs & maintenance is about 45 years.

General Information:

A.		Introduction
1	Name of Building	"Vasant Vihar Co-Op. Hsg. Soc. Ltd."
2	Property Address	Residential Flat No. 12, 2 nd Floor, "Vasant Vihar Co-Op.
		Hsg. Soc. Ltd. ", Plot No. 17, New Nagardas Cross Road,
		Village - Andheri, Andheri (East), Mumbai - 400 069, State
		- Maharashtra, Country - India
3	Type of Building	Residential used
4	No. of Floors	Ground + 6 th Upper Floors
5	Whether stilt / podium / open parking	Open Car Parking Space
	provided	Fig/
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	2005 (As per site information)
11	Present age of building	19 years
12	Residual age of the building	41 years Subject to proper, preventive periodic
		maintenance & structural repairs.
13	No. of flats (Per Floor)	04 Flats on 2 nd Floor
14	Methodology adopted	As per visual site inspection

B.	External Observation of the Building		
1	Plaster	Normal Condition	
2	Chajjas	Normal Condition	A CONSULTANTO
3	Plumbing	Normal Condition	Valuers & Appraisers Architects &
4	Cracks on the external walls	Not Found	Charlered Engineers (I) TEV Consultants
5	Filling cracks on the external walls	Not Found	Lender's Engineer
6	Cracks on columns & beams	Not Found	37201011

Our Pan India Presence at:

♀ Aurangabad
♀ Pune

Nanded Mumbai

Thane Nashik

Ahmedabad Opelhi NCR Rajkot

💡 Raipur

Jaipur

Regd. Office

B1-001, U/B Floor, BOOMERANG, Chandivali Farm Road, Powai, Andheri East, Mumbai: 400072, (M.S), India



🔀 mumbai@vastukala.co.in www.vastukala.co.in



7	Vegetation	Not Found
8	Leakages of water in the drainage pipes	Not Found
	or water pipes	
9	Dampness external in the wall due to	Not Found
	leakages	
10	Any other observation about the condition	Structural Stability Report from licensed structural
	of external side of the building	engineers not provided for our verification.
С	Internal Observation of the common areas of the building and captioned premises	
-	_	
1	Beams (Cracks & Leakages)	Not Found
2	Beams (Cracks & Leakages) Columns (Cracks & Leakages)	Not Found Not Found
2 3	3 9 7	
	Columns (Cracks & Leakages)	Not Found
3	Columns (Cracks & Leakages) Ceiling (Cracks & Leakages)	Not Found Not Found

D	Common Observation	
1	Structural Audit of the Building Under Bye	As per bye Laws No. 77 of Co-Op. Societies bye Laws
	- Laws No. 77 of the Model Bye Laws (Co-	under the Act the society shall conduct a Structural Audit of
	Operative Societies Act / Rules)	the building of the society as follows
2	Remark	No Structural Audit Report is furnished for the perusal.

E Conclusion

The captioned building is having Ground + 6th Upper Floors which are constructed in year 2005 (As per site information) Estimated future life under present circumstances is about 41 years subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 16.08.2024 of building. The building is well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & Good structural repairs.

Our Observations about the structure are given above.

The above assessment is based on visual inspection only. Separate structural audit from licensed structural engineers is advised to assess exact balance life of structure.

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Director Auth. Sign.

Sharadkumar B. Chalikwar

Structural Engineer Licence No. STATE/R/2022/APL/01785 Govt. Reg. Valuer Chartered Engineer (India) Reg No. (N) CCIT/1-14/52/2008-09





An ISO 9001: 2015 Certified Company

Actual site photographs

















An ISO 9001: 2015 Certified Company