

MSME Reg No: UDYAM-MH-18-0083617 An ISO 9001: 2015 Certified Company CIN: U74120MH2010PTC207869

Vastukala Consultants (I) Pvt. Ltd.

Structural Stability Report Prepared for SBI / RACPC Kalyan / Deepti Singh W/O. Sachin Singh (010596 /2307705)

Page 1 of 4

www.vastukala.co.in

Vastu/Thane/08/2024/010596/2307705 14/8-183-PSB Date: 14.08.2024

Structural Stability Report

Structural Observation Report of Residential Flat No. C - 36, 1st Floor, "Happy Home Co.-Op. Hsg. Soc. Ltd.", Near Shahad Railway Station, Village - Shahad, Taluka - Kalyan, District - Thane, Shahad (West), PIN Code - 421 103, State - Maharashtra, India.

Name of Owner: Deepti Singh W/O. Sachin Singh

This is to certify that on visual inspection, it appears that the structure of the at "Happy Home Co.-Op. Hsg. Soc. Ltd.", is in normal condition and the future life can be reasonably taken under good condition and with proper periodic repairs & maintenance is about 29 years.

General Information:

A.		Introduction			
1	Name of Building	"Happy Home CoOp. Hsg. Soc. Ltd."			
2	Property Address	Residential Flat No. C - 36, 1st Floor, "Happy Home Co Op. Hsg. Soc. Ltd.", Near Shahad Railway Station, Village - Shahad, Taluka - Kalyan, District - Thane, Shahad (West), PIN Code - 421 103, State - Maharashtra, India.			
3	Type of Building	Residential used			
4	No. of Floors	(Part) Ground + (Part) Stilt 4th Upper Floors			
5	Whether stilt / podium / open parking provided	Stilt Parking			
6	Type of Construction	R.C.C. Framed Structure			
7	Type of Foundation	R.C.C. Footing			
8	Thickness of the External Walls	9" thick brick walls both sides plastered			
9	Type of Compound	Brick Masonry Walls			
10	Year of Construction	1993 (As per Occupancy Certificate)			
11	Present age of building	31 years			
12	Residual age of the building	29 years Subject to proper, preventive periodic maintenance & structural repairs.			
13	No. of flats (Per Floor)	04 Flats on 1st Floor			
14	Methodology adopted	As per visual site inspection			

B.	Externa		
1	Plaster	Normal Condition	acili Ta
2	Chajjas	Normal Condition	WI CONSULTANTS
3	Plumbing	Normal Condition	Valuers Appraisers Architects & Interior Assigners
4	Cracks on the external walls	Not Found	Charter of Engineers (i) TEV Constitutions
5	Filling cracks on the external walls	Not Found	Lenger & Chinese PTC 2018
6	Cracks on columns & beams	Not Found	112010

Our Pan India Presence at:

Nanded

Ahmedabad Opelhi NCR

Nashik Mumbai

Aurangabad
Pune

Rajkot Raipur

Regd. Office

B1-001, U/B Floor, BOOMERANG, Chandivali Farm Road, Powai, Andheri East, **Mumbai**: 400072, (M.S), India

+91 2247495919

mumbai@vastukala.co.in www.vastukala.co.in



	-	~	-	0	-	£	i
М	а	g	е	2	0	T	4

7	Vegetation	Not Found	
8	Leakages of water in the drainage pipes	Not Found	
	or water pipes		
9	Dampness external in the wall due to	Not Found	
	leakages		
10	Any other observation about the condition	Structural Stability Report from licensed structural	
	of external side of the building	engineers not provided for our verification.	
С	Internal Observation of the common areas of the building and captioned premises		
1	Beams (Cracks & Leakages)	Not Found	
2	Columns (Cracks & Leakages)	Not Found	
3	Ceiling (Cracks & Leakages)	Not Found	
4	Leakages inside the property	Not Found	
5	Wall (Cracks)	Not Found	
6	Painting inside the property	Good	
7	Maintenance of staircase & cracks	Good	

D	Common Observation		
1	Structural Audit of the Building Under Bye	As per bye Laws No. 77 of Co-Op. Societies bye Laws	
	- Laws No. 77 of the Model Bye Laws (Co-	under the Act the society shall conduct a Structural Audit of	
	Operative Societies Act / Rules)	the building of the society as follows	
2	Remark	No Structural Audit Report is furnished for the perusal.	

Ε Conclusion

The captioned building is having (Part) Ground + (Part) Stilt 4th Upper Floors Upper Floors which are constructed in year 1993 (As per Occupancy Certificate). Estimated future life under present circumstances is about 29 years subject to proper, preventive periodic maintenance & structural repairs.

The inspection dated 08.08.2024 of building. The building is well as the property is maintained in good condition & will stand future life subject to proper, preventive periodic maintenance & Good structural repairs.

Our Observations about the structure are given above.

The above assessment is based on visual inspection only. Separate structural audit from licensed structural engineers is advised to assess exact balance life of structure.

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Sharadkuma Digitally si r Chalikwar

c=IN Date: 2024.08.14 17:58:25 +05'30'

Director

Auth. Sign.

Sharadkumar B. Chalikwar

Structural Engineer Licence No. STATE/R/2022/APL/01785 Govt. Reg. Valuer


Chartered Engineer (India)

Reg No. (N) CCIT/1-14/52/2008-09

SBI Empanelment No.: SME / TCC / 2021 - 22 / 85 / 13



Since 1989



An ISO 9001: 2015 Certified Company



Actual site photographs

















Since 1989



Actual site photographs





