

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64d3753487258203eab0187e"
    },
    "firstName": "Malge Yogesh",
    "type": "CREDITOFFICER",
    "_id": "64d3753487258203eab01880",
    "lastName": "Veebhadrswami",
    "mobileNo": "",
    "workMobileNo": "9008175721",
    "email": "yogesh.malge@unionbankofindia.bank"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "8000000",
    "discussWithPerson": "Malge Yogesh",
    "expectedFees": 4000,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64d3753487258203eab0187e",
  "name": "Corporate & SME Powai Branch",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "ubin0556688@unionbankofindia.bank",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Dikshant Bhawan, 1st FLOOR, Shop No 101, Above Indian Oil Petrol
Pump, Opp IIT Main Gate, Powai, Mumbai - 40076"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "667112d324f3ba1343e5ac5c",
"role": "PICKUPPERSON",
"firstName": "SAHADEV ",
"email": "temkarsahdaev@gmail.com",
"lastName": "TEMKAR",
"mobileNo": "9869931652",
"shortName": "SAHADEV",
"workWithDocumentMaker": ""
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63fc4680ce84bf289ba9c7fc",
"role": "SITEENGINEER",
"firstName": "Nikhil ",
"email": "valtechnical2022@gmail.com",
"lastName": "Sonawane",
"mobileNo": "9819470709",
"designation": "",
"shortName": "NS",
"workWithDocumentMaker": "6006d4ce5080a310ac1fdcf2",
"profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1720806809901_image.jpg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "64dc7184ccaf1e7b7f637f47",
"role": "FRONTDESK",
"firstName": "Binumon",
"email": "binu@vastukala.org",
"lastName": "Moozhickal",
"mobileNo": "9930252906",
"designation": "Back Office Team Leader",
"shortName": "BS",
"workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
"profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "627221f4afd7d55eddeddcb4",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Prajakta",
"email": "prajakta@vastukala.org",
"lastName": "Patil",
"mobileNo": "9769797568",
"designation": ""
```

```
"shortName": "P",
"workWithDocumentMaker": "",
"profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      }
    ],
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    }
  },
}
```

```
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
},
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.145144996815493",
  "longitude": "73.07798110283035"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.07798110283035,
    19.145144996815493
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-11-21",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-11-20",
      "remark": "MANUAL_IN_TASK"
    }
  ]
}
```

```
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "3BHK",
  "label": "3 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Nilje & Ghesar",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "16",
    "label": false
  },
  "buildingNo": {
    "status": false,
```

```
"name": "Building No",
"key": "buildingNo",
"value": "",
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "River View Co-op. Hsg. Soc. Ltd.",
  "label": false
}
```

```
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Kalyan Shill Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "F",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Casa Rio",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
```



```
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "63/1, 92/1, 60/2",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1601",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
}
```

```
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 421 204",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
```

```
    "value": "Dombivli (East)",
    "label": false
  }
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Powder_coated_Aluminum_sliding_windows",
    "label": "Powder coated Aluminum sliding windows"
  },
  "fittings": {
    "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
    "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
  },
  "finishing": {
    "value": "Cement_Plastering",
    "label": "Cement Plastering"
  }
},
"general": {
  "ownership": {
    "value": "Pvt._Ltd._Company_Ownership",
    "label": "Pvt. Ltd. Company Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "Kalyan_Dombivali_Municipal_Corporation",
```

```
"label": "Kalyan Dombivali Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Internal Road & River Dale CHSL",
  "west": "Viviana CHSL",
  "south": "Wing - E",
  "east": "Internal Road & River Retreat CHSL"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Marginal Space",
    "east": "Marginal Space",
    "south": "Flat No. 1602",
    "west": "Staircase & Flat No. 1604"
  },
  "asPerDocument": {
    "north": "Details not available",
    "east": "Details not available",
    "south": "Details not available",
    "west": "Details not available"
  },
  "isDisplay": true,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
}
```

```
    }
  },
  "extraDetailOfProperty": "",
  "dateOfIssusApprovePlan": "Copy of Approved Plan were not provided and not
verified",
  "approvePlanVerified": "N.A.",
  "empanelledOfApprovePlan": "N.A.",
  "unauthorizedConstruction": "",
  "extraDetailOfBuilding": "",
  "compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "10.5",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "8606",
  "depreciatedBuildingRate": "2506"
},
"igrRate": {
  "propertyName": "Flat",
  "rate": "70000",
  "landRate": "21000",
  "igrImage": "cases/66c044e9da840b1214c861f1/igr_1733829722831_Image.png",
  "squareMeterGuideLineRate": "77000.00",
  "squareFeetGuideLineRate": "7154.00"
},
"igrFinalRate": {
  "floorRatePercentage": "10",
  "depreciationPercentage": "93",
  "rate": "6789.00",
  "squareFeetGuideLineRate": "6789.00",
  "squareMeterGuideLineRate": "73080.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  }
}
```

```
},
"propertyTypeOfUseList": {
  "value": "Residential_Purpose",
  "label": "Residential Purpose"
},
"propertyOccupiedByList": {
  "value": "Employee_of_the_company_occupied",
  "label": "Employee of the company occupied"
},
"monthlyRent": "18,000/- Present rental income per month",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per KDMC norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  }
},
"anyFavouringForExtraPotentialValue": "Located in Developed Area",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  }
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Stilt Car Parking",
```

```
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2017",
  "fullDate": "1/1/2017"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
}
```

```
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "Approx.",
  "label": "Approx."
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "53",
"ageOfBuilding": "7",
"noOfBasement": "",
"noOfPodium": ""
```



```
"noOfAmenityFloors": "",
"noOfFloors": "19",
"flatFloorNo": "16",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/66c044e9da840b1214c861f1/
routeMap_1733891677996_Image.png",
    "routeLat": "19.145253",
    "routeLng": "73.077746",
    "stationName": "Dombivli",
    "routeDistance": "9.2 Km.",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  },
  "finalLatLng": {
    "coordinates": [
      0,
      0
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": false,
    "finallatLng": false
  },
  "locationMapImg": [
    {
      "id": "vpu72",
      "name": "vpu72",
      "image": "cases/66c044e9da840b1214c861f1/
routeMap_1733891597341_Image.png"
    }
  ],
  "valuation": {
    "fairMarketValue": {
      "costOfConstruction": "",
      "depreciationPercentage": ""
    }
  }
}
```

```
"depreciatedCostOfConstruction": "",
"totalFairMarketValue": ""
},
"wardrobesRate": "0",
"totalwardrobesRate": "0",
"wardrobesQty": "0",
"showcasesQty": "0",
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "6867588.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "6867588.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "5959384.00",
  "selectedBuildUpValue": "877.80",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "673ee8ef572e264e52152d7e",
      "name": "externallmg_r_1732176107298_1732176098561_image_0.jpg",
      "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176107298_1732176098561_image_0.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "673ee8d6e077c54e532601e5",
```

```
    "name": "externallmg_r_1732176061703_1732176056379_image_2.jpg",
    "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176061703_1732176056379_image_2.jpg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "673ee8ef572e264e52152d7f",
    "name": "externallmg_r_1732176108688_1732176098561_image_1.jpg",
    "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176108688_1732176098561_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "673ee8d6e077c54e532601f4",
    "name": "externallmg_r_1732176079191_1732176056379_image_19.jpg",
    "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176079191_1732176056379_image_19.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "673ee8d6e077c54e532601f5",
    "name": "externallmg_r_1732176078002_1732176056379_image_18.jpg",
    "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176078002_1732176056379_image_18.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "673ee8d6e077c54e532601f1",
    "name": "externallmg_r_1732176076474_1732176056379_image_16.jpg",
    "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176076474_1732176056379_image_16.jpg",
    "orientation": "landscape"
  }
],
"compositionImages": [
  {
    "status": false,
```

```
    "_id": "673ee8d6e077c54e532601e4",
    "name": "Bedroom",
    "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176064231_1732176056379_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "673ee8d6e077c54e532601e7",
    "name": "Bedroom",
    "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176066003_1732176056379_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "673ee8d6e077c54e532601e9",
    "name": "Bedroom",
    "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176066734_1732176056379_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "673ee8d6e077c54e532601ea",
    "name": "Bedroom",
    "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176067622_1732176056379_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "673ee8d6e077c54e532601eb",
    "name": "Bedroom",
    "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176068675_1732176056379_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "673ee8d6e077c54e532601ec",
    "name": "Bedroom",
    "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176070924_1732176056379_image_11.jpg",
    "orientation": "portrait"
  },
}
```

```
{
  "status": false,
  "_id": "673ee8d6e077c54e532601ed",
  "name": "Bedroom",
  "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176069866_1732176056379_image_10.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "673ee8d6e077c54e532601f0",
  "name": "Bedroom",
  "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176074268_1732176056379_image_14.jpg",
  "orientation": "portrait"
}
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "7154.00",
    "max": "9590.00"
  },
  "builtUpRateRange": {
    "min": "6504.00",
    "max": "8718.00"
  },
  "saleableRateRange": {
    "min": "5420.00",
    "max": "7265.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
```

```
"label": "Lead",
"value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "798.00",
"empanelmentNo": [
  "ROS:ADV:Valuer/033:008:2021-22"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "66c044e9da840b1214c861f1",
"ownerName": "Nandan Ground Support Equipments Ltd.",
"ownerPhoneNo": "9833963928",
"appAddress": "Flat No F-1601, 16 th Floor, River View bulding, F-Wing, River view
CHSL, S No. 63/1,92/1,60/2, at kalin shil road village, Nile and ghesar, DombivaliØ=P (E),
Taluka-kalyan.",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1288aa6d152c1801b41a",
      "label": "Deed of Simple Mortgage"
    },
    "inputs": {
      "documentDate": "29/08/2022",
      "remark": " b/w. M/s. Nandan Ground Support Equipments Pvt. Ltd. (The
Mortgagor) and Union Bank of India (The Mortgagee)"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "493246",
    "path": "cases/66c044e9da840b1214c861f1/
document_1728129720093_1728129717337_New_Report_Plot_No_205.pdf",
    "fileName":
"document_1728129720093_1728129717337_New_Report_Plot_No_205.pdf"
  },
  {
    "documentType": {
      "value": "60ae1288aa6d152c1801b41a",
      "label": "Deed of Simple Mortgage"
    }
  }
]
```

```
    },
    "inputs": {
      "remark": "b/w. M/s. Nandan Ground Support Equipments Pvt. Ltd. (The
Mortgagor) and Union Bank of India (The Mortgagee) in the year 2019"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "739238",
    "path": "cases/66c044e9da840b1214c861f1/document_1728130657798_17281306
55296_New_Report_Nandan_Ground_Flat_No_F160116th_flr_Dombivali.pdf",
    "fileName": "document_1728130657798_1728130655296_New_Report_Nandan_G
round_Flat_No_F160116th_flr_Dombivali.pdf"
  }
],
"caseNumber": "010643",
"createdBy": "667112d324f3ba1343e5ac5c",
"caseHistory": [
  {
    "id": "902954",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Aug 17 2024 12:06:25 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Nandan Ground Support Equipment Pvt. Ltd.",
    "phone": "9833963928",
    "ownershipShare": "",
    "email": "",
    "id": "436426"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "560992",
    "name": "Bedroom",
    "length": "11.42",
    "length1": "11",
    "length2": "5",
```

```
"width": "10.25",
"width1": "10",
"width2": "3",
"totalArea": "117.02",
"images": [],
"extraAreas": [],
"finalArea": "117.02"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Toilet",
  "length": "7.83",
  "length1": "7",
  "length2": "10",
  "width": "4.67",
  "width1": "4",
  "width2": "8",
  "totalArea": "36.56",
  "images": [],
  "extraAreas": [],
  "finalArea": "36.56"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Passage",
  "length": "10.25",
  "length1": "10",
  "length2": "3",
  "width": "3.08",
  "width1": "3",
  "width2": "1",
  "totalArea": "31.60",
  "images": [],
  "extraAreas": [],
  "finalArea": "31.60"
},
{
  "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Passage",
  "length": "10.25",
  "length1": "10",
  "length2": "3",
  "width": "3.08",
  "width1": "3",
  "width2": "1",
  "totalArea": "31.60",
  "images": [],
  "extraAreas": [],
  "finalArea": "31.60"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Toilet",
  "length": "4.67",
  "length1": "4",
  "length2": "8",
  "width": "7.83",
  "width1": "7",
  "width2": "10",
  "totalArea": "36.56",
  "images": [],
  "extraAreas": [],
  "finalArea": "36.56"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Bedroom",
  "length": "",
  "length1": "9",
  "length2": "6",
  "width": "",
  "width1": "10",
```

```
"width2": "0",
"totalArea": "95.00",
"images": [],
"finalArea": "95.00",
"extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Living Room",
  "length": "10.67",
  "length1": "10",
  "length2": "8",
  "width": "17.17",
  "width1": "17",
  "width2": "2",
  "totalArea": "183.11",
  "images": [],
  "extraAreas": [],
  "finalArea": "183.11"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Bedroom",
  "length": "7.67",
  "length1": "7",
  "length2": "8",
  "width": "6.42",
  "width1": "6",
  "width2": "5",
  "totalArea": "49.19",
  "images": [],
  "extraAreas": [],
  "finalArea": "49.19"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  }
```

```
},
  "id": "8",
  "name": "Kitchen",
  "length": "13.25",
  "length1": "13",
  "length2": "3",
  "width": "8.00",
  "width1": "8",
  "width2": "00",
  "totalArea": "106.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "106.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "9",
  "name": "Passage",
  "length": "3.08",
  "length1": "3",
  "length2": "1",
  "width": "8.25",
  "width1": "8",
  "width2": "3",
  "totalArea": "25.44",
  "images": [],
  "extraAreas": [],
  "finalArea": "25.44"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "10",
  "name": "Passage",
  "length": "1.42",
  "length1": "1",
  "length2": "5",
  "width": "3.58",
  "width1": "3",
  "width2": "7",
  "totalArea": "5.08",
```



```
"images": [],
"extraAreas": [],
"finalArea": "5.08"
}
],
"otherComposition": [
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Cupboard",
    "value": "Cupboard"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length": "6.67",
  "length1": "6",
  "length2": "8",
  "width": "2.08",
  "width1": "2",
  "width2": "1",
  "totalArea": "13.89",
  "images": [],
  "extraAreas": [],
  "finalArea": "13.89",
  "percentageBeforeTotal": "13.89",
  "percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Cupboard",
    "value": "Cupboard"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
}
```

```
"id": "1",
"length": "4.42",
"length1": "4",
"length2": "5",
"width": "2.08",
"width1": "2",
"width2": "1",
"totalArea": "9.20",
"images": [],
"extraAreas": [],
"finalArea": "9.2",
"percentageBeforeTotal": "9.20",
"percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Balcony Area",
    "value": "Balcony_Area"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "length": "8.50",
  "length1": "8",
  "length2": "6",
  "width": "3.58",
  "width1": "3",
  "width2": "7",
  "totalArea": "30.46",
  "images": [],
  "extraAreas": [],
  "finalArea": "30.46",
  "percentageBeforeTotal": "30.46",
  "percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
}
```

```
"name": {
  "label": "Cupboard",
  "value": "Cupboard"
},
"measurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "3",
"length": "3.33",
"length1": "3",
"length2": "4",
"width": "2.00",
"width1": "2",
"width2": "00",
"totalArea": "6.67",
"images": [],
"extraAreas": [],
"finalArea": "6.67",
"percentageBeforeTotal": "6.67",
"percentage": "100"
},
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Dry Balcony",
    "value": "Dry_Balcony"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "length": "5.25",
  "length1": "5",
  "length2": "3",
  "width": "3.08",
  "width1": "3",
  "width2": "1",
  "totalArea": "16.19",
  "images": [],
  "extraAreas": [],
  "finalArea": "16.19",
```

```
"percentageBeforeTotal": "16.19",
"percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "value": "60ae1288aa6d152c1801b41a",
    "label": "Deed of Simple Mortgage"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "851962",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "798",
  "squareMeterArea": "74.14",
  "docFinalBuiltUp": "877.8",
  "docFinalBuiltUpSquareMeter": "81.554",
  "docBuiltupPercentage": "10",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "carpetArea": {
    "area": "730.00",
    "squareMeterArea": "67.82",
    "expectedRate": "9589.04",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "803.00",
    "squareMeterArea": "74.60",
    "expectedRate": "8717.31",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "963.60",
    "squareMeterArea": "89.52",
    "expectedRate": "7264.43",
```

```
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "675825e4befd7f3db9095441",
  "property": "Flat",
  "area": "730",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "Nobroker.com",
  "expectedPrice": "7000000",
  "expectedRate": "9589.04",
  "builtUpExpectedRate": "8717.31",
  "image": "cases/66c044e9da840b1214c861f1/
indicator_1733830081208_Image.png",
  "squareMeter": "67.82",
  "id": "272584"
},
{
  "carpetArea": {
    "area": "795.00",
    "squareMeterArea": "73.86",
    "expectedRate": "8553.46",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "874.50",
    "squareMeterArea": "81.24",
    "expectedRate": "7775.87",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "1049.40",
    "squareMeterArea": "97.49",
    "expectedRate": "6479.89",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "675825e4befd7f3db9095442",
  "property": "Flat",
  "area": "795",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "price_Indicator",
```

```
"areaType": "Carpet",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "6800000",
"expectedRate": "8553.46",
"builtUpExpectedRate": "7775.87",
"image": "cases/66c044e9da840b1214c861f1/
indicator_1733829366194_Image.png",
"squareMeter": "73.86",
"id": "372800"
},
{
"carpetArea": {
"area": "686.00",
"squareMeterArea": "63.73",
"expectedRate": "7142.86",
"percentage": ""
},
"builtUpArea": {
"area": "754.60",
"squareMeterArea": "70.10",
"expectedRate": "6493.51",
"percentage": "10"
},
"saleableArea": {
"area": "905.52",
"squareMeterArea": "84.13",
"expectedRate": "5411.26",
"percentage": "20"
},
"printlnReport": false,
"_id": "675825e4befd7f3db9095443",
"property": "Flat",
"area": "686",
"builtUpPercentage": "10",
"saleablePercentage": "20",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "4900000",
"expectedRate": "7142.86",
"builtUpExpectedRate": "6493.51",
"image": "cases/66c044e9da840b1214c861f1/
indicator_1733829411859_Image.png",
"squareMeter": "63.73",
```

```
"id": "958322"
},
{
  "carpetArea": {
    "area": "657.00",
    "squareMeterArea": "61.04",
    "expectedRate": "7153.73",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "722.70",
    "squareMeterArea": "67.14",
    "expectedRate": "6503.39",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "867.24",
    "squareMeterArea": "80.57",
    "expectedRate": "5419.49",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "675825e4befd7f3db9095444",
  "property": "Flat",
  "area": "657",
  "builtUpPercentage": "10",
  "saleablePercentage": "20",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "4700000",
  "expectedRate": "7153.73",
  "builtUpExpectedRate": "6503.39",
  "image": "cases/66c044e9da840b1214c861f1/
indicator_1733829645920_Image.png",
  "squareMeter": "61.04",
  "id": "426550"
}
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673ee8d6e077c54e532601e2",
    "name": "externallmg_1732176060809_1732176056379_image_1.png",
```

```
    "path": "cases/66c044e9da840b1214c861f1/
externallmg_1732176060809_1732176056379_image_1.png",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673ee8d6e077c54e532601e3",
    "name": "externallmg_r_1732176063413_1732176056379_image_3.jpg",
    "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176063413_1732176056379_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673ee8d6e077c54e532601e4",
    "name": "externallmg_r_1732176064231_1732176056379_image_4.jpg",
    "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176064231_1732176056379_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673ee8d6e077c54e532601e5",
    "name": "externallmg_r_1732176061703_1732176056379_image_2.jpg",
    "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176061703_1732176056379_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673ee8d6e077c54e532601e6",
    "name": "externallmg_r_1732176059287_1732176056379_image_0.jpg",
    "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176059287_1732176056379_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673ee8d6e077c54e532601e7",
    "name": "externallmg_r_1732176066003_1732176056379_image_6.jpg",
    "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176066003_1732176056379_image_6.jpg",
```



```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "673ee8d6e077c54e532601e8",
  "name": "externallmg_r_1732176065082_1732176056379_image_5.jpg",
  "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176065082_1732176056379_image_5.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "673ee8d6e077c54e532601e9",
  "name": "externallmg_r_1732176066734_1732176056379_image_7.jpg",
  "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176066734_1732176056379_image_7.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "673ee8d6e077c54e532601ea",
  "name": "externallmg_r_1732176067622_1732176056379_image_8.jpg",
  "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176067622_1732176056379_image_8.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "673ee8d6e077c54e532601eb",
  "name": "externallmg_r_1732176068675_1732176056379_image_9.jpg",
  "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176068675_1732176056379_image_9.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "673ee8d6e077c54e532601ec",
  "name": "externallmg_r_1732176070924_1732176056379_image_11.jpg",
  "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176070924_1732176056379_image_11.jpg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "673ee8d6e077c54e532601ed",
  "name": "externallmg_r_1732176069866_1732176056379_image_10.jpg",
  "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176069866_1732176056379_image_10.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "673ee8d6e077c54e532601ee",
  "name": "externallmg_r_1732176072147_1732176056379_image_12.jpg",
  "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176072147_1732176056379_image_12.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "673ee8d6e077c54e532601ef",
  "name": "externallmg_r_1732176073383_1732176056379_image_13.jpg",
  "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176073383_1732176056379_image_13.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "673ee8d6e077c54e532601f0",
  "name": "externallmg_r_1732176074268_1732176056379_image_14.jpg",
  "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176074268_1732176056379_image_14.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "673ee8d6e077c54e532601f1",
  "name": "externallmg_r_1732176076474_1732176056379_image_16.jpg",
  "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176076474_1732176056379_image_16.jpg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "673ee8d6e077c54e532601f2",
  "name": "externallmg_r_1732176075480_1732176056379_image_15.jpg",
  "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176075480_1732176056379_image_15.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "673ee8d6e077c54e532601f3",
  "name": "externallmg_r_1732176077216_1732176056379_image_17.jpg",
  "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176077216_1732176056379_image_17.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "673ee8d6e077c54e532601f4",
  "name": "externallmg_r_1732176079191_1732176056379_image_19.jpg",
  "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176079191_1732176056379_image_19.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "673ee8d6e077c54e532601f5",
  "name": "externallmg_r_1732176078002_1732176056379_image_18.jpg",
  "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176078002_1732176056379_image_18.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "673ee8ef572e264e52152d7e",
  "name": "externallmg_r_1732176107298_1732176098561_image_0.jpg",
  "path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176107298_1732176098561_image_0.jpg",
  "orientation": "portrait"
},
{
```

```
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "673ee8ef572e264e52152d7f",
"name": "externallmg_r_1732176108688_1732176098561_image_1.jpg",
"path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176108688_1732176098561_image_1.jpg",
"orientation": "portrait"
},
{
"type": "MEASUREMENT_IMAGE",
"status": false,
"_id": "673ee8a2d1078a4ea7f7dcc3",
"name": "externallmg_r_1732176032248_1732176030600_image_0.jpg",
"path": "cases/66c044e9da840b1214c861f1/
externallmg_r_1732176032248_1732176030600_image_0.jpg",
"orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
{
"originalname": "Nandan Ground Equipment Pvt Ltd - Flat No. 1601 - Union Bank of
India ( Corporate & SME Powai Branch ).xlsx",
"filename": "1733830156595_Nandan_Ground_Equipment_Pvt_Ltd__Flat_No_1601
__Union_Bank_of_India__Corporate__SME_Powai_Branch_.xlsx",
"path": "cases/66c044e9da840b1214c861f1/processingDocuments/1733830156595
_Nandan_Ground_Equipment_Pvt_Ltd__Flat_No_1601__Union_Bank_of_India__Corp
orate__SME_Powai_Branch_.xlsx",
"size": "1745555",
"createdAt": "Tue Dec 10 2024 11:29:16 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "64dc7184ccaf1e7b7f637f47"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
"createdBy": {
"_id": "64dc7184ccaf1e7b7f637f47",
"role": "FRONTDESK",
"firstName": "Binumon",
"lastName": "Moozhickal",
"profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"workType": "RATE_VERIFY",
```

```
"display": true,
"status": true,
"_id": "671f12b51a3e43c859d43d0c",
"note": "pending for readable copy of approved plan",
"taskId": "671a429cfd14bf9350ab9f52",
"createdAt": "2024-10-28T04:27:33.893Z"
}
],
"createdAt": "2024-08-17T06:36:25.692Z",
"updatedAt": "2024-12-11T05:05:40.129Z",
"__v": 0,
"updatedBy": "627221f4afd7d55eddeddcb4",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 1601, 16th Floor, Wing - F, River View Co-op. Hsg. Soc. Ltd., Casa Rio, Kalyan Shill Road, Village - Nilje & Ghesar, Dombivli (East), Taluka - Kalyan, District - Thane, PIN Code - 421 204, State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "667112d324f3ba1343e5ac5c",
"contactPersonName": "Mr. Nagraj",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Employee of the company",
"rerald": "",
"siteVisitContactNo": "7349678982",
"buildingServicesRate": "2800",
"finalAreaType": "Carpet Area",
"finalAsPerArea": " Agreement",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 798.00",
"flatRate": "8900",
"landOtherRate": "6100",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  }
},
"roadFacing": false,
```

```

    "mall": false
  },
  "siteVisitDate": "2024-11-20",
  "landDetails": {
    "holdType": {
      "label": "Free Hold",
      "value": "Free_Hold"
    },
    "leaseDetails": {
      "lessorName": "",
      "lesseeName": "",
      "leasePremium": "",
      "leaseRent": "",
      "leasePeriod": 0,
      "leaseFrom": "",
      "leaseTo": "",
      "remainingLeasePeriod": 0,
      "leaseDate": ""
    }
  },
  "finalSaleablePercentage": "",
  "briefDescOfProperty": "3 Bedroom + Living Room + Kitchen + 2 Toilet + 4 Passage",
  "carpetTotal": "717.16",
  "otherCarpetTotal": "76.41",
  "otherCompositionBuiltUpTotal": "0.00",
  "otherCompositionCarpetTotal": "76.41",
  "otherCompositionSaleableTotal": "0.00",
  "builtupPercentage": "10",
  "finalBuiltupArea": "872.93",
  "finalCarpetArea": "793.57",
  "finalSalableArea": "960.22",
  "salablePercentage": "10",
  "toBeAdded": "",
  "extendOfSiteRemark": "",
  "siteMeasurementRemark": "\nCarpet Area in Sq. Ft. = 717.00\nCupboard Area in Sq. Ft. = 30.00\nBalcony Area in Sq. Ft. = 31.00\nDry Balcony Area in Sq. Ft. = 16.00\nTotal Carpet Area in Sq. Ft. = 794.00\n(Area as per Actual Site Measurement)\n\n",
  "reportGeneratedDate": "Wed Dec 11 2024 04:28:47 GMT+0000 (Coordinated Universal Time)"
}

```

Name	Length	Width	Total
Composition :			
Bedroom	11'5"	10'3"	117.02

Toilet	7'10"	4'8"	36.56
Passage	10'3"	3'1"	31.60
Passage	10'3"	3'1"	31.60
Toilet	4'8"	7'10"	36.56
Bedroom	9'6"	10'0"	95.00
Living Room	10'8"	17'2"	183.11
Bedroom	7'8"	6'5"	49.19
Kitchen	13'3"	8'00"	106.00
Passage	3'1"	8'3"	25.44
Passage	1'5"	3'7"	5.08
Other Composition :			
Cupboard	6'8"	2'1"	13.89
Cupboard	4'5"	2'1"	9.20
Balcony Area	8'6"	3'7"	30.46
Cupboard	3'4"	2'00"	6.67
Dry Balcony	5'3"	3'1"	16.19