



VASTUKALA
Unlocking Excellence

www.vastukala.co.in

MSME Reg No: UDYAM-MH-18-0083617

An ISO 9001 : 2015 Certified Company

CIN: U74120MH2010PTC207869

Vastukala Consultants (I) Pvt. Ltd.

Page 1 of 3

Vastu/Mumbai/08/2024/010802/2307930

29/13-408-SKVS

Date: 29.08.2024

Structural Stability Report

Structural Observation Report Residential Flat No. 07, 1st Floor, “Sneh Sadan Co-op. Hsg. Soc. Ltd.”, Plot No. 180, Sion Matunga Estate (West), Sion (West), Mumbai – 400022, State - Maharashtra, Country - India.

Name of Owner: **Mr. Amin Chimanlal Shah**

Singh

This is to certify that on visual inspection, it appears that the structure at “Sneh Sadan Co-op. Hsg. Soc. Ltd.” is in normal condition and the future life can be reasonably taken under normal condition and with proper periodic repairs & maintenance is about 6 years.

General Information:

A.	Introduction	
1	Name of Building	“Sneh Sadan Co-op. Hsg. Soc. Ltd.”
2	Property Address	Residential Flat No. 07, 1 st Floor, “Sneh Sadan Co-op. Hsg. Soc. Ltd.”, Plot No. 180, Sion Matunga Estate (West), Sion (West), Mumbai – 400022, State - Maharashtra, Country - India
3	Type of Building	Residential
4	No. of Floors	Ground + 3 Upper Floors
5	Whether stilt / podium / open parking provided	No Parking Space available at site
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	1970 (Approx.)
11	Present age of building	54 years
12	Residual age of the building	6 years Subject to proper, preventive periodic maintenance & structural repairs.
13	No. of flats (Per Floor)	1 st Floor is having 3 Flats
14	Methodology adopted	As per visual site inspection

B.	External Observation of the Building	
1	Plaster	Normal Condition
2	Chajjas	Normal Condition
3	Plumbing	Normal Condition
4	Cracks on the external walls	Minor cracks found
5	Filling cracks on the external walls	Minor cracks found
6	Cracks on columns & beams	Minor cracks found



Our Pan India Presence at :

- Nanded
- Mumbai
- Aurangabad
- Thane
- Nashik
- Pune
- Ahmedabad
- Rajkot
- Indore
- Delhi NCR
- Raipur
- Jaipur

Regd. Office

B1-001, U/B Floor, BOOMERANG, Chandivali Farm Road, Powai, Andheri East, **Mumbai:** 400072, (M.S.), India

+91 2247495919

mumbai@vastukala.co.in

www.vastukala.co.in

7	Vegetation	Found
8	Leakages of water in the drainage pipes or water pipes	Found
9	Dampness external in the wall due to leakages	Not Found
10	Any other observation about the condition of external side of the building	Structural Stability Report from licensed structural engineers not provided for our verification.
C Internal Observation of the common areas of the building and captioned premises		
1	Beams (Cracks & Leakages)	Minor Cracks Found
2	Columns (Cracks & Leakages)	Minor Cracks Found
3	Ceiling (Cracks & Leakages)	Not Found
4	Leakages inside the property	Not Found
5	Painting inside the property	Normal Condition
6	Maintenance of staircase & cracks	Normal

D	Common Observation	
1	Structural Audit of the Building Under Bye – Laws No. 77 of the Model Bye Laws (Co-Operative Societies Act / Rules)	As per bye Laws No. 77 of Co-Op. Societies bye Laws under the Act the society shall conduct a Structural Audit of the building of the society as follows
2	Remark	Structural Stability Report from licensed structural engineers not provided for our verification.

E	Conclusion
<p>The captioned building is having Ground + 3 Upper Floors which are constructed in year 1970 (Approx.). Estimated future life under present circumstances is about 6 years subject to proper, preventive periodic maintenance & structural repairs.</p> <p>The inspection dated 27.08.2024 of building. The building is well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & Good structural repairs.</p> <p>Our Observations about the structure are given above.</p> <p>The above assessment is based on visual inspection only. Separate structural audit from licensed structural engineers is advised to assess exact balance life of structure.</p>	

For VASTUKALA CONSULTANTS (I) PVT. LTD

Sharadkumar
B. Chalikwar

Digitally signed by Sharadkumar B. Chalikwar
DN: cn=Sharadkumar B. Chalikwar, o=Vastukala
Consultants (I) Pvt. Ltd., ou=CMD,
email=cmd@vastukala.org, c=IN
Date: 2024.08.29 16:36:37 +05'30'

Director

Auth. Sign.

Sharadkumar B. Chalikwar

Structural Engineer Licence No. STATE/R/2022/APL/01785
Govt. Reg. Valuer
Chartered Engineer (India)
Reg. No. (N) CCIT/1-14/52/2008-09
UBI Empanelment No.: ROS:ADV:Valuer/033:008:2021-22



Since 1989

Vastukala Consultants (I) Pvt. Ltd.

An ISO 9001 : 2015 Certified Company



Actual site photographs

