



**VASTUKALA**  
Unlocking Excellence

www.vastukala.co.in

MSME Reg No: UDYAM-MH-18-0083617

An ISO 9001 : 2015 Certified Company

CIN: U74120MH2010PTC207869

## Vastukala Consultants (I) Pvt. Ltd.

Page 1 of 4

Vastu/Mumbai/09/2024/10980/2307995

02/01-01-JAVS

Date: 02.09.2024

### Structural Stability Report

Structural Observation Report Residential Flat No. B/308, 3<sup>rd</sup> Floor, Wing - B, "**Dev Angan Co-op. Hsg. Soc. Ltd.**", Bhakti Residency Complex, Plot No. 1 to 17, Village - Nilemore, Taluka - Vasai, District - Palghar, Nalasopara (West), PIN - 401 203, State - Maharashtra, Country - India.

Name of Owner: **Mr. Shridhar H. Katakdhond**


Name of Proposed Purchaser: **Mr. Arun Arjun Patil.**

This is to certify that on visual inspection, it appears that the structure at "**Dev Angan Co-op. Hsg. Soc. Ltd.**" is in normal condition and the future life can be reasonably taken under good condition and with proper periodic repairs & maintenance is about 45 years.

#### General Information:

A.	Introduction	
1	Name of Building	" <b>Dev Angan Co-op. Hsg. Soc. Ltd.</b> "
2	Property Address	Residential Flat No. B/308, 3 <sup>rd</sup> Floor, Wing - B, " <b>Dev Angan Co-op. Hsg. Soc. Ltd.</b> ", Bhakti Residency Complex, Plot No. 1 to 17, Village - Nilemore, Taluka - Vasai, District - Palghar, Nalasopara (West), PIN - 401 203, State - Maharashtra, Country - India.
3	Type of Building	Residential
4	No. of Floors	Ground + 4 Upper Floors
5	Whether stilt / podium / open parking provided	Open Parking Space
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	2009 (As per Part Occupancy Certificate)
11	Present age of building	15 years
12	Residual age of the building	45 years Subject to proper, preventive periodic maintenance & structural repairs.
13	No. of flats (Per Floor)	3 <sup>rd</sup> Floor is having 4 Flats
14	Methodology adopted	As per visual site inspection

B.	External Observation of the Building	
1	Plaster	Good Condition
2	Chajjas	Good Condition
3	Plumbing	Good Condition



#### Our Pan India Presence at :

- 📍 Nanded
- 📍 Thane
- 📍 Ahmedabad
- 📍 Delhi NCR
- 📍 Mumbai
- 📍 Nashik
- 📍 Rajkot
- 📍 Raipur
- 📍 Aurangabad
- 📍 Pune
- 📍 Indore
- 📍 Jaipur

#### Regd. Office

B1-001, U/B Floor, BOOMERANG, Chandivali Farm Road, Powai, Andheri East, **Mumbai:** 400072, (M.S), India

+91 2247495919

mumbai@vastukala.co.in

www.vastukala.co.in

4	Cracks on the external walls	Not Found
5	Filling cracks on the external walls	Not Found
6	Cracks on columns & beams	Not Found
7	Vegetation	Not Found
8	Leakages of water in the drainage pipes or water pipes	Not Found
9	Dampness external in the wall due to leakages	Not Found
10	Any other observation about the condition of external side of the building	Structural Stability Report from licensed structural engineers not provided for our verification.
<b>C</b>	<b>Internal Observation of the common areas of the building and captioned premises</b>	
1	Beams (Cracks & Leakages)	Not Found
2	Columns (Cracks & Leakages)	Not Found
3	Ceiling (Cracks & Leakages)	Not Found
4	Leakages inside the property	Not Found
5	Painting inside the property	Good Condition
6	Maintenance of staircase & cracks	Good

<b>D</b>	<b>Common Observation</b>	
1	Structural Audit of the Building Under Bye – Laws No. 77 of the Model Bye Laws (Co-Operative Societies Act / Rules)	As per bye Laws No. 77 of Co-Op. Societies bye Laws under the Act the society shall conduct a Structural Audit of the building of the society as follows
2	Remark	<p>i) <b>At the time of site inspection, external condition of the building is good,. Dampness, leakages and cracks are not found.</b></p> <p>ii) <b>Structural Stability Report from licensed structural engineers not provided for our verification.</b></p>

<b>E</b>	<b>Conclusion</b>
<p>The captioned building is having Ground + 4 Upper Floors which are constructed in year 2009 (As per Part Occupancy Certificate). Estimated future life under present circumstances is about 45 years subject to proper, preventive periodic maintenance &amp; structural repairs.</p> <p>The inspection dated 18.07.2024 of building. The building is well as the property is maintained in normal condition &amp; will stand future life subject to proper, preventive periodic maintenance &amp; Good structural repairs.</p> <p>Our Observations about the structure are given above.</p> <p>The above assessment is based on visual inspection only. Separate structural audit from licensed structural engineers is advised to assess exact balance life of structure.</p>	

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Sharadkumar  
B. Chalikwar

Digitally signed by Sharadkumar B. Chalikwar  
DN: cn=Sharadkumar B. Chalikwar,  
o=Vastukala Consultants (I) Pvt. Ltd.,  
ou=CMD, email=cmd@vastukala.org, c=IN  
Date: 2024.09.02 10:36:24 +05'30'

Auth. Sign.

Director

Sharadkumar B. Chalikwar

Structural Engineer Licence No. STATE/R/2022/APL/01785

Govt. Reg. Valuer

Chartered Engineer (India)

Reg No. (N) CCIT/1-14/52/2008-09

SBI Panelment No.: SME / TCC / 2021 – 22 / 85 / 13





Since 1989

Vastukala Consultants (I) Pvt. Ltd.

An ISO 9001 : 2015 Certified Company



## Actual site photographs



## Actual site photographs



DEV ANGAN CO-OP. HSG. SOCIETY LTD.		8-WING
<b>GROUND FLOOR</b>	005 SANJEEV S. SINHA 007 KAREL SINDOES	004 VIKAS KUMAR MOOI 008 NIKHIL DILIP RAJANI
<b>FIRST FLOOR</b>	105 SUDHEER SWAMINATHAN 107 VIJAYENDRA B. KHOT	108 RAJENDRAN G. NAIR 206 SUPRIYA S. JANSANI
<b>SECOND FLOOR</b>	208 RAMSUNDARA BILAWA 209 ANHILUPAR DUBEY	308 OMPRAKASH P. RAI 306 ANITA DHIRAMT SHAH
<b>THIRD FLOOR</b>	305 SWATI B. RAWAL 307 VILAS MAHADEV AKERKAR	308 SHRIDHAR R. KATAKOHOND 406 NARENDRA M. JOSHI
<b>FOURTH FLOOR</b>	405 JAYESH D. RANE 407 SANTOSH KUMAR R. SINGH	408 RAVI PRAKASH S. SINGH