

```
{
  "typeOfReport": {
    "value": "TEV_Report",
    "label": "TEV Report"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Project_TEV",
    "label": "Project TEV"
  },
  "masterTypeOfPurpose": {
    "value": "Project_TEV",
    "label": "Project TEV"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "66ed44ddb9ce4dabceedaf"
    },
    "firstName": "Kalpana",
    "type": "CREDITOFFICER",
    "_id": "66ed44fd364a0f4dac12d708",
    "email": "kalpana.mangarsi@newindiabank.in",
    "lastName": "Mangarsi",
    "mobileNo": "",
    "workMobileNo": "9920756938"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "130000",
    "expectedFees": 0,
    "quotedAmount": "130000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "66ed41dc364a0f4dac12cd98",
  "type": "BANK",
  "name": "New India Co Operative Bank Ltd ",
  "displayName": "New India Co Operative Bank Ltd ",
  "initial": "NIB"
},
"branch": {
  "_id": "66ed44ddb9ce4dabceedaf",
  "name": "Administrative office",
  "branchCode": "",
  "mobileNo": "02266264150",
  "alternateMobileNo": "",
  "email": "kalpana.mangarsi@newindiabank.in",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Mahesh Residency, Tandice Building, M G Road, Dahanukar Wadi,
Kandiwali West Mumbai 400067"
},
"assetsClass": {
  "value": "Tecno_Economic_Viability_(TEV)",
  "label": "Tecno Economic Viability (TEV)"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "66ed441cbdd9ce4dabceea41",
  "zoneName": "MUMBAI"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "64de0528ccaf1e7b7f65b92e",
    "role": "PICKUPPERSON",
    "firstName": "G V K ",
```

```
"email": "pillai@vastukala.org",
"lastName": "Pillai ",
"mobileNo": "9820315353",
"shortName": "GP",
"workWithDocumentMaker": ""
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "65d48a59cf7ad63a0af8188b",
  "role": "SITEENGINEER+MAKAR",
  "firstName": "Uday",
  "email": "udayp@vastukala.org",
  "lastName": "Patil",
  "mobileNo": "9730325954",
  "designation": "TEV Maker",
  "shortName": "Uday",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453"
},
```

```
"checker": {
  "type": "EMPLOYEE",
  "_id": "5ffe92d27737ca4d986b6453",
  "role": "VALUER",
  "firstName": "Manoj",
  "email": "manoj@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9819597579",
  "designation": "Registered Valuer",
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg"
},
"valuers": []
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "17.508153431146265",
  "longitude": "75.24942752483439"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "20/09/2024 04:01 pm"
    },
    {
      "dateTime": "20/09/2024 12:00 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
}
```

```
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Manjari",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Solapur",
```

```
"label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Sangola",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
```

```
"name": "Street 1",
"key": "street1",
"value": "Sangola- Pandharpur Road",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
}
```

```
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
```



```
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "413317",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
```

```
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
```

```
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
```

```
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
},
```

```
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
}
```

```
"isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
```



```
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66ed4e95bdd9ce4dabcefd95",
"ownerName": "AYUSH PAPER MILLS",
"ownerPhoneNo": "0000000000",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "0000000000",
"contactPersonName": "AYUSH PAPER MILLS",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "AYUSH PAPER MILLS",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "735096"
  }
],
"caseReferredBy": "64de0528ccaf1e7b7f65b92e",
"relationWithOwner": "self",
"fullAddress": "Residential TEV Report No. Ground Floor, Sangola- Pandharpur Road,
Village - Manjari, Taluka - Sangola, District - Solapur, 413317, State - Maharashtra,
India",
"remark": "",
"documents": [],
"isUrgent": "false",
"isExternal": "false",
"proposePurchaserName": "",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "011335",
"createdBy": "6006d4ce5080a310ac1fd9c2",
"caseHistory": [
  {
    "id": "567251",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Fri Sep 20 2024 15:59:41 GMT+0530 (India Standard Time)"
  }
],
"proposePurchasers": [],
```

```
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67035ae7ba5e64b24a2feea1",
    "name":
"externalImg_1728273127512_WhatsApp_Image_20240927_at_123215_18.jpeg",
    "path": "cases/66ed4e95bdd9ce4dabcefd95/
externalImg_1728273127512_WhatsApp_Image_20240927_at_123215_18.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67035ae7ba5e64b24a2feea2",
    "name":
"externalImg_1728273127513_WhatsApp_Image_20240927_at_123215_19.jpeg",
    "path": "cases/66ed4e95bdd9ce4dabcefd95/
externalImg_1728273127513_WhatsApp_Image_20240927_at_123215_19.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67035ae7ba5e64b24a2feea3",
    "name":
"externalImg_1728273127519_WhatsApp_Image_20240927_at_123215_20.jpeg",
    "path": "cases/66ed4e95bdd9ce4dabcefd95/
externalImg_1728273127519_WhatsApp_Image_20240927_at_123215_20.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67035ae7ba5e64b24a2feea4",
    "name":
"externalImg_1728273127521_WhatsApp_Image_20240927_at_123215_21.jpeg",
    "path": "cases/66ed4e95bdd9ce4dabcefd95/
externalImg_1728273127521_WhatsApp_Image_20240927_at_123215_21.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67035ae7ba5e64b24a2feea5",
    "name":
"externallmg_1728273127525_WhatsApp_Image_20240927_at_123215_22.jpeg",
    "path": "cases/66ed4e95bdd9ce4dabcefd95/
externallmg_1728273127525_WhatsApp_Image_20240927_at_123215_22.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67035ae7ba5e64b24a2feea6",
    "name":
"externallmg_1728273127535_WhatsApp_Image_20240927_at_123216_1.jpeg",
    "path": "cases/66ed4e95bdd9ce4dabcefd95/
externallmg_1728273127535_WhatsApp_Image_20240927_at_123216_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67035ae7ba5e64b24a2feea7",
    "name":
"externallmg_1728273127537_WhatsApp_Image_20240927_at_123216_2.jpeg",
    "path": "cases/66ed4e95bdd9ce4dabcefd95/
externallmg_1728273127537_WhatsApp_Image_20240927_at_123216_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67035ae7ba5e64b24a2feea8",
    "name":
"externallmg_1728273127549_WhatsApp_Image_20240927_at_123216.jpeg",
    "path": "cases/66ed4e95bdd9ce4dabcefd95/
externallmg_1728273127549_WhatsApp_Image_20240927_at_123216.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67035ae7ba5e64b24a2feea9",
```

```
"name":
"externallmg_1728273127552_WhatsApp_Image_20240927_at_123208.jpeg",
  "path": "cases/66ed4e95bdd9ce4dabcefd95/
externallmg_1728273127552_WhatsApp_Image_20240927_at_123208.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67035ae7ba5e64b24a2feea",
  "name":
"externallmg_1728273127553_WhatsApp_Image_20240927_at_123212.jpeg",
  "path": "cases/66ed4e95bdd9ce4dabcefd95/
externallmg_1728273127553_WhatsApp_Image_20240927_at_123212.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67035af3c691adb224f69eab",
  "name":
"externallmg_1728273139789_WhatsApp_Image_20240927_at_123215_1.jpeg",
  "path": "cases/66ed4e95bdd9ce4dabcefd95/
externallmg_1728273139789_WhatsApp_Image_20240927_at_123215_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67035af3c691adb224f69eac",
  "name":
"externallmg_1728273139793_WhatsApp_Image_20240927_at_123215_2.jpeg",
  "path": "cases/66ed4e95bdd9ce4dabcefd95/
externallmg_1728273139793_WhatsApp_Image_20240927_at_123215_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67035af3c691adb224f69ead",
  "name":
"externallmg_1728273139796_WhatsApp_Image_20240927_at_123215_3.jpeg",
  "path": "cases/66ed4e95bdd9ce4dabcefd95/
externallmg_1728273139796_WhatsApp_Image_20240927_at_123215_3.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67035af3c691adb224f69eae",
  "name":
"externallmg_1728273139799_WhatsApp_Image_20240927_at_123215_4.jpeg",
  "path": "cases/66ed4e95bdd9ce4dabcefd95/
externallmg_1728273139799_WhatsApp_Image_20240927_at_123215_4.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67035af3c691adb224f69eaf",
  "name":
"externallmg_1728273139801_WhatsApp_Image_20240927_at_123215_5.jpeg",
  "path": "cases/66ed4e95bdd9ce4dabcefd95/
externallmg_1728273139801_WhatsApp_Image_20240927_at_123215_5.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67035af3c691adb224f69eb0",
  "name":
"externallmg_1728273139803_WhatsApp_Image_20240927_at_123215_6.jpeg",
  "path": "cases/66ed4e95bdd9ce4dabcefd95/
externallmg_1728273139803_WhatsApp_Image_20240927_at_123215_6.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67035af3c691adb224f69eb1",
  "name":
"externallmg_1728273139805_WhatsApp_Image_20240927_at_123215_7.jpeg",
  "path": "cases/66ed4e95bdd9ce4dabcefd95/
externallmg_1728273139805_WhatsApp_Image_20240927_at_123215_7.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67035af3c691adb224f69eb2",
  "name":
"externallmg_1728273139807_WhatsApp_Image_20240927_at_123215_8.jpeg",
```

```
    "path": "cases/66ed4e95bdd9ce4dabcefd95/
externallmg_1728273139807_WhatsApp_Image_20240927_at_123215_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67035af3c691adb224f69eb3",
    "name":
"externallmg_1728273139811_WhatsApp_Image_20240927_at_123215_9.jpeg",
    "path": "cases/66ed4e95bdd9ce4dabcefd95/
externallmg_1728273139811_WhatsApp_Image_20240927_at_123215_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67035af3c691adb224f69eb4",
    "name":
"externallmg_1728273139813_WhatsApp_Image_20240927_at_123215_10.jpeg",
    "path": "cases/66ed4e95bdd9ce4dabcefd95/
externallmg_1728273139813_WhatsApp_Image_20240927_at_123215_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67035af3c691adb224f69eb5",
    "name":
"externallmg_1728273139817_WhatsApp_Image_20240927_at_123215_11.jpeg",
    "path": "cases/66ed4e95bdd9ce4dabcefd95/
externallmg_1728273139817_WhatsApp_Image_20240927_at_123215_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67035af3c691adb224f69eb6",
    "name":
"externallmg_1728273139818_WhatsApp_Image_20240927_at_123215_12.jpeg",
    "path": "cases/66ed4e95bdd9ce4dabcefd95/
externallmg_1728273139818_WhatsApp_Image_20240927_at_123215_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "67035af3c691adb224f69eb7",
    "name":
"externallmg_1728273139820_WhatsApp_Image_20240927_at_123215_13.jpeg",
    "path": "cases/66ed4e95bdd9ce4dabcefd95/
externallmg_1728273139820_WhatsApp_Image_20240927_at_123215_13.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67035af3c691adb224f69eb8",
    "name":
"externallmg_1728273139825_WhatsApp_Image_20240927_at_123215_14.jpeg",
    "path": "cases/66ed4e95bdd9ce4dabcefd95/
externallmg_1728273139825_WhatsApp_Image_20240927_at_123215_14.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67035af3c691adb224f69eb9",
    "name":
"externallmg_1728273139828_WhatsApp_Image_20240927_at_123215_15.jpeg",
    "path": "cases/66ed4e95bdd9ce4dabcefd95/
externallmg_1728273139828_WhatsApp_Image_20240927_at_123215_15.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67035af3c691adb224f69eba",
    "name":
"externallmg_1728273139833_WhatsApp_Image_20240927_at_123215_16.jpeg",
    "path": "cases/66ed4e95bdd9ce4dabcefd95/
externallmg_1728273139833_WhatsApp_Image_20240927_at_123215_16.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67035af3c691adb224f69ebb",
    "name":
"externallmg_1728273139835_WhatsApp_Image_20240927_at_123215_17.jpeg",
    "path": "cases/66ed4e95bdd9ce4dabcefd95/
externallmg_1728273139835_WhatsApp_Image_20240927_at_123215_17.jpeg",
```

```

    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67035af3c691adb224f69ebc",
    "name":
"externallmg_1728273139840_WhatsApp_Image_20240927_at_123215.jpeg",
    "path": "cases/66ed4e95bdd9ce4dabcefd95/
externallmg_1728273139840_WhatsApp_Image_20240927_at_123215.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-09-20T10:29:41.669Z",
"updatedAt": "2024-10-07T03:52:19.883Z",
"__v": 0,
"addressForMap": "",
"updatedBy": "6006d4ce5080a310ac1fdcf2"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			