

## Structural Stability Report

Structural Observation Report of Residential Flat No. 7, Ground Floor, "Swaminarayan Co-Op. Hsg. Soc. Ltd.", Ghodbunder Road, Kapurbawadi, Village - Majiwade, Thane (West), Thane - 400 606, State - Maharashtra, Country - India.

Name of Owner: Mrs. Sonia Mohan Nigam

This is to certify that on visual inspection, it appears that the structure of the at " Swaminarayan Co-Op. Hsg. Soc. Ltd.", is in normal condition and the future life can be reasonably taken under good condition and with proper periodic repairs & maintenance is about 27 years.

### General Information:

A.	Introduction	
1	Name of Building	" Swaminarayan Co-Op. Hsg. Soc. Ltd."
2	Property Address	Residential Flat No. 7, Ground Floor, "Swaminarayan Co-Op. Hsg. Soc. Ltd.", Ghodbunder Road, Kapurbawadi, Village - Majiwade, Thane (West), Thane - 400 606, State - Maharashtra, Country - India.
3	Type of Building	Residential used
4	No. of Floors	Ground + 4 <sup>th</sup> Upper Floors
5	Whether stilt / podium / open parking provided	Open Car Parking Space
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	9" thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	1991 (As Per Occupancy Certificate)
11	Present age of building	33 years
12	Residual age of the building	27 years Subject to proper, preventive periodic maintenance & structural repairs.
13	No. of flats (Per Floor)	08 Flats on Ground Floor
14	Methodology adopted	As per visual site inspection

B.	External Observation of the Building	
1	Plaster	Normal Condition
2	Chajjas	Normal Condition
3	Plumbing	Normal Condition
4	Cracks on the external walls	Not Found
5	Filling cracks on the external walls	Not Found
6	Cracks on columns & beams	Not Found



### Our Pan India Presence at :

- 📍 Nanded
- 📍 Thane
- 📍 Ahmedabad
- 📍 Delhi NCR
- 📍 Mumbai
- 📍 Nashik
- 📍 Rajkot
- 📍 Raipur
- 📍 Aurangabad
- 📍 Pune
- 📍 Indore
- 📍 Jaipur

### Regd. Office

B1-001, U/B Floor, BOOMERANG, Chandivall Farm Road,

Powai, Andheri East, Mumbai- 400072, (M.S), India

☎ +91 2247485919

✉ mumbai@vastukala.co.in

🌐 www.vastukala.co.in

7	Vegetation	Not Found
8	Leakages of water in the drainage pipes or water pipes	Not Found
9	Dampness external in the wall due to leakages	Not Found
10	Any other observation about the condition of external side of the building	Structural Stability Report from licensed structural engineers not provided for our verification.
<b>C</b>	<b>Internal Observation of the common areas of the building and captioned premises</b>	
1	Beams (Cracks & Leakages)	Internal renovation work was in progress
2	Columns (Cracks & Leakages)	Internal renovation work was in progress
3	Ceiling (Cracks & Leakages)	Internal renovation work was in progress
4	Leakages inside the property	Internal renovation work was in progress
5	Painting inside the property	Internal renovation work was in progress
6	Maintenance of staircase & cracks	Internal renovation work was in progress

<b>D</b>	<b>Common Observation</b>	
1	Structural Audit of the Building Under Bye – Laws No. 77 of the Model Bye Laws (Co-Operative Societies Act / Rules)	As per bye Laws No. 77 of Co-Op. Societies bye Laws under the Act the society shall conduct a Structural Audit of the building of the society as follows
2	Remark	i) At the time of site visit, Internal renovation work was in progress.

<b>E</b>	<b>Conclusion</b>
<p>The captioned building is having Ground + 4<sup>th</sup> Upper Floors which are constructed in year 1991 (As Per Occupancy Certificate) Estimated future life under present circumstances is about 27 years subject to proper, preventive periodic maintenance &amp; structural repairs.</p> <p>The inspection dated 12.09.2024 of building. The building is well as the property is maintained in normal condition &amp; will stand future life subject to proper, preventive periodic maintenance &amp; Good structural repairs. Our Observations about the structure are given above.</p> <p>The above assessment is based on visual inspection only. Separate structural audit from licensed structural engineers is advised to assess exact balance life of structure.</p>	

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Sharadkumar  
Chalikwar

Digitally signed by Sharadkumar Chalikwar  
DN: cn=Sharadkumar Chalikwar, o=Vastukala  
Consultants (I) Pvt. Ltd., ou=Mumbal,  
email=cmd@vastukala.org, c=IN  
Date: 2024.09.21 16:14:52 +05'30'



Auth. Sign.

Director

Sharadkumar B. Chalikwar

Structural Engineer Licence No. STATE/R/2022/APL/01785

Govt. Reg. Valuer

Chartered Engineer (India)

Reg No. (N) CCIT/1-14/52/2008-09



Since 1989

Vastukala Consultants (I) Pvt. Ltd.

An ISO 9001 : 2015 Certified Company



### Actual site photographs

