

Structural Stability Report

Residential Land and Bungalow on **Plot No.202**,Ground Floor, Survey No.307B+308A, Near Saigram Garden, Saigram Nagar, Upendra Nagar Colony, Ambad Uttam Nagar Link Road, Village - Ambadkhurd, Taluka - Nashik, District – Nashik, PIN Code – 422 010, State – Maharashtra, Country – India. belongs to **Shri. Rahul Samadhan Pawar & Shri. Samadhan Karbhari Pawar**

This is to certify that on visual inspection, it appears that the structure of "**Bungalow on Plot No.202**" is in normal condition and the future life can be reasonably takes under normal condition and with proper periodic repairs & maintenance is about 35 years.

General Information:

A.	Introduction	
1	Name of Building	" Bungalow on Plot No.202 "
2	Property Address	Residential Land and Bungalow on Plot No.202 ,Ground Floor, Survey No.307B+308A, Near Saigram Garden , Saigram Nagar, Upendra Nagar Colony, Ambad Uttam Nagar Link Road, Village - Ambadkhurd, Taluka - Nashik, District – Nashik, PIN Code – 422 010, State – Maharashtra, Country – India
3	Type of Building	Residential Land and Bungalow on Plot No.202
4	No. of Floors	Ground Floor
5	Whether stilt / podium / open parking provided	Open Car Parking
6	Type of Construction	R.C.C. Framed Structure
7	Type of Foundation	R.C.C. Footing
8	Thickness of the External Walls	6' thick brick walls both sides plastered
9	Type of Compound	Brick Masonry Walls
10	Year of Construction	1999 (As per Full Occupancy Certificate)
11	Present age of building	25 years
12	Residual age of the building	35 years Subject to proper, preventive periodic maintenance & structural repairs.
13	No. of Units	Residential Land and Bungalow on Plot No.202
14	Methodology adopted	As per visual site inspection



B. External Observation of the Building		
1	Plaster	Good
2	Chajjas	Good
3	Plumbing	Good
4	Cracks on the external walls	Not Found
5	Filling cracks on the external walls	Not Found
6	Cracks on columns & beams	Not Found
7	Vegetation	Not Found
8	Leakages of water in the drainage pipes or water pipes	Not Found
9	Dampness external in the wall due to leakages	Found
10	Any other observation about the condition of external side of the building	The external condition of the structure is in Good condition
C Internal Observation of the common areas of the building and captioned premises		
1	Beams (Cracks & Leakages)	Not found
2	Columns (Cracks & Leakages)	Not found
3	Ceiling (Cracks & Leakages)	Not found
4	Leakages inside the property	Not Found
5	Painting inside the property	Good
6	Maintenance of staircase & cracks	Good

D Common Observation		
1	Structural Audit of the Building Under Bye – Laws No. 77 of the Model Bye Laws (Co-Operative Societies Act / Rules)	As per bye Laws No. 77 of Co-Op. Societies bye Laws under the Act the society shall conduct a Structural Audit of the building of the society as follows
2	Remark	-

E Conclusion	
<p>The captioned Flat is having Ground floor which are constructed in year 1999 (As per Possession Receipt). Estimated future life under present circumstances is about 35 years' subject to proper, preventive periodic maintenance & structural repairs.</p> <p>The inspection dated 16.09.2024 reveals no structural damage or deterioration to the building. The building as well as the property is maintained in normal condition & will stand future life subject to proper, preventive periodic maintenance & Average structural repairs.</p> <p>Our Observations about the structure are given above.</p> <p>The above assessment is based on visual inspection only.</p>	

For VASTUKALA CONSULTANTS (I) PVT. LTD.

Sharadkumar
Chalikwar

Digitally signed by Sharadkumar Chalikwar
DN: cn=Sharadkumar Chalikwar, o=Vastukala
Consultants (I) Pvt. Ltd., ou=Mumbai,
email=cmd@vastukala.org, c=IN
Date: 2024.09.25 11:48:48 +05'30'


Auth. Sign.

Director

Sharadkumar B. Chalikwar

Structural Engineer Licence No. STATE/R/2022/APL/01785

Govt. Reg. Valuer

Chartered Engineer (India)

Reg No. (N) CCIT/1-14/52/2008-09

Bank Of Baroda Empanelment No.: ZO:MZ: ADV:44:620



Since 1989

Vastukala Consultants (I) Pvt. Ltd.

An ISO 9001 : 2015 Certified Company



ACTUAL SITE PHOTOGRAPHS

