

```
{
  "typeOfReport": {
    "label": "Office",
    "value": "Office"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6423c8a66c6a0c533530618c"
    },
    "firstName": "Trupti",
    "type": "CREDITOFFICER",
    "_id": "66fb717cd03c6a0f3e4ad8a2",
    "email": "mcc6042@pnb.co.in",
    "lastName": "Shah",
    "mobileNo": "",
    "workMobileNo": "9326334286"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "10454524",
    "discussWithPerson": "Trupti",
    "expectedFees": 5227.262,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1812",
  "type": "BANK",
  "name": "Punjab National Bank",
  "displayName": "Punjab National Bank",
  "initial": "PNB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6423c8a66c6a0c533530618c",
  "name": "MCC Western One",
  "branchCode": "",
  "mobileNo": "7738450231",
  "alternateMobileNo": "",
  "email": "Mcc6042@pnb.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "PNB Pragati Tower C 9, G Block, Ground floor, Bandra Kurla Complex,
Bandra(E), Mumbai - 400051, State - Maharashtra, Country - India"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f7fcadf3dd69653a58d9d7",
  "zoneName": "Mumbai Zone (Maharashtra)"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "62723addafd7d55eddeddfe4",
  "role": "PICKUPPERSON",
  "firstName": "Ramkrishna ",
  "email": "rampatakar1991@gmail.com",
  "lastName": "Patkar",
  "mobileNo": "7045746060",
  "shortName": "RP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62691c48afd7d55eddecfda3",
  "role": "FRONTDESK",
  "firstName": "Bhavika",
  "email": "bhavikachavan0102@gmail.com",
  "lastName": "chavan",
  "mobileNo": "8390804382",
  "designation": "Site Engineer",
  "shortName": "BH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "6084131a13f01f158c6ea1f3",
  "PANNo": "AEAPC7114Q",
  "role": "VALUER",
  "firstName": "Sharadkumar",
  "fatherName": "Baburao",
  "email": "cmd@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9422171100",
  "designation": "CMD",
```

```
"registrationNo": [
  {
    "title": {
      "value": "Wealth_Tax",
      "label": "Wealth Tax"
    },
    "_id": "6084131a13f01f158c6ea1f4",
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
],
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.132903070549354",
  "longitude": "72.83621927896452"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.83621927896452,
    19.132903070549354
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-11-13",
      "remark": "contact person - Nikhil khakhar "
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
}
```

```
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "10",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
    "value": "41",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
    "value": "",

```

```
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Azadnagar Excel CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
```

```
"name": "Street 1",
"key": "street1",
"value": "Azad Nagar",
"label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Veera Desai Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
}
```

```
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1001",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
```



```
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400053",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Andheri West",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
```

```
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
```

```
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
```

```
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": true,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "PARTIAL",
isExternalReport": false,
isSiteMeasurementAllowed": true,
finalValuationArea": "0",
```



```
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67332855de9916aa96461b0f",
"ownerName": "Indman Marine Management Consultant Pvt Ltd",
"ownerPhoneNo": "0000000000",
"appAddress": "OFC no - 1001, B wing , 10th floor, new excle of Azad nagar excle
chsl, Veera Desai road, Andheri West ",
"remark": "contact person - Nikhil khakhar ",
"documents": [
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/67332855de9916aa96461b0f/
document_1731405882926_1731405880074_1001_Indman.pdf",
    "fileName": "document_1731405882926_1731405880074_1001_Indman.pdf",
    "id": "961084",
    "uploadedBy": "62723addafd7d55eddeddfe4",
    "createdAt": "Tue Nov 12 2024 10:05:08 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1731492649296_Document_3.pdf",
    "path": "cases/67332855de9916aa96461b0f/
document_1731492649296_Document_3.pdf",
    "id": "457879",
    "uploadedBy": "62691c48afd7d55eddecfd3",
    "createdAt": "Wed Nov 13 2024 10:10:51 GMT+0000 (Coordinated Universal Time)"
  }
],
"caseNumber": "012320",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
```

```
{
  "id": "896643",
  "title": "Create Lead",
  "description": "Create Lead",
  "datetime": "Tue Nov 12 2024 10:05:09 GMT+0000 (Coordinated Universal Time)"
},
"owners": [
  {
    "name": "Indman Marine Management Consultant Pvt Ltd",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "812006"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673479a279293cc1976190eb",
    "name": "externalimg_1731492250607_1731492244118_image_0.jpeg",
    "path": "cases/67332855de9916aa96461b0f/externalimg_1731492250607_1731492244118_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673479a279293cc1976190ec",
    "name": "externalimg_1731492250973_1731492244121_image_1.jpeg",
    "path": "cases/67332855de9916aa96461b0f/externalimg_1731492250973_1731492244121_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "673479a279293cc1976190ed",
    "name": "externallmg_1731492251415_1731492244121_image_2.jpeg",
    "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492251415_1731492244121_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673479a279293cc1976190ee",
    "name": "externallmg_1731492251605_1731492244121_image_3.jpeg",
    "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492251605_1731492244121_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673479a279293cc1976190ef",
    "name": "externallmg_1731492252119_1731492244121_image_4.jpeg",
    "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492252119_1731492244121_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673479a279293cc1976190f0",
    "name": "externallmg_1731492252263_1731492244121_image_5.jpeg",
    "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492252263_1731492244121_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673479a279293cc1976190f1",
    "name": "externallmg_1731492252903_1731492244121_image_6.jpeg",
    "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492252903_1731492244121_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673479a279293cc1976190f2",
```

```
    "name": "externallmg_1731492253418_1731492244121_image_7.jpeg",
    "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492253418_1731492244121_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673479a279293cc1976190f3",
    "name": "externallmg_1731492253760_1731492244121_image_8.jpeg",
    "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492253760_1731492244121_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673479a279293cc1976190f4",
    "name": "externallmg_1731492254152_1731492244121_image_9.jpeg",
    "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492254152_1731492244121_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673479a279293cc1976190f5",
    "name": "externallmg_1731492254496_1731492244121_image_10.jpeg",
    "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492254496_1731492244121_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673479a279293cc1976190f6",
    "name": "externallmg_1731492254693_1731492244121_image_11.jpeg",
    "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492254693_1731492244121_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673479a279293cc1976190f7",
    "name": "externallmg_1731492254968_1731492244121_image_12.jpeg",
```

```
    "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492254968_1731492244121_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673479a279293cc1976190f8",
    "name": "externallmg_1731492255093_1731492244121_image_13.jpeg",
    "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492255093_1731492244121_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673479a279293cc1976190f9",
    "name": "externallmg_1731492255804_1731492244121_image_14.jpeg",
    "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492255804_1731492244121_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673479a279293cc1976190fa",
    "name": "externallmg_1731492256249_1731492244121_image_15.jpeg",
    "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492256249_1731492244121_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673479a279293cc1976190fb",
    "name": "externallmg_1731492256619_1731492244121_image_16.jpeg",
    "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492256619_1731492244121_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673479a279293cc1976190fc",
    "name": "externallmg_1731492257082_1731492244121_image_17.jpeg",
    "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492257082_1731492244121_image_17.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "673479a279293cc1976190fd",
  "name": "externallmg_1731492257617_1731492244121_image_18.jpeg",
  "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492257617_1731492244121_image_18.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6734798379293cc19761908e",
  "name": "externallmg_1731492220020_1731492186021_image_1.jpeg",
  "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492220020_1731492186021_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6734798379293cc197619090",
  "name": "externallmg_1731492220278_1731492186021_image_3.jpeg",
  "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492220278_1731492186021_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6734798379293cc197619091",
  "name": "externallmg_1731492220683_1731492186021_image_4.jpeg",
  "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492220683_1731492186021_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6734798379293cc197619092",
  "name": "externallmg_1731492221092_1731492186021_image_5.jpeg",
  "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492221092_1731492186021_image_5.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6734798379293cc197619093",
      "name": "externallmg_1731492221498_1731492186021_image_6.jpeg",
      "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492221498_1731492186021_image_6.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6734798379293cc197619094",
      "name": "externallmg_1731492221935_1731492186021_image_7.jpeg",
      "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492221935_1731492186021_image_7.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6734798379293cc197619095",
      "name": "externallmg_1731492221943_1731492186021_image_8.jpeg",
      "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492221943_1731492186021_image_8.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6734798379293cc197619096",
      "name": "externallmg_1731492222156_1731492186021_image_9.jpeg",
      "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492222156_1731492186021_image_9.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "6734798379293cc197619097",
      "name": "externallmg_1731492222213_1731492186021_image_10.jpeg",
      "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492222213_1731492186021_image_10.jpeg",
      "orientation": "portrait"
    },
  },
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6734798379293cc197619098",
  "name": "externallmg_1731492222638_1731492186021_image_11.jpeg",
  "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492222638_1731492186021_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6734798379293cc197619099",
  "name": "externallmg_1731492222713_1731492186021_image_12.jpeg",
  "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492222713_1731492186021_image_12.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6734798379293cc19761909a",
  "name": "externallmg_1731492223300_1731492186021_image_13.jpeg",
  "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492223300_1731492186021_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6734798379293cc19761909b",
  "name": "externallmg_1731492223538_1731492186021_image_14.jpeg",
  "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492223538_1731492186021_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "6734798379293cc19761909c",
  "name": "externallmg_1731492224143_1731492186021_image_15.jpeg",
  "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492224143_1731492186021_image_15.jpeg",
  "orientation": "portrait"
},
{
```



```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6734798379293cc19761909d",
    "name": "externallmg_1731492224742_1731492186021_image_16.jpeg",
    "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492224742_1731492186021_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6734798379293cc19761909e",
    "name": "externallmg_1731492225070_1731492186021_image_17.jpeg",
    "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492225070_1731492186021_image_17.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6734798379293cc19761909f",
    "name": "externallmg_1731492225703_1731492186021_image_18.jpeg",
    "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492225703_1731492186021_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6734798379293cc1976190a0",
    "name": "externallmg_1731492226260_1731492186021_image_19.jpeg",
    "path": "cases/67332855de9916aa96461b0f/
externallmg_1731492226260_1731492186021_image_19.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673485de79293cc19761a7e5",
    "name":
"externallmg_1731495390503_WhatsApp_Image_20241113_at_42532_PM_1.jpeg",
    "path": "cases/67332855de9916aa96461b0f/
externallmg_1731495390503_WhatsApp_Image_20241113_at_42532_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673485de79293cc19761a7e6",
    "name":
"externalImg_1731495390507_WhatsApp_Image_20241113_at_42532_PM.jpeg",
    "path": "cases/67332855de9916aa96461b0f/
externalImg_1731495390507_WhatsApp_Image_20241113_at_42532_PM.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "62691c48afd7d55eddecfda3",
      "role": "FRONTDESK",
      "firstName": "Bhavika",
      "lastName": "chavan",
      "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
    },
    "workType": "SITE_INSPECTION",
    "display": true,
    "status": true,
    "_id": "67348586ddcb46c198ac7aa8",
    "note": "Photos (Task Reopen)",
    "taskId": "673338a3c3f75eaa95dfb295",
    "createdAt": "2024-11-13T10:55:02.069Z"
  }
],
"createdAt": "2024-11-12T10:05:09.110Z",
"updatedAt": "2024-11-13T10:56:30.635Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Office No. 1001, 10th Floor, Building No 41, Wing - B,
Azadnagar Excel CHSL, Azad Nagar, Veera Desai Road, Andheri West, Mumbai,
400053, State - Maharashtra, India",
"updatedBy": "62691c48afd7d55eddecfda3",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
```

"contactPersonName": "Indman Marine Management Consultant Pvt Ltd",  
"email": "",  
"isExternal": "false",  
"isUrgent": "false",  
"ownershipShare": "",  
"proposePurchaserName": "",  
"purchaseValueAsPerDocument": "",  
"relationWithOwner": "self",  
"rerald": "",  
"siteVisitContactNo": "0000000000",  
"siteVisitDate": "2024-11-13"

}

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
-------------	---------------	--------------	--------------

---

Composition :

---

Other

Composition :

---